G1 - 3818	3818 SEQUENCE NO. (MDE USE ONLY)		STATE OF MARYLAND	THIS REPORT MUST BE SUBMITTED WITHIN 45 DAYS AFTER WELL IS COMPLETED.	
1 2 3 (THIS NUMBER IS TO BE PUNCHED			WELL COMPLETION REPORT FILL IN THIS FORM COMPLETELY PLEASE TYPE	COUNTY NUMBER (73) A520852	
IN COLS. 3-6 ON ALL CARDS) ST/CO USE ONLY DATE WELL COMPLE		COMPL		PERMIT NO	
DATE Received			2 700 26	FROM "PERMIT TO DRILL WELL"	
6 13	1 7 0	11	(TO NEAREST FOOT)	3 /4/05 28 29 30 31 32 33 34 38 36 37	
OWNER	Phillip	5	Chia Mill Road TOWN C	Interitte	
STREET OR RFD	harles	Dor		LOT	
WELL			GROUTING RECORD no	C 3	
Not required for			WELL HAS BEEN GROUTED (Circle Appropriate Box)	1 2 PUMPING TEST	
STATE THE KIND OF FORMA COLOR, DEPTH, THICKNESS	TIONS PENETRATED S AND IF WATER BE		TYPE OF GROUTING MATERIAL (Circle one)	HOURS PUMPED (nearest hour)	
DESCRIPTION (Use additional sheets if needed)	FEET TO	check if water bearing	CEMENT C M BENTONITE CLAY B C	DUMPING DATE (and pass min.)	
TOPSOUL,	0 2		NO. OF BAGS NO. OF POUNDS 1600	PUMPING RATE (gal. per min.)	
Grang 15h brown	26		DEPTH OF GROUT SEAL (to nearest foot)	METHOD USED TO MEASURE PUMPING RATE Bucket	
Tockyclay	. 0		from 48 TOP 52 ft. to 54 BOTTOM 58 ft.	WATER LEVEL (distance from land surface)	
Brown rocky chy	20		(enter 0 if from surface) Casing CASING RECORD	BEFORE PUMPING 101 ft.	
Brown Mica	8 29		types the transfer to the tran	227	
Grayish/Dlue Slate			(appropriate) STEEL CONCRETE	WHEN PUMPING 25 ft.	
Gray Mica	43 70		code below PLASTIC OTHER	TYPE OF PUMP USED (for test)	
Grown Mica	70 -73		MAIN Nominal diameter Total depth	A air P piston T turbine	
Brown Mica	73 77	. /	CASING top (main) casing of main casing TYPE (nearest inch)! (nearest foot)	C centrifugal R rotary O (describe	
Gray MK9	77 375	/	St 6 40	27 below)	
Green Mica	375 380	9	60 61 66 64 66 70	J jet S submersible	
bray Mica	380 394		A diemeter depth (feet)	/	
Green Mica	394 397			PUMP INSTALLED TO DRILLER INSTALLED PUMP YES NO	
	397 525	-	\$ · · · · · · · · · · · · · · · · · · ·	(CIRCLE) (YES or NO)	
Gray MICA	525 529		ë —	IF DRILLER INSTALLS PUMP, THIS SECTION MUST BE COMPLETED FOR ALL WELLS.	
Green MICA	529 622		screen type or open hole	TYPE OF PUMP INSTALLED PLACE (A,C,J,P,R,S,T,O) 29	
Gray Mica	622 625		insert STEFT BRASS OPEN	IN BOX 29.	
Gravel Bed Sandstone	625 700		appropriate BRONZE HOLE	CAPACITY: GALLONS PER MINUTE	
Sands ronc	60 100		below PLASTIC OTHER	(to nearest gallon) 31 35	
			C 2 DEPTH (nearest ft.)	PUMP HORSE POWER 37 41 PUMP COLUMN LENGTH	
NUMBER OF UNSUCCESS	FUL WELLS:	0_	121/0 40	(nearest ft.)	
WELL HYDROFRACTURED	yes	no N)	E 8 9 11 15 17 21	CASING HEIGHT (circle appropriate box and enter casing height)	
	PRIATE LETTER		C 2 1 23 24 26 30 32 36	LAND SURFACE	
A A WELL WAS ABANDON WHEN THIS WELL WAS	COMPLETED		S C 3	below 2 (nearest) foot)	
P TEST WELL CONVERTE		N	R 38 39 41 45 47 51	49 50 51 A LOCATION OF WELL ON LOT	
I HEREBY CERTIFY THAT THIS W			E SLOT SIZE 1 2 3	SHOW PERMANENT STRUCTURE SUCH AS	
ACCORDANCE WITH COMAR 26.04 IN CONFORMANCE WITH ALL COL CAPTIONED PERMIT, AND THAT	4.04 "WELL CONSTRUCT NOTIONS STATED IN 1	TION" AND	DIAMETER (NEAREST INCH)	BUILDING, SEPTIC TANKS, AND /OR LANDMARKS AND INDICATE NOT LESS	
HEREIN IS ACCURATE AND CO			56 60 from to	THAN TWO DISTANCES (MEASUREMENTS TO WELL)	
DRILLERS LIC. NO. 1 M WD 040 1 GRA			GRAVEL PACK	tradelphia Mill Rd	
Searce 7 Kestenlyn W.			IF WELL DRILLED WAS FLOWING WELL INSERT F IN BOX 68 68	12	
to the second se			MDE USE ONLY		
LIC. NO.1 IWD227			T (E.R.O.S.) W Q	6	
Harblin Si	encletin 1	SW	70 72	, , ,	
SITE SUPERVISOR (sign. responsible for sitework if d			TELESCOPE LOG 74 75 78	10 %	
	The state of the s		CASING INDICATOR OTHER DATA	•	
DENV-CR00			COUNTY		

DENV-Permit 97

② COUNTY

ge of	
U1	
Date	

10.28.	.04	
10.20		

	The second secon	
Done i or .		
Review		6000

FIELD DATA SHEET HOWARD COUNTY WELL YIELD TEST

Well Permit No. HO - <u>94-4039</u>	15 AAC 0 O	
Location of property (road) Triadelf	phia Mill Road	
Subdivision Charles Dorsey	Lot Block	Plat Sec.
Well Driller Easterday	Owner Grea Ph	illips
Depth of well 700 GPN Distance of measuring point (M.P.) about Static water level (S.W.L.) below M.P.	ve ground 2 PT	
I. High rate pumping reservoir drawdown		
Time pump started 8:45	Pumping rate	15 675
Total time 45 min to reach pumping	water level 333	ft. below M.P.

II. Recovery pump test data - observations to be recorded every 15 minutes

TIME (in 15 minute in- tervals	WATER LEVEL below M.P.	PUMPING RATE time to fill # gallon bucket	PLOW METER READING (if used) Pump 8E7	CALCULATED FLOW (gallons per minute)
936 Am	333 AT	60 su	380 RT	1600
945	333 RT	60 see		1 com
1600	53 3 FT	60 800		1 cem
1015	333 FT	60 See		1 con
1630	333 RT	6084		1600
10 45	333 PT	60 Su		160m
1100	333 PT	60 su		1 cpm
11.15	333 AT	60 SEC)	1 6 Dm
1150	333 pt	60 SEZ	1	1 600
1145	333RT	C6 me	380 PT	16mm
1200 PM	333 RT	37 SER		1.03 6000
1215	334 PT	58 562	7	1.03 CPM
1230	334 61	585EC		1.03 CPM
1245	334 Km	58 SEC	7	1.03 cm
100	334 ET	58 SEC		1.03 GPM
115	334 ES	58 Sec	5	1.03 CPM
130	33469	58 sa		1.05 600
145	334 KI	58826		1.03 6pm
200	334AT	58 3-66		1.03 614
215	334 CT	58 SEC		1.03 Cpm
230	334 151	58 SEC		1.03 600
245	334 RT	58 Sec		1.03 6m
360	334 Pr	58 Sec	7	1,03 60m
315	334 FT	58 Dec	7	1,03 614
HD-224 330	334 RT	58 SE	380 FT	1,03 GPM

FIELD DATA SHEET HOWARD COUNTY WELL YIELD TEST Well Permit No. HO - 94-4039 Location of property (road) Triadelphia Mill Road Subdivision Charles Dorsey Lot Block Plat Sec. Well Driller Fasterday Owner Greg Phillips Depth of well Distance of measuring point (M.P.) above ground Static water level (S.W.L.) below M.P.								
Time pum Total ti		reach pumping water	Pumping rate ft. recorded every 15 minu					
TIME (in 15 minute in-tervals	WATER LEVEL	PUMPING RATE time to fill 5 gallon bucket	FLOW METER READING (if used)	CALCULATED FLOW (gallons per minute)				
	· · · · · · · · · · · · · · · · · · ·							
		·						
			, .					
,								

Review

· Page _____ of



Bureau of Environmental Health 8930 Stanford Blvd | Columbia, MD 21045 410.313.2640 - Voice/Relay 410.313.2648 - Fax 1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

INTERIM CERTIFICATE OF POTABILITY

Expiration Date - JULY 3, 2019

January 3, 2019

Homeowner 13571 Triadelphia Mill Road Clarksville, MD 21029

RE: Charles Dorsey Property, P. 173

13574 Triadelphia Mill Road Building Permit: B17003339 Well Permit: HO-94-4039

Dear Homeowner:

This is to advise you that the septic system installation and water well construction for the above referenced property have been inspected and approved. Final approval of the septic system was granted on 8/31/2018. Final approval of the well line connection to the dwelling was granted on 1/2/2019. The well construction was completed on 10/28/2004. Water samples were collected on 5/29/2018, 7/17/2018, 12/11/2018, 1/2/2019.

The water sample results indicate that the water samples submitted for testing were free of coliform and fecal coliform bacteria at the time of sampling and are bacteriologically safe for drinking. This certifies that the initial sampling requirements of COMAR 26.04.04 "Well Regulations" have been met for the water supply system installed under well permit HO-94-4039. Although the submitted sample results are in compliance with COMAR standards, the Health Department does not guarantee water supplies.

This Interim Certificate of Potability will expire six months from the date of issuance. Submission of a second bacteriological test indicating the water is free of coliform and fecal coliform bacteria is required prior to the expiration date, after which time a Final Certificate of Potability will be issued. Failure to submit an additional sample and obtain a Final Certificate of Potability will result in a Notice of Violation and is punishable as a misdemeanor under the Annotated Code of Maryland, Environment Article, 9-1311, subject to a fine of up to \$500 or imprisonment not to exceed three months.

Please contact (410) 313-1773 to schedule a final water sample appointment or contact a Maryland certified water laboratory to schedule a water sample. A list of laboratories certified by the state of Maryland may be found at the following website: http://www.mde.state.md.us/assets/document/WSP-Labs-2010apr16.pdf

Website: www.hchealth.org Facebook: www.facebook.com/hocohealth Twitter: @HoCoHealth



Bureau of Environmental Health 8930 Stanford Blvd | Columbia, MD 21045 410.313.2640 - Voice/Relay 410.313.2648 - Fax 1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

In closing, please refer to our "<u>Homeowner Fact Sheet</u>" which illustrates a better understanding for your Onsite Sewage Disposal System. You will also find a link to Maryland Department of the Environments website which describes in further detail operation and maintenance of your septic system.

Approving Authority,

Kevin M. Wolf, LEHS, R.S./REHS, Supervisor

- n. VM

Groundwater Management Section

Well & Septic Program

c: Howard County Dept. of Inspections, Licenses, and Permits

Community Hygiene Program

File

1413 Fair town Rd. Westminster, MD (410) 848-1014 (410) 876-4554 FAX (410) 848-0298

REPORT OF ANALYSIS

Laboratory ID #: 122151

Account #: 3690

Reference:

l a Homes

Rylea Homes Company:

Location:

. 5 1 Triadelphia Mill Road

lar sville, MD 21029

Requested By: Jim Ryan

Date/ Time Coll ed: . '29 018

1116

Source:

Well Water Pressure Tank

Date/Tim: Rec' ':

3' '8

1356

Treatment:

Site:

None

C'' :: :

(1, , , ,)

Total: ND

7.6

(1) ! '

4269RO

pH: Well #:

HO-94-4039

PARAM TER Bacteria, Coliform, Total, MPN

LESULTS >200.5 Bacteria, E. coli, N. 'N. <1.0

REFERENCE UNITS MPN/ 100 ml MPN/ 100 ml

mg/L

<1.0 <1.0 10

SM20 9223 601

METHOD

SM20 9223

5/30/2018 / 0900 / CRS 5/29/2018 / 1445 / CRS

DATE/TIME/ANALYST

5/30/2018 / 0900 / CRS

Turbidity Sand

Nitrate

3.97 NS

<1.0

NTU <10 mg/L 5

SM20 2130B

5/29/2018 / 1520 / RER Visual/Gravimetric 5/29/2018 / 1520 / RER

NOTES

- mg/L m'" aris p r liter (also, parts per million)
- A PN' Probable Number [of viable bacteria] per 100 ml of sample.
- indicates less than 5 mg/L)
 - · Jility Units
 - in the reference range are considered satisfactory and within potable water limits at the time of
- 'i i e e c k: Sealed, vented cap
- min evel tested on site

Reason for ! t: Lse & Occupancy

B iil ling Per iit #: B 7003339

FAX (410) 848-0298 1413 Old Taneytown Rd. Westminster, MD (410) 848-1014 (410) 876-4554

REPORT OF ANALYSIS

Laboratory ID #:

123414

Account #:

Reference:

Rylea Homes

3690

Company:

Rylea Homes

Location:

13571 Triadelphia Mill Road

Requested By: Jim Ryan

Clarksville, MD 21029 Date/ Time Collected: 7/17/2018

Source:

Well Water

Date/Time Rec'd:

1400

Site: Treatment:

Pressure Tank None

Chlorine ppm:

7/17/2018 Free: ND

Total: ND

pH:

7.6

Collected By:

G. Lana

3799GL

Well #:

HO-94-4039

PARAMETERS	ESULTS	UNITS RE	FERENCE	METHOD D	ATE/TIME/ANALYST
Bacteria, Coliform, Total, MPN	>200.5	MPN/ 100 ml	<1.0	SM20 9223	7/18/2018 / 1040 / RER
Bacteria, E. coli, MPN	<1.0	MPN/ 100 ml	<1.0	SM20 9223	7/18/2018 / 1040 / RER

NOTES

- MPN/ 100 ml = Most Probable Number [of viable bacteria] per 100 ml of sample. 1
- Results less than or within the reference range are considered satisfactory and within potable water limits at the time of 2 sampling.
- ND:None Detected 3
- Visual well check: Sealed, vented cap
- pH & Chlorine level tested on site

Reason for Test:

Use & Occupancy

Building Permit #:

B17003339

Date Reported:

7/18/2018

1413 Old Taneytown Rd. Westminster, MD (410) 848-1014 (410) 876-4554 FAX (410) 848-0298

REPORT OF ANALYSIS

Laboratory ID #:

127273

Account #:

3690

Reference:

Rylea Homes

Company:

Rylea Homes

Location:

13571 Triadelphia Mill Road

Requested By:

Clarksville, MD 21029

Jim Ryan

Date/ Time Collected: 12/11/2018

Source: 1344

Well Water

Date/Time Rec'd:

1518

Site: Treatment: Kitchen Sink Tap Sediment Filter/**

Chlorine ppm:

12/11/2018 Free: ND

Total: ND

pH:

8.4

Collected By:

J. Yeager

6176JY

Well #:

HO-94-4039

UNITS REFERENCE METHOD DATE/TIME/ANALYST

PARAMETERS -Bacteria, Coliform, Total, MPN Bacteria, E. coli, MPN

12.4 <1.0

RESULTS

MPN/ 100 ml MPN/ 100 ml <1.0 <1.0 SM20 9223B SM20 9223B 12/12/2018 / 1000 / CRS 12/12/2018 / 1000 / CRS

NOTES

- **UV Light disconnected at time of sample collection 1
- 2 MPN/ 100 ml = Most Probable Number [of viable bacteria] per 100 ml of sample.
- 3 Results less than or within the reference range are considered satisfactory and within potable water limits at the time of sampling.
- ND = None Detected 4
- 5 Visual well check: Sealed, vented cap
- pH & Chlorine level tested on site 6

Reason for Test:

Use & Occupancy

Building Permit#:

B17003339

Date Reported:

12/12/2018

1413 Old Taneytown Rd. Westminster, MD (410) 848-1014 (410) 876-4554 FAX (410) 848-0298

REPORT OF ANALYSIS

Laboratory ID #:

127658

Reference:

Account #:

3690

Rylea Homes

Company:

Rylea Homes

Location:

13571 Triadelphia Mill Road Clarksville, MD 21029

Requested By:

Jim Ryan

1045

Source:

Well Water

Date/ Time Collected: 1/2/2019

Site:

Kitchen Sink Tap

Date/Time Rec'd:

1/2/2019

1430

Treatment:

Sediment Filter/UV Light**

Chlorine ppm:

Free: ND

Total: ND

pH:

8.3

Collected By: J. Yeager

6176JY

Well #:

HO-94-4039

PARAMETERS	RESULTS	UNITS RE	RERENCE.	METHOD	ATE/TIME/ANALYST
Bacteria, Coliform, Total, MPN	<1.0	MPN/ 100 ml	<1.0	SM20 9223B	1/3/2019 / 0930 / RER
Bacteria, E. coli, MPN	<1.0	MPN/ 100 ml	<1.0	SM20 9223B	1/3/2019 / 0930 / RER

NOTES

- **UV Light disconnected at time of sample collection 1
- MPN/ 100 ml = Most Probable Number [of viable bacteria] per 100 ml of sample. 2
- Results less than or within the reference range are considered satisfactory and within potable water limits at the time of 3 sampling.
- ND = None Detected
- Visual well check: Sealed, vented cap 5
- pH & Chlorine level tested on site

Reason for Test:

Use & Occupancy

Building Permit#:

B17003339

Date Reported:

1/3/2019

Wolf, Kevin

From:

Wolf, Kevin

Sent:

Friday, December 14, 2018 5:14 PM

To:

'JAMES RYAN'

Subject:

RE: 13571 Triadelphia Mill Road water test results with failing Coliform bacteria

Cheryl,

I spoke with the well driller in length. He explained to me that the well needs to be flushed out completely possibly several attempts. Mr. Greer told me that well cap was not on the well head and looked to be that way for several month. He also went to tell me that there was a lot of debris (i.e. leaves, mud, silt, etc...) that was inside the well column. There is no reason why this should be this way. Standard re-chlorination may be all you need after this flush out is complete. No deviation will be given and you may have the homeowners call me directly with questions and concerns as I would be happy to explain this.

Thanks,

Kevin M. Wolf, LEHS, REHS/RS Groundwater Mgmt. Sec. Supervisor Well & Septic Program Bureau of Environmental Health 8930 Stanford Blvd. Columbia, MD 21045 (o) 410-313-2645 (f) 410-313-2648





kwolf@howardcountymd.gov

CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

From: JAMES RYAN [mailto:ryleahomes@msn.com]

Sent: Friday, December 14, 2018 10:22 AM

To: Wolf, Kevin

Subject: Re: 13571 Triadelphia Mill Road water test results with failing Coliform bacteria

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Kevin -

Wolf, Kevin

From:

Wolf, Kevin

Sent:

Friday, December 14, 2018 10:04 AM

To:

'JAMES RYAN'

Subject:

RE: 13571 Triadelphia Mill Road water test results with failing Coliform bacteria

Cheryl,

After review of the submitted information, we feel the well was not chlorinated correctly per the regulations. It states very clearly:

- E. Disinfection Procedure for Wells That Do Not Respond to the Standard Procedure.
- (1) If, after testing, the well cannot meet the bacteriological standard of this chapter, it shall be chlorinated as in 伶 of this regulation.
- (2) If the well remains unresponsive after repeating the standard disinfection procedure per this section, a volume of water chlorinated to a concentration of 100 mg/l and at least two times the volume of chlorinated, standing water in the well, but not less than 50 gallons, shall be introduced into the well in order to completely displace the volume of chlorinated, standing water and force it out into the water bearing formation.
- F. If bacteriological contamination persists after repeated disinfection, the Approving Authority may require the well to be abandoned and sealed in accordance with this chapter.

At this point, you must re-chlorinate the well per what the regulations state. Make sure there is chlorinated water in the well prior to introducing separate volume of disinfected water 2x the volume. Done correctly, this will force the chlorinated water into the fractures. The report from the driller says they pumped the well out. We do not want to pump the water out of the well prior to introducing the new disinfected water. Please forward this along to the well driller.

Kevin

From: JAMES RYAN [mailto:ryleahomes@msn.com]
Sent: Wednesday, December 12, 2018 3:15 PM

To: Wolf, Kevin

Subject: Fwd: 13571 Triadelphia Mill Road water test results with failing Coliform bacteria

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Kevin -

Attached are the water test results.

I am waiting for an email from John Greer on what he used to ultra chlorinate this well and I will send that when it comes in.

Thank you.

Cheryl Ryan Rylea homes Get <u>Outlook for iOS</u>

From: ccholland < ccholland@fval.com >

Sent: Wednesday, December 12, 2018 3:09 PM

To: 'JAMES RYAN'

Subject: 13571 Triadelphia Mill Road water test results with failing Coliform bacteria

H.J. GREER & SONS DRILLING CO., INC.

Complete Water Systems and Water Conditioning Equipment RESIDENTIAL - COMMERCIAL - INDUSTRIAL P.O. DRAWER A GAMBRILLS, MARYLAND 21054



December 13, 2018

Ref: 13571 Triadelphia Road Clarksville, MD 21029

To whom it may concern,

The well at the aforementioned address was serviced as follows:

The well was pumped out.

Flushed leaves out of the well. This was do to a well cap not being installed. 200 Gallons of Sodium Dichloroxtriazine Mix. 100 PPM (Parts per Million) pumped into well.

Installation of well cap.

Ran water into hose bibs.

Sincerely,

John Greer

License # MSD 086

Lol me in well

1. - chlorhode that

noter - ther add

2x volume

2 - pum at - then c

2 add 3x volume

Wolf, Kevin

From: Wolf, Kevin

Sent: Wednesday, November 28, 2018 4:51 PM

To: 'ryleahomes@msn.com' **Subject:** 13571 Triadelphia Mill Road

Cheryl,

As I discussed earlier, from the looks of the water analysis reports submitted, the first two reports showed total coliform >200. This tells me the sample location has been compromised and the system needs another proper disinfection. Now since you are pressed for time, you may want to think about a "super" chlorination based on the sections referenced in COMAR. See the highlighted yellow section below. This section states:

26.04.04.24

.24 Disinfection of Wells and Water Supply Systems.

A. Upon completion of well construction activities, the permittee shall disinfect a water supply well in accordance with this regulation.

- B. Whenever any work is done on the well after disinfection of the well by the well driller, the person doing the work shall be responsible for disinfection of the well and water supply system in accordance with this regulation.
- C. Material. Tablets or dry granular material may not be used as the only chlorination material. The materials, which may be used for disinfection, are:
- (1) Calcium hypochlorite,
- (2) Sodium dichloro-triazine dehydrate; or
- (3) Sodium hypochlorite.
- D. Standard Disinfection Procedure.
- (1) The chlorine shall be placed in the well in quantities that will produce a concentration of at least 100 mg/l chlorine. The amount required to obtain this concentration will depend on the casing diameter and the amount of water in the well.
- (2) The well shall be chlorinated using all of the following sequential steps:
- (a) Chlorine tablets or granular chlorine shall be dropped in the top of the well and allowed to settle to the bottom, or a prepared 10 gallon chlorine solution, with a chlorine concentration of at least 100 mg/l, but not more than 500 mg/l, shall be placed in the bottom of the well by pumping or gravity through a tremie pipe, drill rod, hose, or other approved method.
- (b) A chlorine solution of at least 10 gallons and producing a concentration of at least 100 mg/l, but not more than 500 mg/l, in the well shall be introduced (poured) into the top of the well. All surfaces above the static level shall be washed with this solution.
- (c) After the solution has been placed in the well, the water shall be agitated to thoroughly disperse the solution. Agitation may be accomplished by turning the pump on and off, or if no pump is available, by using a bailer, a swab, a plunger, air, or other approved method.
- (d) If the well has been connected to the pressure tank and distribution system, a small amount of the chlorinated water shall then be pumped through the system to thoroughly disinfect the system.
- (e) The well shall be allowed to stand without further agitation for at least 12 hours.

- (f) If a residual of at least 5 mg/l chlorine remains in the water after 12 hours, the well shall then be pumped to waste until the odor and taste of chlorine is no longer detectable. If less than 5 mg/l free residual chlorine is found in the water after 12 hours, the disinfection procedure shall be repeated.
- (3) Chlorinated water and water pumped during the flushing of the well during the disinfection procedure may not be discharged:
- (a) To an on-site sewage disposal system; or
- (b) Directly to surface waters of the State.
- E. Disinfection Procedure for Wells That Do Not Respond to the Standard Procedure.
- (1) If, after testing, the well cannot meet the bacteriological standard of this chapter, it shall be chlorinated as in §D of this regulation.
- (2) If the well remains unresponsive after repeating the standard disinfection procedure per this section, a volume of water chlorinated to a concentration of 100 mg/l and at least two times the volume of chlorinated, standing water in the well, but not less than 50 gallons, shall be introduced into the well in order to completely displace the volume of chlorinated, standing water and force it out into the water bearing formation.
- F. If bacteriological contamination persists after repeated disinfection, the Approving Authority may require the well to be abandoned and sealed in accordance with this chapter.

Thanks,

Kevin M. Wolf, LEHS, REHS/RS Groundwater Mgmt. Sec. Supervisor Well & Septic Program Bureau of Environmental Health 8930 Stanford Blvd. Columbia, MD 21045 (o) 410-313-2645







kwolf@howardcountymd.gov

CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

1413 O Tancytown Rd. Westminster, MD (410) 848-1014 (410) 876-4554 FAX (410) 848-0298

REPORT OF ANALYSIS

Laboratory ID #:

123791

Account #:

Reference:

Rylea Homes

Company:

3690

Requested By: Jim Ryan

Rylea Homes

Location:

13571 Triadelphia Mill Road Clarksville, MD 21029

Date/ Time Collected: 8/1/2018

Source: Site:

Well Water

Date/Time Rec'll:

8/1/2018

1505

Treatment:

Laundry Room Utility Tap Sediment Filter/UV Light

Chlorite ppi :

PARAMETURS

: m 1)

Total: ND

pH:

7.3

Collec 1.35:

6176JY

Well #:

HO-94-4039

DATE/TIME/ANALYST

Bacteria, Coliform. Total, MPN Bacteria, E. coli, N PN

RESULTS <1.0 <1.0

MPN/ 100 ml MPN/ 100 ml

UNITS

<1.0 <1.0

REFERENCE

SM20 9223 SM20 9223

METHOD

8/2/2018 / 1015 / RER 8/2/2018 / 1015 / RER

NOTES

MPN/ 100 ml Most Probable Number [of viable bacteria] per 100 ml of sample. 1

Result less to nor within the reference range are considered satisfactory and within potable water limits at the time of 2 samp "".

one Patret 1 3

pll r pri leva tested on site

Reaso r': : & Occupancy

Building ' + t#:

B17003339

439 East Main Street Westminster, MD 21157-5539



(410) 848-1790 • (301) 662-1799 Fax (410) 848-1791

November 15, 2017

Howard County Health Department 8930 Stanford Blvd Columbia, MD 21045

Attn: Mr. Hank Oswald

Environmental Sanitarian

RE:

13571 Triadelphia Mill Rd, Charles Dorsey Property

CLSI Job No.: 2005004

Dear Mr. Oswald,

We offer the following responses to your comment letter dated September 25, 2017:

- 1. Two alternative well locations have been shown, per our meeting and phone conversation.
- 2. The trenches have been revised to show a 10-foot separation between trenches.
- 3. The owner / client has chosen not to install the system for 5 bedroom.

We believe these revisions will adequately address your concerns. Should you have any questions or concerns, please feel free to contact our office.

Sincerely,

Linda Alexander

Associate/ Project Manager

File Cc:

Oswald, Hank

From:

Oswald, Hank

Sent:

Thursday, October 26, 2017 2:48 PM

To:

'Linda D. Alexander'

Subject:

RE: OSDS_13571 Triadelphia Road

Hi Linda - If it's a lot of record before 1972, then you don't need 10k. You could cut off a portion of the SDA and move the house and septic components forward to fit a 3rd well site in between the two showing on this plan (preferably 50 feet apart). **The existing well only had a yield of 1 gpm so we definitely want to see a 3rd well site.** If the SDA is revised, then the perc cert will need to be revised.

Hank

From: Linda D. Alexander [mailto:lalexander@clsimail.com]

Sent: Wednesday, October 25, 2017 2:59 PM

To: Oswald, Hank

Subject: FW: OSDS_13571 Triadelphia Road

Hi Hank,

I have a question regarding showing two alternative wells. First I have attached the perc certification plan for this lot which shows only one well location. Also this lot was issue a building permit under no. B07000307 at one point. This lot has existed since the 1881. This is why that we only showed the existing well and one replacement well. I am not sure that there is room for a second replacement well.

Regards,

Linda D. Alexander Associate / Senior Project Manager

CLSI

439 East Main Street, Westminster, MD. 21157 lalexander@clsimail.com direct: 410-871-4475 cell: 443-375-9903

From: Oswald, Hank [mailto:hoswald@howardcountymd.gov]

Sent: Monday, September 25, 2017 9:12 AM **To:** Linda D. Alexander < <u>lalexander@clsimail.com</u>>

Subject: OSDS 13571 Triadelphia Road

Hi Linda:


Good morning. Please see attachment for comments pertaining to OSDS Plan for 13571 Triadelphia Road.


Should you have any questions or concerns, please don't hesitate to contact me.

Respectfully,

Hank

Hank Oswald, L.E.H.S. Howard County Health Department Bureau of Environmental Health Well & Septic Program 8930 Stanford Boulevard Columbia, MD 21045 410.313.1786 (Office) 410.313.2648 (Fax)







Greg Phillips has Achieved Over \$195 Million in Career Sales Allow the Phillips Team to Put Their Experience to Work For You www.ThePhillipsRealtyGroup.com

August 31, 2004

Howard County Health Department 3525-H Ellicott Mills Drive Ellicott City, Maryland 21030

Regarding:

THALER ESTATES F-00-59 RELIEF FROM REQUIREMENT TO DRILL REMAINING WELLS

Dear Health Officer,

The owner of parcel 173 has instructed me to submit the attached application for a Septic Reserve area for Parcel 173 tax map 34 located in Howard County Maryland. In anticipation of this submission please find attached preliminary test results conducted by our consultant Mark Rifkin previously of your office. Mark has informed us that his work can only act to provide information and can not be considered independently for an approval. With that in mind we now feel that the attached plan exceeds the standard necessary for approval and we look forward to working with you as soon as arrangements can be made for your review of our project.

Please feel free to contact me If you have any further questions by calling 410.977.0864. Thank you in advance for your immediate attention to this matter.

Respectfully,

Gregory B. Phillips

Mobile: 410 977 0864

Voice Mail: 888.691.4780

R

Email: phillips@ThePhillipsRealtyGroup.com Facsimile: 410 730 2157