

MDEMMA/PER.071



Bureau of Environmental Health 8930 Stanford Blvd | Columbia, MD 21045 410.313.2640 - Voice/Relay 410.313.2648 - Fax 1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

MEMORANDUM

March 19th, 2021

Home Owner

RE: Replacement Well Sampling 4959 Morning Star Drive Dayton, MD 21036 0072 Well Permit # HO-20-0070

Associated with: 5000 Ten Oaks Road Dayton, MD 21036


Dear Homeowner:

According to our records, your replacement well has been connected to the dwelling. The final inspection was granted on 03/09/2021. We request that you contact the Community Hygiene Program at (410) 313-1773 to schedule initial water sampling for the above referenced replacement well, as required by the Maryland Well Construction Regulation (COMAR 26.04.04). This sampling includes testing for <u>bacteria</u>, <u>nitrates</u>, <u>turbidity</u>, and <u>sand</u>.

It is preferred that the sample be collected from the primary indoor drinking tap, but if suitable scheduling is not possible, the sample may be taken from an outside tap to complete your sampling obligation. However, the potential for unsuccessful sample results increases when samples are collected from taps exposed to the outside environment.

If sampling has already been performed by an outside lab, please help us by forwarding the results of the samples to our office. If you have any further questions, you can call me at 410-313-2643. Otherwise, call Community Hygiene at 410-313-1773 to schedule or arrange for them to collect the subsequent water samples.


Sincere Joseph C. Cabahug LEHS Licensed Environmental Health Specialist Well & Septic Program **Bureau of Environmental Health**



FILE INQUIRY NOTES page of_ 4959 Morning Star Dr **RESULTS OF REVIEW FOR FILE** DATE 2/23/21 Two septic cleansuts located in back of nouse 10 and 45 from corner aver has not pumped out tank 10-15 years, is not sure which clean out is tank. Owner believes there is a septre field. Confirmed well locations of neighbors on Marning toc (4995 Prive. Neighbor directly across the street on Ten Oaks Dickyard (hear fence, as shern on intera. and septic presumably in front same. Edge of their front yand is 140' from this properties front land. Duner wanted len Oaks but it Wellthe 4995 Ten Our septer and downgrade from 4956 Muningster De splu Letton in trangle area of driverry, 100 from \$1956 pliningstar Da's spile area, and 10 f edge of dureway B' from edge of read. (SB 2/24/21 and hole dry @ 600'. 50' gas easement marked by Trans Canada. Opened two septic cleaneuts - water level in tank I' from grade, 0.5 from grade in dry well Let owners know they have option of deepening / reworking old well, choosing a new location in triangle of driveway, or possibly moving to lower corner of property near 4963 TC gas says the rig cannot drive over gas so line. Iny well line that goes across gas line must have a 2'

FILE INQUIRY NOTES page 2 4 -4939 Morning Stor RESULTS OF REVIEW FOR FILE DATE verticle offset from gas keeline. Andy from Trans Canada cont. 2/24/21 (previously worked as a gas friller) said hydrofracking Chance development night have caused vell to run dry. Owner Annette, says well was always very low but in the past month has dwindled to nothing. Alerted owner that the septic tank needed to be pumped and the dry well may be close failing. Possible septic repair area could be along Ten Oaks Rd, going towards front yard. ST 2/25/21 After conferring with Jeff Williams, Kevin thinks it best exhaust triangle area and area close to old + house before moving downhill IF a well is to be located in lower corner, it should be as upgrade of 4963's septic as possible, Peven if lot line setback is waived Allied continued to drill deeper on Hole #2 in triangle today. OF 3/2/21 Allied did not get enough water from Hole #2. Drilled Holes #3 and #4 in the drive way triangle over the weekend, but found no water (160' teep each). Selected Hole #5 location Joseph & on 3/1/21, to the left of drivenay ~20 from have. Hit bedrock at 30° although driller, Peter says

FILE INQUIRY NOTES page 3 of 4959 Morning Star RESULTS OF REVIEW FOR FILE DATE it was layers of gray and brown cock. The Put casing to 46' and hit water at 50' Approx 3/4 GPM. cont. 3/2/21 Driller is taking it down to 600' for storage, no additional water found. Driller will also put in liner. F



SITE INSPECTION SHEET

