

C1 36714

SEQUENCE NO. (MDE USE ONLY)

STATE OF MARYLAND WELL COMPLETION REPORT

FILL IN THIS FORM COMPLETELY PLEASE TYPE

THIS REPORT MUST BE SUBMITTED WITHIN 45 DAYS AFTER WELL IS COMPLETED.

COUNTY NUMBER

(THIS NUMBER IS TO BE PUNCHED IN COLS. 3-6 ON ALL CARDS)

ST/CO USE ONLY DATE RECEIVED

DATE WELL COMPLETED

Depth of Well

PERMIT NO. FROM "PERMIT TO DRILL WELL"

OWNER MILLER, BARRY WELL SITE ADDRESS 3715 WOODBINE RD TOWN WOODBINE

WELL LOG table with columns: DESCRIPTION, FEET (FROM, TO), check if water bearing. Includes entries for Top Soil, Brown slate, Grey slate, etc.

GROUTING RECORD: WELL HAS BEEN GROUDED (Y), TYPE OF GROUING MATERIAL (CM, BC), NO. OF BAGS (8), NO. OF POUNDS (400), GALLONS OF WATER (184), DEPTH OF GROUT SEAL (55 ft).

CASING RECORD: MAIN CASING TYPE (ST), Nominal diameter (6 inch), Total depth (60 feet).

OTHER CASING (if used) section with diameter and depth fields.

SCREEN RECORD: screen type or open hole (ST, BR, HO), insert appropriate code below.

NUMBER OF UNSUCCESSFUL WELLS: 0

WELL HYDROFRACTURED (Y), CIRCLE APPROPRIATE LETTER (A, E, P)

I HEREBY CERTIFY THAT THIS WELL HAS BEEN CONSTRUCTED IN ACCORDANCE WITH COMAR 26.04.04

DRILLERS LIC. NO. MW D 040, DRILLERS SIGNATURE, LIC. NO. WR 0064

SITE SUPERVISOR (sign. of driller or journeyman responsible for sitework if different from permittee)

DEPTH (nearest ft.) table with columns 1-21, values: 58, 200

GRAVEL PACK IF WELL DRILLED WAS FLOWING WELL INSERT F IN BOX 68

MDE USE ONLY (NOT TO BE FILLED IN BY DRILLER) T (E.R.O.S.) W Q

PUMPING TEST: HOURS PUMPED (3), PUMPING RATE (20 gal. per min.), METHOD USED TO MEASURE PUMPING RATE (Bucket), WATER LEVEL (50 ft. before, 200 ft. when pumping), TYPE OF PUMP USED (air)

PUMP INSTALLED: DRILLER INSTALLED PUMP (NO), TYPE OF PUMP INSTALLED (A), CAPACITY: GALLONS PER MINUTE (31-35), PUMP HORSE POWER (37-41), PUMP COLUMN LENGTH (43-47), CASING HEIGHT (above/below), LAND SURFACE (2 ft. nearest)

LATITUDE 39.284980, LONGITUDE 77.129447 (DEFAULT COORD. WGS 84)

Pursuant to §10-624 of the State Govt. Article of the Maryland Code personal info. requested on this form is used in processing this form pursuant to COMAR 26.04.04.

B 1 32056
1 2 3 6

SEQUENCE NO.
(MDE USE ONLY)

STATE OF MARYLAND
APPLICATION FOR PERMIT TO DRILL WELL

STATE PERMIT NUMBER

70 10-15-0178 79
fill in this form completely

557446 please type

Date Received (APA)

8 11/15 MM DD YY 13

OWNER INFORMATION

13165

15 MILLER BARRY
Last Name Owner First Name 34

36 3715 WOODBINE ROAD
Street or RFD 55

57 WOODBINE MD 21797
Town 70 State 72 Zip 76

B 3

LOCATION OF WELL CC#

Howard
8 COUNTY 21

23 SUBDIVISION 42

SECTION 44 46 LOT 48 50

Woodbine
52 NEAREST TOWN 71

DRILLER INFORMATION

George F. Easterday M VD 040
Driller's Name 76 License No. 81

Franklin Easterday, Inc.
Firm Name

9265 Brown Church Rd., Mt. Airy, Md. 21771
Address

George F. Easterday 11/3/2015
Signature Date

B 2 WELL INFORMATION

1 2 APPROX. PUMPING RATE 5
(GAL. PER MIN.) 8 12

AVERAGE DAILY QUANTITY NEEDED 500
(GAL. PER DAY) 14 20

B 4

SOURCES OF DRILLING WATER

1. wells

3715 Woodbine Road
11 STREET ADDRESS 30

ON WHICH SIDE OF ROAD
(CIRCLE APPROPRIATE BOX)



34 100 37
DISTANCE FROM ROAD Ft.
ENTER FT OR MI 38 39

TAX MAP: 12 BLK: 24 PARCEL 22

USE FOR WATER (CIRCLE APPROPRIATE BOX)

- DOMESTIC POTABLE SUPPLY & RESIDENTIAL IRRIGATION
- FARMING (LIVESTOCK WATERING & AGRICULTURAL IRRIGATION)
- INDUSTRIAL, COMMERCIAL, DEWATERING
- PUBLIC WATER SUPPLY WELL
- TEST, OBSERVATION, MONITORING
- OPEN LOOP GEOTHERMAL
- CLOSED LOOP GEOTHERMAL

NOT TO BE FILLED IN BY DRILLER
HEALTH DEPARTMENT APPROVAL

Howard 13
COUNTY NAME COUNTY NO.

STATE SIGNATURE INSERT S → 41

DATE ISSUED 11/10/15
43 MM DD YY 48 CO SIGNATURE S.L.M. EXP. DATE 11/10/16

APPROXIMATE DEPTH OF WELL 24 300 28 FEET

APPROXIMATE DIAMETER OF WELL 6 NEAREST INCH

METHOD OF DRILLING (circle one)

- BORED (or Augered) AIR-ROTary
- JETTED AIR-PERCussion
- Jetted & DRIVEN ROTARY (Hydraulic Rotary)
- CABLE REVERSE-ROTary
- DRIVE-POINT
- other _____

REPLACEMENT OR DEEPEMED WELLS
(CIRCLE APPROPRIATE BOX)

- THIS WELL WILL NOT REPLACE AN EXISTING WELL
- THIS WELL WILL REPLACE A WELL THAT WILL BE ABANDONED AND SEALED
- THIS WELL WILL REPLACE A WELL THAT WILL BE USED AS A STANDBY-CONTACT LOCAL APPROVING AUTHORITY FOR POLICY ON STANDBY WELLS
- THIS WELL WILL DEEPEM AN EXISTING WELL

PERMIT NUMBER OF WELL TO BE REPLACED OR DEEPEMED (IF AVAILABLE) 41 _____ 52

Not to be filled in by driller (MDE OR COUNTY USE ONLY)

APPROP. PERMIT NUMBER _____ G _____


PERMIT No. 10-15-0178
70 71 72 73 74 75 76 77 78 79

SPECIAL CONDITIONS

NOTE APPROVING AUTHORITIES SHOULD USE SEPARATE SHEET IF NEEDED=

SEE ATTACHED MEMO

PROPOSED LOCATION OF WELL ON LOT
SHOW PERMANENT STRUCTURES SUCH AS BUILDINGS, SEPTIC SYSTEM,
ROADS AND/OR LANDMARKS AND INDICATE NOT LESS THAN TWO
DISTANCE MEASUREMENTS TO WELL



 WATER WELL ABANDONMENT-SEALING REPORT FORM

SUBMIT COPIES OF COMPLETED FORM TO:

- * COUNTY ENVIRONMENTAL AGENCY (contact MDE, WMA if address needed)
- * WELL OWNER
- * MDE, WATER MANAGEMENT ADMINISTRATION, WELL PROGRAM

OK
 11/18/16 SC

DATE WELL ABANDONED: 6-15-16 (month/day/year)

* PERMIT NUMBER OF ABANDONED WELL (if any) _____

* PERMIT NUMBER OF REPLACEMENT WELL: _____

HO - 15 - 0178

* PERSON ABANDONING WELL: Bruce Thompson


WELL DRILLER'S LICENSE NUMBER: JSD 038

CIRCLE: MWD / MSD / MGD

* OWNER'S NAME: BARRY Miller

SITE LOCATION MAP

* WELL LOCATION:
 COUNTY: Howard
 NEAREST TOWN: WOODBINE
 TAX MAP _____ BLOCK _____ PARCEL _____
 SUBDIVISION: _____
 SECTION: _____ LOT: _____
 STREET ADDRESS: 3715 WOODBINE Rd



LATITUDE 3 9.284688
 LONGITUDE 7 7.129453

LOG OF SEALING MATERIAL

MATERIAL	FEET	
	FROM	TO
Bentonite	50	5
Pit	5	0

* TYPE OF WELL BEING ABANDONED:
 DRILLED _____ JETTED _____
 _____ BORED _____ HAND DUG _____
 _____ OTHER (specify) _____

* USE CODE:
 DOMESTIC _____ MUNICIPAL/PUBLIC _____
 _____ IRRIGATION _____ INDUSTRIAL _____
 _____ TEST/OBSERVATION _____ GEOTHERMAL _____

VOLUME OF MATERIAL USED

350 # Bentonite or slurry

* TYPE OF CASING:
 STEEL _____ PLASTIC _____
 _____ CONCRETE _____ OTHER (specify) _____

SIZE OF CASING: 6 INCHES IN DIAMETER

DEPTH OF WELL: 150 FEET DEEP

WAS ANY CASING REMOVED? _____ YES NO
 If yes, length removed, in feet: _____

WAS CASING RIPPED OR PERFORATED? _____ YES NO


Berge F. Esterlony
 SIGNATURE-MASTER WELL DRILLER OR SUPERVISING SANITARIAN LICENSE# _____

MWD / MSD / MGS
 CIRCLE ONE

6-15-16
 DATE

COUNTY

Pursuant to § 10-624 of the State Govt. Article of the Maryland Code, personal info requested on this form is used in processing this form pursuant to COMAR 26.04.04. Failure to provide the info may result in this form not being processed. You have the right to inspect, amend, or correct this form. The Maryland Department of the Environment is subject to the Maryland Public Information Act. This form may be made available on the Internet via MDE's website and is subject to inspection or copying, in whole or in part, by the public and other governmental agencies, if not protected by federal or State Law.



3525 H Ellicott Mills Drive, Ellicott City, MD 21043
(410) 313-2640 Fax (410) 313-2648
TDD (410) 313-2323 Toll Free 1-866-313-6300
website: www.hchealth.org

Penny E. Borenstein, M.D., M.P.H., Health Officer

TO ALL INTERESTED PARTIES


When submitting a well permit application for a proposed well for new construction, please indicate one of the following:

- The well site has been staked by OWNER,
(professional land surveyor or company employing professional land surveyors)
on 11-2-15 (date) and does not require a site inspection.
- The well driller, builder or property owner will call the Health Department to schedule a time to meet in the field to verify the proposed well site location.

This sheet, along with two copies of an acceptable well site plan, must be attached to the green well permit application.

Revised 6/10/03

3715 WOODBINE Rd



Bureau of Environmental Health

8930 Stanford Blvd, Columbia, MD 21045
Main: 410-313-2640 | Fax: 410-313-2648
TDD 410-313-2323 | Toll Free 1-866-313-6300
www.hchealth.org

Maura J. Rossman, M.D., Health Officer

November 10, 2015

MEMORANDUM

TO: L.F. Easterday, Inc.

FROM: Sarah Collins *SEC*
Howard County Health Department
Well and Septic Program

RE: Replacement well at 3715 Woodbine Road


The Health Department sample collected water samples from the existing pit well at 3175 Woodbine Road on 10/21/2015. The water showed high levels of sodium, chloride, and total dissolved solids.

Due to its proximity to the road, the replacement well must be sampled for sodium, chloride, and total dissolved solids. In addition, the replacement well must be constructed of steel casing that extends 50' below grade or 10' into competent bedrock, whichever is deeper.

The existing pit well on the property must be abandoned.

(sealed)

Cc: File



**HOWARD COUNTY HEALTH DEPARTMENT
BUREAU OF ENVIRONMENTAL HEALTH
WELL & SEPTIC PROGRAM
TEL: (410)313-1771 FAX: (410)313-2648**

Information Form for the Installation of the Well Pump, Pitless Adapter, and Supply Piping

NOTE: The installer is responsible for requesting an inspection prior to 9 am on the day of the desired inspection. No work is to be covered until approved by the Health Department. All installations must comply with the National Standard Plumbing Code (NSPC, as amended locally) and COMAR 26.04.04 (MD Well Construction Regulations). Submission of a complete form is required prior to Use and Occupancy approval.

Company Name: Michael Runk Plumbing & Hvy Telephone #: 410-781-6791
 Address: P.O. Box 1453
Sykesville, MD 21784

(Must circle one) Licensed Plumber Licensed Well Driller Licensed Well Pump Installer
 License # and name of individual responsible for the field installation:
 Name (Print): Michael Runk License# 9698

***A licensed individual must perform the actual installation. Apprentices must be under the supervision of a licensed journeyman or master plumber, pump installer or well driller. Licenses may be subjected to field verification. Unlicensed individuals may be reported to the appropriate licensing agency.**

Name of Property Owner: Barry Miller Telephone #: 410-675-0507
 Subdivision: _____ Lot #: _____ Well Tag #: HO - -
 Site Address: 3715 Woodbine Rd.

Submersible Pump Data

Make: BevKeley
 Model #: 57P4HS05221
 Pump Capacity 7 GPM
 Well Yield: 20 GPM

Pitless Adapter

Make: Harvard
 Model#: PPT 800NL
 Depth: 42" (36" min)
 NSP/WSC approved:

Well Cap and Electric Conduit

Two piece watertight cap:
 Screened, vented well cap:
 Cap secured to casing:
 Conduit min 18" B.G.:
 Conduit secured to well cap:

Depth of well encountered at time of pump installation: 200 (feet)
 If pump capacity exceeds well yield, a low water cut off switch is required by NSPC 1990 Section 17.8.4
 Torque arrestors, Cable guards, or other acceptable method used- Must circle one
 Safety rope, if used, attached to brass rope adapter or other acceptable method inside of well casing

Piping to house

Type: poly
 PSI: 200 (160 psi min)
 Depth of supply line: 42" (36" min)

House Connection

PVC sleeve to undisturbed soil at wall penetration:
 Length of sleeve(5" minimum from foundation): 40ft.
 Sleeve sealed properly: ferroc

The water supply line is required to be at least ten feet from the septic tank, pump chamber, sewage piping, distribution box, drainfields, and sewage reserve area. If this cannot be accomplished, contact this office for approval prior to installation.

Signature of company representative responsible for installation: Michael Runk date: 6/10/16

For Health Department Use Only - Not to be completed by Installer

Date Insp. Requested: 4/26/16 Date Insp. Approved: 4/27/16 Inspector: SC
 Inspection Data: Pitless adapter watertight & water supply line at least 36" below grade
 Two piece cap installed and attached to casing securely
 Elec. conduit extends at least 18" below grade/attached to cap properly
 Safety rope not outside of well cap/casing
 Correct well tag attached properly and casing 8" above finished grade
 Water supply line sleeved adequately at house connection
 Adequate grout observed below pitless adapter

Connection
 at yard hydrant
 good - near
 chicken
 coop
 Under footer

Wolf, Kevin

From: John Boris -MDE- <john.boris@maryland.gov>
Sent: Wednesday, January 13, 2016 12:16 PM
To: Bricker, Robert; Williams, Jeffrey; Wolf, Kevin; Collins, Sarah
Cc: Steven Krieg -MDE-; Naomi Howell -MDE-
Subject: Re: geology inquiry_FW: 3715 Woodbine Road

All,

Thank you all for your participation in this discussion. Here is a summary and response to what was covered.

1. The argument presented by Mr. Bricker regarding the depth of casing issue has a lot of merit. Even if we're present when the well is drilled without extensive logging equipment we'll never know what the depth of the "competent" bedrock is.
2. We now have a new well that, on paper, meets the current construction specs that does not meet a secondary water quality standard. There is no regulatory requirement to deny a COP for secondary contaminants.
3. The math shows that if the well yield was run for the required 3 hours at 20 gallons per minute there was 3,600 gallons pulled from the well. Based on the static and depth of the well that number would be 16 times the volume of the well. Most sampling protocols require at least 3 well volumes be removed prior to sampling. The Applicant of record has indicated that running the well off for another 24 hours may alleviate the high chloride levels. Rather than going through the process of a percolation test and separate drainfield construction for the RO waste water the well owner may wish to consider the applicant's suggestion.
4. Based on the completion report a water bearing fracture exists between 90' to 93'. Sealing off of this zone may prevent the chlorides from entering the well bore. This is speculative, may cause a reduction in yield and cannot be done without additional cost incurred by the well owner. I think this should also be presented to the well owner as an option. This liner may cost less than a drainfield.
5. Although not a concern of ours does this 200' well that still requires treatment meet the SHA contract? For my own clarity and to provide insight into you I will attempt to follow up with SHA.

I think that sums it up. Let me know if you feel I missed something.

John A. Boris, Jr., LEHS
Geologist Program Consultant
Maryland Dept. of the Environment
Onsite Systems Division
Office: (410) 537-3678
Cell: (443) 992-6195
Fax: (410) 537-3163

On Mon, Jan 11, 2016 at 11:38 AM, Bricker, Robert <RBricker@howardcountymd.gov> wrote:

John,

Attached is a well completion report for a well that was drilled to replace a well that has high levels of TDS and chloride. A discussion of conflicting results for chloride and TDS concentrations found in the replacement well (HO-15-0178) is in the email string below.

These wells are located on a tiny parcel next to Route 94 and immediately south of a divide. An upland drain begins on the subject property, near the road, and continues east then southeast, being more or less coincident with the north side line and back line of the parcel. The replacement well would be at the west boundary of this drain feature. Also, there is a thrust fault, illustrated on Geologic Map of Howard County (Maryland Geologic Survey, 1993), that occurs under the property or immediately east of the property. The fault separates the Pleasant Grove Formation (which underlies Route 94 and the area west) from the Morgan Run Formation which lies to the east.

I contend that the well was not sealed deep enough, that the seal should have been at about 71-72 feet. I say this because of the thrust fault, thinking that the layer of 'Grey Slate' that is described at 55-to-70 feet depth was at one time continuous with the layer of 'Grey Slate' that is now 71-to-90 feet depth. For this to be true, an event would had to have occurred relatively early in a period when materials that formed the 'Brown Slate' were being deposited. That event being movement of the fault such that the 'Grey Slate' was thrust up, broken, and turned over upon the thin layer of materials that would eventually become 'Brown Slate' described now as being at 70-to-71 feet depth. In this scenario, any water more shallow than 71 feet, would be directly influenced by water infiltrating from the surface with little or no dilution. Of course, I'm not a geologist and this is conjecture.

The State Highways Commission folks seem satisfied to say that an RO treatment is needed. Kevin and I lean toward requiring a deeper seal, which may result in extending the depth of the well due to lower yield. We really need the opinion of a geologist familiar with Piedmont geology and the types of rocks described and their occurrence.

What's your opinion about the sequence described in the Driller's Well Log? Can you support a requirement to seal the well at greater depth?

Robert Bricker, CPSS, REHS/R.S., L.E.H.S.

From: Wolf, Kevin
Sent: Friday, January 08, 2016 5:02 PM
To: Bricker, Robert
Subject: FW: 3715 Woodbine Road

From: Bonnie Crosby [<mailto:BCrosby@sha.state.md.us>]
Sent: Friday, January 08, 2016 2:34 PM
To: Wolf, Kevin

Cc: Eric Dougherty
Subject: RE: 3715 Woodbine Road

Kevin,

When I was at the Miller home I was told, by the driller, static level is 33 feet, after pumping water table is at 70 feet. The casing is 60 feet and was grouted to 55 feet behind the casing, with a depth of 200 feet. The claimant's hand dug well is 50 feet in depth and was treated with a water softener treatment system. This well should be grouted from the base of the hole and sealed off. It is unclear where the water softener system was discharging to. The site may have limitations for the operation of the claimant's septic systems.

I met Sarah at the site. Our test results are 96 mg/L below the health department result for chloride and our result for TDS is 800 mg/L. We sampled at 10:30 a.m. Sarah sampled after SHA but not sure of the time. Don't understand her result of TDS at 1083 mg/L. Probably should resample. An RO System will work if the level of TDS is below 1000 mg/L. I'm not sure if drilling deeper would improve the water quality.

The claimant is in an area where the water table should be between 10 to 35 feet. Surface flow north of the claimant moves towards Cabin Run. South of the claimant the surface water moves south southwest. Several wells north of the claimant have well yields greater than 15 gallons a minute. South of the claimant the well yield is less than 2 gallons of water a minute. Wells located west of the claimant had dry holes. Well yields in this area are highly variable across short distances and cannot be predicted with much certainty. Fractures may also be more numerous under stream valleys and upland draws.

Thanks,

Bonnie

From: Wolf, Kevin [<mailto:KWolf@howardcountymd.gov>]
Sent: Monday, January 04, 2016 12:26 PM
To: Bonnie Crosby
Subject: 3715 Woodbine Road

Bonnie,

Please see attached water test results for Mr. Miller. I have also attached the Well completion report from Easterday's. Could you possibly have yourself and/or Eric take a look at this. I am a little beyond by expertise here understanding the hydrogeology behind this so I would love to hear Eric's feedback. Please take note of the water bearing fractures and casing depths to rock material. My initial thoughts: would drilling deeper be an option to lower the numbers? Relocation is limited as well. The driller (Mr. George Easterday) explained that an extended run-off on the well of maybe 24hrs might give us a better analytical analysis. Keep in mind, whole-house treatment is an option but Mr. Miller is limited to the area of subsurface treatment.

Thanks,

Kevin M. Wolf, LEHS

Groundwater Mgmt. Sec. Supervisor

Well & Septic Program


Bureau of Environmental Health

8930 Stanford Blvd.

Columbia, MD 21045

(o) [410-313-2645](tel:410-313-2645)

(f) [410-313-2648](tel:410-313-2648)



kwolf@howardcountymd.gov

CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

Wolf, Kevin


From: Wolf, Kevin
Sent: Monday, January 04, 2016 12:26 PM
To: 'bcrosby@sha.state.md.us'
Subject: 3715 Woodbine Road
Attachments: 3715_Woodbine_Road_analysis.pdf; 3715_Woodbine_Road_Completion_report.pdf

Bonnie,

Please see attached water test results for Mr. Miller. I have also attached the Well completion report from Easterday's. Could you possibly have yourself and/or Eric take a look at this. I am a little beyond by expertise here understanding the hydrogeology behind this so I would love to hear Eric's feedback. Please take note of the water bearing fractures and casing depths to rock material. My initial thoughts: would drilling deeper be an option to lower the numbers? Relocation is limited as well. The driller (Mr. George Easterday) explained that an extended run-off on the well of maybe 24hrs might give us a better analytical analysis. Keep in mind, whole-house treatment is an option but Mr. Miller is limited to the area of subsurface treatment.

Thanks,

Kevin M. Wolf, LEHS
Groundwater Mgmt. Sec. Supervisor
Well & Septic Program
Bureau of Environmental Health
8930 Stanford Blvd.
Columbia, MD 21045
(o) 410-313-2645
(f) 410-313-2648



kwolf@howardcountymd.gov

CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

Collins, Sarah

From: Miller, Barry <BMiller@jmt.com>
Sent: Tuesday, May 17, 2016 1:44 PM
To: Collins, Sarah
Subject: 3715 Woodbine road RO

Sarah

Attached is my email from Carroll Water. Rusty from Feezer was planning on calling you directly.

Thanks
Barry

Sent from my iPhone


Begin forwarded message:

From: Charles Samardelis <charlie@carrollwater.com<<mailto:charlie@carrollwater.com>>>
Date: May 17, 2016 at 1:32:58 PM EDT
To: "Miller, Barry" <BMiller@jmt.com<<mailto:BMiller@jmt.com>>>
Subject: Water usage

Hi Barry,

So the RO unit we will be installing has a 50:50 product to waste ratio but can be made to produce 75:25. Reverse osmosis systems are pressure and temperature sensitive so there is some fluctuation in estimated production. But for purposes of calculation we will use the 50:50 ratio. Since we will be installing 400 gallon storage the unit will send equal amount to waste. Given you are a family of 4 using 75 gallons/person/day you will use about 300 gallons of stored water per day. Over a week your usage will be ~2100 gallons of water week. So this would equal your waste stream at a 50:50 ratio. The other equipment will be negligible in waste since the softener is metered and uses only 36 gallons of water to clean itself. In the interest of being as accurate as possible the softener will add another ~ 144 additional gallons week to waste. So your total waste per week should be ~2300 gallons. Since all other quoted devices do not waste any water for cleaning purposes this should be your total. Again these are all approximate and ultimately waste depends on your usage patterns. Hope this helps to clarify numbers.

Kind Regards,
Charlie Samardelis
Certified Water Specialist level 5
Water Quality Association
Cell# 443-605-5029
Ecowater. Purifying the Essential




This message is intended for the use of the individual or entity to which it is addressed and may contain information that is confidential, privileged and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent of the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please contact the sender immediately and delete it from your system.

Thank You.

MVE Series Reverse Osmosis

500 to 2,000 GPD Capacity



Applications



Whole Home



Food Service



Car Wash

Features & Benefits

- ✓ **Compact Design** – Wall mount or floor/shelf mount
- ✓ **Ease of Serviceability** – Zero clearance required on bottom and sides. All components can be serviced from front or top of unit
- ✓ **Pretreatment Lockout** – Disables RO production during pretreatment regeneration
- ✓ **Single Power Connection** – For all controls, switches and solenoid valves
- ✓ **Filter In, Filter Out, Pump and Product Pressure Gauges** – Easy to operate and maintain
- ✓ **High Flow, Low-Pressure XLP Membrane** – 98.5% maximum TDS rejection. Stands up to the most rugged of feed water conditions
- ✓ **Carbon and Sediment Filter Included** – Provides basic pretreatment, dechlorination and sediment removal down to 5 microns.
- ✓ **Standard Plumbing Connection** – Uses 1/2" Inlet, 3/8" permeate and drain connections
- ✓ **Stainless Steel Solenoid Valves**
- ✓ **Brass Vane-Type Pump** – Smooth and quiet operating (pump on 2000 GPD unit only)
- ✓ **Heavy Duty** – Powder-coated steel cabinet for durability and rust resistance. Stainless steel frame available upon request

Pre-treatment Packages Available. Pre-treatment of feed water protects and extends the life of the purification. We offer complete pretreatment capabilities that include iron filters, sediment removal, water softeners, chlorine filters and antiscalant.

Specifications

Model	R2E12-BETTER	R4E12-BETTER	R4E12P-BETTER
Part Number	13000432	13000434	13000444
Nominal Capacity	500 GPD (0.347 gpm)	1,000 GPD (0.694 gpm)	2000 GPD (1.389 gpm)
Membranes (No. & Size)	2 - 3" x 12"	4 - 3" x 12"	4 - 3" x 12"
Operating Pressure (psi)	40-125	40-125	40-125
Recovery*	up to 75%	up to 75%	up to 75%
Typical Rejection**	98%	98%	98%
Max Feed Temperature	113 F (45 C)	113 F (45 C)	113 F (45 C)
Feed pH Range	2-11	2-11	2-11
Max Chlorine***	< 0.1 ppm	< 0.1 ppm	< 0.1 ppm
Max TDS	1000	1000	1000
Electrical	110V 60Hz, 1-phase	110V 60Hz, 1-phase	110V 60Hz, 1-phase
Motor	N/A	N/A	1/3 HP
Shipping Weight (lbs.)	75	80	100

* Ships with flow control to receive approximately 50% recovery.

** RO Performance may vary depending on feed water characteristics.

*** Please ensure carbon filter is replaced regularly to ensure feed water remains dechlorinated for proper performance.

Pre-treatment Packages Available. Pre-treatment of feed water protects and extends the life of the purification. We offer complete pretreatment capabilities that include iron filters, sediment removal, water softeners, chlorine filters and antiscalant.

Accessory Options

651030 - MVE/LVE Replacement Membrane


235024 - 5-Micron Sediment Filter Cartridge

235037 - Carbon Filter

Please see manual and online ordering system for a complete service parts list and pricing.

Please contact ecicustomerservice@ecowater.com to learn more about our offering for both pressurized and atmospheric storage and delivery solutions.

Dimensions



For speedy quotes or answers to questions, contact us at:
ecicustomerservice@ecowater.com



	Design				Rejection and Flow Rates				Connections			Membranes			Vessels		Pumps			Electric	Size ²	
	Configuration	Feed Water Source ¹	System Recovery ³	System Recovery with Recycle	Nominal Salt Rejection	Permeate Flow Rate	Concentrate Flow Rate (Minimum)	Concentrate Recycle Flow Rate	Feed Connection	Permeate Connection	Concentrate Connection	Per Vessel	Quantity	Size	Array	Quantity	Type	HP	RPM @ 60Hz	Standard Voltage	Dimensions (LxWxH in inches)	Weight (lbs)
CRO-500	Single Pass	TDS <2000 ppm	26%	50% – 75%	98.5%	.34 gpm	1.00 gpm	Up to 1.00 gpm	3/4" FNPT	1/2" MNPT	1/2" FNPT	1	2	252l	1:1	2	Multi-Stage	1/2 HP	3450	120V 1Ph 60 Hz 9 Amps	18x18x55	110
CRO-1000	Single Pass	TDS <2000 ppm	41%	50% – 75%	98.5%	.69 gpm	1.00 gpm	Up to 1.00 gpm	3/4" FNPT	1/2" MNPT	1/2" FNPT	1	3	252l	1:1:1	3	Multi-Stage	1/4 HP	3450	120V 1Ph 60 Hz 9 Amps	18x18x55	115
CRO-2000	Single Pass	TDS <2000 ppm	32%	50% – 75%	98.5%	1.39 gpm	3.00 gpm	Up to 5.00 gpm	3/4" FNPT	1/2" MNPT	1/2" FNPT	1	1	4040	1	1	Multi-Stage	1/4 HP	3450	120V 1Ph 60 Hz 9 Amps	18x18x55	130
CRO-4000	Single Pass	TDS <2000 ppm	47%	50% – 75%	98.5%	2.78 gpm	3.00 gpm	Up to 5.00 gpm	3/4" FNPT	1/2" MNPT	1/2" FNPT	1	2	4040	1:1	2	Multi-Stage	1/4 HP	3450	120V 1Ph 60 Hz 9 Amps	18x18x55	135
CRO-6000	Single Pass	TDS <2000 ppm	58%	50% – 75%	98.5%	4.17 gpm	3.00 gpm	Up to 5.00 gpm	3/4" FNPT	1" MNPT	1/2" FNPT	1	3	4040	1:1:1	3	Multi-Stage	1 HP	3450	220V 1Ph 60 Hz 14.2 Amps	18x18x55	155
CRO-8000	Single Pass	TDS <2000 ppm	65%	50% – 75%	98.5%	5.56 gpm	3.00 gpm	Up to 5.00 gpm	3/4" FNPT	1" MNPT	1/2" FNPT	1	4	4040	1:1:1:1	4	Multi-Stage	1 HP	3450	220V 1Ph 60 Hz 14.2 Amps	18x18x55	180

1 CustomCare recommends pretreatment.

2 Does not include operating space requirements.


Test Parameters: Static pressure test for 5 minutes.

3 Lower water temperature and high TDS feed water levels will significantly affect systems production capabilities.

NOTE: Shipping weight is dry.

Operating Limits

Design Temperature	77° F
Max/Min Feed Temperature	85°/40° F
Max/Min Ambient Temperature	120°/40° F
Max/Min Feed Pressure (psi)	85/45
Max Operating Pressure (psi)	150
Max SDI Rating	<3
Max Turbidity NTU	1
Max Free Chlorine, ppm	0
Max TDS, ppm	2000
Max Hardness GPG	0
Max/Min pH (continuous)	11/5
Max/Min pH (cleaning 30 Min.)	12/2





Bureau of Environmental Health

8930 Stanford Blvd, Columbia, MD 21045
Main: 410-313-2640 | Fax: 410-313-2648
TDD 410-313-2323 | Toll Free 1-866-313-6300
www.hchealth.org

Maura J. Rossman, M.D., Health Officer

November 18, 2016

Miller
3715 Woodbine Road
Woodbine, MD 21797
Sent to barry.a.miller@gmail.com on 11/18/16

RE: **Replacement Well Sampling**
3715 Woodbine Road
#HO-15-0178

Dear Mr. Miller,

According to our records, your replacement well has been connected to the dwelling. We request that you contact the Community Hygiene Program at **(410) 313-1773** to schedule initial water sampling for the above referenced replacement well, as required by the Maryland Well Construction Regulation (*COMAR 26.04.04*). This sampling includes testing for bacteria, nitrates, turbidity, and sand. In addition, we would like to collect samples to test for sodium, chloride, and total dissolved solids (TDS) post-treatment by reverse osmosis. There is currently **no charge** for the sampling and it is to your benefit to have it tested.

Sampling of the new well should be collected from the primary indoor drinking tap, but if suitable scheduling is not possible, the sample may be taken from an outside tap to complete your sampling obligation. However, the potential for unsuccessful sample results increases when samples are collected from taps exposed to the outside environment. If sampling has already been performed by an outside lab, please help us by forwarding the results of the samples to our office.

The old well was abandoned by L.F. Easterday, Inc. on 6/15/16. Documentation was received by the Health Department that this task has been completed.


Feel free to contact me with any questions.

Sincerely,

A handwritten signature in cursive script that reads 'Sarah Collins'.

Sarah Collins, L.E.H.S.
Well and Septic Program
SCollins@howardcountymd.gov
410-313-6287

Cc: Community Hygiene Program
File



Bureau of Environmental Health
8930 Stanford Blvd
Columbia, MD 21045
(410) 313-2640 Fax (410) 313-2648
TDD (410) 313-2323 Toll Free 1-866-313-6300
website: www.hchealth.org

Maura J. Rossman, M.D., Health Officer

November 03, 2015

Barry Miller
3715 WOODBINE ROAD
WOODBINE, MD 21797

**RE: Water Sample Results
3715 WOODBINE ROAD**

Dear Mr. Miller,

We have received the results from the testing of the water sample(s) taken from the above referenced property on October 21, 2015. A description of the results and the established standards for each test is included below. Standards such as maximum contaminant levels (MCL), secondary maximum contaminant levels (SMCL), and drinking water equivalency levels (DWEL) are established by the EPA and other agencies to provide a reference for determining when action should be taken. These standards help to improve the overall quality of your water or ensure that steps are taken to treat the water to prevent you and your family from getting sick. Typically, no water is completely free of contamination but you should be concerned if the level of contamination for a particular test exceeds the standard.

A sample was collected to determine the levels of **Chlorides** in your water supply. The chloride level was 698 parts per million. The SMCL for chlorides is 250 parts per million.

A sample was collected to determine the levels of **Dissolved Solids** in your water supply. The Dissolved Solids level was 1405 parts per million. The SMCL for Dissolved Solids is 500 parts per million.

A sample was collected to determine the levels of **Sodium** in your water supply. The Sodium level was 213.80 parts per million. The DWEL for Sodium is 20 parts per million.

Please contact the Health Department at (410) 313-1773 between 8:30 a.m. and 4:30 p.m., Monday through Friday if you have any questions regarding these test results.

Sincerely,



Ramar Martin, R.S.
Community Hygiene Program

Enclosures

SEND REPORT TO:

Howard County Health Department
Bureau of Environmental Health
8930 Stanford Blvd.
Columbia, Maryland 21045

STATE OF MARYLAND
DEPARTMENT OF HEALTH AND MENTAL HYGIENE
LABORATORIES ADMINISTRATION
1770 Ashland Avenue, Baltimore MD 21205
Robert A. Myers, Ph.D., Director

403

Category Code: 4F

Invoice No.: ICCP

Lab No.:

FIELD RECORD

Sample Type:

- Community
- Transient
- Non-Transient
- Private
- Repeat Sample
- C.O.P.
- Bottled Water

Source Address: Barry Miller, 3715 Woodbine Rd.

Sampling Site: POWDER ROOM 1-11-1004 Bottle No.: HC 3715

Iced: Yes No Treated: Yes No County: HOWARD

Date Collected: 7/10/16 Time Collected: 10:00 am pm

Collector Name: BOLESLAV SKRYAR Collector ID No.: 3179 BS

Collector Tel. No.: 410-313-1777 PWS ID No.:

Test Requested:

- Quantitative: Colilert®-QT Enterolert®
- P/A: Colilert® Enterolert®
- Multiple Tube Fermentation: MTF MTF (AI Method-Source Waters Only)
- Heterotrophic Plate Count (HPC-Pour Plate Method)

1	3						
County		Plant No.		Sampling Station			
6	8	0	0	0	0	0	0
pH		Res. CI:		Free		Total	

OTHER: * Sand presence not tested

REMARKS:

LABORATORY RECORD (DHMH Use Only)

- Test SM 9223 Colilert® SM 9223 Colilert®QT SM 9223 Colilert®-18
- Method(s): SM 9221 B (MTF) SM 9221 B, E (MTF) SM 9221 E (A1)
- (Check all that apply) SM 9215B (HPC) Enterolert® ASTM D6503-99
- OTHER:

Temperature Control: 13 °C

Thiosulfate: Present Absent Undetermined

P/A TEST (Colilert®/Enterolert®)

100 mL sample	(+/-)
Total coliforms	
<i>E. coli</i>	
Enterococci	

QUANTITATIVE TEST (Colilert®-QT/Enterolert®)

Dilution	100 mL sample	# Positive wells	MPN/100 mL
<input type="checkbox"/> 1:10	Total coliforms	0	<1
<input type="checkbox"/> 1:100	<i>E. coli</i>	0	<1
<input type="checkbox"/> 1:1000	Enterococci		

HETEROTROPHIC PLATE COUNT (Pour Plate Method, Plate Count Agar)

Plate A: Plate B:

Incubate 24.48.72 hrs @ 35°C (CFU/ml) =

Average:

JUL 11 '16 PM 1:59

RECEIVED JUL 11 '16 PM 3:49

PLACED IN INCUBATOR JUL 12 '16 AM 10:00

RESULTS READ/REPORTED

PRESUMPTIVE MTF TEST

mL of Sample	10
Gas/24h	
Gas/48h	

RECEIVED JUL 15 2016

CONFIRMED MTF TEST (Multiple Tube Method)

mL of Sample	10	1	0.1
Total Coliforms			
Fecal Coliforms			
Coliforms			

RESULTS

No. of Positives (+)	MPN/100 mL	Recorded Value

SAMPLE INVALIDATION:

- Sample Rejection
- Laboratory Accident
- Other: _____

RESAMPLE REQUIRED: YES NO

DATE:

BACTERIOLOGIST: Player 7-12-16 REVIEWED BY/DATE: K. Jones 7/12/16

REMARKS: ea 7/16 FAX EMAIL PHONE

LABORATORY: CENTRAL (443) 681-3960 ES REGIONAL (410) 219-9005 WMD REGIONAL (301) 759-5115

This report shall not be reproduced except in full without the written approval of the laboratory. Results only valid for sample received.



State of Maryland
DHMH-Laboratories Administration
Division of Environmental Chemistry
INORGANICS ANALYTICAL LABORATORY
1770 Ashland Avenue, Baltimore, Maryland 21205
Robert Myers, Ph.D., Director



Certificate of Analysis


HOWARD CO ENVIRONMENTAL HLTH
8930 STANFORD BLVD
COLUMBIA, MD 21045

Lab Project NoE17000110 Date Coll. 07/11/2016 Date Received 07/11/2016 Submitted By: B. Shklyar

Field ID: HC3715
Lab No.: E17000110001

<u>Analyte</u>	<u>Method</u>	<u>Result</u>	<u>Units</u>	<u>Date Analyzed</u>
Nitrate + Nitrite, as N	EPA 353.2	0.61	mg N/L	07/12/2016
Turbidity	EPA 180.1	<0.5	NTU	07/12/2016

Comments:



Approved by: _____

Shabir Aneli

Approval date: 07/14/2016

*The following methods are included in our A2LA Scope of Accreditation: EPA150.1, EPA 353.2, EPA 375.2, SM4500F C, SM 4500-CN G & QCM-CN, QCM-CN.

This document contains confidential health information that is privileged, confidential and exempt from disclosure under law. If you have received this information in error, please call (410) 767-6190 and arrange for return or destruction.

Telephone: (443) 681 - 3855

Fax: (443) 681 - 4507

S:\EnviroFinal-InorganicsA.rpt



State of Maryland
DHMH-Laboratories Administration
Division of Environmental Chemistry
TRACE METALS LABORATORY
1770 Ashland Avenue, Baltimore, Maryland 21205
Robert Myers, Ph.D., Director



Certificate of Analysis

HOWARD CO ENVIRONMENTAL HLTH
8930 STANFORD BLVD
COLUMBIA, MD 21045

Lab Project No: E16002224 Date Coll.: 11/23/2015 Date Received 11/23/2015 Submitted By: Collins

Field ID: HO-15-0178
Lab No.: E16002224001

<u>Method</u>	<u>Element</u>	<u>Result</u>	<u>Units</u>	<u>Date Analyzed</u>
EPA 200.7	Sodium	106.20	ppm	11/24/2015



Comments:

Approved by: *Yinghao Choi*

Approval date: 12/01/2015

**The following methods are included in our A2LA Scope of Accreditation: EPA 200.7, EPA 200.8, EPA 245.1.

This document contains confidential health information that is privileged, confidential and exempt from disclosure under law. If you have received this information in error, please call (410) 767-6944 and arrange for return or destruction.



State of Maryland
DHMH-Laboratories Administration
Division of Environmental Chemistry
INORGANICS ANALYTICAL LABORATORY
1770 Ashland Avenue, Baltimore, Maryland 21205
Robert Myers, Ph.D., Director



Certificate of Analysis


HOWARD CO ENVIRONMENTAL HLTH
8930 STANFORD BLVD
COLUMBIA, MD 21045

Lab Project No E16002211 Date Coll. 11/23/2015 Date Received 11/23/2015 Submitted By: S. Collins

Field ID: HO-15-0178
Lab No.: E16002211001

<u>Analyte</u>	<u>Method</u>	<u>Result</u>	<u>Units</u>	<u>Date Analyzed</u>
Chloride	SM 4500-Cl E	504	mg/L	12/01/2015
Total Dissolved Solids	SM 2540C	1083	mg/L	11/24/2015

Comments:



Approved by: *Shabir Aneli* Approval date: 12/02/2015

*The following methods are included in our A2LA Scope of Accreditation: EPA150.1, EPA 353.2, EPA 375.2, SM4500F C, SM 4500-CN G & QCM-CN, QCM-CN.

This document contains confidential health information that is privileged, confidential and exempt from disclosure under law. If you have received this information in error, please call (410) 767-6190 and arrange for return or destruction.

Send Report To: Bert Nixon
 Howard Co. Health Dept.
 Bureau of Environmental Health
 8930 Stanford Blvd.
 Columbia MD 21045

State of Maryland
 DHMH - Laboratories Administration
 Division of Environmental Chemistry
TRACE METALS LABORATORY
 1770 Ashland Avenue
 Baltimore, Maryland 21205


E16002224001
 Received: 11/23/2015
 Metals HO-15-0178

Do not write above this line

LABORATORY ANALYSIS REQUEST

Please Print

Sample ID No: HO-15-0178 Site Name: 3715 Woodbine Rd County: Howard

Sample Source: 3715 Woodbine Rd Woodbine Collector: S. Collins
Street Town or City Name

Date Collected: 11 / 23 / 20 15 Time Collected: 11 a.m. p.m. Phone #: 410-313-6287

Sample Preserved By: Field ESRL WMRL Central Lab

Preservative Used: HNO₃ pH < 2, SHS, 11/23/15 mL pH:

Sample Type: Drinking Water Landfill Source (Raw Water) Liquid
 Community Stream Distribution (Treated) Solid
 Non-Community Sediment Other
 Private

Specify Program: SDWA NPDES CWA RCRA Consumer Products Other

Type of Sample Preparation: Total Metals Total Metals TCLP Dissolved Metals
(field preparation required)

Remarks: Sample taken during yield

✓	Element	Results (ppm)	✓	Element	Results (ppm)
<input checked="" type="checkbox"/>	Antimony (Sb)		<input type="checkbox"/>	Copper (Cu)	
<input type="checkbox"/>	Arsenic (As)		<input type="checkbox"/>	Lead (Pb)	
<input type="checkbox"/>	Barium (Ba)		<input type="checkbox"/>	Silver (Ag)	
<input type="checkbox"/>	Beryllium (Be)		<input type="checkbox"/>	Zinc (Zn)	
<input type="checkbox"/>	Cadmium (Cd)		<input type="checkbox"/>	Aluminum (Al)	
<input type="checkbox"/>	Chromium (Cr)		<input type="checkbox"/>	Iron (Fe)	
<input type="checkbox"/>	Mercury (Hg)		<input type="checkbox"/>	Manganese (Mn)	
<input type="checkbox"/>	Nickel (Ni)		<input type="checkbox"/>	Calcium (Ca)	
<input type="checkbox"/>	Selenium (Se)		<input type="checkbox"/>	Magnesium (Mg)	
<input checked="" type="checkbox"/>	Sodium (Na) <u>OKS</u>		<input type="checkbox"/>	Potassium (K)	
<input type="checkbox"/>	Thallium (Tl)		<input type="checkbox"/>	Uranium (U)	
<input type="checkbox"/>			<input type="checkbox"/>	Vanadium (V)	

RECEIVED

Date Reported: DEC 07 / 2015 /

HOWARD COUNTY HEALTH DEPT.
 COMMUNITY HYGIENE PROGRAM

Lab Supervisor:

•Phone: (443) 681-3857 •Fax: (443) 681-4507



State of Maryland
DHMH-Laboratories Administration
Division of Environmental Chemistry
INORGANICS ANALYTICAL LABORATORY
1770 Ashland Avenue, Baltimore, Maryland 21205
Robert Myers, Ph.D., Director



Certificate of Analysis


HOWARD CO ENVIRONMENTAL HLTH
8930 STANFORD BLVD
COLUMBIA, MD 21045

Lab Project NoE16001741 Date Coll. 10/21/2015 Date Received 10/21/2015 Submitted By:Boleslav Shklyar

Field ID: HC 3715
Lab No.: E16001741001

<u>Analyte</u>	<u>Method</u>	<u>Result</u>	<u>Units</u>	<u>Date Analyzed</u>
Chloride	SM 4500-Cl E	698	mg/L	10/23/2015
Total Dissolved Solids	SM 2540C	1405	mg/L	10/23/2015

Comments:



Approved by:

Approval date: 10/27/2015

*The following methods are included in our A2LA Scope of Accreditation: EPA150.1, EPA 353.2, EPA 375.2, SM4500F C, SM 4500-CN G & QCM-CN, QCM-CN.

This document contains confidential health information that is privileged, confidential and exempt from disclosure under law. If you have received this information in error, please call (410) 767-6190 and arrange for return or destruction.

Telephone: (443) 681 - 3855

Fax: (443) 681 - 4507

S:\EnviroFinal-InorganicsA.rpt



State of Maryland
DHMH-Laboratories Administration
Division of Environmental Chemistry
TRACE METALS LABORATORY
1770 Ashland Avenue, Baltimore, Maryland 21205
Robert Myers, Ph.D., Director



Certificate of Analysis


HOWARD CO ENVIRONMENTAL HLTH
8930 STANFORD BLVD
COLUMBIA, MD 21045

Lab Project No: E16001766 Date Coll.: 10/21/2015 Date Received 10/21/2015 Submitted By: Shkiyar

Field ID: HC 3715
Lab No.: E16001766001

<u>Method</u>	<u>Element</u>	<u>Result</u>	<u>Units</u>	<u>Date Analyzed</u>
EPA 200.7	Sodium	213.80	ppm	10/23/2015

Comments:



Approved by: Sadia Muneer

Approval date: 10/27/2015

**The following methods are included in our A2LA Scope of Accreditation: EPA 200.7, EPA 200.8, EPA 245.1.

This document contains confidential health information that is privileged, confidential and exempt from disclosure under law. If you have received this information in error, please call (410) 767-6944 and arrange for return or destruction.

Telephone: (443) 681 - 3853

Fax: (443) 681-4507

S:\EnviroFinal-Metals.rpt

Send Report To:

Howard County Health Department
 Bureau of Environmental Health
 6930 Stanford Blvd.
 Columbia, Maryland 21045

Division of Environmental Chemistry
ENVIRONMENTAL METALS SECTION
 201 W. Preston Street, Baltimore, Maryland 21201
 Robert A. Myers Ph.D. Director



E16001766001
 Received: 10/21/2015
 Metals HC 3715

Do not write above this line

LABORATORY ANALYSIS REQUEST
 Please Print

Sample ID No: HC 3715 Site Name: Berry Miller County: Howard

Sample Source: 3715 Woodbine Rd Woodbine Collector: B. SHKLYAK
Street Town or City Name

Date Collected: 10/21/2015 Time Collected: 9:00 a.m. p.m. Phone #: 410-315-1787

Sample Preserved By: Field ESRL WMRL Central Lab

Preservative Used: HNO₃ pH < 2, SHS, 10/22/15

Sample Type: Drinking Water Landfill Source (Raw Water) Liquid
 Community Stream Distribution (Treated) Solid
 Data Category Non-Community Sediment Other _____
 Code Private

Specify Program: SDWA NPDES CWA RCRA Consumer Products Other _____

Type of Sample Preparation: Total Metals Total Metals TCLP Dissolved Metals
(field preparation required)

Remarks: SAMPLES TAKEN FROM OUTDOOR FAUCET

✓	Element	Results (ppm)	✓	Element	Results (ppm)
	Antimony (Sb)			Copper (Cu)	
	Arsenic (As)			Lead (Pb)	
	Barium (Ba)			Silver (Ag)	
	Beryllium (Be)			Zinc (Zn)	
	Cadmium (Cd)			Aluminum (Al)	
	Chromium (Cr)			Iron (Fe)	
	Mercury (Hg)			Manganese (Mn)	
	Nickel (Ni)			Calcium (Ca)	
	Selenium (Se)			Magnesium (Mg)	
✓	Sodium (Na) <u>MS</u>			Potassium (K)	
	Thallium (Tl)			Uranium (U)	

Lab Supervisor: _____

•Phone: (410) 767-6186

•Fax: (410) 333-5122

DHMH 4432 (4/13)

SUBMITTER'S COPY

