UP 9.18.78

REFAIR

MARYLAND STATE DEPARTMENT OF HEALTH*

HOWARD COUNTY

INDEXED

ELLICOTT CITY DISTRICT_ DATE_8/2/78

Bud Arnold IS PERMITTED TO INSTALL ADDRESS_ SUBDIVISION_ PROPERTY OWNER Raymond F. Mills ADDRESS 1310 Route 94, Lisbon, Md. SPECIFICATIONS 2 bedrooms WELL WATER ISSUE SEPTIC TANK CAPACITY 1000 GALLONS RECTIFIED? DRAIN FIELD _____ DEPTH _____ FEET, BOTTOM AREA ___ ___ DEPTH _____ FEET, BOTTOM AREA _____ ____ABSORBENT SIDE-WALL AREA ______ SQ. FT. INLET PIPE _____ FT. BELOW ORIGINAL GRADE. MAXIMUM DEPTH ____ ___ FT. BELOW ORIGINAL GRADE EFFECTIVE DEPTH AT ______ FT. BELOW ORIGINAL GRADE. LOCATE DISPOSAL AREA ______ FT. FROM _____ LOT LINE AND ____ FACING LOT FROM. . REPAIR- CALL FOR INSPECTION WHEN GROUND IS OPENED UP SO SANITARIAN WAN RECOMMEND PLANS APPROVED BY Palmer F. Wine COVER NO WORK UNTIL INSPECTED AND APPROVED. NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM.

IF TRENCH IS USED CALL FOR INSPECTION BEFORE PLACING GRAVEL IN TRENCH. NOTE:

NO DRY WELL SHALL EXCEED 15 FOOT IN DIAMETER. NOTE:


ALL PIPE FROM HOUSE TO DISPOSAL AREA MUST BE CAST IRON.

PERMIT VOID AFTER THREE YEARS.

INSTALL STAND PIPE ON SEPTIC TANK AND DRY WELL. STAND PIPES MUST BE 6 INCHES IN DIAMETER. CAST IRON, CONCRETE OR TERRA

COTTA ACCEPTED.

*INSTALLER IS RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT.




INDICATE NORTH NAME ADJOINING ROADWAY AS BASE LINE.	.l
PERMIT CARD OF NP	
SEPTIC TANK, LEVEL 0 12 CLEANOUTS OK	· · · · · · · · · · · · · · · · · · ·
DISTRIBUTION BOX, LEVEL OL	
TILE FIELD, DEPTH 4 FT. TRENCH WIDTH 3 FT.	* max
GRAVEL DEPTH 18 IN. TOTAL LENGTH 115 FT.	
NUMBER OF TRENCHES 4 TOTAL BOTTOM AREA 345	
SEEPAGE PITS, INSIDE DIAMETERFT. DEPTH BELOW INLETFT.	
ABSORBENT AREASQ. FT.	
REMARKS	
in the second of	
	·
DATE SYSTEM APPROVED 9/18/78 INSPECTOR DW Monagh	4

Call Mus. Ferrarain order to gain access into house
4.014.7
FILE Well & Septic Inspection DATE REPORTED 6/29/78
PROPERTY OWNER Raymond Mills
P.O. ADDRESS 1310 Route 94 TELEPHONE
DIRECTIONS TO PROPERTY Liston, md.
INFORMANT Martla Ferrara 465-6400- home-465-0800
Scenpler Real Est.
4296 Montgomery Rd.
Elliott City, md. 21043
CONDITION FOUND Boxt. P769 10:40 Am 7/5/78 (88)
Dry well full level is up in stand sine wet less
Dry well full. Ievel is up in stand pipe at less than 2 feet below ground. Has been almost to top.
Hel 2 de e 1 cas 1.1 2 de
Had 2 days of rain July 2 and 3 td.
- MICHAIO WALL CAMBAIN
Letter 7-6-78 Needs, septir Repair (MS)
1 1 1 0 7 1 1 1 1 1 1 1 1 1 1
ACTION TAKEN
M
Mus 19:11s 489-4233
* FINAL DISPOSITION
) ————————————————————————————————————

July 6, 1978 Martha Ferrara Grempler Realty 4296 Montgomery Road Ellicott City, Md. 21043 Dear Ms. Ferrara: At your request, I inspected the sewage disposal system at 1310 Route 94, Lisbon, Md. on July 5, 1978. My inspection revealed that the dry well was filled to capacity. This condition indicates that the soil around the dry well is no longer absorbing the sewage as efficiently as it should and the sewage disposal system is failing. To correct this problem, you or your buyer must apply to this office for a permit and percolation test for a repair system. Very truly yours, Lawrence Spilker LS:ds

July 17, 1978 Ms. Martha Ferrara Grempler Real Estate 4296 Montgomery Road Ellicott City, Md. RE: 1310 Route 94 Raymond Mills Dear Ms. Ferrara: The tests run on the above referenced water supply shows the presence of bacteria that may be harmful to your health. In order to correct this, you should have the well checked for breaks in the lines or seals or other structural defects. Then, you should have the well disinfected as shown in the enclosed literature. When you have done this, call the Health Department and we will be glad to arrange for further testing. Very truly yours, Lawrence J. Spilker LJS:ds **Enclosure**



.