INSP 2 // 8 INSP 3 // 5 /	109 (B) INSP 5
APPROVAL DATE	PERVIII-
Hatfield	's Equipment IS PERMITTED TO INSTALL ⊠ ALTER□
ADDRESS:	P.O. Box 519 Annapolis Junction MD PHONE NUMBER: 301-490-4289
SUBDIVISION:	NA LOT NUMBER: NA
ADDRESS:	1565 Woodstock Rd. PROPERTY OWNER: Fred & Susanna Taft
SEPTIC TANK CA	PACITY (GALLONS): 1,500 OUTLET BAFFLE FILTER REQUIRED
PUMP CHAMBER	CAPACITY (GALLONS): 1,000 COMPARTMENTED TANK REQUIRED⊠
NUMBER OF BED	ROOMS: 3
SQUARE FOOTAG	GE OF HOUSE: <u>1500</u>
LINEAR FEET OF	TRENCH REQUIRED: 53'
TRENCHES:	Install 1 x 50' trench on contour. Trench bottom to be measured from lower side of trench.
LOCATION:	Keep septic tanks 20' from proposed addition.
NOTES:	Test of the blower, alarm and Microfast unit is required. Install Microfast unit per manufacturer's instructions. System designed for a maximum of 3 bedrooms. Layout inspection required prior to installation.
PLANS APPROVE	D: Heidi Scott DATE: 12/3/2008
NOTE: WATERTIGHT SEP NOTE: ALL PARTS OF SEP	SPONSIBLE FOR SCHEDULING A PRE-CONSTRUCTION INSPECTION FOR ALL INSTALLATIONS

NEITHER THE HOWARD COUNTY COUNCIL OR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT CALL 410-313-1771 FOR INSPECTION OF SEPTIC SYSTEM

NOT TO SCALE	TRENCH/DRAINFIELD DATA WIDTH INLET BOTTOM 3 5.5 NUMBER OF TRENCHES TOTAL LENGTH 56 ABSORPTION AREA 168 + 5 w DISTRIBUTION BOX LEVEL DISTRIBUTION BOX BAFFLE DISTRIBUTION BOX PORT
See As-Built Drawing On Separate Sheet	SEPTIC TANK DATA SEPTIC TANK I LEVEL YES MANUFACTURER DAY ON CAPACITY 1500 GAL SEAM LOC TOP TANK LID DEPTH T.B.D. BAFFLES Front Middle BAFFLE FILTER NO MANHOLE LOC FOR WATERTIGHT TEST NO SLOTTED NO PUMPYS. TANK LEVEL MANUFACTURER DAY ON CAPACITY JOO GAL SEAM LOC TO TANK LID DEPTH T.B.D. BAFFLES FYONT BAF
	is moving house com to
States from Soil Soles BB 1/9/09 Frast un INSTALLATION connection made. BB	Mine 50 1/8/09 nit set. House
1/12/09 Treach metalled. System complete. test and P/A test for Swall of werk. Red 1/14/09 P/A test ox. or fast unit very field, ok. Ako present Friendig assoc. (Red)	Need stert-up provide OF to conrell Stert-up test for stut-up test
FINAL INSPECTOR	/AL //14/09

.

				HOW	ard
1	NSTALLATION	a 1 1	AUTHO	ORIZED SE	RVICE PROVIDER
Installation Address	: 1565 Was	dstockk	d.		e & Associates,Inc.
A 3	TOST	ua.		1215 (Old Dorsey Road
City: Woo 5 + State: Mod	ook.		4	Harm	ans, MD 21077
State: MA	2	Zip: 21/63		410-768-85	500 Fax 410-768-3400
Phone:			PECTION	and the second s	
MODEL#	SERIAL#	FILTER#		Installed	Last Pumpout Date:
mcf-0.5201795					
EQUIPMENT		YES	NO	MAINTENANCE PERFORME AND COMMENTS	
Electrical Panel(s			The state of the s		and an address of the second s
	m Operating		-	The second secon	
	m Operating			The second secon	and the control of th
(if present)	an in an ann an a	***************************************			
Blower(s)					
Air Inlet Fi	lter Clean			<u> </u>	de statute au compression de la compression della compression dell
	d Vents Clean				
Excessive Noise			1		**************************************
Excessive Vibration			1/		Briggerhaust,
Treatment Unit(s)		Parameter and the second secon			
Unusual Oc			1		
Pumpout Required				and the sales,	rdent var reg 1994 jag sen ett Grigte (gap etta etta etta var etta etta etta etta etta etta etta et
Primary Set				action control of the state of	ggifer to company to global participant and state of the company o
	atment Zone			as/monthmith conference for the first of the	
EFFLUENT (option		LIMIT	RESULT		
Estimated I					
pH (Standa)		6-9 S.U.			
Color		Clear			en e
Temperatur	е				gartinang
Odor		Slightly		Commence of the Commence of th	CONTRACTOR OF THE PROPERTY OF
		Musty			
		Odor (not	ego agranda		
the August Augus		septic)		and the state of t	
OWNER SIGNAT	URE	TECHNICIAN	SIGNATURE	,	SERVICE DATE
	and the final and the same of		wantana	, -	J/J// V
~				On and the Third	Minnshin
L Se	end to MDE	Send to DNI	ALU LI	Send to Bio	IVIICTODICS
					12/10-



MARYLAND DEPARTMENT OF THE ENVIRONMENT

MDE

1800 Washington Boulevard • Baltimore MD 21230 410-537-3000 • 1-800-633-6101

Martin O'Malley Governor Shari T. Wilson Secretary

Anthony G. Brown Lieutenant Governor

Robert M. Summers, Ph.D. Deputy Secretary

March 18, 2009

Fred Taft 1565 Woodstock Road Woodstock, MD 21163

RE:

Request for Additional Funding Tax Map 10, Grid 18, Parcel 144

Dear Mr. Taft;

As a result of your request for additional funding for the installation of the MicroFAST 0.5 treatment technology on your property the Department has approved an additional \$4,000 due to the site conditions found during the installation.

In order to comply with this request please find enclosed a new <u>Agreement and Easement for Installation of Best Available Technology with Bay Restoration Funds</u> and <u>State BRF Septic Grant Payment Disbursement Request Form</u>. The Agreement will need to be re-recorded in the County Land Records and the Disbursement Request Form will need to be signed and returned with the Agreement for payment.

If you have any questions regarding this request please do not hesitate to contact me via email at jboris@mde.state.md.us or phone at (410) 537-3678.

Respectfully

John A. Boris, Jr., R.S. Bay Restoration Fund Project Manager

Cc:

Jay Prager


Howard County Environmental Health Department Ken Hatfield, Hatfield Equipment & Dedication

SITE INSPECTION SHEET

OWNER: Dawn Titsworth PHONE #: ADDRESS: 1565 Woodstock CONTRACTOR: Easterday WELL TAG #: SUBDIVISION: LOT: COUNTY #: PROPOSAL: Ex. hand dug has low flow / sediment problems.
LOCATION DIAGRAM
Flat (Pest Area to knowld Drill) The found previously Future Repair Area Septic on extends on extends fants fants on extends fants on extends fants on extends fants fan
WOODSTOCK RD
comments: Met driller (George Easterday) & owner (Dawn Titsworth). Discussed problem of access to site and potential solutions of obtaining an easement for a new well. Also discussed area of Future septre repair. DATE: 11/21/02 INSPECTOR: Steven P. Krieg

FILE INQUIRY FORM

Property Address: 1565 WODSTOGE ROAD	
Isoloy Spoke to J.D. MARTINO ON MONDAY. HE WANTED	
HOHD TO BE AWARE THAT THERE MAY BE LEGAL	
PROCERDINGS FILED AGAINST HOUTD REGARDING THE	
DRILLING OF A WELL THAT SOME ONE (BEVIOUS OWNER)	
CLAIMS WAS REDUIRED BY HOLD IN A COURT OF	
LAW. THERE ARE NO NOTES OR SOCIEMENTS TUDICATING	
THAT HEHD WAS INVOLVED IN AM COURT PROCEEDINGS.	
A NEW WELL WAS NEVER DRILLED BY THE PREVIOUS OWNER	
+ SUPPOSTEDLY THEY TOOK THE MONEY (\$13,000 #) THAT	
WHE AWARDED TO THEM TO DO SO + SOLD PROPERTY	
TO A NEW HERSON. THIS NEW OWNEL APPARENTLY FEELS	
WITH THE DRILLING OF the WELL I told Mr. Martino that	
I didn't believe that would have gotten invalved in this	
real estate transaction Stephene Nolson	
The factor of the state of the	
* NO WELL PERMIT APPEARS to Have Boen Issues	
·	



7178 Columbia Gateway Drive, Columbia MD 21046 (410) 313-2640 Fax (410) 313-2648 TDD (410) 313-2323 Toll Free 1-866-313-6300 website: www.hchealth.org

Peter L. Beilenson, M.D., M.P.H., Health Officer

MEMORANDUM

TO:

Carl K. Gutschick

GLW

FROM:

Heidi Scott

Well and Septic Program

Development Coordination Section

RE:

Percolation Certification Plan

1565 Woodstock Rd.

DATE:

September 19th, 2008

The comments below are to be addressed for the above referenced plan. Please revise and resubmit prior to approval.

- The following notes must be added:
 - (1) The septic system must have advanced treatment due to restrictive factors such as steep slopes and less than 200' well separation. A supplemental site plan with all of the necessary details for installation of the system will be required prior to release of the building permit and septic installation permit.
 - (2) The existing well is to abandoned and a new well will be drilled to meet current code prior to building permit approval
 - (3) The existing septic system is to be abandoned and upgraded prior to building permit approval
 - (4) House shall have a maximum of 3 bedrooms
- Show a proposed well location as shown on the enclosed markup with a 100' radius
- Modify the proposed septic area as shown on the enclosed markup
- The Perc Certification statement must be signed *or* a professional seal must be shown.

INSTALLATION

Howard

Authorized service provider

		0
Installation Address: 1565	Woodstock	17d.

Owner Name: Fred tast

City: Woods tock

State: MD

Zip: 2//6 3

Freemire & Associates,Inc.
1215 Old Dorsey Road
Harmans, MD 21077

410-768-8500 Fax 410-768-3400

Phone: 4/0 - 750 - 906/ 2nd 13R/

MODEL#	SERIAL#	FILTER#	TER# Date Installed		Last Pumpout Date:
mcF, 5	201795		1/12/	109	
EQUIPMENT		YES	NO		NANCE PERFORMED ID COMMENTS
Electrical Panel	(s)				
Visual Ala	arm Operating	V			
Audio Ala	rm Operating				
(if presen	t)				
Blower(s)					
Air Inlet	Filter Clean	~			
Blower H	ood Vents Clean				
Excessive	Noise		-		
Excessive	Vibration				
Treatment Unit	(s)				
Unusual Odor				most	·/
Pumpout Requi	red				7
	Settling Zone				
Aerobic 7	Freatment Zone				
EFFLUENT (or	otions)	LIMIT	RESULT		
Estimate	ed Daily Flow				
pH (Star	dard Units)	6-9 S.U.			
Color		Clear			
Tempera	ture				
Odor		Slightly			
		Musty			
		Odor (not septic)			

OWNER SIGNATURE	TECHNICIAN SIGN	SERVICE SERVICE	SERVICE DATE	
Send to MDE	Send to DNREC	Send to BioMicrobics	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	

fred. +af+@ verizon. ne+

410-750-9061 Home

410-365-3950 Cell Sisanna FILE INQUIRY NOTES

4	4	3-	324-	8638	cell	Fred

DATE	RESULTS OF REVIEW FOR FILE
5-2-08	Spoke to homeowner uno says previous owner had a new septic
	system installed within the last 10 yrs. Found no previous
	file, permit, or evidence of new system in HCHD files.
	Ms. Taft currently has a well permit application on hold
	pending outcome of septic situation. May not be enough
	area for proposed addition. BP on HOLD - HS
5-2-08	Augers done or property, results incondusive, max, depth
	reached 2.5-3! Only enough area for 2 systems - HS
5-13-08	Spoke to Ms. Taft explaining at this time given what
	we know there is not sufficient area to support
	proposed addittion and pere testing will not guarentee
	onething HS
5-15-08	Meeting w/ Mike + Sara: 1) perc for possible pre-
	treatment system in back 2) new well in front
	3) Ex. system to be abandoned. Issues: streep slope {
	well setbacksHS
5-23-08	Pere testing conducted by R. Bricker - HS
	Emailed Ms. Taft a list of engineers for Perc Cert Plan
	and info needed for variance request. Also attached
	application for BRF Grant HS 1/20- received variance
	Received PC Plan, needs revisions - 48