Destanayske & Resulla Roperty Jay Map 22; Parcell 300 #33 ed mou 3,8 井1 ed Brow R4 % #5 10-20% 12 RY Did not Jest off 2 All manu mical Brou 1 井山 12 #7 Brou Allon 13080 Williamsfield Dr. TIME OF 2ND INCH DEPTH START BREAK 1" DROP P/F/H DATE TEST# STOP mig 2" DROP 10-20% 3. Imi 55 1:00 2m 3. 02 20 :0 1:05 3,8 1-3.20 :25 12 11:10 3 :3 #3 12 :32 ,d 4. 3. 38 Red Brown :40 12 tyl Hal JA Diel not te 6-3-22 3.5 Red Bus Tisin Cleanout/no ptic Jank 10% REMARKS < SANITARIAN BACKHOE OTHERS man miret TEST HOLES USED IN SDA AVG. PERC TIME SQ. FT/BR \_\_\_ INLET DEPTH \_\_\_\_ MAX. BOT DEPTH TRENCH WIDTH \_\_\_\_EFFECTIVE S/W 12 note: Exposed trenches and they were clean.

### Williams, Jeffrey

| From:    | Williams, Jeffrey  |
|----------|--|
| Sent:    | Wednesday, December 21, 2022 2:44 PM   |
| То:      | geckopu (null)   |
| Cc:      | Bernard, Dana; Silvast, Zackary; Dad; Gregory Benefiel; Gregory Benefiel; John |
|          | Hieatzman; Dad   |
| Subject: | RE: 13080 Williamfield Drive   |
|          |  |

Hello all. I spoke with the homeowner and I wanted to put in an email what we will look for moving forward:

1. The existing trenches are big enough for 4 bedrooms, but the tank is only 1000g and will need to be replaced with a larger tank at least 1250 gallons to support the addition.

2. I don't think we need to have someone field locate the existing trenches, we will just need a plan showing where the new tank will go and it will connect into the line heading into the existing distribution box. This will be the tricky part because there is very little room to make that happen unless you send the sewer line down the hill to the side of the house and add a pump tank to pump the sewage effluent back up to head into the d-box. If you do that, I strongly recommend you have someone familiar with system design in Howard County prepare that plan.

3. We will need to approve the plan and have a septic contractor do the tank replacement under a septic permit before we can sign off on the building permit.

4. We also still need to sign the perc cert plan to establish the sewage disposal area. For that, we do not need to see replacement trenches shown on there. We just need to see the proposed area, the existing trenches. It will get a note stating that the tank will be replaced and an OSDS plan and tank replacement must be approved before Health dept approval of the building permit.

Let me know if there are questions. Thanks Jeff

-----Original Message-----From: geckopu (null) <geckopu@aol.com> Sent: Thursday, December 15, 2022 1:10 PM To: Williams, Jeffrey <jewilliams@howardcountymd.gov> Cc: Bernard, Dana <dbernard@howardcountymd.gov>; Silvast, Zackary <zsilvast@howardcountymd.gov>; Dad <Prasad.Dissanayake@tideh2o.net>; Gregory Benefiel <surveysinc1@verizon.net>; Gregory Benefiel <surveysinc@verizon.net>; John Hieatzman <john@foglesinc.com>; Dad <Prasad.Dissanayake@tideh2o.net> Subject: Re: 13080 Williamfield Drive

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Good afternoon, Jeff!

Thank you for your response. We will wait for here from you.

Thank you! Have a great day!

#### Devinka. 🐅 🚱 Sent from my iPhone

> On Dec 15, 2022, at 12:08 PM, Williams, Jeffrey <jewilliams@howardcountymd.gov> wrote:

>

> Hello everyone. Sorry for the confusion, but before you schedule any field work, I'd like to review the file and determine if we need any additional info before finalizing the perc cert and moving to the OSDS plan. I would just like to make sure we don't have people spend money unnecessarily. I can have an answer for you by Monday.

- >
- > Jeff Williams
- > Deputy Director
- > Bureau of Environmental Health
- > Howard County Health Dept.
- > 8930 Stanford Blvd. Columbia, MD 21045
- > 410-313-4261
- > https://gcc02.safelinks.protection.outlook.com/?url=http%3A%2F%2Fwww.h
- > chealth.org%2F&data=05%7C01%7Cjewilliams%40howardcountymd.gov%7C21e610
- > 3ba863406f652008dadec7bc66%7C0538130803664bb7a95b95304bd11a58%7C1%7C0%
- > 7C638067246700878799%7CUnknown%7CTWFpbGZsb3d8eyJWIjoiMC4wLjAwMDAiLCJQI
- > joiV2luMzliLCJBTiI6lk1haWwiLCJXVCI6Mn0%3D%7C3000%7C%7C%7C&sdata=dPX9Qr
- > 6FpFVm4dYM9CBIABcYrWPxG84tGoIcbOgZ%2F5U%3D&reserved=0

>

- > DISCLAIMER: This e-mail is intended only for the individual to whom it
- > is addressed. It may be used only in accordance with applicable laws.
- > If you are not the intended recipient, you are strictly prohibited
- > from reading, disseminating, distributing, or copying this message. If
- > you received this e-mail by mistake, please notify the sender and
- > destroy this e-mail
- >
- >
- >
- > -----Original Message-----
- > From: Bernard, Dana < dbernard@howardcountymd.gov>
- > Sent: Thursday, December 15, 2022 11:24 AM
- > To: geckopu (null) <geckopu@aol.com>; Silvast, Zackary
- > <zsilvast@howardcountymd.gov>; Dad <Prasad.Dissanayake@tideh2o.net>;
- > Gregory Benefiel <surveysinc1@verizon.net>; Gregory Benefiel
- > <surveysinc@verizon.net>; John Hieatzman <John@foglesinc.com>
- > Subject: RE: 13080 Williamfield Drive
- >
- >

> Good Morning All,

>

> After speaking with the Assistant Director, we have decided it will not be necessary to include me in your visit because you will be using the existing trenches for your proposal. We are recommending you locate the septic components and survey the property to locate the trenches. Which can be achieved with the engineer, surveyor, and your septic installer. And if you are interested in scoping your system to examine health of your system we will accept this report. A sewer scope inspection uses a video attached to a snake-like cable to examine the home's sewer line. Sewer scope inspections can reveal damage to the pipes, blockages, and other problems.

>

> When your engineer completes all the tasks discussed in our meeting. Please have your engineer provide our office with your results and a new percolation certification plan. Once the percolation certification plan is signed, then we will need an OSDS plan submitted and we will review as soon as possible.

>

- > Respectfully,
- > Dana Bernard
- >
- >
- >
- > -----Original Message-----
- > From: geckopu (null) <geckopu@aol.com>
- > Sent: Thursday, December 15, 2022 10:23 AM
- > To: Bernard, Dana <dbernard@howardcountymd.gov>; Silvast, Zackary
- > <zsilvast@howardcountymd.gov>; Dad <Prasad.Dissanayake@tideh2o.net>;
- > Gregory Benefiel <surveysinc1@verizon.net>; Gregory Benefiel
- > <surveysinc@verizon.net>; John Hieatzman <John@foglesinc.com>
- > Subject: 13080 Williamfield Drive
- >
- > [Note: This email originated from outside of the organization. Please
- > only click on links or attachments if you know the sender.]
- >
- >
- > Good morning, Dana!

> Please give us a few options for dates for the excavation. I would like this done as soon as possible.

- >
- > Thank you!
- > Have a good day!
- >

> Devinka. 🐅 🕼

> Sent from my iPhone

From: surveysinc1@verizon.net,

- To: dbernard@howardcountymd.gov,
- Cc: jewilliams@howardcountymd.gov,
- Bcc: geckopu@aol.com,
- Subject: 13080 Williamfield Drive
- Date: Wed, Jan 4, 2023 9:55 am

Attachments: Ex DB.pdf (2387K), OSDS Plan 1 of 2.pdf (4952K), OSDS Plan 2 of 2.pdf (3510K), Perc Cert Plan.pdf (3973K)

Dana & Jeff,

Attached is the Perc Certification Plan revised using the existing system from the existing distribution box. We were able to locate the DB and get an invert at the bottom. It's a concrete and in good shape.


Not sure if it need replacing. We had to relocate the Septic tank as Jeff mentioned we may, to the front side of the existing house. Due to the fact that the DB is so deep in the ground, we are able to still get gravity flow. Also attached is the OSDS Plan sheet 1 of 2 & 2 of 2. These may help you see how I came up with the elevations (profile and tank detail). I'm not sure how the Health department wanted me to show the replacement trenches. The existing system consist of two 100' trenches, we're required to have one 100' for the initial and 1st replacement. Basically we are using two trenches for the initial. There

is room still for an 1st & 2nd replacement system. I moved the 1st & 2nd replacement trenches to the bottom of the sewage disposal area to stay clear of the existing trenches because there locations are not

known and field located, but believe there are shown closely correct. If you could take a look at the attached plans and get your input to see if you would like any modification to the plan, I would greatly appreciate it.

Thanks, Happy new year, I'll wait to hear from you.

Gregory Benefiel Survey's, Inc. 301-776-0561



Date: August 16, 2022

To: Surveys, Inc. C/O Gregory Benefiel 350 Main Street Laurel, Maryland 20707

Via E-mail: <u>surveysinc1@verizon.net</u> CC: Homeowner: <u>geckopu@aol.com</u>

### RE: Percolation Certification Plan Revision 13080 Williamsfield Dr., Tax Map 22: Parcel 300

Mr. Benefiel,

As discussed in the percolation testing results letter, the purpose for conducting percolation tests was to re-establishment of a sewage disposal area for the lot. The plan you submitted did not reflect the new test holes that was dug. Your plan reflects the original proposed plan. The septic system must be redesigned showing the new percolation holes and labeled according to the report provided to you. You cannot use testing holes in your septic system that was not tested. And the edge of the septic area must be cut off by the testing holes used. As we discussed in the field the new tank cannot be placed in the swale and must be moved uphill. And the new tank must be shown on the plan to be installed with a riser. The existing tank must be marked abandoned because it will not support a 4-bedroom house.


The existing trenched were exposed and they should be field located and placed on your plan and labeled. The percolation testing holes should be field located, and elevations of the holes should be shown on the plan. The septic area and all its components must be 20 feet away from the house. I would recommend submitting a revised OSDS plan to reflect the changes with your percolation certification plan to save time in completing your review.

The following items must also be addressed. This item pertains to the percolation certification plan general notes:

• The lot(s) shown herein complies/comply with the minimum ownership width and lot area as required by the Maryland Department of Environment.

The next step in this process is to resubmit a Percolation Certification Plan to confirm the design of the septic reserve area. If you have any questions regarding this evaluation or requirements for the Percolation Certification Plan, please contact me at the above address or by telephone at (410) 313-2775.

Respectfully, Dana Bernard, REHS/RS Well and Septic Program File



Bureau of Environmental Health 7178 Gateway Drive Columbia, MD 21046 (410) 313-2640 Fax (410) 313-2648 TDD (410) 313-2323 Toll Free 1-866-313-6300 Website: www.hchealth.org Maura J. Rossman, M.D., Health Officer

Date: June 7, 2022

To: Surveys, Inc. C/o Gregory Benefiel 350 Main Street Laurel, Maryland 20707

### RE: Percolation Testing Report 113080 Williamsfield Dr. Tax Map 22: Parcel 300

Mr. Benefiel,

Percolation testing was conducted on the referenced property on June 3, 2022. The purpose for conducting these percolation tests was to re-establishment of a sewage disposal area for the lot.

A total of five (5) test holes were evaluated and five (5) were found to be satisfactory with moderate percolation rates. Acceptable ranges for recommended inlet and trench bottom depth, and usable sidewall are indicated, and may be confirmed at the time of installation. Field data collected is shown on the Percolation Test Worksheet enclosed with this letter.

All percolation tests conducted were standard tests, measuring rate of fall for a pre-wet period followed by measurement and recordation of the time required for the water level to drop 1 inch. Areas that may be included in a septic reserve are represented by test locations having satisfactory soil conditions. The area of the septic reserve must be at least 10,000 square feet, though Howard County Code [3.805.A.2.X] requires that the area be large enough to accommodate an initial drain field and two repair drain fields for the planned residence.

The next step in this process is to submit a Percolation Certification Plan to confirm the design of the septic reserve area. Please remember you will have to show the existing tank as abandoned and show a new tank to be installed with a riser. If you have any questions regarding this evaluation or requirements for the Percolation Certification Plan, please contact me at the above address or by telephone at (410) 313-2775.

Respectfully, tana Benerd

Dana Bernard, REHS/RS Environmental Specialist II Well and Septic Program

Enclosures File

HOWARD COUNTY HEALTH PARTMENT DE 11506 44398 1394 teceived From \_\_\_\_ P3 AONE # iansfield For \_ CASH NÓ. Dollars **Received By** 

#### 4/21/22, 11:53 AM

Show Receipt Detail

RECEIPT

Howard County, MD HOWARD COUNTY HEALTH DEPARTMENT ASCEND ONE BUILDING Columbia, MD 21045 8930 STANFORD BLVD

#### Application: WS-PT-22-01148 Application Type: EnvHealth/Well and Septic/Percolation Test/Application Address: 13080 Williamsfield DR,

| Receipt No.       | 3634                              |             |              |            |          |  |
|-------------------|-----------------------------------|-------------|--------------|------------|----------|--|
| Payment Method    | Ref Number                        | Amount Paid | Payment Date | Cashler ID | Received | Comments                               |
| Check             | 165                               | \$506.00    | 04/21/2022   | JUKING     |          | Perc Test App/ 13080 Williamsfield Dr. |
| Work Description: | 13080 williamsfield Dr / Perc app |             |              |            |          |  |

https://eh\_howarbps-prod-av.accela.com/portlets/fee/receiptView.do?mode=view&autoPrint=false&receiptnbr=3634&module=EnvHealth&spaceName=spaces.e

|                  | Howard County<br>Health Department   | Bureau of Environmental Health<br>8930 Stanford Boulevard, Columbia, MD 21045<br>Main: 410-313-2640   Fax: 410-313-2648<br>TDD 410-313-2323   Toll Free 1-866-313-6300<br>www.hchealth.org<br>Facebook: www.facebook.com/hocohealth<br>Twitter: HowardCoHealthDep |
|------------------|--|---|
|                  |  | n, M.D., Health Officer   |
|                  |  | SATION<br>NG AND SITE EVALUATION  |
|                  | PROPERTY LOCATION  |   |
| 2 - <u>199</u> 9 | SUBDIVISION/PROPERTY NAME ROSE MARY ES   | TATES - LOT 16  |
|                  | PROPERTY ADDRESS 13080 WILLIAMSFIELD   | DRIVE, ELLICOTTUTY, MD. 21042   |
|                  | TAX ACCOUNT #03-294579 TAX MAP 0022 GRID 0004  | PROPOSED LOT (EX)   |
|                  | ZONING CATEGORY <b>RR-DEO</b> TIER   | Fisisan al  |
|                  | DAYTIME PHONE X CELL X   |   |
|                  | MAILING ADDRESS 13080 WILLIAMSFIELD DRIV   |   |
|                  | APPLICANT <u>* Hay sha Fransad</u> Dissince<br>Daytime phone <u>*443 -983-139</u> (cell <u>443</u> )<br>Mailing address <u>* 5124 Sante</u> Fe (Just E<br>STREET<br>I HEREBY APPLY FOR THE NECESSARY TESTING/EVALUATION PRIM | ACGELATIONSHIP TO OWNER: X OWNER ON MOU<br>39 EMAIL X 986 KOP 18 AOU (OM) 210<br>Ellicoff (182 MD) 21043<br>CITY, STATE<br>OR TO ISSUANCE OF SEWAGE DISPOSAL SYSTEM PERMIT(S):  |
|                  | COMMERCIAL (PROVIDE DETAIL OF TYPE OF USE AND NUMBERS ( IS THE PROPERTY WITHIN 2500 FEET OF ANY RESERVOIR? YES U   | DOMS IN THE COMPLETED STRUCTURE (4BK. TOTAL)  |
|                  | AS APPLICA<br>• THIS A<br>• THE AF<br>• THIS AF<br>• THIS IS   | FEE PAYMENT AND APPROVAL IS BASED UPON HEALTH   |
|                  | I declare an<br>property or<br>regulations. be put in<br>By signature<br>purpose of l  | ntaine Missing<br>er. 1 a<br>mit/si h Deccolog 2  |
|                  | signatu acsigned to DB.  | mit/si<br>— Pl fill dit   |
|                  | JW 10/29/15 acsigned to VD.  | - Please contact  |
|                  | - 25   | owner, let them know  |
|                  |  | they need an engineer.  |

### Williams, Jeffrey

| From:    | Williams, Jeffrey                  |
|----------|------------------------------------|
| Sent:    | Monday, January 9, 2023 11:25 AM   |
| То:      | Gregory Benefiel                   |
| Cc:      | geckopu (null); Bernard, Dana; Dad |
| Subject: | RE: 13080 Williamfield Drive       |

Hello Greg. I have signed the perc cert for the property and 2 copies are ready for pickup at our front counter. I also reviewed the OSDS plan in the package and have the following comments for revision:

- 1. The sewer line between the house and septic tank cannot have bends more than 45 degrees. Any greater bend must be in steps of 45 degrees or less.
- 2. The tank is being shown with the pipe entering the side of the tank. You must verify that the pre-caster can make a tank with the side entrance and show that on the plan or, ideally, it looks like the tank can be rotated and the line leaving the tank will just bend to resume its course to the d-box.
- 3. The tank could be raised to provide 1' ground cover and still have over 2% fall from house. That would allow for more fall to d-box, possibly over 2%, which is ideal.
- 4. There is no health officer signature block needed on this plan.
- 5. The plan is not signed or stamped (I believe you may have just sent this as an example plan?). We will also need 3 copies of this plan.

Let me know if there are questions. Thanks Jeff

From: Gregory Benefiel <surveysinc1@verizon.net>
Sent: Wednesday, January 4, 2023 9:56 AM
To: Bernard, Dana <dbernard@howardcountymd.gov>
Cc: Williams, Jeffrey <jewilliams@howardcountymd.gov>
Subject: 13080 Williamfield Drive

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Dana & Jeff,

Attached is the Perc Certification Plan revised using the existing system from the existing distribution box. We were able to locate the DB and get an invert at the bottom. It's a concrete and in good shape.

Not sure if it need replacing. We had to relocate the Septic tank as Jeff mentioned we may, to the front side of the existing house. Due to the fact that the DB is so deep in the ground, we are able to still get gravity flow. Also attached is the OSDS Plan sheet 1 of 2 & 2 of 2. These may help you see how I came up with the elevations (profile and tank detail). I'm not sure how the Health department wanted me to show the replacement trenches. The existing system consist of two 100' trenches, we're required to have one 100' for the initial and 1st replacement. Basically we are using two trenches for the initial. There

is room still for an 1st & 2nd replacement system. I moved the 1st & 2nd replacement trenches to the bottom of the sewage disposal area to stay clear of the existing trenches because there locations are not

known and field located, but believe there are shown closely correct. If you could take a look at the attached plans and get your input to see if you would like any modification to the plan, I would greatly appreciate it.

Thanks, Happy new year, I'll wait to hear from you.

Gregory Benefiel **Survey's**, Inc.



### Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045

Main: 410-313-2640 | Fax: 410-313-2648

TDD 410-313-2323 | Toll Free 1-866-313-6300

## Maura J. Rossman, M.D., Health Officer

Date: October 6, 2022

- To: Gregory Benefiel Via E-mail: <u>surveysinc1@verizon.net</u>
- CC: Homeowner via email: geckopu@aol.com

### RE: Percolation Testing Plan Revisions 13080 Williamfield Drive Tax Map: 22 Parcel: 300

### Mr. Fleming,

The following items must also be addressed regarding your percolation certification plan for the development of 13080 Williamsfield. The following items must be addressed and resubmitted.

- > Show > 25% slopes and place a symbol in legend.
- > Extend contours across the entire property.
- Show easement 25 feet off swales.
- Is note #13 complete? It should not state septic easement and should state septic disposal area.
- Note #14 Are we going to use the existing septic system. Please state so and make sure you state sewage disposal area.
- > There should not be (2) two statements labeled #14
- What are the approximate locations of the trenches? We need to show the length and distances between. Label existing trenches and proposed trenches. We need to make sure the trench location information is current and up to date. You cannot propose new trenches between existing trenches. Please verify locations.

The next step in this process is to resubmit a Percolation Certification Plan to confirm the design of the septic reserve area and well area. If you have any questions regarding this evaluation or requirements for the Percolation Certification Testing Plan, please contact me at the above address or by telephone at (410) 313-2775.

Respectfully,

Dana Bernard, REHS/RS Environmental Specialist II Well and Septic Program File



**Bureau of Environmental Health** 

8930 Stanford Blvd | Columbia, MD 21045 410.313.2648 - Fax 1.866.313.6300

Maura J. Rossman, M.D., Health Officer

DATE: February 23, 2022

TO: Harsha P. Dissanayake Via E-mail: prasnd.dissanayake@tidehzo.net

CC: Rick Fleming at: Rick.Fleming@RTFS-exc.com

### RE: Building Permit # B22000269 13080 Williamfield Drive Ellicott City, MD 21042


Mrs. Dissanayake,

Our department has reviewed your building permit B22000269 and based on your proposal, your septic system must be upgraded. Our records indicate that you file is not compete. Our requirements for building permits are a full complete file for application approval. Therefore, percolation testing and a percolation certification plan will be required to complete your file. After percolation testing has been completed, we will require the percolation certification plan to be submitted to our office for approval. This plan along with testing results will complete your file and allow us to review your building application. A new septic system must be installed prior to building permit approval.

To get started, percolation testing must occur on the property. Please submit a percolation test application, percolation test plan and fee of \$506 to the Health Department (Application Attached). The homeowner will be responsible for hiring an engineer to create a percolation test plan and a septic contractor with a backhoe to dig the percolation test holes. Once the testing is completed a sewage disposal area (SDA) for the proposed house and future repairs must be established on a percolation certification plan." Since a percolation certification plan does not exist for this property, it will have to be updated prior to building permit approval (Howard County Code Sec 3.805). Also, your tank which is a 1000-gallon tank will have to be upgraded to a 2000-gallon tank. And your trenches will have to be extended.

Your building permit will be placed "on hold" until all Health Department requirements are met. If you have any questions or correspondence, I can be reached at the above address or by telephone at (410) 313-2775.

Respectfully, Dana Bernard, REHS/RS Environmental Specialist II, Phone (410) 313-2775 E-mail: <u>DBernard@howardcountymd.gov</u>



Bureau of Environmental Health 7178 Gateway Drive Columbia, MD 21046 (410) 313-2640 Fax (410) 313-2648 TDD (410) 313-2323 Toll Free 1-866-313-6300 Website: <u>www.hchealth.org</u> Maura J. Rossman, M.D., Health Officer

Date: June 28, 2022

To: Surveys, Inc. C/o Gregory Benefiel 350 Main Street Laurel, Maryland 20707

Via E-mail: surveysinc1@verizon.net

CC: Homeowner: geckopu@aol.com

### RE: Percolation Testing Report 113080 Williamsfield Dr. Tax Map 22: Parcel 300

Mr. Benefiel,

Percolation testing was conducted on the referenced property on June 3, 2022. The purpose for conducting these percolation tests was to re-establishment of a sewage disposal area for the lot. The plan you submitted was the original plan submitted with minor changes. The septic system must be redesigned showing the new percolation holes labeled according to the report provided to you. You cannot use testing holes in your septic system that was not tested. And the edge of the septic area must be cut off by the testing holes used. As we discussed in the field the new tank cannot be placed in the swale and must be moved uphill. The existing tank must be marked abandoned.

The existing trenched were exposed and they should be field located and placed on your plan. You must also show the calculation to prove you can fit three systems in your septic area. The percolation testing holes should be field located, and elevations of the holes should be shown on the plan. The septic area and all its components must be 20 feet away from the house. I would recommend submitting an OSDS plan with your percolation certification plan to save time in completing your review. I have included the septic specification sheet to help with this process.

The following items must also be addressed. These items pertain to the percolation certification plan general notes:

• Please add these statements to the general notes and adjust according to your project. Most are just statements and others will have to be modified to support your project:

- 1. Any adjustments/modifications to the existing septic easement showing area lost and area gained.
- 2. Determine if the lot was created AFTER March 1972 or PRIOR to March 1072.

- If the lot was created AFTER March 1972 a minimum area of 10,000 sq. ft. is required as the designated septic reserve area.
- If the lot was created PRIOR to March 1972 a septic reserve area large enough to accommodate 3 systems (an initial and 2 replacements) must be proposed.

Once this is determined it must be noted in the general notes.

- 3. Certification of compliance with MDE ownership width and lot area requirements for lots created after 1985:
  - The lot(s) shown herein complies/comply with the minimum ownership width and lot area as required by the Maryland Department of Environment.

4. In line 12 on your percolation plan it is stated that the area is not field located. This project must be field located and verified by an engineer or surveyor. The following statement must be added to support your plan.

- The topography of this plat is taken from \_\_\_\_\_ and is verified to accurately represent the relative changes on the subject property.
- 5. All wells and septic systems located within 100' of the property boundaries and 200' down gradient of any wells and/or septic systems have been shown.
- 6. A purpose statement indicating the purpose of the plan.
- 7. Please title your plan Percolation Certification Plan.
- 8. Please adjust the legend to support your plan.

(Example: There is no water valve or fire hydrant and it is shown in the legend.)

The next step in this process is to resubmit a Percolation Certification Plan to confirm the design of the septic reserve area. Along with your OSDS plan. Please remember you will have to show the existing tank as abandoned and show a new tank to be installed with a riser. If you have any questions regarding this evaluation or requirements for the Percolation Certification Plan, please contact me at the above address or by telephone at (410) 313-2775.

Respectfully,

Dana Bernard, REHS/RS Environmental Specialist II Well and Septic Program

Enclosures File

# SURVEYS, INC.

## Surveying \* Engineering \* Land Planning \* Permits

350 Main Street

Laurel, Maryland 20707

Phone: 301-776-0561 \* Email: surveysinc1@verizon.net

Howard County Health Department 8930 Stanford Boulevard Columbia, Maryland 21045 Date: Nov. 9, 2022

Attn: Dana Bernard Ref: Percolation Testing Plan Revisions 13080 Williamsfield Drive Tax Map: 22, Parcel 300

### POINT BY POINT

Dear Dana,

- 1. 25% slopes have been added to the Site and Legend.
- 2. Contours have been extended across the entire property.
- 3. swales are not defined, a ravine is present below the sewage disposal area.
- 4. Note # 13 has been revised.
- 5. Note #14, states the creation of the site and a deed reference. Also 10,000 sf. Sewage disposal area will be required on sites created after 1972. Item # 6 in The Septic Notes states that we are **not** using the existing septic system.
- 6. The approximate location of the existing system is shown and labeled on the plan in color and shown in the Legend referencing the color. Distances between the proposed trenches at the closest points have been shown on the plan. The minimum distances between the trenches are in the "Septic Trench Design Information". I cannot certify to the exact location of the existing trenches. Between the Health Department measured distances when the system was built and the length recorded are too conflicting in relation to the existing septic tank. The proposed system may run parallel and between or possibly cross the existing trenches. To verify the exact location will require excavation or possibly ground penetrating radar. If required, I'll notify the applicant.

Gregory/Benefiel

Registered Professional Land Surveyor, Md.# 10994 License Expiration 08-08-2024

Destanayske & Resulla Roperty Jay Map 22; Parcell 300 #33 ed mou 3,8 井1 ed Brow R4 % #5 10-20% 12 RY Did not Jest off 2 All manu mical Brou 1 北 12 #7 Brou Allon 13080 Williamsfield Dr. TIME OF 2ND INCH DEPTH START BREAK 1" DROP P/F/H DATE TEST# STOP mig 2" DROP 10-20% 3. Imi 55 1:00 3. 2m 02 20 :0 1:05 3,8 1-3.20 :25 12 11:10 3 :3 #3 12 :32 ,d 4. 3. 38 Red Brown :40 12 tyl JA Diel not te 6-3-22 3.5 Red Bus Tisin Cleanout/no ptic Jank 10% REMARKS < SANITARIAN BACKHOE OTHERS man miret TEST HOLES USED IN SDA AVG. PERC TIME SQ. FT/BR \_\_\_ INLET DEPTH \_\_\_\_ MAX. BOT DEPTH TRENCH WIDTH \_\_\_\_EFFECTIVE S/W 12 note: Exposed trenches and they were clean.