
	HOWARD COUNTY HEALTH DEPARTMENT 72691
Received From	Eco Splic (100) PHONE # 195-50/0
☐ CASH	For Horce Roper 1/29/0
NO. 77749	Received By CONO Received By CONO



Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-2640 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org


Facebook: www.facebook.com/hocohealth


Maura J. Rossman, M.D., Health Officer

RECEIPT DATE: 11/16/22 ONSITE SEWAGE DISPOSAL SYSTEM P 572691
APPROVAL DATE: 3/16/23 PERMIT: REPAIR A
PROPERTY ADDRESS: 12910 SW. Wexford Park
SUBDIVISION: Waterford LOT: 4 TAX ID:
CONTRACTOR: Fogle's Septic Clean Inc. EMAIL: kim@foglesinc.com
CONTRACTOR ADDRESS: 580 Obrecht Road, Sykesville, MD 21784 PHONE: 410-795-5670
PROPERTY OWNER: Zachary Jones EMAIL:
OWNER ADDRESS: 12910 Wexford Park, Clarksville, MD 21029 PHONE:
SEPTIC TANK SIZE (GALLONS): For String TANK MANUFACTURER: PUMP MODEL: PUMP SIZE PUMP TANK CAPACITY: —
DISTRIBUTION SYSTEM: GRAVITY PRESSURE DOSED BEDROOMS: 6 APPLICATION RATE: 1.2
TRENCHES: TRENCH WIDTH: 2' MAXIMUM BOTTOM DEPTH: 9' MINIMUM SPACE BETWEEN TRENCHES: 16' EFFECTIVE AREA BEGINNING DEPTH: 5'
LOCATION: PER APPROVED SITE PLAN. SEWAGE DISPOSAL AREA AND TANK LOCATIONS MUST BE STAKED BY LICENSED SURVEYOR PRIOR TO PRE-CONSTRUCTION INSPECTION.
NOTES:
ISSUED BY: K. WOLF ISSUE DATE: 1/13/2023 EXPIRATION DATE: 1/13/2024
NOTE: CONTRACTOR MUST SCHEDULE A PRE-CONSTRUCTION INSPECTION PRIOR TO BEGINNING ANY INSTALLATION NOTE: CONTRACTOR MUST SCHEDULE AN INSPECTION AND GAIN APPROVAL OF ALL COMPONENTS PRIOR TO COVERING NOTE: STONE MUST BE APPROVED BY HEALTH DEPARTMENT AND GRAVEL TICKET MUST BE AVAILABLE FOR REVIEW. NOTE: WATERTIGHT TANKS REQUIRED NOTE: ALL PARTS OF SEPTIC SYSTEM SHALL BE AT LEAST 100 FEET DOWNGRADIENT FROM ANY WATER WELL NOTE: MANHOLE RISERS REQUIRED ON ALL SEPTIC TANKS AND PUMP CHAMBERS NOTE: AN ELECTRICAL PERMIT IS REQUIRED FOR INSTALLATION OF ANY ELECTRICAL COMPONENTS OF THE SYSTEM ELECTRICAL PERMIT ISSUED E
NOTE: MDE RECOMMENDS SEPTIC TANKS, BAT, AND OTHER PRETREATMENT UNITS BE PUMPED AT A FREQUENCY ADEQUATE TO ENSURE THAT SOLIDS ARE NOT DISCHARGED TO THE DISPOSAL AREA NEITHER THE HOMARD COUNTY COUNTY AND THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM.

PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT. CALL 410-313-1771 TO SCHEDULE INSPECTIONS.





FILE INQUIRY NOTES

DATE			RE	SULTS	OF RE	VIEW FO	R FILE		
3/13/23	- Site insp.	2+	reactives	have	been	Stailer	out	905'd	Well (RY)
	,							l'	
		-		v 100 cm					
			.VI.A. P.M						
			· · · · · · · · · · · · · · · · · · ·			***************************************	<u> </u>		
									
									7,
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							• IF
			4 - 54 - 40 - 40 - 40 - 40 - 40 - 40 - 4						
									entropy of the second
					<u></u>				
			· · · · · · · · · · · · · · · · · · ·						
								· · · · · · · · · · · · · · · · · · ·	
		-0.0							



Bureau of Environmental Health 8930 Stanford Blvd | Columbia, MD 21045 410.313.2640 - Voice/Relay 410.313.2648 - Fax 1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

INFORMATION FORM - SEPTIC SYSTEM REPAIR/UPGRADE

Reason for Request:	Has the septic tank been pumped within the last month?
Failing System System relocation for proposed addition System upgrade for proposed addition Inadequate treatment zone Collapsed septic tank Collapsed drywell	Yes Date pumped: No Was a visual inspection of the septic tank and/or drain fields conducted? Yes Explain observation: No
Existing system design	Was a visual inspection of the sewage line conducted?
Drywell Trench Mound Unknown Other:	Yes No Blockage Leading to the field Yes Explain No
Is discharge surfacing on the ground?	
No Additional Comments: Homeland report from April 2022 found outlet and system and are ready to proceed with repair.	d-box submerged; new homeowners have been nursing the
garages, etc? This information must be disclosed at the time of the	n the future any additions or modifications to the property, i.e. pools, living space additions, his application. The Health Department will not be able to accommodate requests in the field for uests may require an additional fee, testing, and submittal of a Percolation Certification Plan, if
Septic Contractor: Fogle's Septic Clean, Inc.	Contractor's Phone: 410-795-5670
Contractor's Address: 580 Obrecht Rd Sykesville, MI	D 21784
Property Address: 12910 Wexford Park	County File: 05-407532
Subdivision: Waterford	Lot: 13 Year Built: 1989
Owner's Name: Zachary Jones	Existing bedrooms:6
Name of previous owners: Bharat M. Patel	Existing bedrooms:
John M. Flaherty	Proposed bedrooms:
the repair or upgrade. *Prior to scheduling inspections, scaled plans should be surprint out a copy of Real Property Data via Dept. of Taxation If soil/site conditions are limited and sewer and/or Metro of Emergency Sewer Extension or Emergency Metro District	Indexed file found

Website: www.hchealth.org Facebook: www.facebook.com/hocohealth Twitter: @HoCoHealth

WS-PT- 22-03555

ENVIRONMENTAL


p: 443-995-5385 | info@homelandhealthyhomes.com | www.homelandhealthyhomes.com

Front of the House

ADDRESS: 12910 Wextord Park Clarksviller MD 20079 All measurements are approximate distances.

ST=Septic Tank; DB=Distribution Box; DF=Drainfield; DW=Drywell FL=Font Line; BL=Back Line; BG=Below Grade; '= Feet; "= Inches

SCALE: 1:40



Note: No Neighboring Wells within 100ft




p:443-995-5385 | info@homelandhealthyhomes.com | www.homelandhealthyhomes.com

ran arangan, was aren aren aren aren aren aren aren aren	The second advantagement to the second control of the second contr		man and a supplied that the specific construction of the supplied of the suppl		
Date: April 18, 2022 Name of Evaluator: Mitchel Ruhkar Time: 11:30 AM Property Address: 12910 Wexford Park Clarksville, MD 21029 Recent Weather Conditions: Norm	Homeowner Interview: The interview was sent but was in prior to the evaluation	1	Occupied: Yes No Length of Time Vacant: N/A # of People Living in Home: 5 # of People moving in: 3-4 Property Age: 1989 System Age: 1989 Last Date of Cleaning: Unknown Recomm'd Pumping Freq: 2-3 Years		
Liquid level in tank is: 🛛 Above	Normal Normal Below N	ormal	Bottom Solids Depth: 26 Inches		
Depth of tank: 12 Inches	Type of Tank Access: 6-inch (leanout	Depth of tank access: At Grade		
Maintenance appears: Good	☐ Fair		Depth to Distribution Box: ~72 Inches		
Effluent Filter present: Yes	Previous high liquid level: 🛛	Yes 🗌 No	Distance to well: ~100 Feet		
Records Search: Records were req	uested and were received from Howar	d County prior to	o the evaluation.		
Were there any impermeable sur	faces above the septic system (i.e. d	riveway)? 🔲 🗅	res ⊠ No		
Type of Lank () (A) 2 () ()	Tank Composition and Size	Type of Abs	oppion System		
Septic Tank (1 tank)	☐ Metal ☑ Concrete ☐ Plastic	□ Raised Mound			
Aeration System		Drywell (Number of:) Cesspool			
Other:	Tank Size: 1,250 gallons	Unknown:			
System Companient	Sondition	Comments	"在这种的一种"的一种"基本"的一种		
Septic Tank	☐ Acceptable ☐ Unacceptable ☑ Needs Further Evaluation	approximately septic tank is 1 via a PVC clear manhole riser future mainter solids in the secteaning. Upor tank was above backup. Due to and compositio backup is remecomposition w	k is composed of concrete and is 1250 gallons in total capacity. The 12 inches below grade and is accessible nout at grade. It is recommended a be installed to grade to facilitate nance. Currently, there are 28 inches of eptic tank. The septic tank is due for a n arrival the liquid level in the septic e normal operating level indicating a to the backup back baffle placement on could not be determined. Once the ediated back baffle placement and ill need to be verified. Please refer to e camera septic report for further		
Absorption System	☐ Acceptable☑ Unacceptable☐ Needs Further Evaluation	property. The be dry within sused during the inspection the observed to be cause of the baremediated by	cords three drainfields service this drainfields were probed and found to 55 inches below grade. A camera was e inspection. During the camera back line and distribution box were e submerged due to a backup. The ackup will need to be determined and a licensed septic contractor. ould include replacement of the tem.		

HOME LAND

ENVIRONMENTAL
p:443-995-5385 | f:443-267-0098 | info@homelandhealthyhomes.com | www.homelandhealthyhomes.com



Picture 1:

This shows the septic tank in relation to the house.



Picture 2:

This shows the drainfields in relation to the house.



p:443-995-5385 | info@homelandhealthyhomes.com | www.homelandhealthyhomes.com

	Picture 3:
	Visual of high liquid level and submerged outlet line in septic tank upon arrival.
	Picture 4:
	Picture 4: Space intentionally left blank.
No Picture	



p:443-995-5385 | f:443-267-0098 | info@homelandhealthyhomes.com | www.homelandhealthyhomes.com


Sketch of System

Please refer to separate sketch of the system.

DISCLAIMERS

- This is a subjective and visual inspection only, the conclusions of which are based on the observed condition of the system
 components that could reasonably be accessed, and information known about the system at the time this report was
 completed. There may be unknown historical problems or unseen conditions which may compromise the conclusions stated
 in this report.
- Suggestions or recommendations for repairs or remediation may result in the need for further repair or remediation once the system components are fully excavated.
- A 'Satisfactory' evaluation does not mean the system will meet the local approving authority's criteria for determining compliance with state code: COMAR 26.04.02.02 D(4).
- The evaluation of the Sewage Disposal System as reported is based on the conditions observed on the day of the inspection.
- This report is neither a WARRANTY nor does it GUARANTEE continued acceptable functionality or performance of the Sewage Disposal Systems operations.
- If the house has been unoccupied the findings in this report may not be accurate, as limited or no use of the system may
 conceal or mask problems that may be revealed under typical sewage loading.
- If the general ground condition is excessively wet at the time of inspection, the findings in this report may not be accurate,
 as ground moisture may cover or hide septic effluent that may be on or near the ground surface.
- If the house is vacant or the conditions excessively wet during inspection, it is recommended that the system be reevaluated at a later date and/or alternate techniques be used to address those potential issues.
- Payment and/or use of this evaluation signify understanding and acceptances of the above clauses, as well as any noted faults with the system.

Representative's Signature:		Date: 4/18/2022
-----------------------------	--	-----------------



Real Property Data Search () Search Result for HOWARD COUNTY

View Map	View Map View GroundRent Redemption			View GroundRent Registration			
pecial Tax Recapture	iune						
Account Identifier:	District - 05 Acc	ount Number - 40'	7532				
	0	wner Information					
Owner Name:	JONES ZACHAR	Y Use:	:	RESIDENTIAL			
	JONES RISHANK	(A Prin	cipal Residence	e: YES			
Mailing Address:	12910 WEXFORD	PARK Dee	d Reference:	/21541/ 00036			
-	CLARKSVILLE M	D 21029-1400					
	Location	& Structure Infor	mation				
Premises Address:	12910 SW WEXFO	ORD PARK Leg	al Description:	LOT 13 3.2825 A			
	CLARKSVILLE 21	029-0000	•	12910 WEXFORD PARK			
				WATERFORD S 2 RSB LOT			
Map: Grid: Parcel: Neig	hborhood: Subdivisi	ion: Section: Blo	ck: Lot: Assess	ment Year: Plat No: 767			
0034 0009 0261 5010	102.14 1002		13 2023	Plat Ref:			
Town: None							
Primary Structure Built	Above Grade Living A	rea Finished Base	ment Area Pro	perty Land Area County Us			
989	6,081 SF	1400 SF		800 AC			
		lityFull/Half BathC		lotice of Major Improvemen			
Stories Basement Type	ARD UNITBRICK/ 6	•	Attached	totice of Major Improvemen			
YES STAND			Attached				
	V	/alue Information					
	Base Value	Value		in Assessments			
		As of	As of	As of			
		01/01/2020	07/01/2022	07/01/2023			
and:	242,100	242,100					
mprovements	1,010,800	1,010,800	1252000				
Total:	1,252,900	1,252,900	1,252,900				
Preferential Land:	0						
	Tra	ansfer Information	า				
Seller: PATEL BHARAT M	Da	te: 05/26/2022		Price: \$1,570,000			
Type: ARMS LENGTH IMI	PROVED De	ed1: /21541/ 00036		Deed2:			
Seller: FLAHERTY JOHN	M Da	te: 08/13/2003		Price: \$740,000			
Type: ARMS LENGTH IMI	PROVED De	ed1: /07484/ 00522	2	Deed2:			
Seller: BRIGHTON GROUP THE		te: 06/14/1988		Price: \$98,000			
Type: ARMS LENGTH IMI	PROVED De	ed1: /01838/ 00714		Deed2:			
DECEMBER 1	Exe	mption Information	on				
Type: ARMS ELITOTT IM	=/(4	-	01/2022	07/01/2023			
	ents: Class		,,	0.,0.,2020			
Partial Exempt Assessm)				
Partial Exempt Assessm County:	000	0.00					
Partial Exempt Assessm County: State:)	0.00			
Partial Exempt Assessm County: State: Municipal:	000 000 000	0.00)	0.00			
Partial Exempt Assessm County: State:	000 000 000	0.00 0.00 0.00))	0.00			
Partial Exempt Assessm County: State: Municipal: Special Tax Recap ur	000 000 000 Homestea	0.00 0.00 0.00 0.00 ad Application Info))	0.00			
Partial Exempt Assessm County: State: Municipal:	000 000 000 Homestea Status: No Application	0.00 0.00 0.00 ad Application Info)) ormation				
Partial Exempt Assessm County: State: Municipal: Special Tax Recap ur	000 000 000 Homestea Status: No Application	0.00 0.00 0.00 0.00 ad Application Info)) ormation				

