SITE INSPECTION SHEET

OWNER: Ellen Gosling PHONE #: _____

ADDRESS: 7413 Meadow View Ct CONTRACTOR: _____

Clarksville WELL TAG #: No Tag

SUBDIVISION: _____ LOT: _____ COUNTY #: _____

PROPOSAL: Convert BR#2 into full bathroom and add a BR.

LOCATION DIAGRAM

NOT TO SCALE



COMMENTS: 1 pc well cap secure. Pvc flush w/ cap. Well pump rope observed. No well tag. Well has been GPS'd. Septic tank c/o pvc w/ cap. No septic issue observed

DATE: 11/27/18 INSPECTOR: Hank Oswald

Site Visit 11.27.18
7413 Meadow View Court
Clarksville, MD

Well is located in front of house approximately 11 feet from foundation. 1 piece secured cap. PVC flush with cap. Well pump rope observed on outside of well. Well tag is missing.

Site Visit 11.27.18
7413 Meadow View Court
Clarksville, MD

PVC septic tank clean-out located 33 feet from foundation. No septic issues observed.

Oswald, Hank

From: Ellen Geiling <etg1216@gmail.com>
Sent: Saturday, December 01, 2018 10:41 AM
To: Oswald, Hank
Subject: Photo of well

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Hank,

The photo of my well is attached. Let me know if you need anything else.
Have a good weekend.
Ellen

Ellen Geiling

JPG PLUMBING SERVICES, INC.

8260 Patuxent Range R.
Suite H
Jessup MD 20794
(240) 241-5060
accounting@jpgplumbing.com
www.jpgplumbing.com

Service Invoice

Invoice#: 40353

Date: 11/30/2018

Due Date: 12/30/2018

Billed To: Ellen Geiling
7413 Meadowview Circle
Clarksville MD 21029

Service Location
7413 Meadowview Circle
Clarksville MD 21029

Order#: 40353

Customer PO:

Description	Quantity	Rate	Amount
Journeyman - Standard Rate	5.00	135.00	675.00
Materials	1.00	123.00	123.00
Truck Charge	1.00	25.00	25.00

Notes:

11/29/18 - Jim S. - 5 hours
Checked in with EllenG. after service meeting.
Went to her house and looked over well head located in front yard.
Called into Ferguson's was able to find new updated two piece well
cap at fergusons in Westminster.Picked up and delivered to job.
Had to drill out set screws on old well head to remove.Turned off power to well pump and unwired power supply.Relocated wires into new head and
set back on well casing/pipe.Reconnected wires and ele. taped wire nuts. Moved existing rope to inside of well casing under lid of cap.
Bolted new lid in place and sealed conduit connection with silicon.Turned
power back on and ran faucet on mop sink until well pump cycled.
Working as it should.
Moved to kitchen sink and swapped hot and cold supply's as per Ellen
so faucet handle when moved to left has hot water coming from spout.
Hooked up and tested no leaks (hot & cold are on the proper sides now.
Moved to hallway bathroom and checked drain on tub.Ellen had previously
pulled tip toe from drain and cleared obstruction/ hair from drain.
Installed new 1.5" o-ring on grove of tip tow and reinstalled ontub drain.
Cleaned up all work areas.

Thank you for your business! We appreciate it!

Our terms are 30DY
All taxes included
A service charge of 24% per annum will be charged on all overdue accounts.

Non-Taxable Amount:	823.00
Discount/Credit:	0.00
Taxable Amount:	0.00
Sales Tax:	0.00
Amount Due	**$823.00**

JPG PLUMBING SERVICES, INC.
8260 Patuxent Range R.
Suite H
Jessup MD 20794
(240) 241-5060
accounting@jpgplumbing.com
www.jpgplumbing.com

Service Invoice

Invoice#: 17168

Date: 05/05/2017

Due Date:

Billed To: Ellen Geiling
7413 Meadowview Circle
Clarksville MD 21029

Service Location
7413 Meadowview Circle
Clarksville MD 21029

Order#: 9833

Customer PO:

Description	Quantity	Rate	Amount
Residential Septic No Charge Service - Friends & Family	1.00		

Notes:

May 5, 2017 - Pump 1500 gallon residential septic; 150 feet of hose required.

Thank you for your business! We appreciate it!

Our terms are 30DY
All taxes included
A service charge of 24% per annum will be charged on all overdue accounts.

Non-Taxable Amount:	0.00
Discount/Credit:	0.00
Taxable Amount:	0.00
Sales Tax:	0.00
Amount Due	**$0.00**