

9/10/97
ASAP

PERMIT

SEWAGE DISPOSAL SYSTEM

DEPARTMENT OF HEALTH AND MENTAL HYGIENE

02-254328

HOWARD COUNTY HEALTH DEPARTMENT

BUREAU OF ENVIRONMENTAL HEALTH

~~X-100-1000~~

410-313-2640

INDEXED

P 58965A

A REPAIR

DISTRICT

DATE 9-9-97

DATE SYSTEM APPROVED 9/10/97

INSPECTOR KM

Jack Fyock Septic Service

IS PERMITTED TO INSTALL ☐ ALTER ☒

ADDRESS 13775 Triadelphia Road, Glenelg, Maryland 21737 PHONE 410-988-9270

SUBDIVISION LOT ROAD 9944 Route 108

PROPERTY OWNER Carl Zaiser & Evelyn Nolan

ADDRESS 9944 Route 108
Ellicott City, Maryland 21042

SEPTIC TANK CAPACITY 1000 GALLONS

PUBLIC SEWER NOT AVAILABLE PER MARK RIFKIN - 08/15/97

NUMBER OF BEDROOMS 3

125 SQUARE FEET PER BEDROOM

LINEAR FEET OF TRENCH REQUIRED 57'

REPAIR - PURPOSE - REPAIR FOR FAILING SEPTIC SYSTEM.

Call for inspection when ground is opened so sanitarian can recommend repair.
08/15/97

Trench to be 2 feet wide, bottom at 9.5 feet, inlet at 3.0 feet, 6.5 feet of stone

PLANS APPROVED BY

Kim Maiste / Glen Savage

DATE

9/10/97

COVER NO WORK UNTIL INSPECTED AND APPROVED

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM

NOTE: CLEANOUT REQUIRED EVERY 70 FEET OF SEWER LINE AND/OR AT 90° SWEEPS IN LINES FROM HOUSE TO DRAIN FIELDS, 90° ELBOWS NOT ACCEPTABLE.

NOTE: ALL PARTS OF SEPTIC SYSTEMS (I.E. TANK, DISTRIBUTION BOX TRENCHES) TO BE 100 FEET FROM WELL (UNLESS OTHERWISE SPECIFICALLY AUTHORIZED)

NOTE: IF DEEP TRENCH(ES) ARE USED CALL FOR INSPECTION BEFORE AND AFTER PLACING GRAVEL IN TRENCH(ES)

NOTE: NO DRY WELL SHALL EXCEED 15 FOOT IN DIAMETER NO ABSORPTION TRENCH TO EXCEED 100 FEET IN LENGTH

NOTE: ALL PIPE FROM HOUSE TO SEPTIC TANK MUST BE CAST IRON OR SCHEDULE 35/40 PVC OR ABS

PERMIT VOID AFTER TWO YEARS


NOTE: INSTALL STAND PIPE ON SEPTIC TANK AND DRY WELL STAND PIPES MUST BE 6 INCHES IN DIAMETER CAST IRON. CONCRETE OR TERRA COTTA OR PVA OR ABS ACCEPTED. IF TOP OF SEPTIC TANK IS DEEPER THAN 3 FEET. MANHOLE TO GRADE REQUIRED.

NOTE: DISTRIBUTION BOXES MUST HAVE BAFFLES

*INSTALLER IS RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT

58965A

(A)
 orange/tan
 Clay 1m
 3.0
 tan/brown
 red
 Silty 1m
 10% shale
 frags
 10.0



INDICATE NORTH - NAME ADJOINING ROADWAY AS BASE LINE Route 108

SEPTIC TANK LEVEL OK, 1000 gallons CLEANOUTS 1 on tank, 1 on line, 1 on drywell

DISTRIBUTION BOX LEVEL (haffle in tank)

DRAIN FIELD/TITLE DEPTH 9.5 FT. TRENCH WIDTH 2.0 FT. INLET DEPTH 3.0 FT.

EFFECTIVE GRAVEL DEPTH 6.5 FT. TOTAL LENGTH 68 FT.

NUMBER OF TRENCHES 1 ONE SIDEWALL/BOTTOM AREA 442 SQ. FT.

DRYWALL INSIDE DIAMETER FT. EFFECTIVE DEPTH BELOW INLET FT.

ABSORBENT AREA SQ. FT.

REMARKS: 9/10/97pm OK to continue, drywell and tank have both been
pumped, trench from tank is connected only to bathrooms in house,
greywater discharges into drywell with cleanout on drywell and one
cleanout on line RM/GS

9/10/97pm OK to finish stoning trench and cover all work (RM)

DATE SYSTEM APPROVED 9/10/97 INSPECTOR Kim Maister

Line: Septic
Permit For ~~the~~ ^{8/18} Mon 3 BR

Carl Zaiser & Evelyn Nolan

9944 Rt. 108

Repair for failing system

for Fyock

NO Sewer Avail

Thx MR 8/15



HOWARD COUNTY HEALTH DEPARTMENT

Joyce M. Boyd, M.D., County Health Officer

August 12, 1997

Ms. Patricia Hunt
5923 Gales Lane
Columbia, MD 21045

RE: Emergency Water Supply Condition
5923 Gales Lane
Tax Map 36, Parcel 12

7/14/97 8:45 AM NO AVAILABLE WATER SUPPLY

Map 30
Grid 8
9944 Rt. 108

