ISSUE DATE:

10/3/2001

INDEXED

APPROVAL DATE:

PERMIT

516054

A REPAIR

ON-SITE SEWAGE DISPOSAL SYSTEM HOWARD COUNTY HEALTH DEPARTMENT BUREAU OF ENVIRONMENTAL HEALTH

05-383625

Zepp Plumbing & Heat	ing, Inc	IS PER	MITTED TO INS	STALL [ALTER 🖂
ADDRESS: 12447	Route 108		PHONE NUMBER	: 410-5	31-6712
SUBDIVISION: Highland Lake			LOT NUMBER:	_77	
ADDRESS: 6563 River Clyde Drive		PRO	PERTY OWNER:	Peterson	1
SEPTIC TANK CAPACITY (GALLONS): 1500			XISTING)		
PUMP CHAMBER CAPACITY (GALLONS):		N/A		ETURNED	9-12-120
NUMBER OF BEDROOMS:		5	Boo	0131565	8-02-2007 and Store
SQUARE FEET PER BEDROOM:		180	HI	d Seu	ind I thre
LINEAR FEET OF TRENCH REQUIRED: 45 -					
TRENCHES:	Trench to be 2.0 feet wid depth 8.0 feet below origing grade. 4.0 feet of stone be	nal grade. Ef	fective area begins at		
LOCATION:	Extend each existing trench approximately 25 feet in length. Install Wye connection off of existing house sewer and the into new additions' plumbing.				
NOTES:	Pre-construction -	Inspection	critical		
PLANS APPROVED:	SRK/RJP			DATE:	8/8/01
NOTE, DEDMIT VOID AFTED 2 VEADS					

NOTE: CONTRACTOR RESPONSIBLE FOR SCHEDULING A PRE-CONSTRUCTION INSPECTION FOR ALL INSTALLATIONS

NOTE: WATERTIGHT SEPTIC TANKS REQUIRED

NOTE: ALL PARTS OF SEPTIC SYSTMEM SHALL BE 100 FEET FROM ANY WATER WELL NOTE: MANHOLE RISERS REQUIRED ON ALL SEPTIC TANKS AND PUMP CHAMBERS

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT CALL 410-313-2640 FOR INSPECTION OF SEPTIC SYSTEM

NOT TO SCALE	Repair
SWING SET 6'CO Fernes Wye Fernes Cost iren -2'c" 1'Cast icon -184	TRENCH DATA TRENCH WIDTH
House	SEPTIC TANK DATA SEPTIC TANK OX ISOO GALLONS MANHOLE RISER NO 6 INCH INSPECTION PORT OF FORT PUMP CHAMBER DATA PUMP CHAMBER GALLONS MANHOLE RISER NA ALARM
RIVER CLYDE DRIVE	PUMP PERFORMANCE TEST
INSPECTION COMMENTS: 11/2/01-NO ONE PRESENT, OF NOT EXTENDED, - FRID 11/5/01-T/C W/INSTA	LLER ED ZEPP, HE CLAIMS TRENCHES A
11/6/01-MET ED ZEPP AT SITE, BECAUSE OF	F LIMITED REPAIR AREA, BEST OPTION
IS TO EXTEND EX. TRENCHES & DO THE ME	ATEST JOB POSSIBLE - SEND
1/2/0, Of to corn all work. Sign	sed formit(s)
INSPECTOR LET DA	TE SYSTEM APPROVED 11/8/6/
NEXT REPAIR SPECS -	H. T. (1987년 - 1987년 -

PROPERTY

LINE

Extending existing trenches.