

Building Permit Application
Howard County Maryland
Department of Inspections, Licenses and Permits
3430 Court House Drive
Permits: 410-313-2455
www.howardcountymd.gov

)//_P	2008	وريان	1	ŭ¥;∹.	, i-,	
Date F	evienas	d:				

, , , <u></u>	Nº 437		. 10	
Date	Receive	d:		

Building Address: 2	600	MCKENDIER KO	<u>d</u>	Property Owner's Name:	Stephen	rettit
aw. WAN WOOD) St	ate: MD Zip Code:	11738	Address: 2600 MCK	enbre	Red.
Suite/Apt. #				City:() (* DUC)()	State:	D Zip Code: 2/738 Fax: 30/- 6/10 5725
Suite/Apt. #	-	Subdivision: McKene	Car Cartata	Email: Steve net	1.1 6200	HI COMPANIES C
				/		•
Section:	· ·	Area:Lot:	ARCELD	Applicant's Name & Mailing	Address, (If	other than stated herein)
Tax Map:	Pare	cel: 123 Grid:	14-12	Applicant's Name: SAM	16 115	HOUVE
		dinates: 48/2-J2Lot Siz		City:	State:	Zip Code:
Lonning. 100	wap coore	amates. 101 - Ozatot siz	c	Phone:	Fax:	
Evicting User 5	1. F.	n. la		Email:		
Proposed Use:	1 7	1			51000	Palit
Proposed Use:	12 /2	m.ly		Contractor Company: Contact Person:	21606	Di II
Estimated Construction	Cost: \$	600,00.		Address: 2600 MC	<u>Jacue</u>	0-1
Description of Work:	Re-ho	Id house INSAD	15 SANT	City: GRANGED Sta	4 6 6 10 1 C	4 601
		E DUENED HOWN		License No. : O WN	o ()	Zip Code: Z1125
				Dhogs: 304:254 of	2 E A Fave	301-252-0305
		-1707247-600	<u> </u>	Email:	Je G rak.	16/21/2-2-3
Occupant/Tenant Name	:_ <i>51e</i>	ue fe++1+			+0004	fit compares com
Was tenant space previo	usly occup	ied? ☐res	□No	Engineer/Architect Company	TALAL	CONSULTING SE
Contact Name:57			2			CHANT MC DONALH
Address: 2600 M				Address: <u>7941</u> HC		
City: GLENCOOD)	State: M D Zip Code:	21738	City MIDDLE TOWN Sta	ite: MD	Zip Code: 21749
Phone: 301-157 -0	305	Fax: 301-670-92	259	Phone: 240.439.9		
					y - Oax:	
Email: STEUE PE	THITE	pettitrompanics.	Com	Email:		
Commercial Building Ch	anactarict	ics Residential Building Ch	angueto eletion	Utilities		References to the second secon
Height:	ioracteristi	SF Dwelling SF Tov] No	
No. of stories:] No	Street Street
Gross area, sq. ft./floor:			108'	Water Supply		
1.		2 11001. 76	44'	Public	· · · · · · · · · · · · · · · · · · ·	
Area of construction (sq.	. ft.):	Basement: 3 4	10%	Private		
754		☐ Finished Basement				
Use group:		Unfinished Basement		Sewage Dispose	<u> </u>	
Construction ty	mar	☐ Crawl Space ☐ Slab on Grade		☐ Public		(4) TO 10 MIN TO 10 MIN
☐ Reinforced Concrete	DC.	No. of Bedrooms:		Private		fight of the same
☐ Structural Steel		Multi-family Dw	elling	Heating System	2	
☐ Masonry		No. of efficiency units:		☐ Electric ☐ Oil		
☐ Wood Frame		No. of 1 BR units:		☐ Natural Gas ☐ Propan	e Gas	
☐ State Certified Modula	ar	No. of 2 BR units:		☐ Other:		
		No. of 3 BR units:	i	Sprinkler Systen	<u>1:</u>	
		Other Structure: Dimensions:		Yes □ No		
T. 201		Footings:			11	
Peur Control of the C		Roof:		Grading Permi	t Number:	618000021
		☐ State Certified Modul	ar			19
	1.	☐ Manufactured Home		Building Shell Peri	mit Number:	
THE UNDERSIGNED HEREBY CER	TIFIES AND A	GREES AS FOLLOWS: (1) THAT HE/SHE	IS AUTHORIZED TO	MAKE THIS APPLICATION; (2) THAT THE IN	FORMATION IS C	ORRECT; (3) THAT HE/SHE WILL COMPLY
THIS APPLICATION; (5) THAT HE	SHE GRANTS	TY WHICH ARE APPLICABLE THERETO; COUNTY OF SICIALS THE RIGHT TO ENT	(4) THAT HE/SHE W TER ONTO THIS PROP	ILL PERFORM NO WORK ON THE ABOVE ERTY FOR THE PURPOSE OF INSPECTING T	referenced pro He work per <u>m</u> i	operty not specifically described in TTED and posting notices.
Some WVL	De 1	etter	24	ON STEAMEN FE	+4+	RECEIVED
Applicant's Signature				int Name	1.	
Steve potti	tope	ttit companies de	NiA		į.	MAD 1 / 2010
						PAR 1 1 2010
CHONER						LICENSES & PERMITS
Title/Company						DIVISION
				INANCE OF HOWARD COUNTY		
Marine			LEASE WRITE NEA	yiyatananya.		
				THE PROPERTY OF STREET, STREET		
AGENCY	DATE	SIGNATURE OF APPROVAL	Pront:	INFORMATION	Filing Fee Permit Fee	\$ 100.00
State Highways			Rear:		Tech Fee	\$
Barliding Officials			Side:		Excise Tax	
PSZA (Zoning)			Side St.:	setbacks met?	PSF5	\$ Fund \$
PSZA (Engineering)	1		All minimum :	setbacks met?	Guaranty i	
	Wille	2+11	Historic Distri		Total Fees	
Health	14/4/18	my fight		for New Town Zone:	Sub- Total	
Is Sediment Control appr CONTINGENCY CONST		d for issuance? Thes I No	SDP/Red-line	approval date:	Balance Du	
D COMMINGENCY CONST	MUCHUR SI	OL: 1			GREUK	# 4-30

T:\Operations\Updated Forms\Building appimp 03.21.2917.docx

Green: PSZA,Zoning Yellow: PSZA,Engineering Pink: Health

Gold: SHA

Columbia, MD 21046 410 313 6000

swilson@howardcountymd.gov Printed: 07/21/2017 11:52:26 Number of Pages: 11

Incident Report 2017-1707247 -000

	Basic		
Alarm Date and Time	20:57:46 Wednesday, March 15, 2017		
Arrival Time	21:02:48		
Controlled Date and Time			
Last Unit Cleared Date and Time	03:58:05 Thursday, March 16, 2017		
Response Time	0:05:02		
Completed	Yes		
Release to Public	Yes		
Fire Department Station	13		
Shift	В		
Incident Type	111 - Building fire		
Aid Given or Received	2 - Automatic aid received		
Mutual Aid Department	06000-Carroll County		
Action Taken 1	11 - Extinguish		
Casualties	No No		
Apparatus - Suppression	7		
Apparatus - EMS	2		
Apparatus - Other	35		
Personnel - Suppression Personnel	16		
Personnel - EMS Personnel	5		
Personnel - Other	65		
Property Loss	\$600,000.00		
Contents Loss	\$60,000.00		
Property Value	\$600,000.00		
Contents Value	\$60,000.00		
Detector Alerted occupants	U		
Property Use	419 - 1 or 2 family dwelling, detached, duplex, mobile home		
Location Type	Address		
Address	2600 MCKENDREE RD		
City, State Zip	Glenwood, MD 21738		
District	13009		
Latitude	13.09811140		
Longitude -596.367493			

	Situation	
Initial Dispatch Code	HOUSE	
	Additional Mutual Aid Agencies	
Aid Department	Montgomery County	
	Fire	
Structure Type	1 - Enclosed building	
Number of Residential 1		
Area of Origin 47 - Vehicle storage area; garage, carport		
Heat Source UU - Undetermined		
Item First Ignited	00 - Item, Other	

Columbia, MD 21046 410 313 6000

Incident Report 2017-1707247 -000

swilson@howardcountymd.gov Printed: 07/21/2017 11:52:26 Number of Pages: 11

Fire		
Type of Material	UU - Undetermined	
Cause of Ignition	5 - Cause under investigation	
Contribution To Ignition 1	UU - Undetermined	

	Structure
Status	2 - In normal use
Floor of Origin	1 ·
Stories Above Grade	2
Total Square Feet	4000
Fire Spread	4 - Confined to building of origin
Item Contributing To Spread UU - Undetermined	
Detector Presence	3
AES Presence	3

Authority	
3618 - Zour, James G	
22:58:24 Monday, April 3, 2017	
~ ,	
-,	
_	3618 - Zour, James G 22:58:24 Monday, April 3, 2017 -,

	Narratives	
Narrative Name	MAB13	
Narrative Type	Company	
Narrative Date	23:54:14 Wednesday, March 15, 2017	
Author	3604 - King, Jeffrey P	
Author Rank	LT	
Author Assignment	1	
Narrative Text	Staged until released by command.	
Narrative Name	P45	
Narrative Type	Company	
Narrative Date	01:32:45 Thursday, March 16, 2017	
Author	3660 - Hobbs, Graham M	
Author Rank	LT	
Author Assignment	1	
Narrative Text	Second arriving transport. Staged until placed in service.	
Narrative Name	T-7	
Narrative Type	Company	
Narrative Date	01:51:03 Thursday, March 16, 2017	
Author	1512 - Frank, Gregory E	
Author Rank	LT-P	
Author Assignment	1	
Narrative Text	Assisted with containing the fire and moving equipment/hoses.	
Narrative Name	TNK5	

Howard County Fire and Rescue 6751 COLUMBIA GATEWAY DR. Suite 400 Columbia, MD 21046

410 313 6000

Incident Report 2017-1707247 -000 swilson@howardcountymd.gov Printed: 07/21/2017 11:52:26 Number of Pages: 11

-PV	ar	rati	ves

Narrative Type Company

Narrative Date 02:54:32 Thursday, March 16, 2017

2315 - DeBow, John R Author

VAC Author Rank Author Assignment 1

Transported 20,000 gallons of water to the fire scene and placed in service by water supply Narrative Text

command.

Narrative Name TNK3 Narrative Type Company

03:13:54 Thursday, March 16, 2017 Narrative Date

8470 - Schwarz, Ian T Author

VFF Author Rank Author Assignment

pulled to the end of the driveway to set up the water supply. Had other tankers maintain Narrative Text

water for tanker 3 as we supplied water to fireground with the help of tankers.

Narrative Name TNK34 Narrative Type Company

Narrative Date 03:41:15 Thursday, March 16, 2017

1295 - Wiseman, Robert P Author

Author Rank CAPT Author Assignment

Narrative Text Shuttled water at scene of house fire // approximately 6 loads (6 x 3400 gallons).

Narrative Name SQ-3 Company Narrative Type

Narrative Date 03:42:51 Thursday, March 16, 2017

Author 1295 - Wiseman, Robert P

CAPT Author Rank Author Assignment Responded on house fire // arrived on scene and directed to join with E41 crew and take

Narrative Text

hose to 2nd floor and attack fire on 2nd floor and attic // SQ-3 officer assigned "Division 2" // Crews advanced a 1-3/4" hose line to 2nd floor // 1st floor was light smoke conditions only // 2nd floor was moderate to heavy dark gray smoke down to floor level // shortly after reaching 2nd floor, crews were ordered to evacuate the structure // All SQ-3 and E41 crew personnel were accounted for and exited via Side A with our hoseline // Crews were reassigned to perform exterior firefighting // SQ-3 crew was then directed to report to rehab // SQ-3 crew was redeployed from rehab back to Operations // SQ-3 officer was assigned "Alpha Sector", supervising crews working on Side A // Alpha Sector consisted of SQ-3 and CE124 // CE124 was later relieved by E101 and E31 // It was noted that the Side A wall was beginning to lean outward, and personnel working in Alpha were instructed to operate outside of the collapse zone // while crews were operating, the Side A

wall collapsed outward // all Alpha personnel were accounted for and were unaffected by the collapse // Alpha Sector was demobilized when TWR2 began ladder pipe operations // SQ-3 crew assisted with retrieving hose that was no longer being used and gathering tools // SQ-3 in service. RPW1295

NOTE: SO-3 was TWR-3 without aerial capabilities. TWR3 aerial ladder was placed out

Page 3 of 11

Columbia, MD 21046 410 313 6000

Incident Report 2017-1707247 -000

swilson@howardcountymd.gov Printed: 07/21/2017 11:52:26 Number of Pages: 11

Narratives

of service due to mechanical issues, prior to this incident.

Narrative Name E31
Narrative Type Company

Narrative Date 04:27:40 Thursday, March 16, 2017

Author 8695 - Fuller, Trenton R

Author Rank VFF
Author Assignment 1

Narrative Text Arrived on scene as 3rd in engine. left driver and one of the crew members back to take water supply command. Three members of the E31 walked down to command post and set

up a 2 1/2 line off of E131 and operated the line in a defensive manner.

Narrative Name E131
Narrative Type Company

Narrative Date 04:41:30 Thursday, March 16, 2017

Author 3618 - Zour, James G

Author Rank LT-P Author Assignment 1

Narrative Text E131 layed a supply line from mckendree road up the driveway. E131 arrived with heavy

fire showing from the bravo side originating in the garage. A task force with 2 additional tankers, was requested. The fire was under the influence of the prevailing strong wind conditions with the wind direction going from the bravo side to the delta side of the home. Upon conducting a 360 survey it was observed that the fire was extending to the attic and second floor. At this time the firefighters from engine 131 were flowing water from a 1 3/4 inch handline and the blitzfire on the garage and the bravo gable end of the 2nd floor with little effect. E131 established the command and requested a 2nd alarm. E41 was directed to work for Squad 3 designated division 2. Division 2's assignment was to stretch a line to the 2nd floor and pull ceilings to stop the fire from consuming the attic space. Command was transferred to BC 2 and E131 officer assumed fire attack. E131 crew continued to apply water from the bravo side. E131 worked with E41 and P135 to get handlines in place on the alpha and charlie side of the structure. E131 was then assigned as the charlie division supervisor. E131 continued to assist in the deployment of handlines.

E131 was sent to rehab. E131 returned form rehab to assist in fire attack. E131 placed in service after assisting Tanker 13 with applying foam to the building.

Printed: 07/21/2017 11:52:26

JGZ3618 TNK13 Company

Narrative Date 04:42:32 Thursday, March 16, 2017

Author 3221 - Brown, Levet G

Author Rank MFF
Author Assignment 1

Narrative Name

Narrative Type

Narrative Text Tanker 13 provided water and foam

- 1. Initial tank water to E!131
- Fill Site-McKendree/Rover Mill (Fill tank)
- 3. Dumped water at dump site
- 4. Fill Stie-Station 13 (Fill tank)
- 5. Dumped water at dump site

Columbia, MD 21046 410 313 6000

swilson@howardcountymd.gov Printed: 07/21/2017 11:52:26 Number of Pages: 11

Incident Report 2017-1707247 -000

Narratives

6. Fill Site-McKendree/Rover Mill (Fill tank)

7. Dumped water at dump site 8. Fill Site-Station 13 (Fill tank) 9. Dump water at dump site

10 Fill Site-McKendree/Rover Mill (Fill tank)

11. Dump water at dump site

12. Fill Site-McKendree/Rover Mill (Fill tank)

13. Reported to fire ground per command, used foam and water on fire ground. (entire

tank).

Narrative Name P55 Narrative Type Company

Narrative Date 04:52:23 Thursday, March 16, 2017

3221 - Brown, Levet G Author

Author Rank MFF Author Assignment

Narrative Text assist with hand line to side charlie with E51 crew

Narrative Name Safety 1 Narrative Type Company

Narrative Date 05:09:14 Thursday, March 16, 2017

Author 1771 - Petry, Raymond G

CAPT Author Rank Author Assignment

Narrative Text Assigned to scene Safety Officer on arrival, performed a 360 of the structure. Advised Command of an in ground swimming pool hazard on the Charlie side. Command advised

all personnel on the scene of the hazard.

As conditions changed on the Charlie side, I recommended to Command that side Charlie be placed off limits to all personnel due to high winds and gusts causing low to zero visibility from smoke from the burned out garage on the Bravo / Charlie corner and icy conditions around the in ground pool, as well as a collapse hazard in the same area. Message relayed from Command to all personnel.

Assisted with Charlie side operations throughout the remainder of the incident and continued with scene safety duties.

Narrative Name RTNK11 Narrative Type Company

Narrative Date 07:10:11 Thursday, March 16, 2017

Author 3805 - Young, Adam

Author Rank DRE Author Assignment

Narrative Text Worked under Water Supply. Emptied X6.

Narrative Name FM-202 Narrative Type Company

Narrative Date 07:25:02 Thursday, March 16, 2017

1243 - Saunders, Carlton N Author

Author Rank LT

Page 5 of 11

Columbia, MD 21046 410 313 6000

swilson@howardcountymd.gov Printed: 07/21/2017 11:52:27 Number of Pages: 11

Incident Report 2017-1707247 -000

Author Assignment 8 Narrative Text Responded on the taskforce assisgment asisted the OCFM FM-204 1243 Narrative Name A36

Narrative Name A36
Narrative Type Company

Narrative Date 09:12:44 Thursday, March 16, 2017

Author 1295 - Wiseman, Robert P

Author Rank CAPT
Author Assignment 1

Narrative Text Officer: Besseck

Narrative Name FM204 Narrative Type Other

Narrative Date 13:04:49 Thursday, March 16, 2017

Author 1721 - Mulvihill, Dean C

Author Rank LT Author Assignment 8

Narrative Text Origin and cause investigation with FM213, FM202, and SIS19. fd1721

Narrative Name FIREPIO7
Narrative Type Incident

Narrative Date 16:15:12 Thursday, March 16, 2017

Author 3886 - Weist, Denise L

Author Rank AA
Author Assignment 4

Narrative Text Social media, responded to scene to gather information and responded to inquiries by

phone from media. WBAL sent only a videographer. Press release and posted to FB.

Narrative Name rehab1 Narrative Type Other

Narrative Date 00:23:39 Friday, March 17, 2017 Author 1760 - Amberman, Marcus B

Author Rank VAC
Author Assignment 1

Narrative Text provided food and drink

Narrative Name EMSBC11
Narrative Type Incident

Narrative Date 09:57:32 Friday, March 17, 2017

Author 1800 - Brothers, James M

Author Rank BC-P Author Assignment 2

Narrative Text OCBC Station 2 assist with transfers and covered 2nd battalion

Narrative Name CMD17
Narrative Type Company

Narrative Date 10:43:49 Friday, March 17, 2017

Author 1469 - Gouldin, Joseph W

Author Rank LT Author Assignment 1

Narrative Text Staged till placed inservice.

Narrative Name TWR10

Columbia, MD 21046 410 313 6000

swilson@howardcountymd.gov Printed: 07/21/2017 11:52:27 Number of Pages: 11

Incident Report 2017-1707247 -000

Na	rr	ati	ves
----	----	-----	-----

Narrative Type Company

Narrative Date 06:45:27 Saturday, March 18, 2017

Author 2838 - Sharpe, Michael W

Author Rank CAPT-P
Author Assignment 1

Narrative Text First arriving truck company, directed by the IC to leave the apparatus on McKendree Rd.

and assigned RIT. Units were operating in the defensive strategy, RIT equipment was staged on the A side of the dwelling and TWR10 members monitored crews working on all sides of the structure. Later assisted with moving hoselines out of the collapse zone.

Narrative Name E71
Narrative Type Company

Narrative Date 11:40:31 Saturday, March 18, 2017

Author 7010 - Sabat, David J

Author Rank CAPT-P
Author Assignment 1

Narrative Text Dispatched as part of the initial alarm. Operator remained with the engine to assist with

water supply. E71's crew was assigned to the A side for exterior, defensive operations. Handlines from E131 were utilized. Crews from E31, E41, SQ3 and CCT12 were assigned to the A side. On the A side, strong winds, immenent collapse concerns and a brief electrical fire hindered operations. Eventually, replaced by SQ3 and E71 went to rehab. Afterwards, assigned by IC to assist with picking up hose lines for transport by the

pod truck and U13. Tools and equipment were picked up and E71 placed in serivce.

Narrative Name E51
Narrative Type Company

Narrative Date 14:21:40 Saturday, March 18, 2017

Author 3567 - List, Jamie R

Author Rank FF-P Author Assignment 2

Narrative Text 4th arriving engine. Left the engine on the hard road with driver per command and

reported on foot to command. Pulled a leader line to the Charlie side of the structure and performed defensive operations. Reported to Rehab and afterwards reported back to our previous position. Assisted with reracking lines off of E131 and returned to service

Narrative Name EMS2
Narrative Type Company

Narrative Date 17:46:52 Saturday, March 18, 2017

Author 3549 - Smeltzer, Lisa M

Author Rank CAPT-P
Author Assignment 2

Narrative Text AOL and assisted with initial accountability. Then assigned to establish rehab. Rehab

established in a nearby homeowner's shop. Hot drinks and snacks provided by Duty 4 and

Rehab 1. fd3549

Narrative Name BC2
Narrative Type Incident

Narrative Date 12:18:15 Sunday, March 19, 2017

Author 1232 - Ridgely, Charles H

Author Rank BC

Page 7 of 11 Printed: 07/21/2017 11:52:27

Howard County Fire and Rescue 6751 COLUMBIA GATEWAY DR. Suite 400 Columbia, MD 21046 410 313 6000

swilson@howardcountymd.gov Printed: 07/21/2017 11:52:27 Number of Pages: 11

Incident Report 2017-1707247 -000

Narratives

Author Assignment Narrative Text

responded for the dwelling fire, responded from Sta 2. assured adequate assignment and response of same, reviewed incident information-noted CAD comment indicating all occupants clear of structure and that fire started in garage, review of incident location with regards to water supply, and configuration of structure with prevailing winds, began tracking enroute and monitored incident traffic. E131 first arriving with IRR: laying out from mckendree have Tnk 13 pick it up. break. on location with med 2 story SFD with heavy fire on bravo side, requesting 2 additional tankers and T/F, advancing a 2 1/2, going for a 360, establishing command. IC return: 3 car garage fully involved with extension into 2nd fir of home, requesting 2nd alarm. IC confirmed an All clear of structure. BC2 still enroute and monitoring incident traffic, noted a declaration of Sta 13 cistern as primary water supply, and comms questioning regarding request for 2nd alarm but dispatching as requested, Sq3 first arriving special advising IC of lack of aerial capability, command pulling multiple units back driveway to assist. noted multiple lines in service to include blitzfire deck gun, Chief 3 with watersupply. BC2 on location and able to acheive command position at fence line on Alpha side. BC2 attempting to transfer command with difficulty due to radio traffic. 131 and 41 flowing multiple lines from the Bravo and charlie side with little appearant effect on well advanced fire. concur with structure description and size up, strategy had not been declared, risk benefit analysis considerations: no rescue, all clear confirmed; advanced fire burning for greater than 20 minutes, wind driven fire from bravo to delta with large structural opening on bravo where garage had been; immediate identification of significant extension of wind driven fire conditions into upper levels of home; observed 3 distinct roof lines from Alpha side, two of which were exhibiting some level of fire extension. Assigned BC aide to complete additional 360. During transfer of command observed crew enter side alpha with handline enroute to second floor, monitored tactical IC establish Div 2 with 2 companies. Observed sudden and violent change in fire as wind blown fire erupted out of Delta gable producing approx 20 foot fireball and pressurized flame. Immediate evacuation order given by BC2, declared defensive operations. Assumed command and required immediate PAR check on the crew that went in, Sq3 and E41 had been designated as Div 2 by tactical IC. Assured evacuation of these 2 crews and their PAR, assured PAR of 131 crew which was only other crew operating at this time. 131 and 135 PAR. verbalized defensive strategy to fireground. noted that comms was unable to utilize emergency tone due to radio traffic but they did verbalize evac order and defensive declaration. Assigned tactical IC as Fire Attack with 131, 71, 51, 41, and Sq3. Safety officer on location and assessing scene. Assigned EMS2 as accountibility, assigned Twr10 as RIT. twr2 operator functioning as staging officer. Water supply units on Bravo 5. Continued to monitor fire conditions and deploy resources into defensive firefighting positions, safety advising of inground pool on charlie side obscured by wind driven smoke, announced same to fireground units. BC1 on location and assigned as Operations Officer. split former fire attack group into Alpha div with 71, Twr2, 41, and Sq3; and Charlie Div with 131, 51, and T7. maintaining 3 companies on deck at entrance to hot zone (CC E124, CCTwr12, Eng 44 and Chief 4). Safety declaring Charlie side off limits due to pool and fall hazzard. Safety beginning to establish collapse zones, observed structural instability on Delta wall and communicated same to operating units. Fence around property served as point of entry accountability in front of command position. Bureau Chief 2 in as part of command team, coordinated with Operations for

Page 8 of 11

Howard County Fire and Rescue 6751 COLUMBIA GATEWAY DR. Suite 400 Columbia, MD 21046 410 313 6000

Incident Report 2017-1707247 -000

swilson@howardcountymd.gov Printed: 07/21/2017 11:52:27 Number of Pages: 11

Narratives

defensive strategy and provided resoures as requested. Electrical issue encountered at A/B corner with major arching. Requested priority response of BGE. Assured level 2 accountaity for all operatinng units and transfered responsibiltiy to BC aide. At 30 min mark from comms, performed PAR and all units PAR and accounted for. EMS2 reassigned to Rehab with MAB, Cmd 17, Duty 4, and Twr2 operator. FM units operating outside of hotzone and advised that h/o did not require red cross assistance, FM units would be performing scene assessment in daylight with permision of owner, assisted Rehab with coordination of resources and getting them back to fire scene without disrupting watersupply, once established, began rotating companies into rehab due to extreme cold. assured water supply received salt truck resource as requested from Comms. PIO on location as well as media reps. rehab established in building so placed Cmd 17 in service. water supply advising that breaker on street had blown area without power. adjustements made to power rehab area from Sq3 now sustainable heat and light. BGE on location and confirming all pwr shut off, Operations resuming plan for defensive fire attack from ext positions, Operations reporting significant degradataion of Alpha wall, all units operating outside of collapse zone. Safety 1 advising of free standing chimney on side Charlie and collapse zone established, communciated same to fireground. Operations requiring crews in SCBA due to horizontal blowing smoke. establishing plan to get an aerial device back driveway and into place for ladder pipe ops. side alpha collapse observed, all units clear and PAR. Determined location of underground hazzards from homeowner and communcicated same to Twr2. Twr2 in place and prepared for ladder ops. safety and Operations aware of commencement of ladder ops, all personnel clear of area and most rotating to rehab, began returing units to service as available, assured HCPD maintaining road closures to support water supply. expereinced signal 2 from Twr2 officer, assured accidental and cleared appropriately. 131 reporting low fuel, establishing plan to get unit clear and out for fuel. Taker 13 in for final soak with foam. Requested and received Transport 10 with flat bed to facilitate pick up of frozen hose. Air unit 17 filling scba bottles, units released as avialable, all units clear of hot zone, lines picked up, bottles filled. cistern at 13 will require refilling by Logistics. No injuries reported despite multiple falls on icy fireground. property posted at fence line, owner was not present to provide him with notification and documentation but made aware by FMs earlier. fire apepared to be out but still smoking. BC2 terminating command and relinquishing channel, BC2 last unit to leave fire ground. EOR/1232

Narrative Name Narrative Type Narrative Date

Narrative Date

Author Author Rank

Author Assignment Narrative Text E101 Company

07:14:43 Tuesday, March 21, 2017

7783 - Oursler, Justin W

FF

AOL as the 5th engine. Took personnel back to scene and left driver with apparatus to work with water supply if needed. Strategies changed as we approached the scene and went defensive. Manned various hoselines throughout the incident. Broke down racked 4" supply line into transporter and went in service.

Printed: 07/21/2017 11:52:27

Narrative Name Narrative Type Narrative Date TWR2 Company

20:09:59 Thursday, March 23, 2017

Columbia, MD 21046 410 313 6000

swilson@howardcountymd.gov Printed: 07/21/2017 11:52:27 Number of Pages: 11

Incident Report 2017-1707247 -000

	Narratives
Author	1820 - Alliger, Christopher D

Author Rank LT Author Assignment 5

Narrative Text The last arriving aerial.

Reported to side "A" and began cutting into the soffett to allow for better stream penetration.

- Reported to rehab.

- Assigned to move TWR2 into postion on side "A" for ladder pipe operations.

- Positioned TWR2 on side "A" and flowed > 30K of H2O.

- Took up.

- Followed E131 to Cooksville for fuel.

Narrative Name DC2
Narrative Type Company

Narrative Date 16:31:41 Sunday, March 26, 2017 Author 1506 - Anuszewski, William G

Author Rank DC Author Assignment 7

Narrative Text Responded to multi-alarm building fire. Arrived on scene and met with command.

Narrative Name TRS10
Narrative Type Company

Narrative Date 07:32:01 Monday, March 27, 2017

Author 2838 - Sharpe, Michael W

Author Rank CAPT-P Author Assignment 1

Narrative Text Responded at the request of the IC to transport supply hose back to Sta. 13 using the POD.

Narrative Name FM213 Narrative Type Other

Narrative Date 07:52:55 Monday, March 27, 2017

Author 3568 - Matthews, Craig M

Author Rank LT Author Assignment 8

Narrative Text Assisted FM204 with O&C...CMM3568

Narrative Name A36
Narrative Type Incident

Narrative Date 22:27:00 Monday, March 27, 2017

Author 8815 - Besseck, Daniel W

Author Rank VFF Author Assignment 1

Narrative Text Staged until released from command

Narrative Name U3

Howard County Fire and Rescue 6751 COLUMBIA GATEWAY DR. Suite 400 Columbia, MD 21046

Columbia, MD 21046 410 313 6000

Incident Report 2017-1707247 -000 swilson@howardcountymd.gov Printed: 07/21/2017 11:52:27 Number of Pages: 11

	Narratives
Narrative Type	Company
Narrative Date	22:27:54 Monday, March 27, 2017
Author	8815 - Besseck, Daniel W
Author Rank	VFF
Author Assignment	
Narrative Text	Transport personnel to fire scene.
Narrative Name	AU17
Narrative Type	Company
Author	-,
Narrative Text	filled SCBA

End of Report

Page 11 of 11

Freemon, Robert

To:

stevepettit@pettitcompanies.com

Subject:

2600 McKendree Rd.

Hi Steve,

I am emailing you to let you know that the Health Dept. has signed off on your building permit B18000825. Prior to final approval of the building permit you will need to pick up a Sewer House Connection Permit (\$165) from the Health Dept. Both the septic line connection and the well line connection will need to be inspected prior to covering up. Have the plumber call to schedule the inspection (410-313-1771). If you have any questions let me know.

Robert "Spencer" Freemon Howard County Health Department 8930 Stanford Blvd. Columbia, MD 21045 Bureau of Environmental Health Well and Septic Program

Phone: 410-313-6357

Email: rfreemon@howardcountymd.gov

Website: https://www.howardcountymd.gov/Departments/Health/Environmental-Health/Well-and-Septic

HOWARD COUNTY DEPARTMENT OF INSPECTIONS, LICENSES AND PERMITS 3430 COURT HOUSE DRIVE - ELLICOTT CITY, MD 21043

* THIS PERMIT MUST BE CONSPICUOUSLY POSTED ON SITE *

Residential New Single Family Dwelling Permit

PERMIT NUMBER: B18000825

APPLICATION DATE: 3/14/2018

ISSUE DATE: 4/20/2018

SITE ADDRESS:

2600 MCKENDREE RD GLENWOOD, MD 21738 PROPERTY OWNER INFO:

JOHN STEPHEN PETTIT 2600 MCKENDREE RD GLENWOOD, MD 21738 Phone #: 301-252-0305

Subdivision:

Lot No.: PAR B

Tax Map:

Grid:

ADC Map:

SDP No.:

Zoning:

Census Tract: 605601

DESCRIPTION OF WORK:

SFD / REMOVE AND REPLACE FIRE DAMAGED HOUSE WITH LARGER HOUSE 9R, 3FB, 1HB, 1FP, 3 CAR GARAGE WITH STORAGE ABOVE (5BR), PORCH / ENERGY CODE PRESCRIPTIVE METHOD

PRIMARY CONTRACTOR INFO:

PRIMARY CONTACT INFO:

Contractor License No.: 0

Contact Type: CONTACT

HOMEOWNER TO ACT AS CONTRACTOR

License Address: STEVE PETTIT

18205 FLOWER HILL WAY #D

18205 FLOWER HILL WAY #D

GAITHERSBURG, MD 20879

GAITHERSBURG, MD 20879

301-975-1020

301-975-1020

Phone #:

Building/Lot Characteristics

Legal Description:

IMPSLOT PAR B 50.012 A[]2600 MCKENDREE RD[]GWYNDYL OAK ESTATES

Existing Use:

Phone #:

Vacant Lot

Water Supply:

Private Private

Height:

Sewage Disposal:

Basement:

Unfinished

SF # of Bedrooms:

SF # of Half Baths: 1

SF # of Full Baths:

Zoning Setback Requirements:

Front -

Proposed:

n/a

Required: 75

Permit Fees:

Total Fees Invoiced:

\$4,668.15

Rear -Side -

Proposed: Proposed:

n/a n/a Required:

30

Total Fees Paid:

\$4,668.15

Required:

Balance Due:

\$0.00

Side Street - Proposed:

n/a

Required:

Meets Minimum Required Setbacks?:

Yes

Lot Coverage for NT Zoning:

To schedule an inspection or check the results of an inspection please call (410) 313-3800

APPROVED BY THE DIRECTOR OF INSPECTIONS, LICENSES AND PERMITS - BUILDING OFFICIAL

