

### **Bureau of Environmental Health**

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-2640 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth


Maura J. Rossman, M.D., Health Officer

| RECEIPT   | DATE: 8318 ONSITE SEWAGE DISPOSAL                               | . SYSTEM        | P 563971                    |  |  |  |
|---|---|-----------------|-----------------------------|--|--|--|
| APPROVAL I  | DATE: 11/8/18 SEC PERMIT: CONSTR                                | UCTION          | Α                           |  |  |  |
| PROPERTY A  |   |                 |                             |  |  |  |
| SUBDIVISION   | l:  | LOT:            | TAX ID:                     |  |  |  |
| CONTRACTO   | R: Fogle's Septic Clean Inc.                                    | EMAIL: <u>k</u> | cim@foglesinc.com           |  |  |  |
| CONTRACTOR  | ADDRESS: 580 Obrecht Road, Sykesville, MD 21784                 |                 | PHONE: 410-795-5670         |  |  |  |
| PROPERTY O  | WNER: Maria Aliprande & Press Palmer                            | EMAIL:          |                             |  |  |  |
| OWNER ADDR  | ESS: 10625 Hillingdon Road Suite 1, Woodstock, MD 21            | 163             | PHONE:                      |  |  |  |
| SEPTIC TANK S   | IZE (GALLONS): 1500 TANK MANUFACTU                              | URER:           |                             |  |  |  |
| PUMP MODEL  | : NA PUMP SIZE NA   | PUMP TAI        | NK CAPACITY: NA             |  |  |  |
| DISTRIBUTIO   | N SYSTEM: GRAVITY PRESSURE DOSED                                | BEDROOMS:       | 4 APPLICATION RATE: 1.2     |  |  |  |
|   | LINEAR FEET REQUIRED: 75  |                 | INLET DEPTH: 3.5            |  |  |  |
| TRENCHES:   | TRENCH WIDTH: 3   | MAXIMUM         | BOTTOM DEPTH: <b>7</b>      |  |  |  |
|   | MINIMUM SPACE BETWEEN TRENCHES: 10 EFFEC                        | CTIVE ADEA DE   | CININIANC DEDTHI. 25        |  |  |  |
| BETWEEN TRENCHES: 10 EFFECTIVE AREA BEGINNING DEPTH: 3.5  PER APPROVED SITE PLAN. SEWAGE DISPOSAL AREA AND TANK LOCATIONS MUST BE STAKED BY LICENSED  |   |                 |                             |  |  |  |
| LOCATION:   | SURVEYOR PRIOR TO PRE-CONSTRUCTION INSPECTION.                  |                 | SWOST DE STARED DE EIGENSED |  |  |  |
| NOTES:  | USE 2x59' trenches  1X 75' TRENCH. USE LASER TO KEEP TO  SWALE. | RENCH B         | SOTTOM LEVEL THROUGH        |  |  |  |
| ISSUED BY:  | Hank Oswald ISSUE DATE:   | 83-18           | EXPIRATION DATE: 8-3-19     |  |  |  |
| NOTE: CONT  | TRACTOR MUST SCHEDULE A PRE-CONSTRUCTION INSPECTION             | PRIOR TO BEG    | GINNING ANY INSTALLATION    |  |  |  |
| NOTE: CONT  | RACTOR MUST SCHEDULE AN INSPECTION AND GAIN APPROVA             | L OF ALL COM    | PONENTS PRIOR TO COVERING   |  |  |  |
| NOTE: STONE MUST BE APPROVED BY HEALTH DEPARTMENT AND GRAVEL TICKET MUST BE AVAILABLE FOR REVIEW.   |   |                 |                             |  |  |  |
| NOTE: WATERTIGHT TANKS REQUIRED   |   |                 |                             |  |  |  |
| NOTE: ALL PARTS OF SEPTIC SYSTEM SHALL BE AT LEAST 100 FEET DOWNGRADIENT FROM ANY WATER WELL  NOTE: MANHOLE RISERS REQUIRED ON ALL SEPTIC TANKS AND PUMP CHAMBERS                                   |   |                 |                             |  |  |  |
| NOTE: AN ELECTRICAL PERMIT IS REQUIRED FOR INSTALLATION OF ANY ELECTRICAL COMPONENTS OF THE SYSTEM  |   |                 |                             |  |  |  |
| DELECTRICAL PERMIT ISSUED  E  NOTE: MDE RECOMMENDS SEPTIC TANKS, BAT, AND OTHER PRETREATMENT UNITS BE PUMPED AT A FREQUENCY ADEQUATE  TO ENSURE THAT SOLIDS ARE NOT DISCHARGED TO THE DISPOSAL AREA |   |                 |                             |  |  |  |
|   | R THE HOWARD COUNTY COUNCIL NOR THE HEALTH                      |                 | ENT IS RESPONSIBLE FOR THE  |  |  |  |

SUCCESSFUL OPERATION OF ANY SYSTEM.

PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT. CALL 410-313-1771 TO SCHEDULE INSPECTIONS.

| NOT TO SCALE   | TRENCH/DRAINFIELD DATA WIDTH INLET BOTTOM  3' 3.5' 7'  NUMBER OF TRENCHES I  TOTAL LENGTH 76'  ABSORPTION AREA 228' + SIDEWAY  DISTRIBUTION BOX LEVEL YES  DISTRIBUTION BOX BAFFLE YES  DISTRIBUTION BOX PORT YES |
|--|---|
| D-box: 45' to A  57' to B  2.5'  A  EX.  HOUSE  B  10.5'  70.5'  71.5'  Ho-15-012  | SEPTIC TANK DATA SEPTIC TANK I LEVEL  |
| * SOLVENT WELDED IPS SCH 40 ASTM F891-10 4"PUC<br>ROAD NAME  | MANUFACTURER  CAPACITY GAL  SEAM DOC  TANK LID DEPTH  BAFFLES  BAFFLE FILTER  MANHOLE LOC  6" PORT LOC  WATERTIGHT TEST  SLOTTED  DATE ON LID   |
| PRE-CONSTRUCTION: 08/03/2018 SOA AND TANK LOCATION STAKED. SHE OUT O TO HAVE BEEN MOVED CLOSER TO DRIVE WAY IN HO HOUSE IS I' HIGHER. TRENCH LAYOUT CLOSE TO TOP OS SWALE IN MIDDLE OF SDA. CONTACT BUILDER  | OF SOA TO GET OUT   |
| INSTALLATION: 08/06/2018 TANK SET, HAS T.B. LID. INSTALLED LINE FROM HOUSE TO TANK. 8/7/18 Trench complete: let wide, 3' to stone. Fogle's said they used a laser to check do off tank. Need grading to fill in swale in SDA prior to find 11/8/18 On site to see if swale in SDA was filled in. Swale is still shown on plan and future replacement septic trenches will ne swale. (50) | epths. Start of trench 2.5' approval of permit. @ There - contour is not as   |
| FINAL INSPECTOR Sarah Collins . DATE OF APPROV   | AL 11/8/18  |



Q:\AutoDesk\Jobs\B7-5620 WOODSTOCK\dwg\B7-5620 Woodstock.dwg, 3/8/2018 9:31:28 AM

Clerk of the Circuit Court for Howard County Land Records/Licensing

The Thomas Dorsey Building 9250 Bendix Road Columbia, MD 21045 410-313-5850

LR - Agreement Recording Fee

Name: ALIPRANDO & PALMER 20.00 Ref: 52

LR - Agreement Surcharge

1x 40.00

SubTotal: Total: 60.00

CRD-Credit Credit Card Confirmation: 07978B 60.00

CC13-MM

01/09/2019 13:10 #11501202/497/109 CC13-1 Thank you for visiting us today~

CIRCUIT COURT FOR HOWA 8360 COURT AVENUE **ELLICOTT CITY, MD 21043** 

01/09/2019

13:09:32

CREDIT CARD

VISA SALE

Card # XXXXXXXXXXXXX6456 Chip Card: CAPITAL ONE VISA AID: A0000000031010 ATC: 012E ARQC: 4DD75AD9A8261F68

SEQ #:

Batch #: 610 INVOICE CLERK


0005 Approval Code: 07978B

Entry Method: Chip Read Mode: Issuer

SALE AMOUNT

NO REFUND WITHOUT COURT ORDER

**CUSTOMER COPY** 



| <b>□AGENCY</b> | □ CLIENT | <b>□FILE</b> | $\square$ BILLING | $\Box$ COORESPONDANCE | □OTHER |
|----------------|----------|--------------|-------------------|-----------------------|--------|

# VanMar Associates, Inc.

Engineers ~ Surveyors ~ Planners 310 South Main Street, P.O.Box 328, Mt. Airy, MD 21771 301-829-2890 301-831-5015 301-695-0600 410-549-2751 (FAX) 301-831-5603

To:

Hand Oswald Licensed Environmental Health Specialist Howard County Health Department Bureau of Environmental Health Well & Septic Program 8930 Stanford Boulevard Columbia, Maryland 21045 DATE: February 14, 2018

PROJECT: Maria C. Aliprando & Press Palmer Property

VanMar B7-5620

# ENCLOSED:

| COPIES | DATE      | DESCRIPTION  |
|--------|-----------|--|
| 1      | 2/13/2018 | Email requesting the revision of the OSDS Plan   |
| 3      | 2/14/2018 | On Site Sewage Disposal System Design Plan, Lands Conveyed to Maria<br>C. Aliprando & Press Palmer |
|        |           |  |
|        |           |  |

REMARKS: Hi Hank, here are the copies, revised to reflect the well sites on OSDS Plan match the Percolation Plan. Have a great day! Mary Anne

<u>COPIES TO (ADDRESS):</u> Maria C. Aliprando & Press Palmer, 10625 Hillingdon Road, Suite #1 Woodstock, Maryland 21163

| SUBMITTED BY: Mag-M | G:ENGR:B75620 hd sewage plan rev.2.14.2018 |
|---------------------|--|
|                     |  |

| □AGENCY | □ CLIENT | <b>FILE</b> | $\Box$ ACCT. | $\Box$ CORR. | □OTHER |
|---------|----------|-------------|--------------|--------------|--------|
|---------|----------|-------------|--------------|--------------|--------|

# VanMar Associates, Inc.

Engineers ~ Surveyors ~ Planners 310 South Main Street, P.O.Box 328, Mt. Airy, MD 21771 301-829-2890 301-831-5015 301-695-0600 410-549-2751 (FAX) 301-831-5603

TO: Howard County Department of

Environmental Health 8930 Stanford Boulevard Columbia, Maryland 21045

Attn: Hank Oswald

**DATE:** 5/2/17

**PROJECT:** Aliprando & Palmer Property

1680 Woodstock Road

<u>VMA#</u>: B75620

### ENCLOSED:

| COPIES | DATE   | DESCRIPTION  |
|--------|--------|--|
|        |        | DEVICED  |
| 3      | 5/2/17 | REVISED On Site Sewage Disposal System Design Plan Press Palmer, Maria C. Aliprando & Mary Palmer Property 1680 Woodstock Road |
|        |        |  |
|        |        |  |

| <b>REMARKS:</b> | Hi Hank, plan revised to reflect your comments and submitted for review and approval. | Thank you! |
|-----------------|---|------------|

COPIES TO (ADDRESS: Marie Aliprando & Press Palmer, 10625 Hillingdon Road, Suite #1, Woodstock, MD 21163

| SUBMITTED BY: dkv | g\engr b7 5620 hd sewage disp. Plan 5.2.17 |
|-------------------|--|
|-------------------|--|

| $\Box$ AGENCY | CLIENT | FILE | DACCT. | $\Box$ CORR. | □OTHER |
|---------------|--------|------|--------|--------------|--------|

# VanMar Associates, Inc.

Engineers ~ Surveyors ~ Planners 310 South Main Street, P.O.Box 328, Mt. Airy, MD 21771 301-829-2890 301-831-5015 301-695-0600 410-549-2751 (FAX) 301-831-5603

**TO:** Howard County Department of

Environmental Health 8930 Stanford Boulevard Columbia, Maryland 21045

Attn: Hank Oswald

**DATE:** 4/28/17

**PROJECT:** Aliprando & Palmer Property

1680 Woodstock Road

VMA#: b7562

#### ENCLOSED:

| OPIES | DATE    | DESCRIPTION  |
|-------|---------|--|
| 1     | 4/24/17 | Email from Hank Oswald   |
| 3     | 4/28/17 | REVISED On Site Sewage Disposal System Design Plan Press Palmer, Maria C. Aliprando & Mary Palmer Property 1680 Woodstock Road |
|       |         |  |
|       |         |  |
|       | -       |  |

**REMARKS**: Hi Hank, plan revised and submitted for review and approval. Thank you!

COPIES TO (ADDRESS: Marie Aliprando & Press Palmer, 10625 Hillingdon Road, Suite #1, Woodstock, MD 21163

SUBMITTED BY: dkv g\engr b7 5620 hd sewage disp. Plan 4.28.17

| <b>□AGENCY</b> | □ CLIENT | $\Box$ FILE | $\Box$ ACCT. | $\Box$ CORR. | $\Box$ OTHER_ |  |
|----------------|----------|-------------|--------------|--------------|---------------|--|

# VanMar Associates, Inc.

Engineers ~ Surveyors ~ Planners 310 South Main Street, P.O.Box 328, Mt. Airy, MD 21771 301-829-2890 301-831-5015 301-695-0600 410-549-2751 (FAX) 301-831-5603

TO: Howard County Department of

Environmental Health 8930 Stanford Boulevard Columbia, Maryland 21045

Attn: Hank Oswald

**DATE**: 4/19/17

**PROJECT:** Aliprando & Palmer Property

1680 Woodstock Road

VMA#: b7562

### ENCLOSED:

| COPIES | DATE    | DESCRIPTION  |  |
|--------|---------|--|--|
| 3      | 4/18/17 | On Site Sewage Disposal System Design Plan Press Palmer, Maria C. Aliprando & Mary Palmer Property 1680 Woodstock Road |  |
|        |         | 1000 WOOdstock Road  |  |
|        |         |  |  |
|        |         |  |  |

**REMARKS**: Hi Hank, plan submitted for review and approval. Thank you!

COPIES TO (ADDRESS: Marie Aliprando & Press Palmer, 10625 Hillingdon Road, Suite #1, Woodstock, MD 21163

SUBMITTED BY: dkv g\engr b7 5620 hd sewage disp. Plan 4.19.17

#### Oswald, Hank

From:

Oswald, Hank

Sent:

Monday, May 01, 2017 3:52 PM

To:

'Ron Thompson'

Subject:

RE: OSDS\_1680 Woodstock Road

Hi Ron:

I just looked over the revised plan and I didn't see the changes for 1 and 2.

Thanks,

Hank

From: Ron Thompson [mailto:ron@vanmar.com]

**Sent:** Monday, April 24, 2017 5:04 PM

To: Oswald, Hank

Subject: RE: OSDS\_1680 Woodstock Road

Hank: Please let me know if the following responses are acceptable and then I will resubmit:

- 1. The profile shows more than 3 feet of cover over the septic tank. Is this a heavy load bearing tank? If so, please indicate on the plan. RESPONSE Note added "Heavy Load Bearing Tank".
- The reduction credit for the first replacement should be 0.36 (utilizing 5 foot sidewall credit). RESPONSE Reduction credit revised.
- 3. The grading behind the future garage exceeds 25%. The setback between steep slopes and the SDA is 25 feet. RESPONSE Since this is a fill above the slope, with only drainage from the fill and there is no cut, can this be approved since it will be sheet flow?
- 4. The length of pvc pipe between the house and tank connections is more like 35 feet per layout on plan. RESPONSE The length is 30-ft. between the cleanouts. We consider the distance between the first cleanout and the house to be part of the house plumbing.

Thank you. Look forward to your response.

Ronald E. Thompson, PE VANMAR ASSOCIATES 310 South Main Street PO Box 328 Mount Airy, Maryland 21771 301-829-2890 (O) 443-421-2164 (C) 301-831-5603 (F)

**From:** Oswald, Hank [mailto:hoswald@howardcountymd.gov]

**Sent:** Monday, April 24, 2017 10:47 AM **To:** Ron Thompson < <a href="mailto:ron@vanmar.com">ron@vanmar.com</a> **Subject:** OSDS \_1680 Woodstock Road

#### Hi Ron:


Please see attached letter regarding the review of the OSDS Plan for 1680 Woodstock Road.

Should you have any questions, please don't hesitate to ask.

Thanks,

Hank

Hank Oswald, L.E.H.S.
Howard County Health Department
Bureau of Environmental Health
Well & Septic Program
8930 Stanford Boulevard
Columbia, MD 21045
410.313.1786 (Office)
410.313.2648 (Fax)



#### Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-2640 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth Twitter: HowardCoHealthDep

Maura J. Rossman, M.D., Health Officer

April 24, 2017

Vanmar Associates, INC. 310 South Main Street Mount Airy, MD 21771 Attn: Ron Thompson

Sent via email to: ron@yanmar.com

RE:

**OSDS Plan** 1680 Woodstock Road Woodstock, MD 21163

Hi Ron:

The OSDS Plan for 1680 Woodstock Road has been reviewed with the following comments:

- 1.) The profile shows more than 3 feet of cover over the septic tank. Is this a heavy load bearing tank? If so, please indicate on the plan. Acary led note added

  2.) The reduction credit for the first replacement should be 0.36 (utilizing 5 foot of sidewall
- credit). renseel
- 3.) The grading behind the future garage exceeds 25 %. The setback between steep slopes and the SDA is 25 feet. Changed to lear than 25 %
- 4.) The length of pvc pipe between the house and tank connection is more like 35 feet per layout on plan.

Should you have any questions, please don't hesitate to ask.

Respectfully,

Hank Oswald

Hank Oswald, L.E.H.S Bureau of Environmental Health Well & Septic Program

## Oswald, Hank

From:

Oswald, Hank

Sent:

Monday, April 24, 2017 10:47 AM

To:

ron@vanmar.com

**Subject:** 

OSDS\_1680 Woodstock Road

**Attachments:** 

OSDS\_1680 Woodstock Road\_4.24.17.pdf

Hi Ron:

Please see attached letter regarding the review of the OSDS Plan for 1680 Woodstock Road.

Should you have any questions, please don't hesitate to ask.

Thanks,

Hank

Hank Oswald, L.E.H.S. Howard County Health Department Bureau of Environmental Health Well & Septic Program 8930 Stanford Boulevard Columbia, MD 21045 410.313.1786 (Office) 410.313.2648 (Fax)

### **Ron Thompson**

From:

Oswald, Hank < hoswald@howardcountymd.gov>

Sent:

Tuesday, February 13, 2018 9:17 AM

To:

Ron Thompson

Subject:

RE: OSDS Plan\_1680 Woodstock Road

Okay. The alternate well sites on the OSDS Plan do not match the alt. well sites on the perc cert plan. Can you revise the OSDS plan so that they do match?

Thanks,

Hank

**From:** Ron Thompson [mailto:ron@vanmar.com] **Sent:** Monday, February 12, 2018 3:34 PM

To: Oswald, Hank

Subject: RE: OSDS Plan\_1680 Woodstock Road

The 4/15/11 plan is what we have.

Ronald E. Thompson, PE VANMAR ASSOCIATES 310 South Main Street PO Box 328 Mount Airy, Maryland 21771 301-829-2890 (O) 443-421-2164 (C) 301-831-5603 (F)

From: Oswald, Hank [mailto:hoswald@howardcountymd.gov]

**Sent:** Monday, February 12, 2018 1:43 PM **To:** Ron Thompson < ron@vanmar.com > **Subject:** OSDS Plan 1680 Woodstock Road

Hi Ron:

Our office received floor plan revisions to 1680 Woodstock Road. I am starting to look them over now. What's the most recent perc cert plan you have on file for this address? When I looked over the OSDS Plan again, I noticed that the alternate well sites on the perc cert plan signed on 4/15/2011 do not match the well site locations on the OSDS Plan.

Thanks,

Hank

Hank Oswald Licensed Environmental Health Specialist Howard County Health Department Bureau of Environmental Health Well & Septic Program 8930 Stanford Boulevard Columbia, MD 21045 410.313.1786 (Office) hoswald@howardcountymd.gov

#### **CONFIDENTIALITY NOTICE**

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.



| Oswald, Hank   |  | × |
|--|--|---|
| From: Sent: To: Subject: Attachments:  | Oswald, Hank Tuesday, February 14, 2017 4:24 PM 'Ron Thompson' RE: Woodstock Septic Specs_Costello Property_Lot2.pdf |   |
| Hi Ron:  |  |   |
| Attached, please find the septi  | c specs for Costello Property Lot 2.   |   |
| Hank   |  |   |
| From: Ron Thompson [mailto: Sent: Tuesday, February 14, 2 To: Oswald, Hank Subject: RE: Woodstock  Yes please  Ronald E. Thompson, PE VANMAR ASSOCIATES 310 South Main Street PO Box 328 Mount Airy, Maryland 21771 301-829-2890 (O) 443-421-2164 (C) 301-831-5603 (F) |  |   |
| Sent: Tuesday, February 14, 20 To: Ron Thompson < ron@vanr Subject: FW: Woodstock  |  |   |
| Hi Ron:  |  |   |
| Do you need septic specs for th  | nis property? Please let me know.  |   |
| Thanks   |  |   |
| Hank   |  |   |

From: Ron Thompson [mailto:ron@vanmar.com]
Sent: Tuesday, February 14, 2017 11:26 AM
To: Williams, Jeffrey
Subject: FW: Woodstock

#### Good Morning Jeff:

Attached are the perc results and SEWAGE DISPOSAL SYSTEM SPECIFICATION WORKSHEET for 1680 Woodstock Road.

Thank you.

Ronald E. Thompson, PE VANMAR ASSOCIATES 310 South Main Street PO Box 328 Mount Airy, Maryland 21771 301-829-2890 (O) 443-421-2164 (C) 301-831-5603 (F)

From: Ron Thompson

Sent: Thursday, December 08, 2016 4:36 PM

To: 'Oswald, Hank' < hoswald@howardcountymd.gov>

Subject: FW: Woodstock

Hank:

Attached are the perc results for 1680 Woodstock Road.

Ronald E. Thompson, PE VANMAR ASSOCIATES 310 South Main Street PO Box 328 Mount Airy, Maryland 21771 301-829-2890 (O) 443-421-2164 (C) 301-831-5603 (F)

From: Mike VanSant

**Sent:** Thursday, December 08, 2016 4:33 PM **To:** Ron Thompson <<u>ron@vanmar.com</u>>

Subject: Woodstock

Here you go

