

PERMIT

SEWAGE DISPOSAL SYSTEM

DEPARTMENT OF HEALTH AND MENTAL HYGIENE

P 49372

A REPAIR

DISTRICT _____

DATE 4/25/93

DATE SYSTEM APPROVED 6/24/93

INSPECTOR M.R. F. Kin

HOWARD COUNTY HEALTH DEPARTMENT

BUREAU OF ENVIRONMENTAL HEALTH

~~461-9933~~

313-2640

INDEXED

Wayde Souder/Wesmar Corporation IS PERMITTED TO INSTALL _____ ALTER X

ADDRESS 13990 Triadelphia Mill Road, Dayton, Maryland 21036 PHONE 531-2166

SUBDIVISION _____ LOT _____ ROAD 5605 Waterloo Road

PROPERTY OWNER _____ James Doty

ADDRESS _____

SEPTIC TANK CAPACITY 1000 GALLONS

NUMBER OF BEDROOMS 3

_____ SQUARE FEET PER BEDROOM

LINEAR FEET OF TRENCH REQUIRED _____

REPAIR - PURPOSE - SEPTIC TANK HAS COLLAPSED. REPLACE WITH A 1000 GALLON SEPTIC TANK.
Call for inspection when tank is in place so sanitarian can approve size and location. 06/24/93

PLANS APPROVED BY _____ DATE _____

COVER NO WORK UNTIL INSPECTED AND APPROVED

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM

NOTE: CLEANOUT REQUIRED EVERY 70 FEET OF SEWER LINE AND/OR AT 90° SWEEPS IN LINES FROM HOUSE TO DRAIN FIELDS, 90° ELBOWS NOT ACCEPTABLE.

NOTE: ALL PARTS OF SEPTIC SYSTEMS (I.E. TANK, DISTRIBUTION BOX TRENCHES) TO BE 100 FEET FROM WELL (UNLESS OTHERWISE SPECIFICALLY AUTHORIZED)

NOTE: IF DEEP TRENCH(ES) ARE USED CALL FOR INSPECTION BEFORE AND AFTER PLACING GRAVEL IN TRENCH(ES)

NOTE: NO DRY WELL SHALL EXCEED 15 FOOT IN DIAMETER NO ABSORPTION TRENCH TO EXCEED 100 FEET IN LENGTH

NOTE: ALL PIPE FROM HOUSE TO SEPTIC TANK MUST BE CAST IRON OR SCHEDULE 35/40 PVC OR ABS


PERMIT VOID AFTER TWO YEARS

NOTE: INSTALL STAND PIPE ON SEPTIC TANK AND DRY WELL STAND PIPES MUST BE 6 INCHES IN DIAMETER CAST IRON. CONCRETE OR TERRA COTTA OR PVA OR ABS ACCEPTED. IF TOP OF SEPTIC TANK IS DEEPER THAN 3 FEET. MANHOLE TO GRADE REQUIRED.

NOTE: DISTRIBUTION BOXES MUST HAVE BAFFLES

***INSTALLER IS RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT**

P49372



INDICATE NORTH - NAME ADJOINING ROADWAY AS BASE LINE

SEPTIC TANK LEVEL 1000 GAL - OK CLEANOUTS MANHOLE OK

DISTRIBUTION BOX LEVEL —

DRAIN FIELD/TITLE DEPTH — FT. TRENCH WIDTH — FT. INLET DEPTH — FT.

EFFECTIVE GRAVEL DEPTH — FT. TOTAL LENGTH — FT.

NUMBER OF TRENCHES — ONE SIDEWALL/BOTTOM AREA — SQ. FT.

DRYWALL INSIDE DIAMETER — FT. EFFECTIVE DEPTH BELOW INLET — FT.

ABSORBENT AREA — SQ. FT.

REMARKS: 6/24/93 S.T. OK TO COVER MR

DATE SYSTEM APPROVED 6/24/93 INSPECTOR M. Rifkin



THIS LETTER
RETURNED TO
SENDER

HOWARD COUNTY HEALTH DEPARTMENT

Joyce M. Boyd, M.D., County Health Officer

Reply to:

May 24, 1993

Mr. James C. Doty
P. O. Box 385
Ellicott City, Maryland 21043

NOTICE OF VIOLATION

Address: 5605 Waterloo Road
Ellicott City, Maryland

Dear Mr. Doty:

On May 14, 1993, a sanitarian from this office inspected your property known as Tax Map: 31, Parcel: 494, located at 5605 Waterloo Road, Ellicott City, Maryland in response to a report of an overflowing septic system. On that occasion Mr. Pinkley observed a partially collapsed septic tank full of untreated sewage. The problem is especially severe since the open hole is in close proximity to a children's play area, and is improperly covered against access of entry.

This condition is in violation of Section 12.110 of the Howard County Code.

As the failing septic system creates a condition which is, or may be hazardous to the public health, you are hereby ordered to apply to this office for a septic system repair permit and effect repairs within fifteen (15) days of receipt of this letter. The cost of the septic repair permit is \$25.00. Until repairs are completed, you must immediately (within 48 hours) have the septic tank and dry well contents pumped by a licensed sewage scavenger; and continue pumping, as often as necessary to prevent future sewage overflow.

If you believe that the condition described above is not and could not be a hazard to health, or that the Health Department is not acting in compliance with pertinent laws and regulations, you may request a formal hearing before the Board of Health within ten (10) days of receipt of this letter. If you wish to discuss the evidence, the regulations, or your individual circumstances, you are encouraged to request a meeting with us by calling 313-2640 and scheduling an appointment.

The investigation of this complaint and the enforcement powers of the Health Department are set forth in Section 12 of the Howard County Code, a copy of which is available for your investigation at this office.

Bureau of Environmental Health
3525-H Ellicott Mills Drive Ellicott City, Maryland 21043-4544
Water and Sewerage, Permits 313-2640 Community Environmental Health 313-2642
Technical Services 313-2644 Director 313-2645 TDD 313-2323


Mr. James C. Doty

- 2 -

May 24, 1993

If you have any questions, please contact Ron Pinkley or myself at 313-2640.

Very truly yours,



Craig D. Williams, Program Director
Water and Sewerage Program

CDW:hs

cc: Ron Pinkley
Howard County Bureau of Utilities
File



file

HOWARD COUNTY HEALTH DEPARTMENT

Joyce M. Boyd, M.D., County Health Officer

Reply to:

May 24, 1993

Mr. James C. Doty
P. O. Box 385
Ellicott City, Maryland 21043

NOTICE OF VIOLATION

Address: 5605 Waterloo Road
Ellicott City, Maryland

Dear Mr. Doty:

On May 14, 1993, a sanitarian from this office inspected your property known as Tax Map: 31, Parcel: 494, located at 5605 Waterloo Road, Ellicott City, Maryland in response to a report of an overflowing septic system. On that occasion Mr. Pinkley observed a partially collapsed septic tank full of untreated sewage. The problem is especially severe since the open hole is in close proximity to a children's play area, and is improperly covered against access of entry.

This condition is in violation of Section 12.110 of the Howard County Code.

As the failing septic system creates a condition which is, or may be hazardous to the public health, you are hereby ordered to apply to this office for a septic system repair permit and effect repairs within fifteen (15) days of receipt of this letter. The cost of the septic repair permit is \$25.00. Until repairs are completed, you must immediately (within 48 hours) have the septic tank and dry well contents pumped by a licensed sewage scavenger; and continue pumping, as often as necessary to prevent future sewage overflow.

If you believe that the condition described above is not and could not be a hazard to health, or that the Health Department is not acting in compliance with pertinent laws and regulations, you may request a formal hearing before the Board of Health within ten (10) days of receipt of this letter. If you wish to discuss the evidence, the regulations, or your individual circumstances, you are encouraged to request a meeting with us by calling 313-2640 and scheduling an appointment.

The investigation of this complaint and the enforcement powers of the Health Department are set forth in Section 12 of the Howard County Code, a copy of which is available for your investigation at this office.

Bureau of Environmental Health
3525-H Ellicott Mills Drive Ellicott City, Maryland 21043-4544
Water and Sewerage, Permits 313-2640 Community Environmental Health 313-2642
Technical Services 313-2644 Director 313-2645 TDD 313-2323


Mr. James C. Doty

- 2 -

May 24, 1993

If you have any questions, please contact Ron Pinkley or myself at 313-2640.

Very truly yours,



Craig D. Williams, Program Director
Water and Sewerage Program

CDW:hs

cc: Ron Pinkley
Howard County Bureau of Utilities
File ✓

REGION _____

AREA _____ RATING _____

ACKNOWLEDGMENT AND CONTROLS	DATE

Howard County Department of Health

BUREAU OF ENVIRONMENTAL HEALTH

RECORD OF INVESTIGATION

(scenes
P. 444 on Tax Map)
see A03559 (161)
P03606
M31 P494
Gulley

DISPOSITION	DATE
Send NAV.	

LOCATION Waterloo Rd. opposite Montgomery Run ZIP _____OWNER ☐ ADDRESS PO Box 358 ECH 21042 PHONE 992-8849OCCUPANT ☐ JAMES C. DOTY / CRISB-CROSS ADDRESS 5605 Waterloo Rd. PHONE ext 7309COMPLAINANT Firefighter King ADDRESS Just before Montgomery Run Rd PHONE ext 7309REASON FOR INVESTIGATION Caved septic system & open, several boards covering small children in area (4-5' deep)RECEIVED BY F. Frommelt DATE 5-14-93 ASSIGNED TO RJP CODES _____ DATE 5/14/93DATE OF INVESTIGATION 5/14/93 TIME 3:50 PM WEATHER Sunny

REPORT There is a hole in ground about 4 1/2-5 ft in diameter and 3 ft deep with a pond of sewage water typical of a septic tank with collapsed lid. Hole is covered by a thin (1/4" thick) 4' x 8' section of plywood & several 2"x6" + 4"x4" piece of wood to hold cover down. Hole is 6-12" wider than width of plywood and on a steep (30%) slope 40 ft in front of house, easily accessible by children. Scattered childrens tricycles, toys only 50 ft from this hole of sewage. Definitely a Safety and Health Hazard. RJP 5/14/93

DATE SUBMITTED _____ SANITARIAN _____