
SITE INSPECTION SHEET

OWNER: Theoni H	iotis	PHONE #: _	410-992-9526
ADDRESS: 6650 Sene	ca Farm Rd	CONTRAC	TOR:
Columbia,	mb. 21046	_ WELL TAG	G#: no taq
SUBDIVISION:	LOT:	_ COUNTY#	
PROPOSAL: Site ins	pection for well às	eptic - pro	perty connected to public
water & Sewer	•		\

LOCATION DIAGRAM



COMMENTS: _	Owner had onsily sept	, c Jystem	properly a	boudenes	Sam's
	Inc , but the well is				
well will	be turned into an i	rrigiation well	or sealed	by a li	carsed well
driller.	HP will be notified	either in	au.		
DATE: 1	20 21	INSPECTOR:	R.R. ppc	لممد	

WATER WELL ABANDONMENT-SE	SALING REPORT FORM	******	******
SUBMIT COPIES OF COMPLETED FORM TO: * COUNTY ENVIRONMENTAL AGENCY (contact MDE, WMA if add * WELL OWNER * MDE, WATER MANAGEMENT ADMINISTRATION, WELL PROGR			
DATE WELL ABANDONED: 82122 (mc	onth/day/year)		
PERMIT NUMBER OF ABANDONED WELL (if any) * PERMIT NUMBER OF REPLACEMENT WELL:		N/A_	
* PERSON ABANDONING WELL: Andrew House many * OWNER'S NAME: Throng: Highs	CIRCLE: N	MBER: AMWD/MSD/M	GĎ
* WHEL LOCATION: COUNTY: NEAREST TOWN: TAX MAP 0036 BLOCK 0019 PARCEL 0131 SUBDIVISION: SECTION: STREET ADDRESS: 6650 Sereco Farm Pd	X Fas	ed of	
LATITUDE 39.188609	LOG OF SEAL	LING MATERIA	r
LONGITUDE 7 6 . 8 6 4 4 9 2	EOG OF SEAL	sir. 22	ET
	MATERIAL	FROM	ТО
* TYPE OF WELL BEING ABANDONED: DRILLED JETTED BORED HAND DUG OTHER (specify)	Bentonite	50	0
* USE CODE: DOMESTICMUNICIPAL/PUBLICIRRIGATIONINDUSTRIALTEST/OBSERVATIONGEOTHERMAL			
	VOLUME OF	MATERIAL USED)
* TYPE OF CASING:	Pursuant to § 10-624 of Maryland Code, persona is used in processing this 26.04.04. Failure to provide form not being processing processing the policy of the Environment of the Environ	al info requested on s form pursuant to ovide the info may reseased. You have the tessed. You have the tessed. You have the tonment is subject thation Act. This formeternet via MDE's vor copying, in whole governmental ager State Law.	n this form COMAR esult in e right to laryland to the m may be website and e or in part,
SIGNATURE-MASTER WELL DRILLER OR SUPERVISING SANITARIAN LICENSE#	CIRCLE ONE	0	ATE

Fogle's Well Drilling, LLC

P.O. Box 202 Woodbine, Md 21797 443-609-4195 410-795-5670{24hrs}

08-26-2021

Invoice

Date	Invoice #	
8/23/2021	10398377-551	

Bill To:

Theoni Hioris 6650 Seneca Farm Rd Columbia, Md 21046 **Job Location**

6650 Seneca Farms Rd Columbia, Md 21046

Amount of Remittance

P.O. No.	Terms	Project		** 1-1/2 % Late charge due on boutstanding more than 15 days f	
	C.O.D.	6650 Seneca Farm Rd	invoice** (18% per annum)		
Qty		Description	Price Each	Serviced Amoun	
8		rate & County Regulations. Cail nent report to the County & State once ived. ite	1,500.00 25.00	8/21/2021	1,500.00
t's been a pl stay Healthy	leasure working wi	ith you.		Total	\$1,700.00
				Payments/Credits	-\$1,700.00
				Balance Due	\$0.0



Sam's Excavating, Inc.

P.O. Box 0157 Fulton, MD 20759-0157 Cell Phone: (443) 277-7915

July 26, 2021


Howard County Health Dept Environment Health Bureau Ryan Rappaport 8930 Stanford Blvd Columbia MD 21045

rrappaport@howardcountymd.gov

RE: 6650 Seneca Farm Rd—abandonment of septic tank and dry well

The following is the work that was done at 6650 Seneca Farm Road.

Pumping not necessary- unpumpable Dug up metal septic tank Fill with good compactable dirt Dug up dry well Fill with good compactable dirt



If you have any questions please call me at 443-277-7915.

Sincerely,

Sam Wilkerson, President Sam's Excavating, Inc.

Signature	Date

7/28/21 - p/c from Sam's Excavating - stated that the metal septic tank was rusted out with holes, no liquidor solid material found, crushed tank, left in onsite and buried it with clean fill dirt. @

FILE INQUIRY NOTES

DATE RESULTS OF REVIEW FOR FILE 3/24/00 (all recicud an 3/23/20 about an "at -af-water" situation from Driller Joe May re. (240-586-985). (alled our to Zack knowld (Dew) property mark meto desdret, Dew andred property has chart areas to pet, water (-11ed driller back and explained into. 7/2/20 - Site insp See photos of file found a well behind the house - the well line is pump had been removed but the casing is well cap were. Still there, Disturbed earth in the front of the property leads me to believe that the septic system was abandonned. I spoke
"art-of-water" situation from Driller Joe Majar. (240-586-985). (alled am to Zack knowld (Dew) popular march meto drafted, Den andered prepared has draft areas to pub, water (-11ed driller back and explained into. 7/21/21 Site insp See photos of file found a well behind the house - the well line is pump had been removed but the casing is well cap were Still there. Disturbed earth in the front of the property leads
"art-of-water" situation from Driller Joe May re. (240-586-9885). (alled am to Zack knowld (Dew) popular march meto drafted, Den andred prepared, has chart arraw to pub, water (-11ed driller back and explained into T/21/21 Site insp See photos of file found a well behind the house - the well line is pump had been removed but the casing is well cap were Still there. Disturbed earth in the front of the property leads
(Dew) poperty march meto dratest, Dew andered property has already access to pob. wenter (-11 ed driller back and explained in to. T/21/21 Site insp See photos of file found a well behind the house - the well line is pump had been removed but the casi-q is well cap were Still there. Disturbed earth in the front of the property leads
collect driller bould and explained in for. 7/21/21 - Site insp See photos of file found a well behind the house - the well line is pump had been removed but the casing is well cap were Still there. Disturbed earth in the front of the property leads
Called diller back and explained in the Tourse - the well line is pump had been removed but the casing is well cap were Still there. Disturbed earth in the front of the property leads
7/21/21 - Site insp See photos of file found a well behind the house - the well line is pump had been removed but the casing is well cap were Still there. Disturbed earth in the front of the property leads
line is pump had been removed but the casing is well cap were Still there. Disturbed earth in the front of the property leads
Still there. Disturbed earth in the front of the property leads
me to believe that the septic system was abandonned. I spoke
to the homeowner, Theoni Hiotic 410-992-9526 (theonih@verizon.net)
but it was unclear if she know about the septic abandonment.
She was aware that the property (house) was connected to
public wiss.
7/21/21-Spoke to Sam of Sam's Excavating. 443-277-7915, he did the
septic abondoment and will send invaice we description of work to HD.
Also sent T. Hiotis well driller's phone list for the to well
abando ment. @ Loto call for different estimates.
7/22/21 - emailed bonneaures homeowner uf state is local regs associated uf
well abandonment.
8/28/21 - VM left for Home owner regarding 8/23/21 dead line for well
Abandon munt. D
8/24/21 - Wrote email requesting update of well scaling. theonine verizon not @

3/13 - cond 19. (Except) = comp. 3/16 - 3/24 and 15 (ourpt)

The wife of the said of the said the said of the said

4) water & > Remote - All the well Teleforte - Elf - protovants once to me a foreton

NO WOOK

Time of could if you have The land and the second of the

Rappaport, Ryan

From:

Rappaport, Ryan

Sent:

Friday, July 30, 2021 10:01 AM

To:

Theoni Hiotis

Subject:

RE: Irrigation Well

Attachments:

Retention of Well on Public Water.pdf; WELL DRILLERS updated 7-31-2018.pdf

Hi Mrs. Hiotis, Thanks for reaching out. I know this required work associated with the well is all unexpected and I'm willing to work with you to get it resolved. I'd like you to take into consideration a few things before you decide what to do with that well. I believe your best and cheapest route will be sealing that abandoned well. A lot of the cost for sealing it will depend on how deep it is(needs to be evaluated by a licensed well driller). The deeper it is the more concrete the well driller will have to use to seal the contamination route to our groundwater. Please read the attached policy about retaining your well for irrigation. There are stipulations for the approval which are reviewed by the supervisor and Bureau Director. Currently that well doesn't meet the 30 foot setback requirement to your foundation, that's #1 on section 5.0 Procedure. You also have to have a clean bacteria test which will cost money for the water testing and there's no guarantee that water is free of ecoli and coliform since it's been abandoned for a while. The plumber will have to do a lot of work to get this well up and running as an irrigation well (dropping a submersible pump, running the water line to the house, installing a pitless adapter for a sanitary seal and install water and pressure tanks inside the house). I believe the plumber's quote for all this work will be high.

As I said, I believe your best and cheapest route will be having a well driller seal that abandoned well. I'll give you 2 weeks to go through your options and get quotes/estimates for the work, turning it into an irrigation well or having it sealed. Then an additional week to have the work done. August 23, 2021 will be the deadline for the complete resolution of this matter. Any evaluation work of the well must be done by a Maryland licensed well driller. Let me know if you have any questions.

Ryan

From: Theoni Hiotis <theonih@verizon.net>
Sent: Thursday, July 29, 2021 3:32 PM

To: Rappaport, Ryan <RRappaport@howardcountymd.gov>

Subject: Re: Irrigation Well

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Is there a dead line that?
Please let me know
Thanks
Mrs Hiotis

Sent from the all new AOL app for iOS

On Wednesday, July 28, 2021, 8:23 AM, Rappaport, Ryan < RRappaport@howardcountymd.gov > wrote:

Ms. Hiotis, I wanted to let you know that Sam Wilkerson provided the Health Department with the required septic abandonment information. Can you please provide me with an update on your plans for the well and when the work will be completed? Thanks.

Ryan Rappaport, LEHS

Howard County Health Department

Bureau of Environmental Health

8930 Stanford Blvd.

Columbia, MD. 21045

Phone 410-313-1781

Fax 410-313-2648

rrappaport@howardcountymd.gov

www.co.ho.md.us



CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

From: Theoni Hiotis < theonih@verizon.net>
Sent: Monday, July 26, 2021 9:06 AM

To: Rappaport, Ryan < RRappaport@howardcountymd.gov>

Subject: Re: Irrigation Well

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Got it.

Sent from the all new AOL app for iOS

On Monday, July 26, 2021, 9:04 AM, Rappaport, Ryan < RRappaport@howardcountymd.gov > wrote:

Hello, Ms. Hiotis, I asked my supervisor if there was a different option for you instead of well abandonment. Please see the attached waiver form for the retention of your well as an irrigation well. If you can meet all the requirements of the policy you can have a plumber hook it up as an irrigation well and make sure there's no cross connection with your public water line. Please proceed with this option or the well abandonment by a licensed well driller.

Ryan Rappaport, LEHS

Howard County Health Department

Bureau of Environmental Health

8930 Stanford Blvd.

Columbia, MD. 21045

Phone 410-313-1781

Fax 410-313-2648

rrappaport@howardcountymd.gov

www.co.ho.md.us




CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

SITE INSPECTION SHEET

OWNER: HIOTIS, THEONI	PHONE #:
ADDRESS: 6650 DENECA FARM	CONTRACTOR:
COLUMBIA MD 21046	WELL TAG#: NO THE
SUBDIVISION: SIMBONVILLE LOT:	COUNTY#:
PROPOSAL: AD F - REDAIR	

LOCATION DIAGRAM



COMMENTS: SEE	ATT. Pt	670		
DATE: 09/11/202	<i>></i>	INSPECTOR: CA	BAHUG 00199	7

Wolf, Kevin

From:

Williams, Jeffrey

Sent:

Thursday, July 1, 2021 3:35 PM

To:

Wolf, Kevin

Subject:

FW: 6650 Seneca Farm Rd P21002210

Can you have someone check that they abandoned well and septic?

From: Smith, Darrell <jasmith@howardcountymd.gov>

Sent: Thursday, July 1, 2021 11:57 AM

To: Williams, Jeffrey < jewilliams@howardcountymd.gov>

Subject: 6650 Seneca Farm Rd P21002210

Jeff,

This for an add-on sewer and water.

Darrell Smith
Plumbing/Mechanical Supervisor
Md. State Master Plumbing/Mechanical Inspector
ICC Commercial/Residential Plumbing Inspector
7125 Riverwood Dr. St. D2
Columbia, Md. 21046
Phone: 410-313-1841

7none: 410-313-1841 Fax: 410-313-1861

[&]quot;There is no traffic jam along the extra mile." "Roger Staubach"



Wolf, Kevin

From:

Knight, Zack

Sent:

Tuesday, March 24, 2020 10:21 AM

To: Cc: Wolf, Kevin Roberts, Kyle

Subject:

6650 Seneca Farm Rd New WHC

Hi Kevin,

As discussed on the phone, this address has access to connect to public water via the water main at the dead end of Seneca Farm Road (Contract 24-1892-D). See screenshot below.

Kyle – This house has a failed well and will likely want to connect to public water. I don't think there's a WHC yet for this house. The homeowner/plumber would need to complete and return the new water connection form (link below) and turn into Bureau of Utilities, correct?

https://www.howardcountymd.gov/Departments/Public-Works/Bureau-Of-Utilities/Customer-Service-Division/New-Water-Sewer-House-Connection

Thanks – Zack



Zack Knight, P.E. Howard County DPW Utility Design Division 7125 Riverwood Drive, Suite B Columbia, MD 21046 315.378.6087 zknight@howardcountymd.gov