## **File Inquiry Notes**

## 9722 Whiskey Bottom

## 12/7/2020

Owner wishes to apply for BRF to connect to public sewer.

Upon inspection of property, could not locate septic tank or cleanout based on as-builts. Owner lent me a child's metal detector to use but this turned up nothing. Hank Oswald, who approved the solar panel building permit in 2014, remembers the tank located on the far side of the solar panels. Owner inherited property from her mother. She says she doesn't think her mother had the septic tank pumped for the last four years. She does not know where the septic tank is located.

Trenches look fine. The ground has sunken a little bit and the soil is soft but there is no evidence of wetness or sewage to the surface.

As it stands, there is no evidence that the system is failing and would qualify for a BRF. I told the owner that the next step would probably be to call in a contractor to probe for the tank.

E1900 2751 We approved prior to knowing about the outdoor were and find Nothing about building permit mentioned the out of the permitten 1/15. Soone line and water line to the sink has already been included and left open for inspection. Contractor was to take to inspection before going out to site. (On school)

- 2000