COMPLETE THIS FORM WHEN DROPPING OFF ANY CORRESPONDENCE AND/OR PLANS TO THE HOWARD COUNTY DEPARTMENT OF INSPECTIONS, LICENSES AND PERMITS COUNTER:

Date:	3/10/22
To:	(Person's Name and Division)
From:	Your Name, Company Name and Telephone Number)
Subject	The state of the s
	Project site address
	Permit # B 22000406 SDP #
	Other information pertinent to this project
✓ Pleas	se check the attachments below that you are submitting with this transmittal:
X	Letter of response to address plan review comment letter
×	Revised plans and/or revised details: When submitting for a complete re-review, duplicate sets shall be submitted.
/	Letter Summarizing Changes Description with Summarizing Changes
	Energy conservation calculations @ Thus Culto
×	Copies of (be specific) & First AL HEREH OLEH
	Health Department Request DPZ/ DED Request Applicant's Request
	Two sets of single family dwelling model plans to be placed on permanent file: Model name and/or #
*****	Other
	Contact Person Information: (Required)
	Scott Aktek Bold Telephone No: 43-879-9222 Please Print Name E-Mail Address: SALTER BOLDE
	Please Print Name
	E-Mail Address: SALT & ROURDE THE LAW MAKES Blood com

PLEASE ASSURE ALL DOCUMENTS AND/OR REVISIONS ARE APPROPRIATELY <u>SIGNED AND SEALED</u>, IF NECESSARY, BY A LICENSED ARCHITECT OR ENGINEER. PLEASE BE ADVISED THAT INSUFFICIENT INFORMATION MAY RESULT IN THE DELAY OF REVIEW BY THE PLANS EXAMINER. THE DEPARTMENT OF INSPECTIONS, LICENSES AND PERMITS WILL CONTACT YOU IF THERE IS A PROBLEM. IN ADDITION, ONCE THE BUILDING PERMIT IS APPROVED BY THE PLAN REVIEW DIVISION AND ALL OTHER REQUIRED SIGNATORY AGENCIES, AND THE BUILDING PERMIT <u>IS</u> READY FOR ISSUANCE, THE PERMIT DIVISION WILL NOTIFY THE APPROPRIATE CONTACT PERSON FOR PERMIT PICK UP. ALL PERMIT STATUS INQUIRIES SHALL BE DIRECTED TO THE PERMIT DIVISION AT 410-313-2455. CODE RELATED QUESTIONS AND PLAN REVIEW INQUIRIES SHALL BE DIRECTED TO THE PLAN REVIEW DIVISION AT 410-313-2436. PLEASE ALLOW A <u>MINIMUM OF FIVE (5) WORKING DAYS</u> FOR ANY PLAN SUBMITTALS TO BE REVIEWED. THANK YOU.

Received by





RESIDENTIAL BUILDING PERMIT APPLICATION


HOWARD COUNTY DEPARTMENT OF INSPECTIONS, LICENSES, AND PERMITS 3430 COURT HOUSE DRIVE, ELLICOTT CITY, MD 21043 - PHONE: (410) 313-2455 OPTION #4


BUILDING SITE ADDRESS	REQUIRED					
Street Address: 5178 Ten Oaks F					Unit	
City: Clarksville	Annual Control of the	······································	State: MD	1 (PR 05 - (L) (1) - L (R) (L) (L) (L) (L) (L) (L) (L) (L) (L) (L		Code: 21029
Subdivision/Village/Complex Name:	LINEN CHAPE	LLUDOSS	J	SDI	P/WP/BA #:	North Committee of the
productive a second	- A THE PERSON AND TH	Parcel: 76	Microsoft species of a control of a control of the	Grading Perr		**************************************
DESCRIPTION OF WORK				1		:
Existing Use: Single-family hom		Use:Single-f	amily home	e	Estir	nated Cost: \$200,000.00
Trade Work to Be Completed (Separ	······································	·····		***************************************		None
Remodel existing ranch hom	***************************************			option to a residence of the country according	oms, add nev	v garage, add new MBR
wing, finish portion of basen	nent (existing stairs t	o remain)	1. (10 %	(657 440000
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	om a samula iljan liifetaa irika	akarahaan madifii maa	1000 mm - 1000 m	na Karamana na makamana karamana na maka maka maka maka maka maka m
PROPERTY OWNER INFOR	MATION REQUIRE	O				
Owner(s) Name(s) (As it appears on		ners. LLC			Prim	ary Residence: Yes 🕱 No
Owner's Street Address: 5200 Ten	***************************************		***************************************	and the second decision in the second	an and a see of the se	
City: Clarksville	The second secon		State: MD		Zip	Code: 21029
Phone: (443) 829-9222	AND AND ADDRESS OF THE PARTY OF	Fmail: Ysa		herainmake		
	IRED - INDIVIDUAL W				group.oom	
Business Name: Park Brothers,		770 32573 7	.,	me:Scott Arti	arbuen	
Stroet Address: 5200 Ten Oaks F	MATERIA PROGRAMMENT IN COMPANIES OF THE PROGRAMMENT	forcing the second seco	Contact Ival	ne. Scott Mitt	arbum	denterment sold in the set of the particular and another than a representative and another than a representative and the set of the
City-Clarksville	NOGU		State: MD		Zn	Code: 21029
Phone: (443) 829-9222	- West of the second se	Emailsonré	À	erainmakers		COUC. Z TOZO
CONTRACTOR INFORMATION	ON REQUIRED	Email Sait	erpurnætn	eranımakerç	group.com	
Business Name: Rainmaker Con						~
Licensee's Name: Scott/Todd Art			Licanca #	MDD #6495	MHIC #08050	124004 RA
Street Address: 6755 Business F	The state of the s		LICEITSE W	111017 #0403/	1 FX	1131091 AS
City: Elkridge	arkway, June 103		State: MD			Code: 21075
Phone: (443) 829-9222	MARKET MARKET TO A STATE OF THE	Email: nort	k	erainmaker		CONE. Z 1013
ARCHITECT/ENGINEER IN	EODMATION THOSE					
Business Name: N/A	FURMATION INDIVI	IDUAL WHO S	Name:	INS, IF APPLI	LABLE	
Street Address:	MANUFACTURE INTERPRETATION OF THE PROPERTY OF	www.here	Hame,	Mininger Wennyagen American School (1995) and the control		
City:			State:	III	**************************************	Code:
Phone:	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	Email:	State;		1 49	COGC .
BUILDING CHARACTERIST	ICS REQUIRED	Cillon,				
Primary Structure: SF Dwelling		inlex [7] Mobile	Home D M	ulti-Family Dural	lina (ME*)	Condo: Tyes & No
Utilities: A Electric Gas	Water Supply: Publ	······			sal: D Public	Private (Septic)
Heating System: D Electric Nat			(4403)		e Project: 18 No	**************************************
	NFPA 13R D NFPA 130	***************************************	Eiro Al	·	e Project. Ang No ∐Yes 🗶 No	
ADDITIONAL RESIDENTIAL						O voice tvac
Model Name & Options: N/A	LINFORMATION (PLEASE SELE	LI/COMPLE	TE ALL THAT	APPLY)	
Andrew Control of the	ficiency units (MF*):	# of 1 BR (MF*\	# of 2 BR (M	E*}-	# of 3 BR (MF*):
# Rooms:	# Full Baths:4	1 00 1 000	# Half Bath		Company of the Compan	Fireplaces: 2
Garage/Carport Info: X Attached (rage D Inter	ral Garage		J None	recpiaces, Z
Basement/Foundation Info: Slat	AND THE PROPERTY OF THE PROPER		ned Basement		Basement: D Fi	Il or V Partial
1st Fi Wicth: 90 1st Fi Dec			2" FI Depth		Bsmt Width: 66	Bsmt Depth: 34
Energy Method: ☐ Prescriptive ☐		**************************************	Gross Area:			
AGREEMENT/ DISCALIMER		lauve Li ERI	GIUSS AICA.	4,700	. sq it occ	uplable Area: 3,787 sq ft
THE UNDERSIGNED HEREBY CERTIFIES AND AC		HE IS AUTHORIZED T	O MAKE THIS API	PLICATION; (2) THAT	THE INFORMATION I	S CORRECT; (3) THAT HE/SHE WILL COMPLY
WITH ALL REGULATIONS OF HOWARD COUN	TY WHICH ARE APPLICABLE THERE	TO, (4) THAT HE/SHE	WILL PERFORM	NO WORK ON THE A	BOVE REFERENCED PI	ROPERTY NOT SPECIFICALLY DESCRIBED IN
THIS APPLICATION; (5) THAT HE/SHE GRA	INTO COLUMN OFFICIALS THE MUN	TIGENIERONIOTI	HD) FROPERIT FO	K THE FURPOSE OF	NSPECTING THE WOL	
Set 1	7			2/2/2	- T	1,629 SF NEW
APPLICANT'S DRIGINAL SIGNATURE		- www.		ATE SIGNED	Ç	
			υ	*** (315,8394, 6.7		
FOR OFFICE USE ONLY			CHECKS PAY	ABLE TO: DIRECT	OR OF FINANCE OF	HOWARD COUNTY
AGENCIES REQUIRED/APPROVALS:	and the second s		Marie Marie of proceedings of the parties	2121	22	
76	pr.	and the second		2/1	Pholy	
DPR DPZ		MED		Trifealth	43 miles	SHA CID
SUBMITTAL FEES: \$ 34	PAYMENT	. w1	0		400	EPTED BY:

View GroundRent Registration View GroundRent Redemption View Map Special Tax Recapture: None Account Identifier: District - 05 Account Number - 368316 RESIDENTIAL Owner Name: PARK BROTHERS LLC Use: Principal Residence: NO Deed Reference: /19403/ 00103 Mailing Address: 5200 TEN OAKS RD CLARKSVILLE MD 21029-LOT 3 Legal Description: Premises Address: 5178 TEN OAKS RD 5178 TEN OAKS RD **CLARKSVILLE 21029-0000** LINDEN CHAPEL WDS Assessment Year: Plat No: Neighborhood: Subdivision: Section: Block Lot: Мар: Grid: Parcel: Plat Ref: 5010101.14 3 2020 0127 1001 0028 0014 Town: None **County Use Primary Structure Built Above Grade Living Area** Finished Basement Area **Property Land Area** 2.0100 AC 1969 1,246 SF Stories Basement Type Exterior Quality Full/Half Bath Garage **Last Notice of Major Improvements** YES STANDARD UNIT FRAME/ 2 full 1 Attached **Base Value** Value Phase-in Assessments As of As of As of 07/01/2021 07/01/2022 01/01/2020 Land: 247,600 275,100 Improvements 141,900 132,900 Total: 408,000 389,500 408,000 401,833 Preferential Land: 0 \cap Seller: STONER DONALD R Price: \$375,000 Date: 05/27/2020 Type: ARMS LENGTH IMPROVED Deed1: /19403/ 00103 Deed2: Seller: Date: Price: \$0 Type: Deed1: /00501/ 00445 Deed2: Seller: Price: Date: Type: Deed1: Deed2: 07/01/2022 Partial Exempt Assessments: Class 07/01/2021 County: 000 0.00 State: 000 0.00 Municipal: 000 00.0100.00 0.00[0.00 Special Tax Recapture: None Homestead Application Status: No Application Homeowners' Tax Credit Application Status: No Application Date:










A3

UNDER CABINET RECEPTACLE

 ∇ CATV (FINAL WALL LOCATION TBD IN FIELD)

 ▼ CATV AND PHONE JACK



Bricker, Robert

From:

sarterburn@therainmakergroup.com

Sent:

Monday, March 7, 2022 12:59 PM

To:

Bricker, Robert

Cc:

Williams, Jeffrey

Subject:

RE: 5178 Ten Oaks Road_B22000406-On Hold

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Hi Robert:

If I read your email correctly (forgive me), the Health Department will release its Hold on my building permit application with my agreement that following items must be completed prior to issuance of the Certificate of Occupancy:

- Provide a passing water sample.
- Obtain final approval of OSDS installation.

If this is correct, I certainly agree to these requirements.

Thanks.

Scott Arterburn, P.E. 443-829-9222 (cell)

From: Bricker, Robert < RBricker@howardcountymd.gov>

Sent: Monday, March 7, 2022 11:38 AM **To:** sarterburn@therainmakergroup.com

Cc: Williams, Jeffrey <jewilliams@howardcountymd.gov>
Subject: RE: 5178 Ten Oaks Road_B22000406-On Hold

Hello Scott,

We have received a memo from Freedom Septic which states that they pumped the septic tank and dry well and abandoned them.

Concerning Building Permit approval: I will need a response from you acknowledging these conditions:

- That the OSDS Permit for installation of the replacement system must be approved prior to Building Permit. A
 Control Box, Pump, alarm, and electrical supply must be installed and a 'Pump and Alarm' test successfully
 completed for Final Approval of the OSDS Permit. The OSDS Permit must have Final Approval for the Health
 Department to release the Hold condition on the Final Inspection.
- 2. When completed on October 14, 1969, the existing well was reported as 104 feet total depth with casing to 65 feet, though only 18 feet of grout was applied to seal the well's annular space. The installed original septic tank and dry well have been within 100 feet of the well since the property was first occupied in 1969. The well must be sampled for potable water analyses and the results must PASS by established potable water standards. Should there be persistent bacteria contamination or turbidity exceeding potable standards, a new well must be installed as there are not Permanent Deviations available for the types of treatment which may negate bacteria contamination or reduce turbidity. The well that provides water service for the residence must PASS potable water standards for the Health Department to release the Hold condition on the Final Inspection.

A stated acknowledgement of these conditions in 'Reply' to this email is appropriate.

Robert Bricker, REHS/RS, L.E.H.S. Environmental Sanitarian II Bureau of Environmental Health, Well and Septic Program 8930 Stanford Blvd., Columbia, MD 21045

Phone: (410)313-2691

Email: rbricker@howardcountymd.gov



CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

From: sarterburn@therainmakergroup.com <sarterburn@therainmakergroup.com>

Sent: Friday, March 4, 2022 10:52 AM

To: Bricker, Robert < RBricker@howardcountymd.gov > Subject: RE: 5178 Ten Oaks Road B22000406-On Hold

[Note: This email originated from outside of the organization. Please only click on links or attachments if

you know the sender.]

Hi Robert:

I look forward to hearing from Jeff and Mike.

Can you forward me the email you are referring to? As you are aware (from all your field involvement), a lot has changed on this project since May of 2021. Because of that, is the email still applicable?

Thanks for following up.

Scott Arterburn, P.E. 443-829-9222 (cell)

From: Bricker, Robert < RBricker@howardcountymd.gov>

Sent: Friday, March 4, 2022 9:02 AM

To: Scott Arterburn < subject: RE: 5178 Ten Oaks Road_B22000406-On Hold

Thank you Scott,

I found email from May 2021 concerning the well sample issue and forwarded it to Jeff Williams and Michael Davis for their consideration.

Robert Bricker, REHS/RS, L.E.H.S. Environmental Sanitarian II Bureau of Environmental Health, Well and Septic Program 8930 Stanford Blvd., Columbia, MD 21045

Phone: (410)313-2691

Email: rbricker@howardcountymd.gov



CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

From: Scott Arterburn < sarterburn@therainmakergroup.com>

Sent: Thursday, March 3, 2022 4:29 PM

To: Bricker, Robert < RBricker@howardcountymd.gov> Subject: Re: 5178 Ten Oaks Road B22000406-On Hold

[Note: This email originated from outside of the organization. Please only click on links or attachments if

you know the sender.]

Dan from Freedom Septic just spoke with Susan. Sounds like they are working that out.

I look forward to hearing from you or Jeff tomorrow on the septic system final and the well water timing requirement.

Scott Arterburn Roosevelt Commons The Rainmaker Group 443-829-9222

On Mar 3, 2022, at 3:53 PM, Bricker, Robert RBricker@howardcountymd.gov wrote:

Good afternoon Scott.

We've had a round of discussion (internal) concerning the well and will revisit that issue again tomorrow. It is likely that myself or Jeff Williams will contact you afterwards. Regarding the issue of the abandonment of septic system components: we do not have a report of the abandonment and the attending inspector states that she did not witness the components being abandoned.

Robert Bricker, REHS/RS, L.E.H.S. Environmental Sanitarian II Bureau of Environmental Health, Well and Septic Program 8930 Stanford Blvd., Columbia, MD 21045 Phone: (410)313-2691

Email: rbricker@howardcountymd.gov



CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

From: sarterburn@therainmakergroup.com <sarterburn@therainmakergroup.com>

Sent: Wednesday, March 2, 2022 12:51 PM

To: Bricker, Robert < RBricker@howardcountymd.gov> **Subject:** RE: 5178 Ten Oaks Road B22000406-On Hold

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Good Afternoon Robert:

I haven't heard back from you regarding our emails of last Friday so wanted to follow-up.

Please let me know when we can speak so the issues you raised can be resolved and the project can move forward. Also, I do not believe I have ever met Mike Davis, but, since he placed the note in my file about water testing timing, I would like to speak with him and explain the status of this project.

Please advise how to proceed.

Thanks.

Scott Arterburn, P.E. 443-829-9222 (cell)

From: sarterburn@therainmakergroup.com <sarterburn@therainmakergroup.com>

Sent: Friday, February 25, 2022 5:29 PM

To: 'Bricker, Robert' < RBricker@howardcountymd.gov > Subject: RE: 5178 Ten Oaks Road_B22000406-On Hold

Robert:

I think a phone call would go a long way toward resolving the concerns you raised in your email. Can you please offer a couple of dates and times to discuss this?

In preparation for the call, I offer the following:

- I should start by saying the house not only has no running water, but it also has no plumbing whatsoever – it has all been torn out – so it cannot be used by anyone until the Certificate of Occupancy has been issued.
- All field work for the new septic system was completed on 2/9/22 by Freedom Septic, with the inspection of that work done during installation (by Susan).
- As Susan and I discussed during the installation, the house is not in a condition where the alarm and power to the new septic pump can be installed. These two items need to wait at least until the renovation is far enough along to have power in the correct location(s), the new electric service/panel completed and the appropriate breakers installed to support the new septic system. She was fine with this plan and we agreed I would contact her when the wiring, alarm, etc were installed and ready for final septic inspection. Until that occurred, the septic permit would remain open and the new system would not be fully approved.
- On 2/3/22, the old septic tank and dry well were pumped (the dry well was actually completely
 dry at that time). On 2/9/22, the old septic tank and dry well were collapsed and filled by
 Freedom as required and (I thought) inspected by Susan during her visit. The old sewage pipe
 from the house to the old septic tank has also been disconnected both inside and outside the
 house.
- I will submit the OSDS permit site plan to DILP as it shows the new septic system as designed and installed.
- I was unaware that I needed a well test prior to starting the renovation. The home has been vacant for nearly two years, so no sewage has been flowing from the house, the well is not operational, and the new septic system is now installed. As with all our other projects, I assumed I needed a passing well test prior to the issuance of the Certificate of Occupancy, not the issuance of a building permit. Please explain why that is needed now rather than as a mandatory item at the end. In fact, if for some reason the well that has been in existence for nearly 60 years is no longer satisfactory, there is a well box identified on the OSDS Plan where a new well could be drilled (even though the existing well meets all setback requirements from the new septic system).

Please let me know when you are available to discuss all this.

Thanks.

Scott Arterburn, P.E. 443-829-9222 (cell)

From: Bricker, Robert < RBricker@howardcountymd.gov>

Sent: Friday, February 25, 2022 4:39 PM **To:** sarterburn@therainmakergroup.com

Subject: 5178 Ten Oaks Road_B22000406-On Hold

Dear Mr Arterburn,

I have reviewed the submitted building permit application (B22000406) and Plot Plan for renovation proposed at 5178 Ten Oaks Road. I have assigned a status of 'On Hold' for the project as several issues must be resolved.

Illustration of the locations for the Septic Tank and the Pump Tank is required content for the Plot Plan. As these tanks' locations do not appear on the

submitted Plot Plan, the plan must be revised to include their locations. Submit the Plot Plan revision to the Department of Inspections, Licenses, and Permits.

Conducting a file review, I found a note had been placed in the file by our Bureau Director, Mike Davis, after he signed the Percolation Certification Plan. The note states a requirement for a well test before building permit approval. Water sample analyses results for nitrates, coliform bacteria, and E.coli are to be submitted to the Bureau of Environmental Health, Community Hygiene Program. As I am reviewing the building permit proposal, it is appropriate to copy me on the report. You may contract with a private lab to conduct the analyses, or you may contact the Community Hygiene Program at 410-313-1773 to schedule a sample date.

The Onsite Sewage Disposal System Permit has not been approved by the attending Environmental Sanitarian. The Pump and Alarm test for the pump components and function has not been completed. Another issue affecting approval of the OSDS Permit is that abandonment of the Septic Tank and Dry Well in the front of the house has either not been documented or has not been completed. The OSDS Permit must be approved by the attending Environmental Sanitarian before the building permit may be approved.

If you have questions concerning these requirements, you may contact me by 'Reply' to this email.

Robert Bricker, REHS/RS, L.E.H.S. Environmental Sanitarian II Bureau of Environmental Health, Well and Septic Program 8930 Stanford Blvd., Columbia, MD 21045

Phone: (410)313-2691

Email: rbricker@howardcountymd.gov



CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or

	copying this communication. If you have received this email in error, please notify the sender				
immediately and destroy the original transmission.					

Bricker, Robert

From:

Bricker, Robert

Sent: To: Friday, February 25, 2022 4:39 PM sarterburn@therainmakergroup.com

Subject:

5178 Ten Oaks Road_B22000406-On Hold

Dear Mr Arterburn,

I have reviewed the submitted building permit application (B22000406) and Plot Plan for renovation proposed at 5178 Ten Oaks Road. I have assigned a status of 'On Hold' for the project as several issues must be resolved.

Illustration of the locations for the Septic Tank and the Pump Tank is required content for the Plot Plan. As these tanks' locations do not appear on the submitted Plot Plan, the plan must be revised to include their locations. Submit the Plot Plan revision to the Department of Inspections, Licenses, and Permits.

Conducting a file review, I found a note had been placed in the file by our Bureau Director, Mike Davis, after he signed the Percolation Certification Plan. The note states a requirement for a well test before building permit approval. Water sample analyses results for nitrates, coliform bacteria, and E.coli are to be submitted to the Bureau of Environmental Health, Community Hygiene Program. As I am reviewing the building permit proposal, it is appropriate to copy me on the report. You may contract with a private lab to conduct the analyses, or you may contact the Community Hygiene Program at 410-313-1773 to schedule a sample date.

The Onsite Sewage Disposal System Permit has not been approved by the attending Environmental Sanitarian. The Pump and Alarm test for the pump components and function has not been completed. Another issue affecting approval of the OSDS Permit is that abandonment of the Septic Tank and Dry Well in the front of the house has either not been documented or has not been completed. The OSDS Permit must be approved by the attending Environmental Sanitarian before the building permit may be approved.

If you have questions concerning these requirements, you may contact me by 'Reply' to this email.

Robert Bricker, REHS/RS, L.E.H.S. Environmental Sanitarian II Bureau of Environmental Health, Well and Septic Program 8930 Stanford Blvd., Columbia, MD 21045

Phone: (410)313-2691