



Howard County
Health Department

Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045

Main: 410-313-2640 | Fax: 410-313-2648

TDD 410-313-2323 | Toll Free 1-866-313-6300

www.hchealth.org

Facebook: www.facebook.com/hocohealth

Maura J. Rossman, M.D., Health Officer

RECEIPT DATE: 3/13/23

ONSITE SEWAGE DISPOSAL SYSTEM

P 574027

INSTALLATION

APPROVAL DATE: 3/22/23

PERMIT

A Repair

MINOR REPAIR

PROPERTY ADDRESS: 1210 Sugar Maple Drive

SUBDIVISION: _____ LOT: _____ TAX ID: _____

CONTRACTOR: Singh Sugar Maple Farm LLC. EMAIL: _____

CONTRACTOR ADDRESS: 1210 Sugar Maple Drive, Marriottsville, MD 21104 PHONE: 443-413-2252

PROPERTY OWNER: Singh Sugar Maple Farm LLC. EMAIL: _____

OWNER ADDRESS: 1210 Sugar Maple Drive, Marriottsville, MD 21104 PHONE: _____

NUMBER OF BEDROOMS: 4 SEPTIC TANK SIZE: _____ DRAINFIELD SIZE/TYPE: N/A

LOCATION:	constructed sewer line from the barn to run it to connect to septic system for tenant house (1210 Sugar Maple Dr.) (done w/out a permit)
NOTES:	Expose the sewer line from the barn to the tie in with the septic system for the tenant house. Ask if this is a new sewer line or was it installed to replace an already existing sewer line.

ISSUED BY: R. Rappaport ISSUE DATE: 3/15/23 EXPIRATION DATE: 3/15/24

NOTE: CONTRACTOR MUST SCHEDULE AN INSPECTION AND GAIN APPROVAL OF ALL COMPONENTS PRIOR TO COVERING

NOTE: AN ELECTRICAL PERMIT IS REQUIRED FOR INSTALLATION OF ANY ELECTRICAL COMPONENTS OF THE SYSTEM


NOTE: MDE RECOMMENDS SEPTIC TANKS, BAT, AND OTHER PRETREATMENT UNITS BE PUMPED AT A FREQUENCY ADEQUATE TO ENSURE THAT SOLIDS ARE NOT DISCHARGED TO THE DISPOSAL AREA

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM.

PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT.

CALL 410-313-1771 FOR INSPECTION OF SEPTIC SYSTEM.

NOT TO SCALE



TRENCH/DRAINFIELD DATA

WIDTH _____ INLET _____ BOTTOM _____

NUMBER OF TRENCHES _____

TOTAL LENGTH _____

ABSORPTION AREA _____

DISTRIBUTION BOX LEVEL _____

DISTRIBUTION BOX BAFFLE _____

DISTRIBUTION BOX PORT _____

SEPTIC TANK DATA

SEPTIC TANK 1 LEVEL _____

MANUFACTURER _____

CAPACITY _____ GAL

SEAM LOC _____

TANK LID DEPTH _____

BAFFLES _____

BAFFLE FILTER _____

MANHOLE LOC _____

6" PORT LOC _____

WATERTIGHT TEST _____

SLOTTED _____

DATE ON LID _____

PUMP/SEPTIC TANK LEVEL _____

MANUFACTURER _____

CAPACITY _____ GAL

SEAM LOC _____

TANK LID DEPTH _____

BAFFLES _____

BAFFLE FILTER _____

MANHOLE LOC _____

6" PORT LOC _____

WATERTIGHT TEST _____

SLOTTED _____

DATE ON LID _____

(NOTE FOR FILE)

* * If any future building permits for renovations to 1210 Sugar Maple (the tenant house) and/or the barn are submitted, the HD will need to do a complete SEPTIC EVALUATION since there is currently one septic system serving two buildings. (RE)

INSTALLATION: 3/17/23 - gps'd irrigation well & pit well (barn), inspected sewer line from barn to septic tank, 4" pvc, 181' and only one c/o near the structure, line tied into sewer line for tenant house. (RE) 3/22/23 - 2 c/o's were added to the sewer line from the barn. (RE)

NOTE: This new PVC pipe replaced an exist. terra cotta pipe that collapsed, and it was tied into the septic system for the tenant house (1210 Sugar Maple). This connection was never approved by the HD. (there was never a permit pulled) (from the barn to the tenant septic system). HD has no record of its installation. (RE)

FINAL INSPECTOR R. Rappaport DATE OF APPROVAL 3/22/23

3/17/23 line from barn to tenant house septic tank



3/17/23



3/17/23



3/17/23



RECEIPT

Howard County, MD
HOWARD COUNTY HEALTH DEPARTMENT
ASCEND ONE BUILDING
Columbia, MD 21045
8930 STANFORD BLVD

Application: WS-SP-APP-23-00054

Application Type: EnvHealth/Well and Septic/Sewage Disposal System/Application

Address: 1210 Sugar Maple DR, Marriottsville, MD 21104

Receipt No.	6039					
Payment Method	Ref Number	Amount Paid	Payment Date	Cashier ID	Received	Comments
Credit Card		\$55.00	03/13/2023	VDEKRONY		

Owner Info.: Singh Sugar Maple Farm, LLC
1210 Sugar Maple Drive
Marriottsville, MD 21104

Work Description:

Maura J. Rossman, M.D., Health Officer

INFORMATION FORM - SEPTIC SYSTEM REPAIR/UPGRADE

Reason for Request:

- ☐ Failing System
☐ System relocation for proposed addition
☒ System upgrade for proposed addition
☐ Inadequate treatment zone
☐ Collapsed septic tank
☐ Collapsed drywell

Existing system design

- ☐ Drywell
☐ Trench
☐ Mound
☐ Unknown
☐ Other: _____

Is discharge surfacing on the ground?

___ Yes
___ No

Additional Comments:

Expose the line from (Tie in)

Has the septic tank been pumped within the last month?

___ Yes Date pumped: _____
___ No

Was a visual inspection of the septic tank and/or drain fields conducted?

___ Yes Explain observation: _____
___ No

Was a visual inspection of the sewage line conducted?

___ Yes
___ No

Blockage Leading to the field

___ Yes Explain _____
___ No

*For REPAIRS, are the owners proposing, or do they plan to add in the future any additions or modifications to the property, i.e. pools, living space additions, garages, etc? This information must be disclosed at the time of this application. The Health Department will not be able to accommodate requests in the field for property modifications unrelated to the repair request. Such requests may require an additional fee, testing, and submittal of a Percolation Certification Plan, if the property does not meet current Code and Regulations.

Septic Contractor: SELF

Contractor's Phone: 443-413-2252

Contractor's Address: _____

Property Address: 1210 Sugar Maple Drive

County File: HOWARD COUNTY

Subdivision: MARLBOROUGH, MD 21104

Lot: _____ Year Built: _____

Owner's Name: SINGH SUGAR MAPLE FARM, LLC

Existing bedrooms: 4

Name of previous owners: _____

Existing bedrooms: _____

Kousman - Lijl

Proposed bedrooms: _____

*A Sanitarian will be in contact within three business days, depending upon the urgency of the situation, to coordinate the scheduling/review of the repair or upgrade.

Prior to scheduling inspections, scaled plans should be submitted to clarify the nature of the addition.

Print out a copy of Real Property Data via Dept. of Taxation website _____ Indexed file found _____

If soil/site conditions are limited and sewer and/or Metro District status is not conducive to connection, the Sanitarian may recommend pursuit of Emergency Sewer Extension or Emergency Metro District Inclusion. The Owner should contact the Bureau of Utilities for details.

No permit is to be issued nor inspection to be scheduled without prior fee collection at the office unless an emergency exists.

The contractor is to notify the office of the emergency as soon as possible.

2/2020

Rappaport, Ryan

From: Harsimran singh <harrysingh09@hotmail.com>
Sent: Thursday, March 16, 2023 3:17 PM
To: Rappaport, Ryan
Cc: Davis, Michael J; Williams, Jeffrey; Williams, Jeffrey; Wolf, Kevin; Wolf, Kevin; Silvast, Zackary; Silvast, Zackary; Isaacs, Joel; Isaacs, Joel; Page, Shepsura; Page, Shepsura
Subject: Fw: Health Dept - requirements associated with wells and septic systems on the property

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Hello Mr Rappaport,

Please call me as i have left several messages on your voice and have emailed you informing that as per your instructions, we did get the Minor septic permit and have further questions for you.

My contact number is the same 443-413-2252 Harry Singh

In addition, answer to your 3rd -instruction listed below new structure: Answer is yes, that pre made moveable structure's sole purpose is to be only used as a water pumping and distribution for farming irrigation purposes.

Regards,
Harry Singh, president, Singh Sugar Maple Farm, LLC

From: Rappaport, Ryan <RRappaport@howardcountymd.gov>
Sent: Thursday, February 23, 2023 3:26 PM
To: Harsimran singh <harrysingh09@hotmail.com>
Cc: Davis, Michael J <mjdavis@howardcountymd.gov>; Williams, Jeffrey <jewilliams@howardcountymd.gov>; Wolf, Kevin <KWolf@howardcountymd.gov>; Silvast, Zackary <zsilvast@howardcountymd.gov>; Isaacs, Joel <jisaacs@howardcountymd.gov>; Page, Shepsura <spage@howardcountymd.gov>
Subject: Health Dept - requirements associated with wells and septic systems on the property

Hello Mr. Singh,

To summarize what we discussed on the phone, here are the requirements from our office;

1. Apply for a minor septic permit, with our office, for the barn (the building with the kitchen and bathroom renovations) and expose the line from the barn to the tie in to the septic system for the tenant house. The Health Dept will need to evaluate/inspect this work. Depending on the results of this inspection once the line is exposed, we'll be able to determine if that one septic system is serving two buildings and move forward from there.
2. It is in your best interest and the interest of the people moving into that barn, to have potability water testing completed for that pit well (bacteria, nitrates, turbidity and sand).
3. In regards to the new structure which is housing the pumping equipment for the recently drilled irrigation well, submit a written statement stating that the sole purpose of the building is to house the well pumping equipment. The letter will allow for the approval of a well closer than 30 feet to a building foundation.

Please let me know if you have any questions or concerns.

Rappaport, Ryan

To: Harsimran singh
Cc: Davis, Michael J; Williams, Jeffrey; Wolf, Kevin; Silvast, Zackary; Isaacs, Joel; Page, Shepsura
Subject: Health Dept - requirements associated with wells and septic systems on the property

Hello Mr. Singh,

To summarize what we discussed on the phone, here are the requirements needed by our office;


1. Pull a minor septic permit with our office for the barn (the building with the kitchen and bathroom renovations) and expose the line from the barn to the tie in to the septic system for the tenant house. The Health Dept will need to evaluate/inspect this work. Depending on the results of this inspection once the line is exposed, we'll be able to determine if that one septic system is serving two buildings and move forward from there.
2. It is in your best interest and the interest of the people moving into that barn, to have potability water testing completed for that pit well (bacteria, nitrates, turbidity and sand).
3. In regards to the new structure which is housing the pumping equipment for the new irrigation well, please submit a written statement referencing the Maryland State well regulations

Ryan Rappaport, LEHS
Bureau of Environmental Health
Howard County Health Department
8930 Stanford Blvd.
Columbia, MD. 21045
Phone 410-313-1781
Fax 410-313-2648
www.co.ho.md.us



the

DISCLAIMER: This e-mail is intended only for the individual to whom it is addressed. It may be used only in accordance with applicable laws. If you are not the intended recipient, you are strictly prohibited from reading, disseminating, distributing, or copying this message. If you received this e-mail by mistake, please notify the sender and destroy this e-mail





Rappaport, Ryan

From: Rappaport, Ryan
Sent: Tuesday, January 31, 2023 11:54 AM
To: Davis, Michael J
Subject: FW: 1200 Sugar Maple Dr.

My initial email went to the building tech who responded to me. See below. I just didn't want you to be blindsided when Jeff brings it up tomorrow.

Thanks

From: Huskins, Thomas
Sent: Monday, January 30, 2023 9:52 AM
To: Rappaport, Ryan <RRappaport@howardcountymd.gov>; BuildingTech <buildingtech@howardcountymd.gov>
Cc: Wolf, Kevin <KWolf@howardcountymd.gov>; Page, Shepsura <spage@howardcountymd.gov>; Silvast, Zackary <zsilvast@howardcountymd.gov>; Blotzer, William <wblotzer@howardcountymd.gov>; Marshall, Rodney <romarshall@howardcountymd.gov>; Smith, Darrell <jasmith@howardcountymd.gov>; Self, Lloyd <lself@howardcountymd.gov>
Subject: RE: 1200 Sugar Maple Dr.

Ryan,

The barn is not new, it has been there for decades and according to the owner it had already contained ranch hand living quarters. The building had been neglected and was becoming run down so the owner decided to fix it up and return it to what he claimed was it's former use. Inspector Marshall found no evidence to contradict the owner's claim. It appeared that drywall and flooring were being replaced and new cabinets and fixtures were being installed in the existing kitchen and bathroom. There was an old well adjacent to the structure that appeared to have, at one time, served the living quarters. From inspector Marshall's discussion with the owner and the visible evidence at the time, it was determined that the work being performed did not need a building permit, only plumbing and electric permits would be required and have since been obtained.

We don't require a building permit for well and septic or for irrigation systems. My guess is the shed you referred to, housing the pump and tank, is probably under 200 sq. ft. and would not require a permit and with this property being zoned agricultural we wouldn't require a building permit for any barn(shed) type structure that is being used to house animals or equipment related to the operation of the farm.

So, before you accuse DILP of not being diligent in their investigation, perhaps you and the Health Dept. would do well to stay in your lane. You concern yourself with well and septic and we'll concern ourselves with illegal structures.

Tom

Thomas Huskins
Chief, Inspections and Enforcement Division
Department of Inspections, Licenses and Permits
7125 Riverwood Drive, Suite D2
Columbia, MD 21046
410-313-1801
thuskins@howardcountymd.gov

From: Rappaport, Ryan <RRappaport@howardcountymd.gov>
Sent: Monday, January 30, 2023 8:20 AM

To: BuildingTech <buildingtech@howardcountymd.gov>

Cc: Wolf, Kevin <KWolf@howardcountymd.gov>; Page, Shepsura <spage@howardcountymd.gov>; Silvast, Zackary <zsilvast@howardcountymd.gov>; Huskins, Thomas <thuskins@howardcountymd.gov>; Blotzer, William <wblotzer@howardcountymd.gov>; Marshall, Rodney <romarshall@howardcountymd.gov>; Smith, Darrell <jasmith@howardcountymd.gov>

Subject: RE: 1200 Sugar Maple Dr.

Thanks for the reply Lisa, I appreciate the response. This property owner has attempted to install numerous items without the proper permits. The property owner connected a new dwelling (a barn on the property) to an old pit well and to the septic system for another house on the property. All of this work was completed without the proper permits. Rod Marshall completed an inspection in August and noted that all they were doing was installing new drywall, cabinets and flooring, so no permit was needed for the work in the barn. However, the property owner installed a kitchen and bathroom and connected this new dwelling to a well and septic system. The Health Dept never received a building permit from your office for review. The Health Dept is currently waiting on a reply from Tom Huskins regarding the building permits for all this work. The most recent incident of work without a permit is the plumbing and electrical work completed on the new irrigation well that was installed in 2022. It may be in DILP's best interest to investigate this property more closely to see if the proper electrical and plumbing permits were pulled. Thanks again for the help.

Ryan

From: BuildingTech

Sent: Friday, January 27, 2023 3:59 PM

To: Rappaport, Ryan <RRappaport@howardcountymd.gov>

Cc: Wolf, Kevin <KWolf@howardcountymd.gov>; Page, Shepsura <spage@howardcountymd.gov>

Subject: RE: 1200 Sugar Maple Dr.

Good afternoon Ryan,

All electric work requires a permit. So yes. I am going to forward this information to my supervisor and inspections.

Thank you,

Lisa Logan-Roussell

Regulation Support Technician II

Department of Inspections, Licenses, and Permits

Howard County Maryland

****WHEN REPLYING TO THIS E-MAIL, PLEASE "REPLY ALL"****

For general inquiries, please email buildingtech@howardcountymd.gov to ensure a prompt response by all technicians

****to check the status of a permit or to pay on line <https://dilp.howardcountymd.gov/CitizenAccess/Default.aspx> ****

To request a Use and Occupancy Certificate, please email uo@howardcountymd.gov

From: Rappaport, Ryan <RRappaport@howardcountymd.gov>

Sent: Wednesday, January 18, 2023 10:11 AM

To: BuildingTech <buildingtech@howardcountymd.gov>

Cc: Wolf, Kevin <KWolf@howardcountymd.gov>; Page, Shepsura <spage@howardcountymd.gov>

Subject: 1200 Sugar Maple Dr.

Hello, Health inspected a newly drilled agricultural well at this property and found that they dropped a concrete slab and put a shed on it to house the electrical components and pressure tank. The electrical line has been run to one of the SFD on

the property. I didn't see any electrical permits for this work, are they required to have one? Also, do they need a permit to place a shed onsite?

Ryan Rappaport, LEHS
Bureau of Environmental Health
Howard County Health Department
8930 Stanford Blvd.
Columbia, MD. 21045
Phone 410-313-1781
Fax 410-313-2648
www.co.ho.md.us



DISCLAIMER: This e-mail is intended only for the individual to whom it is addressed. It may be used only in accordance with applicable laws. If you are not the intended recipient, you are strictly prohibited from reading, disseminating, distributing, or copying this message. If you received this e-mail by mistake, please notify the sender and destroy this e-mail.

Silvast, Zackary

From: Isaacs, Joel
Sent: Thursday, December 1, 2022 3:29 PM
To: Silvast, Zackary
Cc: Isaacs, Joel; Smith, Darrell
Subject: FW: 1200 Sugar Maple Dr - unlicensed renovations at property
Attachments: 1.jpg; 2.jpg; 3.jpg; 4.jpg; 5.jpg

Afternoon,
To follow up with our phone call. The attached is the email and photos that started this whole process.
Thanks,

Joel Isaacs

Plumbing & Mechanical Inspector
Inspections and Enforcement
7125 Riverwood Drive, Suite D2
Columbia, MD 21046
410 313-1842
Fax: 410 313-1861

From: Huskins, Thomas <thuskins@howardcountymd.gov>
Sent: Monday, July 18, 2022 10:23 AM
To: Blotzer, William <wblotzer@howardcountymd.gov>; Smith, Darrell <jasmith@howardcountymd.gov>; Self, Lloyd <lself@howardcountymd.gov>
Cc: Schmidt, Heather <hschmidt@howardcountymd.gov>
Subject: FW: 1200 Sugar Maple Dr - unlicensed renovations at property

Another one:

Please see attached email from heath dept, set up complaints and all trades go to site at the same time.

Thanks,

Tom

Thomas Huskins
Chief, Inspections and Enforcement Division
Department of Inspections, Licenses and Permits
7125 Riverwood Drive, Suite D2
Columbia, MD 21046
410-313-1801
thuskins@howardcountymd.gov

From: Rappaport, Ryan <RRappaport@howardcountymd.gov>
Sent: Monday, July 18, 2022 9:39 AM
To: BuildingTech <buildingtech@howardcountymd.gov>
Cc: Huskins, Thomas <thuskins@howardcountymd.gov>; Powell, Markus P. <mpowell@howardcountymd.gov>; Wolf,

Kevin <KWolf@howardcountymd.gov>; Cabahug, Joseph <jcabahug@howardcountymd.gov>

Subject: 1200 Sugar Maple Dr - unlicensed renovations at property

Hello, I'm reviewing a well permit for this property and met with the homeowner last week. While siting the well location, I found what is supposed to be an irrigation well. The HD has no record of this well or any septic system associated with this particular building/barn. It appears to have recently been connected to the building/barn on the property which is having a kitchen and bathroom installed. There is no record in DILP accelera or here at the Health Dept related to the building/renovations to this barn.

The building with the new kitchen and bathroom and no septic system is the barn on the east side of the property. See building construction pics attached. Would it be possible for you to open an investigation and see if you can get him to permit this work? The HD will also need to review it for well and septic but was hoping you could get involved as well. Thanks.

The homeowner's name and info: Harry Singh 443-413-2252 harrysingh09@hotmail.com.

Ryan Rappaport, LEHS
Howard County Health Department
Bureau of Environmental Health
8930 Stanford Blvd.
Columbia, MD. 21045
Phone 410-313-1781
Fax 410-313-2648
rrappaport@howardcountymd.gov
www.co.ho.md.us



CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

Silvast, Zackary

From: Silvast, Zackary
Sent: Monday, December 5, 2022 5:48 PM
To: Williams, Jeffrey
Cc: Wolf, Kevin; Rappaport, Ryan
Subject: Re: regarding 1200 Sugar Maple Lane (illegal septic)

Ok, sounds good.

Get [Outlook for Android](#)

From: Williams, Jeffrey <jewilliams@howardcountymd.gov>
Sent: Monday, December 5, 2022 3:53:26 PM
To: Silvast, Zackary <zsilvast@howardcountymd.gov>
Cc: Wolf, Kevin <KWolf@howardcountymd.gov>; Rappaport, Ryan <RRappaport@howardcountymd.gov>
Subject: RE: regarding 1200 Sugar Maple Lane (illegal septic)

Let's discuss tomorrow before sending anything out. I'll need to refresh my memory from our conversation last week

From: Silvast, Zackary <zsilvast@howardcountymd.gov>
Sent: Monday, December 5, 2022 2:33 PM
To: Williams, Jeffrey <jewilliams@howardcountymd.gov>
Cc: Wolf, Kevin <KWolf@howardcountymd.gov>; Rappaport, Ryan <RRappaport@howardcountymd.gov>
Subject: regarding 1200 Sugar Maple Lane (illegal septic)

Jeff,

I spoke with Ryan today. There is not a current RH or building permit. SO I think we need to hold them to the illegal septic system tie in, maybe generate an internal N.O.V. to get something in motion. I still have not sent the e-mail out to respond to Isaacs phone call regarding "what is the HD going to do about this?"

I was going to send out a very generic response, stating that there is nothing from DPZ that requires a review from the HD for the subject property. But we are handling things internally, separate from all other agencies, regarding the illegal septic system.

I think that should be enough, let me know if anyone else has any input? Thank you.

- ZS

Zack Silvast (LEHS)

Plan Review Supervisor - Water & Sewer Division
410-313-1777

Environmental Health Bureau
Howard County Health Department

connected this new dwelling to a well and septic system. The Health Dept never received a building permit from your office for review. The Health Dept is currently waiting on a reply from Tom Huskins regarding the building permits for all this work. The most recent incident of work without a permit is the plumbing and electrical work completed on the new irrigation well that was installed in 2022. It may be in DILP's best interest to investigate this property more closely to see if the proper electrical and plumbing permits were pulled. Thanks again for the help.

Ryan

From: BuildingTech

Sent: Friday, January 27, 2023 3:59 PM

To: Rappaport, Ryan <RRappaport@howardcountymd.gov>

Cc: Wolf, Kevin <KWolf@howardcountymd.gov>; Page, Shepsura <spage@howardcountymd.gov>

Subject: RE: 1200 Sugar Maple Dr.

Good afternoon Ryan,

All electric work requires a permit. So yes. I am going to forward this information to my supervisor and inspections. Thank you,

Lisa Logan-Roussell

Regulation Support Technician II

Department of Inspections, Licenses, and Permits

Howard County Maryland

****WHEN REPLYING TO THIS E-MAIL, PLEASE "REPLY ALL"****

For general inquiries, please email buildingtech@howardcountymd.gov to ensure a prompt response by all technicians

****to check the status of a permit or to pay on line <https://dilp.howardcountymd.gov/CitizenAccess/Default.aspx> ****

To request a Use and Occupancy Certificate, please email uo@howardcountymd.gov

From: Rappaport, Ryan <RRappaport@howardcountymd.gov>

Sent: Wednesday, January 18, 2023 10:11 AM

To: BuildingTech <buildingtech@howardcountymd.gov>

Cc: Wolf, Kevin <KWolf@howardcountymd.gov>; Page, Shepsura <spage@howardcountymd.gov>

Subject: 1200 Sugar Maple Dr.

Hello, Health inspected a newly drilled agricultural well at this property and found that they dropped a concrete slab and put a shed on it to house the electrical components and pressure tank. The electrical line has been run to one of the SFD on the property. I didn't see any electrical permits for this work, are they required to have one? Also, do they need a permit to place a shed onsite?

Ryan Rappaport, LEHS
Bureau of Environmental Health
Howard County Health Department
8930 Stanford Blvd.
Columbia, MD. 21045
Phone 410-313-1781
Fax 410-313-2648
www.co.ho.md.us



DISCLAIMER: This e-mail is intended only for the individual to whom it is addressed. It may be used only in accordance with applicable laws. If you are not the intended recipient, you are strictly prohibited from reading, disseminating, distributing, or copying this message. If you received this e-mail by mistake, please notify the sender and destroy this e-mail

Silvast, Zackary

From: Huskins, Thomas
Sent: Monday, January 30, 2023 9:52 AM
To: Rappaport, Ryan; BuildingTech
Cc: Wolf, Kevin; Page, Shepsura; Silvast, Zackary; Blotzer, William; Marshall, Rodney; Smith, Darrell; Self, Lloyd
Subject: RE: 1200 Sugar Maple Dr.

Ryan,

The barn is not new, it has been there for decades and according to the owner it had already contained ranch hand living quarters. The building had been neglected and was becoming run down so the owner decided to fix it up and return it to what he claimed was it's former use. Inspector Marshall found no evidence to contradict the owner's claim. It appeared that drywall and flooring were being replaced and new cabinets and fixtures were being installed in the existing kitchen and bathroom. There was an old well adjacent to the structure that appeared to have, at one time, served the living quarters. From inspector Marshall's discussion with the owner and the visible evidence at the time, it was determined that the work being performed did not need a building permit, only plumbing and electric permits would be required and have since been obtained.

We don't require a building permit for well and septic or for irrigation systems. My guess is the shed you referred to, housing the pump and tank, is probably under 200 sq. ft. and would not require a permit and with this property being zoned agricultural we wouldn't require a building permit for any barn(shed) type structure that is being used to house animals or equipment related to the operation of the farm.

So, before you accuse DILP of not being diligent in their investigation, perhaps you and the Health Dept. would do well to stay in your lane. You concern yourself with well and septic and we'll concern ourselves with illegal structures.

Tom

Thomas Huskins

Chief, Inspections and Enforcement Division
Department of Inspections, Licenses and Permits
7125 Riverwood Drive, Suite D2
Columbia, MD 21046
410-313-1801
thuskins@howardcountymd.gov

From: Rappaport, Ryan <RRappaport@howardcountymd.gov>
Sent: Monday, January 30, 2023 8:20 AM
To: BuildingTech <buildingtech@howardcountymd.gov>
Cc: Wolf, Kevin <KWolf@howardcountymd.gov>; Page, Shepsura <spage@howardcountymd.gov>; Silvast, Zackary <zsilvast@howardcountymd.gov>; Huskins, Thomas <thuskins@howardcountymd.gov>; Blotzer, William <wblotzer@howardcountymd.gov>; Marshall, Rodney <romarshall@howardcountymd.gov>; Smith, Darrell <jasmith@howardcountymd.gov>
Subject: RE: 1200 Sugar Maple Dr.

Thanks for the reply Lisa, I appreciate the response. This property owner has attempted to install numerous items without the proper permits. The property owner connected a new dwelling (a barn on the property) to an old pit well and to the septic system for another house on the property. All of this work was completed without the proper permits. Rod Marshall completed an inspection in August and noted that all they were doing was installing new drywall, cabinets and flooring, so no permit was needed for the work in the barn. However, the property owner installed a kitchen and bathroom and

7/12/22



Feb 2/14/23



2/24/23





2/14/23

2/14/23



1200 Sugar Maple - site insp. 7/12/22





7/12/22

7/12/22



1200 Sugar Maple



7/12/22 - well
site insp.

7/12/22



1200 Sugar Maple Drive – electrical work for agricultural well 1/17/2023





TAURUS
ENTERPRISES, INC.

SPECIALIZING
IN CUSTOM HOMES

September 28, 2015

Howard County
8930 Stanford Blvd.
Columbia, MD 21045

To Whom It May Concern:

This is a request for waiver for the property located at 1266 Sugar Maple Drive, Marriottsville, Maryland 21104. The owners are proposing construction of a garage that will be located outside any future septic repairs and readily meets the se-back requirements. Included is the original permitting information and a site plan showing the future structure.

Regards,

Adam Ward

12/7/15
Approved
m. J. J. J.



HOWARD COUNTY HEALTH DEPARTMENT

74027

DATE 3/13/23

Received From

PHONE #

☐ CASH
☐ CHECK

NO.

For

Dollars

\$

Received By



HOWARD COUNTY HEALTH DEPARTMENT

7402

DATE 3/13/23

p5

Received From

Singh Sugar Maple Farm LLC

PHONE #

☐ CASH
☐ CHECK

NO. CC

For

Minor Repair - 1240 Sugar Maple Drive

Fifty five

00/100

Dollars

\$ 55.00

Received By

[Signature]