

CASELL TESTING, INC.

ENVIRONMENTAL SAMPLING AND TESTING
10940 BEAVER DAM ROAD, HUNT VALLEY, MD 21030-2211
(410) 252-7742

REPORT DATE: Aug 4, 2004

County Howard

Lab Number 04-3963

Sample iced Yes

Residual Cl₂ <0.1 mg/L Yes

cc: County Health Dept. Yes

CERTIFICATE OF ANALYSIS

Maryland State Certified Water Quality
Laboratory No. 115

REQUESTER: Dale Thompson Builders
6300 Woodside Court
Columbia, Maryland 21046

Property Sampled: U&D: 7004 Meandering Stream Way

Station Sampled: Basement bath & Pressure tank taps

Tax Map #: 41

Date/Time Sampled: Aug 3, 2004 12:55 pm

Parcel #: 274

Owner, Telephone No.: Diggins

Sampler: 67246P

Subdivision Name: Pindell Woods

Lot Number: 44

Building Permit No.: B00143001

Well Number: HD-94-300B

Observation: 2-Piece Cap
Cap tight
Conduit too short
to fit into cap

RESULTS OF ANALYSIS:

PARAMETER	RESULT	METHOD	*MCL/**SMCL	
Nitrate	<1.0 mg/L as N	SM 4500D	*10 mg/L as N	Pass
Nitrate	1.3 mg/L as N	SM 4500D	*10 mg/L as N	Pass
pH	5.0 Units	EPA 150.1	**6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	PRESENT	SM 9223B	*Absent	UNSAFE
E. coli (18 Hour Test)	Absent			

Treatment/Conditioning: Sediment filter

***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, odor, or color) in drinking water.

Heather R. Beam

Heather R. Beam

*MCL = Maximum Contamination Level

**SMCL = Secondary Maximum Contamination Level

CASSELL TESTING, INC.

ENVIRONMENTAL SAMPLING AND TESTING
10940 BEAVER DAM ROAD, HUNT VALLEY, MD 21030-2211
(410) 252-7742

RECEIVED
HOWARD COUNTY
EXPERIMENTAL
ES: F HA ES UA 1005

REPORT DATE: Aug 12, 2004

County Howard

Lab Number 04-4205

Sample iced Yes

Residual Cl₂ <0.1 mg/L Yes

cc: County Health Dept. Yes

CERTIFICATE OF ANALYSIS

Maryland State Certified Water Quality
Laboratory No. 115

REQUESTER: Dale Thompson Builders
6300 Woodside Court
Columbia, Maryland 21046

Property Sampled: U&D; 7004 Meandering Stream Way, Retest #1

Station Sampled: Basement Bathroom Tap

Tax Map #: 41

Date/Time Sampled: Aug 11, 2004 12:00 n

Parcel #: 274

Owner, Telephone No.: Diggins

Sampler: 6724GP

Subdivision Name: Pindell Woods

Lot Number: 44

Building Permit No.: B00143001

Well Number: HD-94-3008

Observation: 2-Piece Cap
Satisfactory

RESULTS OF ANALYSIS:

PARAMETER	RESULT	METHOD	*MCL/**SMCL	
Total Coliform	PRESENT	SM 9223B	*Absent	UNSAFE
E. coli	Absent			



Treatment/Conditioning: Sediment filter - Filter Out

Heather R. Beam

Heather R. Beam

*MCL = Maximum Contamination Level
**SMCL = Secondary Maximum Contamination Level

CASSELL TESTING, INC.

ENVIRONMENTAL SAMPLING AND TESTING
10940 BEAVER DAM ROAD, HUNT VALLEY, MD 21030-2211
(410) 252-7742

RECEIVED
HOWARD COUNTY HEALTH DEPT
ENVIRONMENTAL HEALTH
3000 VA 8S UA JOOS

REPORT DATE: Aug 19, 2004

County Howard

Lab Number 04-4396

Sample iced Yes

Residual Cl₂ <0.1 mg/L Yes

cc: County Health Dept. Yes

CERTIFICATE OF ANALYSIS

Maryland State Certified Water Quality
Laboratory No. 115

REQUESTER: Dale Thompson Builders
6300 Woodside Court
Columbia, Maryland 21046

Property Sampled: U&D: 7004 Meandering Stream Way, retest #2

Station Sampled: Basement Bathroom Tap

Tax Map #: 41

Date/Time Sampled: Aug 18, 2004 11:25 am

Parcel #: 274

Owner, Telephone No.: Diggins

Sampler: 6724GP

Subdivision Name: Pindell Woods

Lot Number: 44

Building Permit No.: B00143001

Well Number: HO-94-3008

Observation: 2-Piece Cap
Satisfactory

RESULTS OF ANALYSIS:

PARAMETER	RESULT	METHOD	*MCL/**SMCL	
Total Coliform	Absent	SM 9223B	*Absent	SAFE
E. coli	Absent	SM 9223B	*Absent	SAFE



Treatment/Conditioning: Sediment filter - Filter Out

Heather R. Beam

Heather R. Beam

*MCL = Maximum Contamination Level
**SMCL = Secondary Maximum Contamination Level