

ASSELL TESTING, INC.

ENVIRONMENTAL SAMPLING AND TESTING
10940 BEAVER DAM ROAD, HUNT VALLEY, MD 21030-2211
(410) 252-7742

REPORT DATE: Dec 12, 2003

County Howard

Lab Number 03-7215

Sample iced Yes
Residual Cl₂ <0.1 mg/L Yes

cc: County Health Dept. Yes

CERTIFICATE OF ANALYSIS

Maryland State Certified Water Quality
Laboratory No. 115

REQUESTER: Williamsburg Group LLC
P.O. Box 1018
Columbia, Maryland 21044
Attn: Accounts Receivable

Property Sampled: U&O: 3416 Shady Lane

Station Sampled: Bathroom Tap in Back Bedroom

Date/Time Sampled: Dec 11, 2003 10:25 am

Owner, Telephone No.:

Subdivision Name:

Building Permit No.: B00141797

Well Number: HQ-94-3598

Tax Map #:

Parcel #:

Sampler: 67246P

Lot Number:

Observation: 2-Piece Cap
Satisfactory

RESULTS OF ANALYSIS:

PARAMETER	RESULT	METHOD	*MCL/**SMCL	
Nitrate	<1.0 mg/L as N	SM 4500D	*10 mg/L as N	Pass
Turbidity	72.9 NTU	EPA 180.1	*10 NTU	HIGH
pH	7.4 Units	EPA 150.1	**6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	PRESENT	SM 9223B	*Absent	UNSAFE
E. coli (18 Hour Test)	Absent			

Treatment/Conditioning: None

***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, odor, or color) in drinking water.

Heather R. Beam

Heather R. Beam

*MCL = Maximum Contamination Level

**SMCL = Secondary Maximum Contamination Level

CASELL TESTING, INC.

ENVIRONMENTAL SAMPLING AND TESTING
10940 BEAVER DAM ROAD, HUNT VALLEY, MD 21030-2211
(410) 252-7742

REPORT DATE: Jan 1, 2004

County Howard

Lab Number 03-7470

Sample iced Yes
Residual Cl₂ <0.1 mg/L Yes

cc: County Health Dept. Yes

CERTIFICATE OF ANALYSIS

Maryland State Certified Water Quality
Laboratory No. 115

REQUESTER: Williamsburg Group LLC
P.O. Box 101B
Columbia, Maryland 21044
Attn: Accounts Receivable

Property Sampled: U&O: 3416 Shady Lane, retest #2

Station Sampled: Laundry tub tap

Date/Time Sampled: Dec 31, 2003 10:45 am

Owner, Telephone No.:

Subdivision Name:

Building Permit No.: B00141797

Well Number: HO-94-3598

Tax Map #:

Parcel #:

Sampler: 67246P

Lot Number:

Observation: 2-Piece Cap
Satisfactory

RESULTS OF ANALYSIS:

PARAMETER	RESULT	METHOD	*MCL/**SMCL
Total Coliform	Absent	SM 9223B	*Absent SAFE
E. coli (18 Hour Test)	Absent	SM 9223B	*Absent SAFE

Treatment/Conditioning: None

300r 7V -2 VN 8: 0P

Sharon K. Cassell

*MCL = Maximum Contamination Level
**SMCL = Secondary Maximum Contamination Level

ASSELL TESTING, INC.

ENVIRONMENTAL SAMPLING AND TESTING
10940 BEAVER DAM ROAD, HUNT VALLEY, MD 21030-2211
(410) 252-7742

REPORT DATE: Dec 16, 2003

County Howard

Lab Number 03-7263

Sample iced Yes

Residual Cl₂ <0.1 mg/L Yes

cc: County Health Dept. Yes

CERTIFICATE OF ANALYSIS

Maryland State Certified Water Quality
Laboratory No. 115

REQUESTER: Williamsburg Group LLC
P.O. Box 1018
Columbia, Maryland 21044
Attn: Accounts Receivable

Property Sampled: U&O: 3416 Shady Lane, retest #1

Station Sampled: Laundry tub tap

Date/Time Sampled: Dec 15, 2003 12:45 pm

Owner, Telephone No.:

Subdivision Name:

Building Permit No.: B00141797

Well Number: HO-94-3598

Tax Map #:

Parcel #:

Sampler: 6724GP

Lot Number:

Observation: 2-Piece Cap
Satisfactory

RESULTS OF ANALYSIS:

PARAMETER	RESULT	METHOD	*MCL/**SMCL	
Turbidity	5.8 NTU	EPA 180.1	*10 NTU	Pass
Total Coliform E. coli (18 Hour Test)	PRESENT Absent	SM 9223B	*Absent	UNSAFE

Treatment/Conditioning: None

500r 5M-2/ VA d#18: 0r

Heather R. Beam

Heather R. Beam

*MCL = Maximum Contamination Level
**SMCL = Secondary Maximum Contamination Level