

FOUNTAIN VALLEY ANALYTICAL LABORATORY, INC.

1413 Old Taneytown Rd. Westminster, MD (410) 848-1014 (410) 876-4554 FAX (410) 848-0298

REPORT OF ANALYSIS

Laboratory ID #: 61392	Account #: 3123
Reference: National Water Servicing	Company: National Water Servicing
Location: 418 Brighton Dam Road Brookeville, MD 20833	Requested By: Dave Rycke
Date/ Time Collected: 11/21/2006 1059	Source: Well Water
Date/Time Rec'd: 11/21/2006 1300	Site: Pressure Tank
Chlorine ppm: Free: ND Total: ND	Treatment: Softener/Sediment Filter/Neutralizer**
Collected By: J.Yeager 6176JY	pH: 6.7
	Well #: HO-94-3857

PARAMETERS	RESULTS	UNITS	REFERENCE	METHOD	DATE/TIME/ANALYS
Bacteria, Coliform, Total, MPN	<1.0	MPN/ 100 ml	<1.0	SM18 9223 B.	11/22/2006 / 0900 / AD/BD
Bacteria, E. coli, MPN	<1.0	MPN/ 100 ml	<1.0	SM18 9223 B.	11/22/2006 / 0900 / AD/BD
Turbidity	3.07	NTU	<10	SM18 2130B	11/21/2006 / 1520 / AD/BD

NOTES

- 1 **Sample collected prior to treatment
- 2 MPN/ 100 ml = Most Probable Number [of viable bacteria] per 100 ml of sample.
- 3 NTU = Nephelometric Turbidity Units
- 4 Results less than or within the reference range are considered satisfactory and within potable water limits at the time of sampling.
- 5 ND:None Detected
- 6 Visual well check: Sealed, vented cap
- 7 pH tested on-site

Reason for Test : Use & Occupancy retest 61289

Building Permit # : 434788

Date Reported: 11/22/2006