



3525 H Ellicott Mills Drive, Ellicott City, MD 21043
(410) 313-2640 Fax (410) 313-2648
TDD (410) 313-2323 Toll Free 1-866-313-6300
website: www.hchealth.org

Penny E. Borenstein, M.D., M.P.H., Health Officer

December 18, 2002

Mr. & Mrs. Baker
1730 Florence Road
Mt. Airy, MD 21771

RE: Percolation Test Results A-517963
Baker Property
Tax Map: 6 Parcel:151

Dear Mr. Baker:

Percolation testing was done on December 12, 2002 on the above referenced property. At this time, the percolation test results are not acceptable to support septic disposal areas. Shallow depth to rock was encountered for the proposed lots two and three, and deep clay within the soil profile prevented acceptable percolation rates for lot one.

If you have any questions, please feel free to call our office. Thank you in advance for your time and cooperation.

Sincerely,

Kacie Noonan, Sanitarian
Well and Septic Program

KN
Enclosures

Cc: file