

Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-2640 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth


Maura J. Rossman, M.D., Health Officer


RECEIPT DATE: 7/24/15 ONSITE SEWAGE DISPOSAL SYSTEM P 556550				
APPROVAL DATE: 10/26/15 PERMIT: Repair A Repair				
PROPERTY ADDRESS: 14010 Burntwoods Road				
SUBDIVISION: LOT: TAX ID:				
CONTRACTOR: Hatfield's Equipment EMAIL: ken@hatfieldsequipment.com				
CONTRACTOR ADDRESS: P.O. Box 519 Annapolis Junction, MD 20701 PHONE: 301-490-4289				
CONTRACTOR CERTIFIED FOR BAT INSTALLATION: MDE MANUFACTURER:				
PROPERTY OWNER: Robert Hite EMAIL:				
OWNER ADDRESS: 14010 Burntwoods Road, Glenelg, MD 21737 PHONE: 410-997-9167				
BAT UNIT MODEL: Norweco 500 PUMP SIZE: ½-3/4 PUMP TANK CAPACITY: 1500				
OPERATION & MAINTENANCE AGREEMENT DATE SIGNED: DATE RECORDED:				
DISTRIBUTION SYSTEM: GRAVITY PRESSURE DOSED BEDROOMS: 4 APPLICATION RATE: 0,8				
BED LENGTH REQUIRED: 24-36' INLET DEPTH: 2.5'				
BED: TRENCH WIDTH: 24' MAXIMUM BOTTOM DEPTH: 4.5'				
MINIMUM SPACE BETWEEN TRENCHES: EFFECTIVE AREA BEGINNING DEPTH: 2.5'				
LOCATION: PER APPROVED SITE PLAN. SEWAGE DISPOSAL AREA AND BAT UNIT LOCATION MUST BE STAKED BY LICENSED SURVEYOR PRIOR TO PRE-CONSTRUCTION INSPECTION.				
See Septic design plan. Location 2' from front left property corner. Need property lines staked before installation.				
NOTES:				
ISSUED BY: Jeff Williams ISSUE DATE: EXPIRATION DATE:				
NOTE: CONTRACTOR MUST SCHEDULE A PRE-CONSTRUCTION INSPECTION PRIOR TO BEGINNING ANY INSTALLATION				
NOTE: CONTRACTOR MUST SCHEDULE AN INSPECTION AND GAIN APPROVAL OF ALL COMPONENTS PRIOR TO COVERING				
NOTE: STONE MUST BE APPROVED BY HEALTH DEPARTMENT AND GRAVEL TICKET MUST BE AVAILABLE FOR REVIEW.				
NOTE: WATERTIGHT SEPTIC TANKS REQUIRED				
NOTE: ALL PARTS OF SEPTIC SYSTEM SHALL BE AT LEAST 100 FEET DOWNGRADIENT FROM ANY WATER WELL NOTE: MANHOLE RISERS REQUIRED ON ALL SEPTIC TANKS AND PUMP CHAMBERS				
NOTE: AN ELECTRICAL PERMIT IS REQUIRED FOR INSTALLATION OF ANY ELECTRICAL COMPONENTS OF THE SYSTEM				
ELECTRICAL PERMIT ISSUED E E15004565				
NOTE: AN INDIVIDUAL CERTIFIED BY MDE AND THE MANUFACTURER FOR BAT INSTALLATION MUST BE PRESENT AT ALL TIMES				
DURING BAT INSTALLATION. NOTE: MDE RECOMMENDS SEPTIC TANKS, BAT, AND OTHER PRETREATMENT UNITS BE PUMPED AT A FREQUENCY ADEQUATE				
TO ENSURE THAT SOLIDS ARE NOT DISCHARGED TO THE DISPOSAL AREA				

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM.

PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT.

CALL 410-313-1771 TO SCHEDULE INSPECTIONS.







HOWARD COUNTY HEALTH DEPARTMENT

56550

ed be	at the	17 071	PHONE #	1-9
41012	V IIIC		FROME # //	/ //
	Chaball	an in the	14010	
CASH	2000	CICY YCC J	out vy di	200
CHECK -		a	E UI COUCH	
عسرا والأ				
0 1	ou klench	ed Hur	4- ore	XX
		OV		
31 00	Received By	7	LND	

Back River Pre-Cast, LLC

PO BOX 329 Glyndon, MD 21071 Phone # 410-833-3394 Fax # 410-833-4116

Letter of Certification

This is to certify that the Norweco Singulair TNT 600 GPD Septic Tank installed at 14010 Burntwoods Rd., Glenelg, MD 21737 on October 22, 2015 was installed according to the manufacture's specifications.


Installer: Jeff Reiter


Property Owner: Robert & Kerry Hite


Permit#

MATTHEW GECKLE

Vice-President









Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-2640 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth
Twitter: HowardCoHealthDep

Dr. Maura J. Rossman, M.D., Health Officer

	INFORMATION FOR	M – SEPTIC SYSTEM REPAIR/UPGRADE	
Reas	on for Request:	Has the septic tank been pumped within the last, month?	
X	Failing System	Yes Date pumped: 28 may 14	
	System relocation for proposed addition	□ No	•
	System upgrade for proposed addition	Was a visual inspection of the septic tank and/or drain fields conducted?	p.
	Inadequate treatment zone	Yes Explain observations: #20 Flowing beck	
	Collapsed septic tank	□ No 1nto tank. Tank was Overfull.	
	Collapsed drywell	,	
Exist	ing system design	Was a visual inspection of the sewage line conducted?	
	Drywell	Yes Blockage leading to the tank	
	Trench	Yes Explain:	
	Mound	No	
•	Unknown	Blockage leading to the field	
_	Other:	☐ Yes Explain:	
To dia	charge gurfacing on the ground?	No	
	charge surfacing on the ground? Yes		
-	No Backing Uf	Additional Comments: FAICING Drounkeld	
living spable to a	pace additions, garages, etc? This information accommodate requests in the field for proper	by plan to add in the future, any additions or modifications to the property, i.e. pools, on must be disclosed at the time of this application. The Health Department will not be try modifications unrelated to the repair request. Such requests may require an Certification Plan, if the property does not meet current Code and Regulation.	;
Se Ce	eptic Contractor: FOGLES ontractor's Address: 580 OBRE	Contractor's Phone: 410 - 795-5670 CHT RD. SYKESVILLE MD, 21784	мар-2
Pr St O	roperty Address: 14010 BURNTA ubdivision: BURNTA wner's Name: BOB HIFE	5000 S. GLENELG MO. County file: 6 Lot: 24 Year Built: 1969 Owner's Phone: 410-997-9167	SRID-G Parcel - 11 District
- 14	arile of previous owners.	Proposed bedrooms:	
H	as this request been previously discussed ublic Sewer available/nearby:	d with a Sanitarian? (Name): NO	
*A San		siness days, depending upon the urgency of the situation, to coordinate the	
Print ou If public If sewer exempti If soil/si	t a copy of Real Property Data via Dept. of To sewer may be nearby, verify whether sewer is available and the property is within the Mon exists, the owner should justify the requested conditions are limited and sewer and/or Months.	r is technically "available" through the Bureau of Engineering. Metropolitan District, connection to sewer is required. If the owner believes reason for	

No permit is to be issued nor inspection to be scheduled without prior fee collection at the office unless an emergency situation exists.

The contractor is to notify office of the emergency situation as soon as possible.

Septic System Repair for 14010 Burntwoods Road -

The system will be comprised of a 4 bedroom Hoot tank with 2 pumps and a shallow low pressure distributed bed. I have drawn a diagram of the bed that is to scale. The additional pump is to have a float tree and has to be wired separately from the HOOT tank. A 1/2 to 3/4 HP pump should be able to sufficiently pressurize the bed.

- Bed Inlet 2.5+, Bed Bottom 4.5+ - 2' of Gravel Bolow Inlet and Gravel to

- Cover Laterals

- Use Clean Washed Grave or River Rock
- Bed to Be 2' From Front and Side Property Lines Force Main 3", Laterals 1/4", /4" Lateral
Holes

Procedure:

- Mark Out the Bed Perimeter

- Find the Lowest Part of the Bed Area and Dig Down to 4,5', This is the Reference Point Make the Rest of the Bed Bottom Level to this Point

- Add 2 of Gravel and Level It Out

· · · · ·					
	Drill and Clean the Lateral Holes				
	Install the Lateral Network				
	+ Cover the Laterals with Gravel and Level				
	It Out .				
	Put On Geotextile Fabric and Cover Bed				
	See Plot Plan For Tank and Bed				
	Locations				
N.E.					
- 15.13					
MARINE TE					

August 6, 2014

Mr. Robert Hite 14010 Burntwoods Road Glenelg, MD 21737

RE: FY 2015 Howard County Bay Restoration Fund OSDS Upgrade Program

Dear Mr. Hite:

Thank you for your application to participate in the Howard County Bay Restoration Fund OSDS Upgrade Program. The Howard County Health Department has verified that your existing septic system is failing and in need of repair. Based on your 2013 income tax return form, you are eligible to receive funding to cover **100%** of the cost to upgrade your system to one of the MDE approved BAT units listed below. The approved price includes the cost of the unit, installation of the unit, and 5 years of operation and maintenance. The price does not include the cost of permits.

<u>System</u>	<u>Vendor</u>	<u>Contact</u>	<u>Phone</u>
Orenco (Advantex AX20)	Atlantic Solutions	Robert Johnson	877-214-9283
HOOT 600 BNR	Mayer Bros, Inc	Nancy Mayer	410-796-1434
Norweco Singulair TNT	Back River Precast LLC	Matthew Geckle	410-833-3394
SeptiTech	Maryland Concrete, Inc	Rodney Glace	443-491-3598

In order to receive your OSDS upgrade, you MUST follow these steps:

- 1. **Sign this letter** on the bottom of page 2 **and return it** in the envelope provided within 2 weeks of the date of this letter.
- 2. File a septic repair permit application with the Howard County Health Department within 2 weeks of the date of this letter. The permit application fee is \$396.00 (\$165 for tank approval only).
- 3. Obtain the Agreement and Easement for Installation of Best Available Technology Systems with Bay Restoration Funds from the Howard County Health Department, have it signed by a Howard County Health Department Bureau Director or Designee. Then take it to the Circuit Court and have it recorded in Land Records within 2 weeks of the date of this letter.
- 4. Prepare your property and schedule installation of the system. The system must be installed within 6 weeks of the date the Agreement and Easement is recorded.

If assistance is needed in completing any of the steps listed above, you may contact me at 304-940-3443 or kristin.mielcarek@canaanvi.org.

494 RiverStone Road | Davis, WV 26260 Phone: (304) 259.4739 or (800) 922.3601|Fax: (304) 259.4759 www.canaanvi.org The system vendor may provide a contractor to install your BAT unit. CVI will provide payment directly to the vendor. The vendor may also require proof of insurance from your contractor.

If your system is not installed within the 8 week timeframe listed in the steps on page 1, the funds may be released and used elsewhere. If you cannot complete installation in within this timeframe, please contact me to request an extension. Please note that failure to request an extension may result in termination of your grant and your system must be installed no later than June 27, 2015 in order to retain your funding.

For more information on septic repair permitting, contact:

Jeff Williams Program Supervisor, Well and Septic 410-313-1771

Please sign and return this original letter and keep a copy for your records. If you have any questions, please contact me at 304-940-3443 or by email at kristin.mielcarek@canaanvi.org.

Sincerely,	
Kristin Mielcarek, Watershed Circuit Rider	
Accepted by: Robert Hite, Property Owner	
I have read and agree to the conditions of this Agreement	Letter.
Signature	Date

Williams, Jeffrey

From:

Williams, Jeffrey

Sent:

Friday, October 31, 2014 1:53 PM 'Robert Hite'; Kristin Mielcarek

To: Subject:

RE: Bay Restoration Fund grant application

Hello Bob. I've heard back from MDE and their position is that a tank replacement to a BAT unit using BRF money is not approvable if the drainfield does not meet code requirements. Hopefully your existing system is still operating properly. If you choose to move forward with the repair at any time, we have a septic design in your file and you may apply for a BRF grant at that time. Thanks

Jeff Williams

Program Supervisor, Well & Septic Program Bureau of Environmental Health Howard County Health Dept. 410-313-4261 jewilliams@howardcountymd.gov

CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

From: Robert Hite [mailto: Sent: Tuesday, August 05, 2014 10:57 PM

To: Kristin Mielcarek **Cc:** Williams, Jeffrey

Subject: Re: Bay Restoration Fund grant application

Kristin,

Attached is the completed Bay Restoration Fund application. I am a little surprised that after E-mailing you with questions and leaving you a voicemail that I did not hear back. Please let me know that you have received what you need. Thanks.

Bob Hite

On Mon, Jul 28, 2014 at 9:37 PM, Robert Hite wrote: Kristin,

Who am I supposed to put down for the contact? Is that the contract company, the county sanitarian, or is it my information again? Also, is the phone number, fax, and E-mail suppose to be my contact info as well. I feel

like it would be, but the fax number line made me curious enough to ask. Last, how do I determine if I can check off any of the prioritization factors?

To get started, I attached a copy of our 2013 Tax return to verify income. The document is password protected and is '8185'. Thanks.

Bob Hite

On Fri, Jul 25, 2014 at 11:36 AM, Kristin Mielcarek

Hello Mr. Hite,

I was given your contact information by Jeff Williams at the Howard County Health Department. He notified me that you are interested in applying for a grant to upgrade your septic system.

Attached is the application for enrollment into the Bay Restoration Fund septic grant program. To apply, please fill it out and send it back to me along with a copy of your 2013 tax return. This is used for income verification purposes.

Once I receive your application and tax information, I can process your application.

Sincerely,

Kristin

Kristin Mielcarek

Watershed Circuit Rider

Canaan Valley Institute

494 Riverstone Road

Davis, WV 26260

Ph: 30

Fax:

v ·

14

.

[·] Hospinger Carrier (A)

