


1700 -0 с ГЛ **~**-1000 1010 E002

U.S. Postal Service CERTIFIED MAIL (Domestic Mail Only; No Insurance Coverage Provided)



PS Form 3800, June 2002





Bureau of Environmental Health 7178 Gateway Drive Columbia, MD 21046 (410) 313-2640 Fax (410) 313-2648 TDD (410) 313-2323 Toll Free 1-866-313-6300 website: www.hchealth.org

Peter L. Beilenson, M.D., M.P.H., Health Officer

NOTICE OF VIOLATION

SENT VIA CERTIFIED MAIL RETURN RECEIPT REQUESTED

March 12th, 2012

Dong Kim 15901 Willis Way Woodbine, MD 21797

RE: Sewage overflow; pollution of ground surface 15901 Willis Way, Tax Map 20 Grid 12 Parcel 139 HAND CARRY/REGULAR MAIL

Dear Mr. Kim:

A field review was conducted in relation to a citizen complaint regarding a sewage overflow on the subject property (Tax Map 22, Grid 19, Parcel 217), also known as 15901 Willis Way. Observation of the private sewage disposal system at the subject property on March 12th, 2012, revealed that there is an ongoing surface discharge from the septic system that serves the existing residence.

The source of the discharge is coming from the septic tank and extends from along the side of the dwelling around to the back of the property. There is flow directed down and across the backyard that has caused a gully to form towards the neighboring property line. There was a strong odor observed that is associated with the overflow.

Be advised that the observed sewage condition is in violation of the Code of Maryland Regulations (COMAR) 26.04.02.02(E): "A person may not dispose of sewage, body, or industrial wastes in any manner which may cause pollution of the ground surface, the waters of the State, or create a nuisance." This condition is also in violation of the Howard County Code 3.804(a)(1), as a sewage overflow is defined as a nuisance, $\{12.110(a)\}$.

You are hereby ordered to take the necessary actions to eliminate these on-going nuisance conditions on your property. You must immediately contact a licensed septic waste hauler to pump the septic tank and if necessary apply for a septic system installation (repair) permit within 15 (fifteen) days of the date on this notice. All soil surface areas that have been contaminated by sewage must also immediately be treated with anhydrous lime. The septic tank must be serviced as often as needed so that further surface discharge does not continue. The septic system must be properly repaired, and the installation (repair) permit approved by Health Department inspectors, within 30 (thirty) days of the date on this letter. The Howard County Health Department will conduct follow-up inspections to assure that actions are taken to correct and abate the nuisance condition and that the conditions do not recur. Failure to comply will result in the issuance of a civil citation(s). Under Howard County Code, paragraph 12.112, each day this violation is allowed to occur is considered a separate offense.

If you believe that the condition described above is not and could not be a hazard to health, or that the Health Department is not acting in compliance with pertinent laws and regulations, you may request a formal hearing before the Board of Health within 15 (fifteen) days of receipt of this letter. All requests are to be made in writing and directed to the Executive Secretary of the Board of Health at the above address.

If you have any questions regarding this letter, please contact me at the Bureau of Environmental Health, phone 410-313-1771.

Sincerely,

Heidi Scott, R.S. Bureau of Environmental Health Well and Septic Program

Copy: Executive Secretary, Board of Health File



2/12/13

Hend delivered NOV ~ 105 am to 15901 WIIIIS Way

