

Howard County Health Department		Bureau of Environmental Health 8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-2640 Fax: 410-313-2648 TDD 410-313-2323 Toll Free 1-866-313-6300 www.hchealth.org Facebook: www.facebook.com/hocohealth Maura J. Rossman, M.D., Health Officer				
RECEIPT DATE: 1/16/19 ONSITE SEWAGE DISPOSAL SYSTEM						
APPROVAL	DATE: 2/26/19 SEC	PERMIT:	REPAIR	· · · · A		
PROPERTY ADDRESS: 1127 Taylor Park Road						
SUBDIVISION: River Park Estates LOT: 27 TAX ID: 03-28799					3-287998	
CONTRACTOR: Fogle's Septic Clean Inc. EMAIL: kim@foglesinc.com					<u>m</u>	
CONTRACTOR ADDRESS: 580 Obrecht Road, Sykesville, MD 21784 PHONE: 410-795-5670						
PROPERTY OWNER: Ivan Inkman EMAIL:						
OWNER AD	DRESS: 1127 Taylor Par	k Road, Sykesville, MD 21	784	PHONE:	443-398-6168	
SEPTIC TANK SIZE (GALLONS): PUMP CHAMBER CAPACITY (GALLONS): PUMP SIZE:						
NUMBER OF BEDROOMS: 3 HOUSE SQ. FT APPLICATION RATE: 1.2						
DISTRIBUTION SYSTEM: GRAVITY FED 🛛 LOW PRESSURE DOSED						
	LINEAR FEET REQUIRED:	80		INLET DEPTH:	2	
TRENCHES:	TRENCH WIDTH:	3	MAXIMUM B	OTTOM DEPTH:	5	
	MINIMUM SPACE BETWEEN TRENCHES:	10	EFFECTIVE AREA BEG	INNING DEPTH:	3	
LOCATION:	TO BE STAKED BY SANITA	RIAN DURING PRE-CONSTRU	CTION INSPECTION.			
	Install 2 × 40'	trenches				
NOTES:			-			
ISSUED BY:	Sarah Collins	ISSUE DATI	F. Vischa	EXPIRATION DAT	F: 1/25/19	
		A PRE-CONSTRUCTION INSPE				
NOTE: CON	ITRACTOR MUST SCHEDULE	N INSPECTION AND GAIN AP	PROVAL OF ALL COMPO	ONENTS PRIOR TO	COVERING	
		EALTH DEPARTMENT AND G	RAVEL TICKET MUST BE	AVAILABLE FOR RE	EVIEW.	
NOTE: WATERTIGHT SEPTIC TANKS REQUIRED NOTE: ALL PARTS OF SEPTIC SYSTEM SHALL BE AT LEAST 100 FEET DOW/NGRADIENT FROM ANY WATER WELL						
NOTE: MANHOLE RISERS REQUIRED ON ALL SEPTIC TANKS AND PUMP CHAMBERS						
NOTE: AN ELECTRICAL PERMIT IS REQUIRED FOR INSTALLATION OF ANY ELECTRICAL COMPONENTS OF THE SYSTEM						
NOTE: THE HCHD DOES NOT WARRANTY ANY SYSTEM AND CANNOT GUARANTEE THE PERFORMANCE OF THIS SYSTEM AS						
DESIGNED. BY ACCEPTING THIS PERMIT, THE OWNER AND/OR APPLICANT ACKOWLEDGE THAT THE SPECIFICATIONS						
DETAILED IN THIS DESIGN ARE ONE POSSIBLE OPTION AND THAT THE HCHD WILL REVIEW OTHER PROPOSALS. YOU HAVE THE OPTION TO SEEK THE ADVICE OF A QUALIFIED DESIGN CONSULTANT OR PROFESSIONAL ENGINEER FOR FURTHER						
GUIADNCE. NOTE: MDE RECOMMENDS SEPTIC TANKS, BAT, AND OTHER PRETREATMENT UNITS BE PUMPED AT A FREQUENCY ADEQUATE TO ENSURE THAT SOLIDS ARE NOT DISCHARGED TO THE DISPOSAL AREA						
NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE						
SUCCESSFUL OPERATION OF ANY SYSTEM.						
		NSIBLE FOR OBTAINING			т.	
	CAL	L 410-313-1771 TO SCHI	DULE INSPECTION	5.		





MEMBER N. C. B. V. A.



Burial Vaults - Septic Tanks

MEMBER P. C. B. V. A.

925 WAKEFIELD VALLEY ROAD

New WINDSOR, MD 21776

PHONE: 410-848-0393 Fax: 410-848-3551

February 7, 2019

Howard County Health Department

The septic tank that was vacuum tested for 1127 Taylor Park Road in Sykesville was 4 inches Hg and held for the required 2 minutes, in fact it held for over 5 minutes until released. We at Babylon Vault Company certify this tank has passed it vacuum test.

Sincerely,

Steven R Koontz

General Manager

MEMBER N. C. B. V. A.



SINCE 1930

Burial Vaults - Septic Tanks

925 WAKEFIELD VALLEY ROAD NEW WINDSOR, MD 21776

Рноле: 410-848-0393 Fax: 410-848-3551

February 5, 2019

Howard County Health Department

Babylon Vault Company will stand behind the tank at 1127 Taylor Park Road with Fogles Septic putting two 30" risers on the tank. The inlet at 5'6" and the outlet at 5'2". Tar and sealing them to the tank will make the tank fine at this depth underground.

Sincerely,

Steven R Koontz 💪 bont G.M Taum

IS Rowani Gomu	Facebook: www.facebook.com/hocohealth vitter: HowardCoHealthDep				
Dr. Maura J. Rossman, M.D., Health Officer					
INFORMATION FOR	M - SEPTIC SYSTEM REPAIR/UPGRADE				
Reason for Request:	Has the septic tank been pumped within the last month?				
Failing System	12 Yes Date pumped: 12/22/18				
System relocation for proposed addition	D No				
System upgrade for proposed addition	Was a visual inspection of the septic tank and/or drain.fields conducted?				
Inadequate treatment zone	· D Yes Explain observations:				
Collapsed septic tank	No				
Collapsed drywell	CH0 140				
Bxisting system design	Was a visual inspection of the sewage line conducted?				
Drywell	C Yes				
· Drench	Blockage leading to the tank				
	Yes. Explain:				
· D · Mound D Unknown	☑ No				
	Blockage leading to the field				
Other:	Yes. Explain:				
Is discharge surfacing on the ground?	□ No				
🗆 Yes	No No				
D No	Additional Comments:				
living space additions, garages, etc? This information able to accommodate requests in the field for property additional fee, testing, and submittal of a Percolation	plan to add in the future, any additions or modifications to the property, i.e. pools, a must be disclosed at the time of this application. The Health Department will not be y modifications unrelated to the repair request. Such requests may require an Certification Plan, if the property does not meet current Code and Regulation.				
Septic Contractor: Fogles Se Contractor's Address: 580 0	Contractor's Phone: (410) - 795-5620				
Property Address: 1/27 Taylor Park Rd County file: Subdivision: River Park Bolances Lot: 27 Year Built: 1973 Owner's Name: Twan Takkman Owner's Phone: 443-266-8162 Name of previous owners: N/A 443-288-6168 Bxisting bedrooms: No Additional					
Has this request been previously discussed Public Sewer available/nearby:	with a Sanitarian? (Name): 16mm work & South Clim				
*A Sanitarian will be in contact within three busi scheduling/review of the repair or upgrade.	ness days, depending upon the urgency of the situation, to coordinate the				
Print out a copy of Real Property Data via Dept. of Ta If public sewer may be nearby, verify whether sewer is If sewer is available and the property is within the Me exemption exists, the owner should justify the request If soil/site conditions are limited and sewer and/or Me pursuit of Emergency Sewer Extension or Emergency details.	i technically "available" through the Bureau of Engineering. ropolitan District, connection to sewer is required; if the owner believes reason for in writing. To District status is not conducive to connection, the Sanitarian may recommend Metro District Inclusion. The Owner should contact the Bureau of Utilities for d without prior fee collection at the office unless an emergency situation exists.				