

Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-2640 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth

Maura J. Rossman, M.D., Health Officer

RECEIPT	DATE: 07/26/2021 ONSITE SEWAGE DISPOSAL SYSTEM P 569623			
APPROVAL	DATE: 3/4/22 PERMIT: CONSTRUCTION A			
PROPERTY A	DDRESS: 1441 Underwood Road, Sykesville, MD 21784			
SUBDIVISION	I: Rizk Property LOT: 2 TAX ID: 03-601462			
CONTRACTO	R: Sam's Creek EMAIL: Sams.creek@aol.com			
CONTRACTOR	ADDRESS: 2810 Sams Creek Road, New Windsor, MD 21776 PHONE: (443) 821 - 4932			
CONTRACT	TOR CERTIFIED FOR BAT INSTALLATION: 🖂 MDE 🖂 MANUFACTURER:			
PROPERTY O	OWNER: Lockwood, Mary Kae; Takashima, Naruhisa EMAIL:			
OWNER ADDR	RESS: 4325 Doncaster Drive, Ellicott City, MD 21043 PHONE:			
BAT UNIT MO	ODEL: Norweco TNTLP-500 PUMP SIZE: 0.3 HP PUMP TANK CAPACITY: 1500			
OPERATION & MAINTENANCE AGREEMENT DATE SIGNED: 3/2/2022 DATE RECORDED: 3/2/2022				
DISTRIBUTION SYSTEM: GRAVITY PRESSURE DOSED BEDROOMS: 3 APPLICATION RATE: 0.8				
	LINEAR FEET REQUIRED: 188' INLET DEPTH: 4'			
TRENCHES:	TRENCH WIDTH: 3' MAXIMUM BOTTOM DEPTH: 8'			
	MINIMUM SPACE BETWEEN TRENCHES: 10' EFFECTIVE AREA BEGINNING DEPTH: 7.5'			
LOCATION:	PER APPROVED SITE PLAN. SEWAGE DISPOSAL AREA AND BAT UNIT LOCATION MUST BE STAKED BY LICENSED			
LOCATION.	SURVEYOR PRIOR TO PRE-CONSTRUCTION INSPECTION.			
	Use Zoeller Model 50 Series Pump.			
NOTES:				
ISSUED BY:	Cabahug ISSUE DATE: 08/02/2021 EXPIRATION DATE: 08/02/2022			
	TRACTOR MUST SCHEDULE A PRE-CONSTRUCTION INSPECTION PRIOR TO BEGINNING ANY INSTALLATION			
NOTE: CONTRACTOR MUST SCHEDULE AN INSPECTION AND GAIN APPROVAL OF ALL COMPONENTS PRIOR TO COVERING				
NOTE: STONE MUST BE APPROVED BY HEALTH DEPARTMENT AND GRAVEL TICKET MUST BE AVAILABLE FOR REVIEW.				
NOTE: WATERTIGHT SEPTIC TANKS REQUIRED				
NOTE: ALL PARTS OF SEPTIC SYSTEM SHALL BE AT LEAST 100 FEET DOWNGRADIENT FROM ANY WATER WELL				
NOTE: MANHOLE RISERS REQUIRED ON ALL SEPTIC TANKS AND PUMP CHAMBERS NOTE: AN ELECTRICAL PERMIT IS REQUIRED FOR INSTALLATION OF ANY ELECTRICAL COMPONENTS OF THE SYSTEM				
ELECTRICAL PERMIT IS REQUIRED FOR INSTALLATION OF ANY ELECTRICAL COMPONENTS OF THE SYSTEM				
NOTE: AN INDIVIDUAL CERTIFIED BY MDE AND THE MANUFACTURER FOR BAT INSTALLATION MUST BE PRESENT AT ALL TIMES				
DURING BAT INSTALLATION. NOTE: MDE RECOMMENDS SEPTIC TANKS, BAT, AND OTHER PRETREATMENT UNITS BE PUMPED AT A FREQUENCY ADEQUATE				
TO ENSURE THAT SOLIDS ARE NOT DISCHARGED TO THE DISPOSAL AREA				

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM.

PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT.

CALL 410-313-1771 TO SCHEDULE INSPECTIONS.

NOT TO SCALE	TRENCH/DRAINFIELD DATA WIDTH INLET BOTTOM
NB	NUMBER OF TRENCHES 2 CENTER FEED
	TOTAL LENGTH
	ABSORPTION AREA 564 SP + 5 SIDE
	DISTRIBUTION BOX LEVELPD
	DISTRIBUTION BOX BAFFLE
	DISTRIBUTION BOX PORT
	SEPTIC TANK DATA SEPTIC TANK 1 LEVEL YES
	MANUFACTURER BACKRUES
	CAPACITY TATLE SO GAL
	SEAM LOC
	BAFFLES
	W BAFFLE FILTER BAT
	3 MANHOLE LOC FRANCISCO
500	6" PORT LOC
	SLOTTED
111-0-1	DATE ON LID 06/05/2021
Hous€	PUMP/SEPTIC TANK LEVEL 435
	MANUFACTURER BARYLON
DRIVE	CAPACITYGAL
94 142 54	SEAM LOC
35	TANK LID DEPTH 3.5
, Re-	BAFFLES BAFFLE FILTER
94' 15 14' 10 00 1000	MANHOLE LOC FRONT BACK
8	6" PORT LOC
	WATERTIGHT TEST SLOTTED
ROAD NAME - SHARED DRIVE-	DATE ON LID 09/21/21
ROAD WANTE STATE OF THE STATE O	
PRE-CONSTRUCTION: 10/29/201 LAID OUT 2x 94' TRS CONFIRMER	120 7008
STAKES W LASER OF	2 4 0 GNOOF
others wi discrete	
INSTALLATION: INTO TOOL TANK SET; WORKING ON SON	
11/15/2021 INSTALLED 2×94 TRS CENTER PEED; CONI	CIRMED 10 OR TEL
- AND 8 OR THE - 90° OFF ON SIDE DUE TO DIAG	- INSTRUCT TO ALMAYS
INSTALL ON OUT PACING SIDE INTO AGGREGATE . @ 3	3/4/22 Punip and alarm
observed to function. Pump and alarm on separar	le circuits in Normeco circuit
Lox located outside house Alarm located in box. Grea	
of head pressure in Trenches 1A, 18 and 2A, 2B respective	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
1 7	1 ,
FINAL INSPECTOR Juan /homas DATE OF APPRO	VAL 3/4/22.
	, ,



BACK RIVER PRE-CAST, LLC PO BOX 329 GLYNDON, MD 21071 PH# 410-833-3394

NORWECO CERTIFICATION

PROPERTY OWNER: MARY LOCKWOOD	INSTALLATION COMPANY: SAM'S CREEK
ADDRESS: 1441 UNDERWOOD RD.	CERTIFIED INSTALLER: JOE WRIGHT
CITY, ZIPCODE & COUNTY: SYKESVILLE, 21784, HOWARD	PERMIT#
SIZE OF SYSTEM INSTALLED:	DATE INSTALLED: 11-03-21
600 GPD CONCRETE	START-UP DATE: 03-03-22
NUMBER OF BEDROOMS:	DATE OF FINAL INSPECTION:
TYPE OF INSTALLATION: NEW	DATE OF ELECTRICAL INSPECTION:
ELECTRICAL WIRING PER ELECTRICAL INSTRUCTIONS: YES	TANK LEVEL: YES
HT. OF CONTROL PANEL ABOVE FINAL GRADE: 45"	BURIAL DEPTH OF TANK: 408"
SYSTEM WIRED ON A 15-AMP DEDICATED CIRCUIT WITH STD. BREAKER: YES	RISERS 4" - 6" ABOVE GRADE: NO
LENGTH(S) OF UF WIRE PAST LAST AERATION RISER(S): 36"	VENTED LID(S) ON AERATION CHAMBER(S): YES
FEMALE PLUG(S) WIRED TO UF WIRE: YES	ANY GROUND SETTLING AROUND TANK:
CONDUIT(S) ENTERING AERATION RISER MADE WITH A WATERTIGHT CONNECTION: YES	NO
ISTHE INSIDE OF THE CONDUIT ENTERING THE CONTROL PA WITH DUCT SEAL: YES	NEL(S) AND AERATION RISER(S) SEALED

ON 2ND PAGE MAKE A ROUGH SKETCH OF THE HOUSE, WHERE THE SYSTEM IS LOCATED, WHERE THE CONTROL PANEL IS LOCATED, WHERE THE FRONT OF THE IS AND DIRECTIONS TO THE PROPERTY.

DIRECTIONS CAN START A FEW STREETS AWAY

EXAMPLE: RT. X LEFT ONTO XX STREET RIGHT ONTO PRIVATE DRIVEWAY 5TH HOUSE OF THE LEFT.

I certify that the Norweco Singulair TNT Wastewater Treatment System was installed according to the manufacture's specifications.

Matthew Geckle March 03,2022

Signature of BRP Representative

Vice-President

Date



Bureau of Environmental Health 8930 Stanford Blvd | Columbia, MD 21045 410.313.2640 - Voice/Relay 410.313.2648 - Fax 1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

OPERATION AND MAINTENANCE AGREEMENT FOR AN ON-SITE SEWAGE DISPOSAL SYSTEM HAVING AN ADVANCED PRE-TREATMENT SYSTEM

Website: www.hchealth.org Facebook: www.facebook.com/hocohealth Twitter: @HoCoHealth

E. This agreement shall run with the land and upon Owner's taking title to the Property shall bind the Owner, their heirs, successors, and assigns to the provisions of the agreement as long as

the property is in existence and after installation of the system. Owner further agrees that they shall inform in writing any subsequent purchaser or lessee of the Property that the system shall require maintenance or other attention. Upon taking title to the Property, the Owner agrees to cause this agreement to be recorded in the Land Records of Howard County and assure that it becomes part of the Deed for the subject property in order that prospective buyers may be aware of the special conditions affecting this property.

- F. This agreement shall not be construed to limit any authority of the County to protect the public health, safety or comfort or to issue any other orders to take any other action which is now or may hereafter be within its authority.
- G. This agreement may be voided at any time at the discretion of the County.
- H. This agreement contains the entire agreement and understanding between the County and the Owner. There are no additional terms other than as contained in this agreement. This agreement may not be modified, except in writing signed by each of the parties or by their authorized representatives.
- I. The laws of the State of Maryland govern the provisions of all transactions pursuant to this agreement.
- J. Owner acknowledges and agrees that interior renovations to increase the number of bedrooms or an increase in living space shall not be permitted without approval from the County.

IN WITNESS WHEREOF, the parties have signed this agreement on the date indicated above.

3/3/2022							
Howard County Health Department							
Mung K Zhu ZMarzozz	Da .	2 Mar 202					
Owner #1 Signature Date	Owner#2 Signature	Date					
Mary Kae Lockwood	Naruhisa Tak	ashina					
Owner #1 Print Name	Owner #2 Print Name						
Buyer #1 Signature Date	Buyer #2 Signature	Date					
Buyer #1 Print Name	Buyer #2 Print Name						

Clerk of the Circuit Court for Howard County

9250 Judicial Way Ellicott City, MD 21043 410-313-2111

LR - Agreement Recording Fee 1x 20.00 20.00

Name: Lockwood Ref: 15

LR - Agreement Surcharge 40.00 40.00 60.00 SubTotal: 60.00 Total:

60.00 REV-Check-WFB Number: 13776

CC17-DH 03/03/2022 11:03 CC1 #15930844/396/4 Thank you for visiting us today ~

Wolf, Kevin

From:

Wolf, Kevin

Sent:

Wednesday, March 2, 2022 11:33 AM

To:

Cary Cumberland

Subject:

RE: 1441 Underwood road ICOP

Attachments:

O&M agreement 4.23.18.pdf

Cary,

I do not see a copy of the Operations and Maintenance (O&M) agreement for the BAT. If you have the recorded copy can you forward me please? I will need this in order to issue the ICOP.

Kevin

From: Cary Cumberland <cary@vikingcustomhomes.com>

Sent: Tuesday, March 1, 2022 6:18 PM

To: Wolf, Kevin < KWolf@howardcountymd.gov>

Subject: 1441 Underwood road ICOP

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Hi Kevin, I wanted to follow up and make sure you got the lab results for a passing test at 1441 Underwood road Sykesville Md 21784. BP20004289. This is the one we had failed for sand and then we raised pump and ran it out and got a passing test. Fountain valley sent results to you last week.

Is there any chance you vould give me the ICOP letter to get the U and O. Thanks

Cary

Sent from my Verizon, Samsung Galaxy smartphone

Get Outlook for Android

Sams Greek

2810 Sams Creek Road New Windsor, MD 21776

Ph # (443) 821-4932 Email: Sams.creek@aol.com


To whom it may concern,

Enclosed is a copy of a wall check for lot 2 at Rizk property. Also Attached is payment for permit with check # 1203.

Please do not hesitate to call me with any questions or concerns.

Thanks,

Jessica



Oswald, Hank

From:

Williams, Jeffrey

Sent:

Wednesday, January 20, 2021 10:39 AM

To:

Oswald, Hank

Subject:

RE: BAT Plan 1441 Underwood Road

Yeah that's better

From: Oswald, Hank < hoswald@howardcountymd.gov>

Sent: Wednesday, January 20, 2021 9:14 AM

To: Williams, Jeffrey < jewilliams@howardcountymd.gov>

Subject: Fwd: BAT Plan_1441 Underwood Road

The engineer adjusted the swale. Is this better?

Sent from my Verizon, Samsung Galaxy smartphone

Get <u>Outlook for Android</u>

From: Stephanie Tuite < Stephanie@fcc-eng.com > Sent: Tuesday, January 19, 2021 3:48:04 PM

To: Oswald, Hank < hoswald@howardcountymd.gov >

Subject: RE: BAT Plan 1441 Underwood Road

[Note: This email originated from outside of the organization. Please only click on links or attachments if

you know the sender.]

More like this be ok?

Stephanie Tuite, RLA, PE, LEED AP BD&C FISHER, COLLINS & CARTER, INC.

From: Oswald, Hank < hoswald@howardcountymd.gov>

Sent: Tuesday, January 19, 2021 3:30 PM **To:** Stephanie Tuite < Stephanie@fcc-eng.com >

Subject: Re: BAT Plan_1441 Underwood Road

Can you at least alter it to get the edge with a slight berm further away from the SDA and the initial trench?

Hank

From: Stephanie Tuite < Stephanie@fcc-eng.com >

Sent: Tuesday, January 19, 2021 1:42 PM

To: Oswald, Hank < hoswald@howardcountymd.gov>

Cc: Tony Fertitta <tonyf@fcc-eng.com>

Subject: RE: BAT Plan_1441 Underwood Road

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

The swale is just has a gentle slope around 2% from the front to the side. it is not taking a lot of drainage. It is not big.

Steph

Stephanie Tuite, RLA, PE, LEED AP BD&C FISHER, COLLINS & CARTER, INC.

From: Tony Fertitta < tonyf@fcc-eng.com > Sent: Tuesday, January 19, 2021 10:17 AM
To: Stephanie Tuite < Stephanie@fcc-eng.com > Subject: FW: BAT Plan_1441 Underwood Road

From: Oswald, Hank < hoswald@howardcountymd.gov >

Sent: Tuesday, January 19, 2021 10:12 AM
To: Tony Fertitta < tonyf@fcc-eng.com >
Subject: BAT Plan_1441 Underwood Road

Hi Tony:

I consulted with Jeff on the swale in between the house and SDA for Rizc Property Lot 2. He says the swale is too big, and It's running to close to the initial trench. Also, the title on this plan doesn't include anything about the BAT. It should really read, *Site Plan for BAT Installation*. Also, note #5 doesn't make sense to me. Can you make sure the notes match up with the BAT notes on page 2 in the attachment.

Let me know if you have any questions.

Thanks,

Hank

Hank Oswald, L.E.H.S.
Howard County Health Department
Bureau of Environmental Health
Well & Septic Program
8930 Stanford Boulevard
Columbia, MD 21045
(410) 313 - 1786
hoswald@howardcountymd.gov

Oswald, Hank

From:

Oswald, Hank

Sent:

Tuesday, January 19, 2021 10:12 AM

To:

Tony Fertitta (tonyf@fcc-eng.com)

Subject:

BAT Plan_1441 Underwood Road

Attachments:

BAT Site Plan Requirements_Updated 5.31.17.pdf

Hi Tony:

I consulted with Jeff on the swale in between the house and SDA for Rizc Property Lot 2. He says the swale is too big, and It's running to close to the initial trench. Also, the title on this plan doesn't include anything about the BAT. It should really read, *Site Plan for BAT Installation*. Also, note #5 doesn't make sense to me. Can you make sure the notes match up with the BAT notes on page 2 in the attachment.

Let me know if you have any questions.

Thanks,

Hank

Hank Oswald, L.E.H.S.
Howard County Health Department
Bureau of Environmental Health
Well & Septic Program
8930 Stanford Boulevard
Columbia, MD 21045
(410) 313 - 1786
hoswald@howardcountymd.gov

Oswald, Hank

From:

Oswald, Hank

Sent:

Monday, January 4, 2021 4:22 PM

To:

Tony Fertitta

Subject:

BAT Plan_1441 Underwood Road_Lot 2

Attachments:

BAT Site Plan Requirements_Updated 5.31.17 (1).pdf; Table 4.3 Equil Lenth of Pipe for

Fric Loss.pdf

Hi Tony:

The Site Plan for BAT Installation for 1441 Underwood Road, Lot 2 has been reviewed with the following comment:

- 1.) Add title "Site Plan for BAT Installation" to both pages
- 2.) Add required BAT Site Plan Notes to plan (see attachment)
- 3.) Pull pump tank out of the sewage disposal area (if possible).
- 4.) Match friction loss #s on plan with #s on chart provided (see attachment)

Should you have any questions or concerns, please don't hesitate to ask.

Thanks,

Hank

Hank Oswald, L.E.H.S. Howard County Health Department Well and Septic Program 410.313.1786



Bureau of Environmental Health 8930 Stanford Blvd | Columbia, MD 21045 410.313.2640 - Voice/Relay 410.313.2648 - Fax 1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

MEMORANDUM

TO:

Michael Barlow (MWD 355)

FROM:

Sarah Collins, L.E.H.S. SEC

Howard County Health Department

Well and Septic Program

DATE:

July 25, 2018

RE:

Well permit for lot 2 of the Rizk Property

1441 Underwood Road

#HO-17-0316

The initial well for lot 2 of the Rizk Property is staked as a single location close to the future common driveway. Any future replacement wells will be located in the well box located towards the center of the lot.

Please note that any well drilled in the well box must have 50' of steel casing or 10' into competent bedrock, whichever is greater. This condition is part of a waiver that Maryland Department of the Environment approved for the well to be located downgrade of the septic areas on lots 1 and 2.

Feel free to contact me at 410-313-6287 or <u>SCollins@howardcountymd.gov</u> with any questions.

Cc: Tony Fertita – Fisher, Collins & Carter (tonyf@fcc-eng.com)
File