

HEALTH



## Peter L. Beilenson, M.D., M.P.H., Health Officer

Tuesday, December 09, 2008

MEMORANDUM

To: FILE

- From: Sara Sappington Well and Septic Program
- Re: 1275 Underwood Rd Well condition

Due to landscape positioning and uphill septic areas, a replacement well for the property must have an extended casing and be grouted the entire depth of the casing.

## IMPORTANT WELL CONDITION