



APPLICATION

æ.	HOWARD COUNTY HEALTH DEPARTMENT BUREAU OF ENVIRONMENTAL HEALTH 3525-H ELLICOTT MILLS DRIVE/ELLICOTT CITY, MARYLAND 21043 TELEPHONE: 313-2840		ing Perc to t. Septic - Area Vox Recorda	DISTRICT_ DATE_	A REPAIR P 5/8563 3-7-03
TO:	THE COUNTY HEALTH OFFICER ELLICOTT CITY, MARYLAND	MK			
PROI	PERTY OWNER SULLY ROLLING RIDGE ADDRESS 8447 Rolling Ridge	1			
AGE	ADDRESS 3602 TURKEY FOOT RAL	WEST MO	_PHONE	984-540	, 4
SUBO	DIVISION ROlling Ridge DIAND DESCRIPTION Old Fredwick	+ Rollmy	LOTNO. Lot Ridge CT		
	MAP 18 PARCEL 320	TYPE BLOG	. Single FA	sub Dwe	LUNZ COMMERCIAL)
THE	SYSTEM INSTALLED UNDER THIS APPLICATION IS ACCEPTAB	BLE ONLY UNTIL PUE	BLIC FACILITIES BECOME	E AVAILABLE. I FI	JLLY UNDERSTAND THE
	CONNECTED WITH THE FILING OF THIS PERC TEST APPR	The state of the s	wife of	Y CIRCUMSTANCE	S. I ALSO AGREE TO
APPF	NOVED BY	FOR		DATE	
DISA	PPROVED BY	FOR		DATE	
HOLE	PENDING FURTHER TESTS			·	
REAS	SONS FOR REJECTION OR HOLDING				
PERC	COLATION TEST PLAT/PRELIMINARY PLAT - TITLE OR I.D. #			DATE	
SITE	DEVELOPMENT PLAN/FINAL PLAT - TITLE OR I.D. #			DATE	

THIS IS NOT A PERMIT





3525 H Ellicott Mills Drive, Ellicott City, MD 21043 (410) 313-2640 Fax (410) 313-2648 TDD (410) 313-2323 Toll Free 1-866-313-6300 website: www.hchealth.org

Penny E. Borenstein, M.D., M.P.H., Health Officer March 31, 2003

Mr. & Mrs. Quesenberry 8447 Rolling Ridge Court Ellicott City, MD 21043

RE:

Percolation Test Results – A518653

Establish Repair Area in Support of Plat

Rolling Ridge, Lot 1 8447 Rolling Ridge Court

Dear Mr. and Mrs. Quesenberry:

Percolation testing conducted March 11, 2003 on the referenced property indicated unsatisfactory soil conditions due to shallow groundwater downhill of the existing septic drywell. Satisfactory soils were found uphill of the existing drywell. Copies of the test results are enclosed.

Further review is contingent upon submission by a registered engineer/surveyor of a percolation certification plan showing the following:

- 1) actual locations and elevations of all excavated test holes
- 2) the existing house, accessory structures, well, and septic system on the property
- 3) all proposed structures
- 4) a suitable schedule for sealing of the existing well due to its proximity to the proposed structure and location downhill of septic repair area to be established by this plan
- 5) a purpose statement
- 6) a note must be included certifying that all existing wells and septic systems within 100 feet of property boundaries have been shown
- 7) a note indicating that depicted topography reflects field-matched information
- 8) a note stipulating that future septic repairs will require installation of a pump and a pump chamber and abandonment of the existing drywell

Bear in mind the septic repair area established by this plan is not subject to the standard 10,000 ft² requirement. The percolation certification plat should be submitted within 60 days to allow field verification if necessary. If you have any questions regarding this matter, please contact me according to the above information.

Very truly yours,

Mark E. Rifkin, R.S

Water and Sewerage Program


MR

Enclosures

cc:

Tim Peters

File



Terrell A. Fisher, P.E., L.S. Earl D. Collins, P.E. Ronald B. Carter, L.S. Charles J. Crovo, Sr., P.E., L.S.

May 9, 2003

Mr. Mark Rifkin Howard County Health Dept. 3525 Ellicott Mills Dr. Ellicott City, MD 21043

RE: #8447 S. Rolling Ridge Court

Perc Certification Plan Quesenberry Property

Dear Mark:

A.518563

On behalf of our client, Mr. Tim Peters, we have field surveyed the above referenced property located at 8447 S. Rolling Ridge Court to identify the existing building and site improvements, septic test sites and topography to prepare a Perc Certification Plan for your review and approval.

It is our understanding that a 12' x 12' addition will be extended from the existing house and a 24' x 24' detached garage will be added. Both of these building entities are shown on the enclosed Perc Certification Plan.

We are enclosing two (2) prints of this Perc Certification Plan and photocopy of your notes for this site.

Understanding that this is a unique well and septic situation, please notify either myself or Mr. Tim Peters at 410-984-5464 if you require any additional information.

Thanks, as always, for your help.

Very truly yours,


Fisher, Collins & Carter, Inc.

Terrell A. Fisher, P.E., L.S.

WO #30792

c.c. Mr. Tim Peters (w/print)

W.DE, DE, 68 For Perc rop Septic Reserve Ex. Hse Ex. Well EX. S.S. (Tank, Drywell + Trench, Topo Ex. Wells on Adjacent Lots (Maintain 700) Prof. Garage, BR expansion Schedule to Fill Ex. Well aby Whom mt = ,57,17,575 Ex. & Prop. BRL MR W/TimPeters



Scale: 1"=50" Date: June 25, 2003


F-04-002

Zoned R-20

Tax Map: 10 Parcel: 320 Grid: 7 Second Election District Howard County, Maryland

6/26/03

Terrell A. Fisher ALArofessional Land Surveyor No. 10692



PC 5/8563