

Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-2640 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth
Twitter: HowardCoHealthDep

Maura J. Rossman, M.D., Health Officer

May 13, 2014

Keith Ramsay 6725 Surrey Lane Clarksville, MD 21029

RE:

Variance Approval 6725 Surrey Lane Clarksville, MD 21029

Mr. Ramsay:

The Health Department received your waiver request dated May 2, 2014 for the above referenced property. This agency will grant approval of the waiver to the required Percolation Certification Plan as required by the Howard County Code, Subtitle 8, Section 3.805. The waiver has been approved on the basis that the proposed in-ground pool has a minimal, if any, impact on-site sewage disposal system repair area because the improvements are within the one hundred (100) foot setback to the existing well.

Be advised that any future addition may require percolation testing and a Percolation Certification Plan will be required. Any deviations from the site plan submitted with the request will be subject to further review by this Department.

Any questions regarding this decision may be directed to the Well and Septic Program of the Howard County Health Department.

Respectfully,

Michael J. Davis Assistant Director

Bureau of Environmental Health

May 2, 2014

Michael J. Davis, Deputy Director Howard County Health Department 8930 Stanford Blvd, Columbia, MD 21045

Waiver Request - Pool Permit 6725 Surrey Lane Clarksville, MD 21029 5/13/14
Approved
M. Com

Mr. Davis:

I am currently replacing an in ground swimming pool at my residence. As a part of the permit review process, I have been notified that I need to provide a Perc Certification Plan. I would like to formally request a waiver to the perc certification plan. The following points may be notable in my request:

- 1. The location on the property is an existing pool constructed approximately 30 years prior.
- 2. The work will retrofit the pool in the existing location.
- 3. My septic field is located in the southwest corner of the property away from the existing pool location and has enough space to construct reserve fields in the future if necessary.
- 4. The location of the exiting/proposed pool is not suitable for a reserve septic field due to the fact it is located within 50' of the well.

I have attached information for your reference - Should you have any questions or need additional information please do not hesitate to contact me at your convenience at (410) 370-6362.


Sincerely,

Keith Ramsay

6725 Surrey Lane Clarksville, MD 21209

Attachments:

- 1) 6725 Surrey Location Drawing
- 2) 6725 Surrey Health File
- 3) Amended 6725 Surrey Health File (Per Email 5/06/2014)



Bureau of Environmental Health

7178 Gateway Drive (410) 313-2640 TDD (410) 313-2323 Columbia, MD 21046 Fax (410) 313-2648 Toll Free 1-866-313-6300

website: www.hchealth.org

Peter L. Beilenson, M.D., M.P.H., Health Officer

May 18, 2012

To Whom It May Concern:

On May 03, 2012, you submitted a request to the Howard County Health Department for a Public Information Act for—6725 Surrey Lane., regarding <u>A Complete Lot File</u>, using the information provided, your request was adhered to and finalized. The Howard County Health Department has produced <u>4 Page</u> copies for each relevant to your request.

There is no fee associated with this request due to the amount of pages requested. As requested, Howard County Health Department will send your request regular mail.

Should you have further questions or concerns regarding this matter, feel free to contact me at (410) 313-4251.

Juanita King
Bureau of Environmental Health
Program Secretary
(410) 313-4251
juking@howardcountymd.gov

PERMIT

ufep. 8-17-6

13032

SEWAGE DISPOSAL SYSTEM

MARYLAND STATE DEPARTMENT OF HEALTH .

HOWARD COUNTY

INDEXED

ELLICOTT CITY
DISTRICT___5


DATE_8/21/67_

Robert Dubin	IS PERMITTED TO INSTALL	_ALTER	<u>x</u> _
ADDRESS Rt. 2, Clarkaville, Md.	· ·		
A SEWAGE DISPOSAL SYSTEM LOCATED AT			
SUBDIVISIONClarksville RidgeROA	* *	·	
PROPERTY OWNER Gordon Amato			
ADDRESS			• •
SPECIFICATIONS	k m	١.;	
DRAIN FIELD DEPTH FEET, BOT	TOM AREA		
SEEPAGE PITS ABSORBENT SIDE-WAL	L AREASQ. FT.		. '
SEPTIC TANK CAPACITY	GALLONS	, ,	
for garbage grinder, increase disposa	AL AREA 22% & TANK CAPACITY 50%.	• • •	٠٠
OTHER REPAIR - Trench - min. 40 ft. long	- 2 ft. wide - 5 ft. grave	1	<u></u>
under pipe			
			• • • •
			•
PLANS APPROVED BY.	DATE8/17/67		
FILL SEPTIC TANK AND DISTRIBUTION BOX WITH WATER SEF UNTIL INSPECTED AND APPROVED.			o work

NOTIFY THE HEALTH DEPARTMENT 48 HOURS BEFORE EXCAVATIONS ARE TO BE BACK FILLED.

NEITHER THE HOWARD COUNTY COMMISSIONERS NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE

PROFESSIONAL CERTIFICATION: I HEREBY CERTIFY THAT THESE DOCUMENTS WERE PREPARED BY ME OR UNDER MY RESPONSIBLE CHARGE, AND THAT I AM A DULY LICENSED PROFESSIONAL LAND SURVEYOR UNDER THE LAWS OF THE STATE OF MARYLAND, LICENSE NO. 21328, EXPIRATION DATE 1/8/13.



BUILDING SETBACK DISTANCES SHOWN HEREON AS "±" HAVE AN ACCURACY OF ±0.5' FOOT.

SURVEYOR'S NOTE

I HEREBY CERTIFY THAT THE POSITION OF THE EXISTING IMPROVEMENTS SHOWN HEREON HAVE BEEN CAREFULLY ESTABLISHED BY ACCEPTED LAND SURVEYING PRACTICES AND THAT, UNLESS SHOWN, THERE ARE NO VISIBLE ENCROACHMENTS EITHER WAY ACROSS THE PROPERTY LINES. THE PLANS IS OF BENEFIT TO A CONSUMER ONLY INSOFAR AS IT IS REQUIRED BY A LENDER OR A TITLE INSURANCE COMPANY OR ITS AGENT IN CONNECTION WITH CONTEMPLATED TRANSFER, FINANCING, OR REFINANCING. THE PLAN IS NOT TO BE RELIED UPON FOR THE ESTABLISHMENT OR LOCATION OF FENCES, GARAGES, BUILDINGS, OR OTHER EXISTING OR FUTURE IMPROVEMENTS. THE PLAN DOES NOT PROVIDE FOR THE ACCURATE IDENTIFICATION OF PROPERTY BOUNDARY LINES, BUT SUCH IDENTIFICATION MAY NOT BE REQUIRED FOR THE TRANSFER OF TITLE OR SECURING FINANCING OR REFINANCING. THIS DRAWING WAS PREPARED W/O THE BENEFIT OF A TITLE REPORT.

ADDRESS: 6725 SURREY LN CLARKSVILLE MD

LOCATION DRAWING 48

6725 SURREY LN

LIBER 12808, FOLIO 466 PB 7 FOLIO 29 CARKSVILLE