

Building Permit Application
Howard County Maryland
Department of Inspections, Licenses and Permits
3430 Court House Drive Permits: 410-313-2455 www.howardcountymd.gov

Date Received:	1271	16

Permit No.: 811000366

Building Address:	87 whatt	carp	Property Owner's Name: _		ller
City: Lellic # Co	State: Zip Code	11043	Address:	12 15 10 1 Z	LIN
Suite/Apt. #	SDP/WP/BA #:		Phone:		
	Subdivision:	BANK THE PARK	Email:		
	Area:Lo				
			Applicant's Name & Mailir Applicant's Name:	ig Address, (if othe	er than stated nerein)
	_ Parcel: Grid		Address:		
Zoning: Map	Coordinates:Lo	ot Size:	City:		
ZEN			Phone:Email:	Fax:	
Existing Use:	Λ				
Proposed Use:	11		Contractor Company:		about four
Estimated Construction Cost:	\$ 250,000		Contact Person:		
	ling indiction, 3	and Convi	Address:	toto	7in Cada
(ar of Dotal	1 01 - 1	04	City:S		zip Code:
3 1/1 1 E			Phone:		
7		Kall	Email:	7347	THE REPORT OF THE PARTY OF THE
Occupant or Tenant:	in Knowletay o	CERTIFE.			
Was tenant space previously	occupied?	□No	Engineer/Architect Compar	ту:	STORES OF THE STORES
Contact Name:			Responsible Design Prof.:		
Address:			Address:		
	Chris	and an			- C-1-
	State: Zip C	oue:	City:S		
Phone:	Fax:		Phone:	Fax:	
Email:			Email:		
2 110 111 01			The state of		
Commercial Building Charac Height:	teristics Residential Buildin		Utilities Water Supp	4.	
No. of stories:	Depth	Width	Water Supp	iX	
Gross area, sq. ft./floor:	1 st floor:		DI-Public CI Private		
	2 nd floor:	THE PERSON NAMED IN	Private	and and	
Area of construction (sq. ft.):	Basement:		Sewage Dispo	isai	
Use group:	☐ Finished Baseme ☐ Unfinished Baser				
ose group.	☐ Crawl Space	Hent	☐ Private Electric: ☐ Yes	□No	
Construction type:	☐ Slab on Grade		Gas: Yes	E No	
☐ Reinforced Concrete	No. of Bedrooms:	3	Heating Syste	The same of the sa	
Structural Steel	Multi-family		☐ Electric ☐ Oil	<u>-111</u>	70 70 TO 170 170 170 170 170 170 170 170 170 170
☐ Masonry ☐ Wood Frame	No. of efficiency uni	its:	□ Natural Gas □ Propa	ane Gas	
☐ State Certified Modular	No. of 2 BR units:		Other:	arie das	
	No. of 3 BR units:		Sprinkler Syste	em:	
	Other Structure:		☐ Yes ☐ No		
Non-deld-To- Daily T	Dimensions:			-	
➤ Roadside Tree Project Po	THE RESERVE TO THE PARTY OF THE		Grading Po	ermit Number:	
Roadside Tree Project Per		lodular	- Contract C		
	☐ Manufactured He	The state of the s	Building Shell Po	ermit Number:	THE PROPERTY OF THE PARTY OF TH
WITH ALL REGULATIONS OF HOWARD THIS APPLICATION; (5) THAT HE/SHE OF Applicant's Signature Email Address	AND AGREES AS FOLLOWS: (1) THAT H D COUNTY WHICH ARE APPLICABLE THE GRANTS COUNTY OFFICIALS THE RIGHT T	ERETO; (4) THAT HE/SHE N TO ENTER ONTO THIS PRO	VILL PERFORM NO WORK ON THE ABO	VE REFERENCED PROPER	RTY NOT SPECIFICALLY DESCRIBE
	UE STARHOUS	MONE			
Title/Company	Checks David	able to: DIRECTOR OF I	INANCE OF HOWARD COUNTY		
	Cricus Payo	**PLEASE WRITE NE	ATLY & LEGIBLY**		
		-FOR OFFICE	USE ONLY-		
AGENCY D	DATE SIGNATURE OF APPROVA		INFORMATION	Filing Fee Permit Fee	\$ 25.00

Building Officials PSZA (Zoning) PSZA (Engineering) 5/16/16

Is Sediment Control approval required for ISSU

CONTINGENCY CONSTRUCTION START ice? 🗆 Yes 🗆 No

Green: PSZA,Zoning

SDP/Red-line approval date: Yellow: PSZA,Engineering

Lot Coverage for New Town Zone:

All minimum setbacks met? ☐ Yes ☐ No

Is Entrance Permit Required? ☐ Yes ☐ No Historic District? ☐ Yes ☐ No

Side St.:


Historic District?


Excise Tax PSFS **Guaranty Fund** Add'l per Fee **Total Fees** Sub-Total Paid **Balance Due** Check

Pink: Health


Gold: SHA


istribution of Copies: White: Building Officials





4





Bricker, Robert

Updated Plan

From:

johnkkeller < john@hlussta.houses.com

Sent:

Thursday, April 14, 2016 4:11 PM

To:

Bricker, Robert

Subject:

RE: B16000366 Health Department comment - Keller 4887 Wharff Lane

Attachments:

Keller SDK 041416.pdf

Mr. Bricker,

I spoke with the the guy that did the well abondonment and he will send me a well abondonment certificate that I will forward to you. Aslo, I have attached an updated House Plan showing the 2nd fl office with clearly marked shelving and cabinets on all walls. Let me know if you need anything else.

Regards, John

From: Bricker, Robert [mailto:PR

Sent: Thursday, April 14, 2016 3:45 PM

To:

Subject: FW: B16000366_Health Department comment - Keller 4887 Wharff Lane

Mr. Keller, I did not originally see all of the attachments that you sent. I will review the remainder this afternoon.

Robert Bricker, REHS/RS, L.E.H.S.

From: John Keller [mailtoxicha@blucettarhousen]

Sent: Monday, April 11, 2016 4:44 PM

To: Bricker, Robert **Cc:** John Keller

Subject: RE: B16000366_Health Department comment - Keller 4887 Wharff Lane

Mr. Bricker.

I have attached the items you requested: Location of septic system and Invoice for work, Well abandonment work and invoice, revised house plans showing my office on 2nd floor and appeal letter for perc. cert. Please call me if you need anything else.

Regards, John Keller (410) 804-0448

From: Bricker, Robert [mailto: P.Bricker Chowardsount; md.gov]

Sent: Thursday, February 25, 2016 1:54 PM

To: john@bleestarhouses.com

Subject: B16000366_Health Department comment

See attached PDF.

ROBERT BRICKER, REHS/R.S., L.E.H.S. ENVIRONMENTAL SANITARIAN II BUREAU OF ENVIRONMENTAL HEALTH, WELL AND SEPTIC PROGRAM 8930 STANFORD BLVD., COLUMBIA, MD 21045

Phone: Desk, 410-313-2691; Program, 410-313-1771; Bureau, 410-313-1774

Fax: 410-313-2648

February 25, 2016

John Keller/Elena Keller 4887 Wharff Lane Ellicott City, MD 21043

Howard County Health Dept.

Bureau of Environmental Health

Attn: Mike Davis

Re: B16000366: proposal for addition – Waiver of Percolation Certification Plan

Dear Mr. Davis,

Per the correspondence from Robert Bricker, as the co-owner of the home at 4887 Wharff Lane, I would like to request a waiver of the Percolation Certification Plan. I am adding an addition on to my home to make it handicap accessible for my twelve year old son who is in a power-chair and would like to start the renovations as soon as possible with all the proper permits.

Thank you for your timely consideration.


- Elanc Kelh

Best Regards,

John Kæller

Mena Keller

3/10/16
Approved
malal J Javin



Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-1771 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth
Twitter: HowardCoHealthDep

Maura J. Rossman, M.D., Health Officer

Date: April 13, 2016

To:

John Keller, Applicant

Later Company Company

RE:

B16000366; proposal for construction of addition at 4487 Wharff Lane

Dear Mr. Keller,

I have received the copy of invoice you submitted for having your well 'sealed'. I expect that a Licensed Well Driller will soon be sending me a Well Abandonment Report as required by Code of Maryland Annotated Regulations [COMAR] 26.04.04.34.G..

I can inform you that Mr. Davis has approved a waiver, per your request that a Percolation Certification Plan will not be required for this proposal (B16000366).

There remain two primary issues: a revision of the floor plan and a revision of the plot plan. The revised plot plan and the revised floor plan are to be submitted to the Department of Inspections, Licenses, and Permits (DILP). A formal revision sheet must be submitted with the plans in response to Health Department comment.

1. The Plot Plan must be revised to include the locations of the septic tank and the septic system distribution trenches.

While there is a record for the installation of a 1000-gallon septic tank in 1991, the record does not include a description of the distribution trenches, their location(s), inlet depth, gravel depth, and/or trench bottom depth.

- a. The Health Department requires that the septic tank location be accurately illustrated on the Plot Plan, and the distribution trench location(s), or dry well location, be illustrated as accurately as possible.
- b. The Health Department requires a report, generated by a professional and presented on their official letterhead that describes the values for the aforementioned distribution system parameters.

Location of distribution trenches may be obtained by several methods:

 A contractor that conducts surveys with a Ground Penetrating Radar can locate the trenches, and may also be able to confirm trench bottom depths and estimate trench inlet depths. Limited excavation may be required for confirmation.

- ii. A septic contractor may be able to locate the septic system trenches by utilizing a combination of methods that includes probes and articulated electronic sensors. Excavation may be utilized for confirmation. It may be difficult to predict the extent of excavation required to confirm trench location(s), length and depth.
- 2. The floor plan includes a room (labeled as 'Playroom') that is greater than 90 sq.ft., and has a door, a closet, and a window. Construction of the room as proposed creates a space that fits the Code definition for a bedroom [Howard County Code 3.801(B)], and triggers the requirement for a septic system upgrade to include a Best Available Technology (BAT) unit and possibly additional trench absorption area.

The 'Playroom' configuration may be modified. So as not to fit the Code definition of a bedroom, a redesign of the 'Playroom' would <u>eliminate the closet (re: "storage")</u>, most likely by removing the doors, <u>and</u> incorporate <u>one</u> of these three options:

- i. Eliminate the room entrance door and make the entrance to the room 4-feet wide,
- ii. Construct a half-wall between the 'Playroom' and another room, OR
- iii. Encumber all walls in the 'Playroom' with built-in components such as shelving and cabinets

Should you have any questions concerning this matter, you may contact me by email (rbricker@howardcountymd.gov), or by calling 410-313-2691.

Respectfully,

Robert Bricker, REHS/R.S., L.E.H.S.

Environmental Sanitarian, Well and Septic Program

Howard County Bureau of Environmental Health

Enclosure: (1) definition of Bedroom

Copy: file

+887 Whorly Lm.

Davis, Michael J

From:

Bricker, Robert

Sent:

Friday, April 22, 2016 8:49 AM

To:

Davis, Michael J

Subject:

FW: B16000366_Health Dept follow-up

Mike,

See below, Mr. Keller's request for waiver.

Robert Bricker

From: johnkkeller [mailtout

Johnkkeller [Barran Jan 1987]

Sent: Thursday, April 21, 2016 5:06 PM **To:** Bricker, Robert

Cc: okallar amunada

Subject: RE: B16000366_Health Dept follow-up

Mr. Bricker,

Per our conversation, I am requesting a hardship on the additional charge of \$506 for overseeing the septic co. when they dig an observation pit to analize soil composition.

The reason I am seeking a permit is to renovate my house to make it handicap accessiable for my 13 year old son who has Cerebral Palsy and is in a powerchair. We must build a ramp, enlarge all openings, install a walk-in shower, install an elevator etc. We have maxed out our home equity line of credit to renovate and have no room in our budget for any and all additional expenses.

Every day that goes by without a permit to start renovation is costing me money and putting my son at a further disadvantage for quality of life. We supplied all the necessary things that were required in your initial letter, at considerable cost, but we knew we had to in order to obtain a permit. There was no request for dry well depth in the initial letter, just location of the septic system.

Now you are requesting additional work to be done because of the location of the dry well to perc test B. I was told by Fogles that there was no issue with the location of the dry well because it was far enough away, per code and health dep. parameters. Just to check it out, could cost me \$1,000 or more. I can understand needing the depth of the dry well and I can have Fogle come back out and give me that considering that should have been included in their initial survey, but I do not understand why we need to go to the additional time and expense of digging an observation hole when our septic system is fully operational and will prolong the permit process even further.

I am asking you and your supervisor to take all this into consideration and help me do what is best for my son. Best regards,

John Keller

From: Bricker, Robert [mailto: Robert Columnia | Column

Sent: Thursday, April 21, 2016 11:48 AM

To:sinha@hlumbanhana

Subject: B16000366_Health Dept follow-up

Mr. Keller,

I apologize that my review has taken longer than expected. Please see attached PDF for a summary of the review of all submittals and the Health Department requirements for approval.

ROBERT BRICKER, REHS/R.S., L.E.H.S.
ENVIRONMENTAL SANITARIAN II
BUREAU OF ENVIRONMENTAL HEALTH, WELL AND SEPTIC PROGRAM


COMPLETE THIS FORM WHEN DROPPING OFF ANY CORRESPONDENCE AND/OR PLANS TO THE HOWARD COUNTY DEPARTMENT OF INSPECTIONS, LICENSES AND PERMITS COUNTER:

Date:	7-216	
To:	(Person's Name and Division)	_
From:	(Your Name, Company Name and Telephone Number)	RECEIVED.
Subject:	Project name Celler	VPCTIA
	Project site address 4897 Wharff Care	MAY 02 2016
	Permit # \(\begin{aligned} \b	PLAN REVIEW DIVISION
	Other information pertinent to this project	PLANT NET
✓ Please chec	k the attachments below that you are submitting with this transmittal:	
Letter	of response to address plan review comment letter	
Revise	ed plans and/or revised details: When submitting for a complete re-review, duplicate	e sets shall be submitted.
Letter	Summarizing Changes	
Energ	y conservation calculations	
Copie	s of (be specific).	
	Health Department Request DPZ/ DED Request	Applicant's Request
Two s	ets of single family dwelling model plans to be placed on permanent file: Model name of the source of the plans of the pla	/
Cont	act Person Information: (Required)	shetve
Diam	John Celler Telephone No: 40	8040418
Pleaso	e Print Name E-Mail Address:	- Office ther
		Locytes . Con
PLEASE ASS	SURE ALL DOCUMENTS AND/OR REVISIONS ARE APPROPRIATELY SIG	GNED AND SEALED, IF
INFORMATI OF INSPECT	Y, BY A LICENSED ARCHITECT OR ENGINEER. PLEASE BE ADVISED YON MAY RESULT IN THE DELAY OF REVIEW BY THE PLANS EXAMINE YIONS, LICENSES AND PERMITS WILL CONTACT YOU IF THERE IS A PROBUILDING PERMIT IS APPROVED BY THE PLAN REVIEW DIVISION AND A	R. THE DEPARTMENT OBLEM. IN ADDITION,
	AGENCIES, AND THE BUILDING PERMIT <u>IS</u> READY FOR ISSUANCE, T	
	FY THE APPROPRIATE CONTACT PERSON FOR PERMIT PICK UP.	
_	SHALL BE DIRECTED TO THE PERMIT DIVISION AT 410-313-2455. CODE REVIEW INQUIRIES SHALL BE DIRECTED TO THE PLAN REVIEW DIV	_
	LOW A MINIMUM OF FIVE (5) WORKING DAYS FOR ANY PLAN SUBMITT	

Received by

THANK YOU.

White-Plan Review / Yellow-Applicant / Pink-Permit Division t:\forms\transmit.frm - Rev. 04/2014



Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-1771 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth
Twitter: HowardCoHealthDep

Maura J. Rossman, M.D., Health Officer

Date: April 21, 2016

To: John Keller, Applicant

John Chlusterhomes.com

RE: B16000366; proposal for construction of addition at 4487 Wharff Lane

Dear Mr. Keller,

Myself and others in the Bureau of Environmental Health (the Bureau) have reviewed the documents that you sent in response to my comments concerning the proposed addition for your residence (B16000366). Summarizing the documents received and reviewed:

- 1. A request for waiver from the Percolation Certification Plan requirement was received, then reviewed and approved by Michael Davis, Assistant Director of the Bureau.
- 2. A copy of the invoice from R & G Water Systems, Inc. was received and reviewed. I understand that you will be forwarding a copy of the Well Abandonment Report from Licensed Well Driller as soon as you receive it.
- 3. A revision of the 2nd Floor (Upper Level) floor plan illustrating that the "Office" has no closet and the walls of the described space will be encumbered by built-in shelving and cabinets. This revision, received by email on April 14, illustrates a design for a three-bedroom residence, and is approvable when submitted to DILP as a formal revision.
- 4. An edited version of the sketch on the back of the Septic System Installation Permit (A49839) apparently modified by the information gathered by Fogle's Septic Clean, Inc. on or about March 2, 2106.
 - a. The relative locations of the septic tank and dry well are illustrated as amendment of the original sketch.
 - i. The modified sketch is not acceptable as a substitute for a Plot Plan revision.
 - ii. The location data gathered by Fogle's may be accurately represented on a drawing for your property, i.e., the drawing originally submitted as your Plot Plan, then formally re-submitted to DILP as a revision.

- iii. The depth of the dry well was not determined.
- iv. The proximity of the dry well to perc test location 'B' presents a condition for further investigation.
 - 1. The observation hole was dug to a depth of 9 feet where ">50" rock is described.
 - 2. The results of percolation tests conducted at 5 feet depth indicate that coarse materials such as sand or fragmented rock occurs at that level in the profile as the tests were all less than 2 minutes per inch.

Code of Maryland Regulations 26.04.02.03F(4) requires the Health Department to certify the existing on-site sewage disposal and water supply systems as capable of treating and disposing the existing sewage flows and meeting the water demand and any reasonable foreseeable increase in sewage flows or water demand before approving the building permit. The Health Department shall consider the number of bedrooms, total enclosed living space and changes that affect the volume or character of the wastewater in making this determination. Therefore, it is necessary to observe the soil profile in the immediate vicinity of the dry well. The observation pit must be dug, and the soil profile described, to a depth of at least 4 feet greater than the depth to the bottom of the dry well. The result of the observation will determine whether the Building Permit (B16000366) can be approved without additional requirements or if there will be additional requirements for septic system upgrade in order to gain approval.

- a. Permit B16000336 may be approved if the dry well is located in soil where the soil profile is observed to a depth at least 4 feet greater than the depth of the dry well and that profile does not have rock content greater 50 percent in the infiltration zone or the 4-foot buffer zone.
- b. If the soil profile in the vicinity of the dry well fails, a septic system upgrade will be required that includes a BAT unit and trench absorption system designed for the existing residence and the proposed addition.

Should you have any questions concerning this matter, you may contact me by email (rbricker@howardcountymd.gov), or by calling 410-313-2691.

Respectfully.

Robert Bricker, REHS/R.S., L.E.H.S.

Environmental Sanitarian, Well and Septic Program Howard County Bureau of Environmental Health


Enclosure: Copy: file

8930 STANFORD BLVD., COLUMBIA, MD 21045

Phone: Desk, 410-313-2691; Program, 410-313-1771; Bureau, 410-313-1774

Fax: 410-313-2648

E-mail: rbricker@howardcountymd.gov



Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-1771 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth
Twitter: HowardCoHealthDep

Maura J. Rossman, M.D., Health Officer

Date: February 24, 2016

To:

John Keller, Applicant

John@bluestarhomes.com

RE:

B16000366; proposal for construction of addition at 4487 Wharff Lane

Dear Mr. Keller,

I have conducted a review of the referenced Building Permit Application (B16000366) and associated Plot Plan, and Health Department records for "4487 Wharff Lane". I have placed the proposal 'On Hold'.

Several issues must be resolved.

- 1. There is a pit well on the property that has been abandoned since the property was connected to the public water supply. That pit well must be sealed for the Health Department to be able to exercise its authority to approve a building permit for the proposed improvements. The well must be sealed by a Licensed Well Driller. This is an ongoing issue, and the Health Department will consider this issue resolved when a Well Abandonment Report has been received and approved by an Environmental Health Specialist.
- 2. The Plot Plan must be revised to include the locations of the septic tank and the septic system distribution trenches. The revised Plot Plan is to be submitted to the Department of Inspections, Licenses, and Permits (DILP) in response to this Health Department comment. While there is a record for the installation of a 1000-gallon septic tank in 1991, the record does not include a description of the distribution trenches, their location(s), inlet depth, gravel depth, and/or trench bottom depth.
 - a. The Health Department requires that the septic tank location be accurately illustrated on the Plot Plan, and the distribution trench location(s) be illustrated as accurately as possible.
 - b. The Health Department requires a report, generated by a professional and presented on their official letterhead that describes the values for the aforementioned distribution system parameters.

Location of distribution trenches may be obtained by several methods:

 A contractor that conducts surveys with a Ground Penetrating Radar can locate the trenches, and may also be able to confirm

- trench bottom depths and estimate trench inlet depths. Limited excavation may be required for confirmation.
- ii. A septic contractor may be able to locate the septic system trenches by utilizing a combination of methods that includes probes and articulated electronic sensors. Excavation may be utilized for confirmation. It may be difficult to predict the extent of excavation required to confirm trench location(s), length and depth.
- 3. There is not a Percolation Certification Plan among the Health Department's record for your property. The signed Percolation Certification Plan is the basis for the Health Department's authority to approve building permits and well and septic system permits.
 - a. There is a copy of a plat of re-subdivision (F-94-109, Smith Property Lots 1 and 2) in Health Department records on which is illustrated two sewage disposal areas (SDA) on your property (Lot 1).
 - b. A waiver from the Percolation Certification Plan requirement may be available.
 - i. The property owner must request the waiver from Percolation Certification Plan requirement.
 - ii. The request to waive the Percolation Certification Plan requirement must be in writing, signed by the owner is addressed to Mike Davis, Associate Director, Bureau of Environmental Health.
- 4. The floor plan includes a room (labeled as 'Playroom') that is greater than 90 sq.ft., and has a door, a closet, and a window. This room fits the Howard County Code definition of a bedroom [3.801(B)]. Construction of the room as proposed will cause an increase in the estimated daily peak wastewater flow for the residence, a condition which triggers the requirement for a septic system upgrade to include a Best Available Technology (BAT) unit and possibly additional trench absorption area.
 - a. The 'Playroom' configuration may be modified. The revised floor plan must be submitted to DILP as a formal revision required by the Health Department.
 - b. So as not to fit the Code definition of a bedroom, a redesign of the 'Playroom' would <u>eliminate the 'closet (re: storage)</u> and incorporate one of these three options:
 - i. Eliminate the door and make the entrance to the room 4-feet wide,

- ii. Construct a half-wall between the 'Playroom' and another room, OR
- iii. Encumber all walls in the 'Playroom' with built-in components such as shelving and cabinets

Should you have any questions concerning this matter, you may contact me by email (rbricker@howardcountymd.gov), or by calling 410-313-2691.


Respectfully,

Robert Bricker, REHS/R.S., L.E.H.S.

Environmental Sanitarian, Well and Septic Program Howard County Bureau of Environmental Health

Enclosure: (1) definition of Bedroom

Copy: file



RG WATER SYSTEMS, INC. TM FAMILY OWNED & OPERATED

SED	VICE	TNV	OICE
1301	K B C . D'	, 11 V	TILL P

G WATER SYSTE	OPERATED	ime m:		ic Gui.	Total Hours.
3102 Main Street Man Md. Lic.# WCI1 PHONE - 410-239-0700 To Fax 443-500	33, PI0141 oll Free – 800-352-9836	er A Ywe e		рН НА	TDS
NAME: MY. JOHN KEL	IETL	DATE:	4/11/	lis TIM	√E:
ADDRESS: 4887 WHAR	UF LANE				40448
ELLICOTT	City My. 21043	- WORK		10-0-	110/10
JOB ADDRESS:		1 .			
		- CELL#	•	:	
		-			
TYPE OF SERVICE: PROPOS	AL INSTALL SERVICE	PUMP	HW	H WO	MISC.
WORK PERFORMED:					
LEWOVED JET	PUP SYSTEM	FROM	w	FU	(HOUTE)
55/0" STOWN (A)	E) WELL SHUT			•	
J / Jieer City	Ly Muller Jimes				7
	1.			***************************************	
QTY MATERIAL/EQUIPM	FNT				
1 - 1	HED PEA CHANT				
1 CHORINE.	117 7 011 07110				
1,200 LBS. OF FOR	MARIO CROUTT.				
		T	ob Tota	- I.	
WELL TAG# NONE	PERMIT#		Varrant		
Payment is due upon completion of wor					t# 850.00
or the service of a collection agency, all re- customer's responsibility. The cost of thes			ay Im	s Amoun	W 850.00
Finance charges of 2% per month will be	•	oc adc.			
All work specified will be completed in a workmanlik	•	es, unless Wor	k Order	Complete	1
requested differently by Homeowner and as described		7.1	Kufl	ap re	
specifications involving extra costs will be executed or charge over and above the estimate. All agreements or			1	rvicemān's	Signature
control.	onlingula upon su nes, accidents de ceiays objet	0.00	iii Card iration [
Acceptance of Proposal		-Seci	inty Co		· · · · · · · · · · · · · · · · · · ·
The above prices, specifications and conditions are sa do the work specified. Payment will be made upon co		orized to			
оф ые мога эрестиса. глуппан with не инное ароп со	пересон от аз эрееней авоче.	1	1		
	Service and Job Complet	ion:X	//	1	2
•	Payment Amount Reciev	red: 45575	100	INF	ULL_PARTIAL
How did you hear about us?	Payment Method:	X#/10	<u>/</u>	87-	**************************************
9	Balance Due	Due (Jn	1-7	

Fogle's Septic Clean, Inc.

580 Obrect Road Sykesville, MD 21784 410-795-5670

Customer Phone

10-14 50	
Date	3/2/2016

WORK ORDER

JOB LOCATION	Name / Address	
JOHN KELLER 4887 WHARFF LN ELLICOTT CITY, MD 21043	JOHN KELLER 4887 WHARFF LN ELLICOTT CITY, MD 21043	

410-804-0448

Description	Qty	Cost	Total	
***** CALL AHEAD ****				
SERVICE CALL - LOCATE AND MARK TRENCHES		250.00	250.00	
Lantz & painted out	fano	f t Dy we	11	
y v		4 + 250.00 4 + Dy Wo 5715 CK	#	
		2113 011	* .	
TANK ACCESS TANK LEVEL TANK CONDITION	1			
Manhole: Y N Normal Good Cleanout: Y N Overfull Heavy Solids				
Low Roots				
Tank Depth Wipes Other:	4			
TO ENSURE PROPER CLEANING. FOGLE'S SEPTIC RECOMMENDS				
PUMPING FROM THE MANHOLE AND NOT THE 6" CLEANOUT				
CALL OFFICE TO SCHEDULE: Snake inlet line Other:			· ·	
Snake outlet line				
		Total	\$250.00	

Customer Signature

Rickey L. Roos, Sr. President 24-Hour J WAYTER SYSTEMS W

Within Hours of 3102 MAIN STREET, MANCHESTER, MD 21102

410-239-0700 • 800-352-9836 • 443-508-2902 Fax 443-508-2903 ♦ www.rgwater.com Specialty Licensed Water Conditioner & Pump Installers

Well Pumps • Well Tanks • Neutralizers/Softeners • Reverse Osmosis Units

Specializing In:

 Ultra-Violet Sterilizer Lights • Constant Pressure/Booster Systems Family Owned & Operated . Solving your water problems one drop at a time!!



