DATE	RESULTS OF REVIEW FOR FILE
5/6/16	TC- I spoke to Tony w/ FCC and stated
	that the SDA mist be >100' from pand. He
	also met show well/septe for property across
	shoet it croppedos for septie. He can
	resulant t we will see how under toolse looks
	Roc possible testing. Des
-	



Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045 Main: 410-313-2640 | Fax: 410-313-2648 TDD 410-313-2323 | Toll Free 1-866-313-6300 www.hchealth.org

Facebook: www.facebook.com/hocohealth
Twitter: HowardCoHealthDep

Maura J. Rossman, M.D., Health Officer

MEMORANDUM

TO:

Juanita King

FROM:

Jeff Williams 🔗 🗸

RE:

Refund, receipt # 58039, refunding \$506 for a perc test application at 12210 Hall Shop

Road

DATE:

August 22, 2017

Please submit the paperwork for a refund of \$506 to Dorothy Stull who paid \$506 for a perc test at 12210 Hall Shop Road as part of receipt #58039.

Ms. Stull paid for the testing, but decided not to follow through with perc testing on the lot. There was no plan submitted with the original application, so there was no plan review conducted. No work was performed by the Health Department as part of the application. Therefore, the \$506 may be refunded.

Bureau of Environmental Health 8930 Stanford Blvd | Columbia, MD 21045 410.313.2640 - Voice/Relay 410.313.2648 - Fax 1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

Date: February 7, 2019

TO: Tony Fertitta.

Fisher, Collins & Carter, Inc.

FROM: Robert Bricker, REHS/R.S., L.E.H.S.

Environmental Sanitarian II, Well and Septic Program

RE: 12210 Hall Shop Road (Stull Property, Part 1), Percolation Certification Plan, comments

Edits are required in plan content, as described:

- 1. Include the property address as a subtitle for the plan.
- 2. In Replacement System design,
 - a. Delete the term "1st" in the title as there is only one replacement system,
 - b. Use the design criteria issued on the spec sheet for the '2nd' Replacement, i.e.,
 - i. Effective Sidewall Begins at 4.0 feet, and
 - ii. Trench (Bottom) Depth is 5.5 feet.
- Illustrate field-run 1-ft elevation contours in the sewage disposal area (SDA).
- 4. Edit General Note 7 as necessary.
- 5. The correct identifier for the perc test in the center of the SDA is '502'.
- 6. Attached is a graphic that is a markup on a photocopy of the Plan View.
 - a. Adjust the lower boundary of the SDA as indicated.
 - b. Adjust the upper boundary slightly, if needed.
 - c. Consider the length and arrangement of the trenches sketched onto the markup. I placed the suggested locations for trenches working from the lower boundary toward the upper boundary.
- 7. In General Note 1, first sentence, delete the (19) words between PRIVATE SEWAGE AREA and AS REQUIRED. In essence, the first sentence begins by stating THIS AREA DESIGNATES A PRIVATE SEWAGE AREA AS REQUIRED BY THE MARYLAND.....
- 8. In Notes 2, 4 and 9, replace the terms "EASEMENT" and "EASEMENTS", with the terms 'AREA' and 'AREAS', respectively.
- 9. Include the owner's name, the owner's address, and the owner's phone number on the plan.

Website: www.hchealth.org Facebook: www.facebook.com/hocohealth Twitter: @HoCoHealth

10. Delete General Note 13.

11. Replace General Note 6 with this note:

THE WELL SHALL BE DRILLED PRIOR TO HEALTH DEPARTMENT APPROVAL OF THE BUILDING PERMIT FOR CONSTRUCTION OF A RESIDENCE ON THIS PARCEL. IT IS THE DEVELOPER'S RESPONSIBILITY TO SCHEDULE WELL DRILLING PRIOR TO SUBMITTING A BUILDING PERMIT PROPOSAL. IT SHALL NOT BE CONSIDERED 'GOVERNMENT DELAY' IF THE WELL-DRILLING HOLDS UP HEALTH DEPARTMENT APPROVAL OF THE BUILDING PERMIT APPLICATION.

12. Replace General Note 11 with this note:


THE SUBJECT PROPERTY HAS A LIMITATION OF THREE (3) BEDROOMS UNLESS AN EXHIBIT PRESENTED BY A CERTIFIED PROFESSIONAL DEMONSTRATES THAT THE SEWAGE DISPOSAL AREA WILL ACCOMMODATE THE WASTEWATER DISCHARGE FOR A RESIDENCE HAVING MORE THAN 3 BEDROOMS. A WAIVER TO THIS LIMITATION MAY BE AVAILABLE THROUGH THE BUREAU OF ENVIRONMENTAL HEALTH IF THE OWNER COMMITS TO INSTALLING AN APPROVED ADVANCED PRE-TREATMENT UNIT AS A COMPONENT OF THE SEPTIC SYSTEM.

13. Replace General Note 12 with this note:

AN INITIAL DRAINFIELD SYSTEM FOR A 4-BEDROOM RESIDENCE AND ONE REPLACEMENT DRAINFIELD SYSTEM FOR A 4-BEDROOM RESIDENCE WILL FIT WITHIN THE PROPOSED SEWAGE DISPOSAL AREA ON THIS PARCEL. THEREFORE, INSTALLATION OF AN ADVANCED PRE-TREATMENT UNIT IS REQUIRED TO QUALIFY FOR A WAIVER FROM THE REQUIREMENT THAT THE SEWAGE DISPOSAL AREA BE LARGE ENOUGH TO ACCOMMODATE AN INITIAL DRAINFIELD SYSTEM AND TWO REPLACEMENT DRAINFIELD SYSTEMS FOR THE RESIDENCE BEING PROPOSED. A SUPPLEMENTAL SITE PLAN WITH ALL OF THE NECESSARY DETAILS FOR INSTALLATION OF THE SEPTIC SYSTEM, INCLUDING THE ADVANCED PRE-TREATMENT UNIT, WILL BE REQUIRED PRIOR TO THE RELEASE OF THE BUILDING PERMIT.

RB

Copy: file



FISHER, COLLINS & CARTER, INC.

CIVIL ENGINEERING CONSULTANTS and LAND SURVEYORS

Transmittal

Terrell A. Fisher, P.E., L.S. Earl D. Collins, P.E. Charles J. Crovo, Sr., P.E., L.S.

Paul W. Kriebel, P.E.
Mark L. Robel, P.L.S.
Aldo M. Vitucci, P.E.
Frank Manalansan II, L.S.
Stephanie Tuite, RLA, P.E., LEED AP BD&C

Via:	Fax	Mail	Messeng	er	E-Mail		☐ To Be Picked Up		
	Fax (ori	ginal to follow via L	J.S. Mail)						
То:	Bureau of Environmental Health				Attn:	Ro	bert		
	8930 Stanfo	ord Boulevard		1	Fax:	(41	0) 313-2648		
	Columbia, MD 21046-4544				Phone: (410) 313-2640				
From:	Tony Fertit	ta		(CC:				
Re:	: Stull Property					W.O.# 16019-7001			
Date:	January 29	, 2019		1	Pages:	3	Page(s) Including this cover		
We a	re forwarding:	⊠ Prints □	Copy of Letter	Speci	fication	ıs	Shop drawings Other		
		Urgent U	For your use	As red	queste	d	For Review & Comment		
Rema	urke.								
Robe									
Enclosed please find Two (2) prints of the drawing entitled " Perc Certification Plan " dated January 29, 2019.									
If we may be of any further assistance, please do not hesitate to call.									
	Very truly yours,								
	Tony Fertitta								

CONFIDENTIALITY NOTICE

This transmission contains confidential information which may be legally privileged, and is intended only for the use of the individual named above. If you are not the intended recipient, you are hereby notified that any distribution (except to the intended recipient), copying, or disclosure of this transmission is strictly prohibited.

Hall Shop Kond #500 Existing Well for House nelyt doos ·#501 ww o depos Wishing 7100 te deposits many puch /4 #503 500 Red Brown ,000 must maintain, from Pond White Sand. through DATE TEST# DEPTH START BREAK STOP TIME OF P/F/H 1" DROP 2" DROP 2ND INCH out I until 4-12-1750019 Red Brown 861 SBK 0.8 10:00 10:15 10:05 Red Brown 10:30 10:50 ixella #501 Brown 10:58 10:12 4.5 Red Brow white Wellow 0.8 Brown Xllow area must be 100 away Many itu, BACKHOE TEST HOLES USED IN SDA INLET DEPTH Please get an exact location wish, > Very little Had supage @ 14 well. It is located in well

Williams, Jeffrey

From:

Williams, Jeffrey

Sent:

Thursday, June 29, 2017 11:36 AM

To:

tonyf@fcc-eng.com

Cc:

Bernard, Dana

Subject:

12210 Hall Shop Rd

Hi Tony. Dana sent this PC up for signature and I have a comment for revision:

1. Note 1 is inaccurate for the project. The note should specify that it is showing area for an initial and one replacement system with pretreatment.

Thanks

Jeff Williams
Program Supervisor, Well & Septic Program
Bureau of Environmental Health
Howard County Health Dept.
410-313-4261
jewilliams@howardcountymd.gov

CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

Hall Shop Kond #500 Existing Well for House nelyt doos ·#501 ww o depos Wishing 7100 te deposits many puch /4 #503 500 Red Brown ,000 must maintain, from Pond White Sand. through DATE TEST# DEPTH START BREAK STOP TIME OF P/F/H 1" DROP 2" DROP 2ND INCH out I until 4-12-1750019 Red Brown 861 SBK 0.8 10:00 10:15 10:05 Red Brown 10:30 10:50 ixella #501 Brown 10:58 10:12 4.5 Red Brow white Wellow 0.8 Brown Xllow area must be 100 away Many itu, BACKHOE TEST HOLES USED IN SDA INLET DEPTH Please get an exact location wish, > Very little Had supage @ 14 well. It is located in well

Williams, Jeffrey

From:

Williams, Jeffrey

Sent:

Thursday, June 29, 2017 11:36 AM

To:

tonyf@fcc-eng.com

Cc:

Bernard, Dana

Subject:

12210 Hall Shop Rd

Hi Tony. Dana sent this PC up for signature and I have a comment for revision:


1. Note 1 is inaccurate for the project. The note should specify that it is showing area for an initial and one replacement system with pretreatment.

Thanks


Jeff Williams
Program Supervisor, Well & Septic Program
Bureau of Environmental Health
Howard County Health Dept.
410-313-4261
jewilliams@howardcountymd.gov

CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.



(in-law) representing 2.04 Ac. Jarce's



Bureau of Environmental Health

7178 Gateway Drive (410) 313-2640 TDD (410) 313-2323 Columbia, MD 21046 Fax (410) 313-2648 Toll Free 1-866-313-6300

website: www.hchealth.org

Maura J. Rossman, M.D., Health Officer

August 28, 2017

To Whom It May Concern:

Dorothy Stull paid for a Perc Test in the Amount of \$506.00 (check #191); for 12210 Hall Shop Rd, however Ms. Stull decided not to follow through with the Perc Test. No file work was done by the Health Department and no plan review was performed.

Therefore the \$506.00 test application fee may be refunded. (Receipt # 58039)

Attn: Dorothy Stull. 12620 Hall shop Rd. Fulton, MD 20759

> #58039 03/18/2016 written by Juanita King #89003 03/23/2016 written by Willie Sims

Thanks in advance,

Jeff Williams

Jeff Williams **Howard County Health Department** 8930 Stanford Blvd. Columbia, MD 21045

To Whom it May Concern:

Per telephone conversation between Jeff Williams and Gordon Walker, this letter is to request a refund of \$495.00.

I paid for two perc tests on the property at 12210 Hall Shop Road, Clarksville, MD but only one was completed.

The attached documents further substantiate this request.


If there are any questions as to the validity of this refund, please contact me at (410) 531-2306.

Sincerely, June Stull Halfer


JUNE STULL WALKER 12620 Hall Shop Road


Fulton, MD 20759

(Dorothy Stull Revocable Trust)



019\Engineering\Dwas\16019-6001 Perc Plan.dwg. 5/5/2016 8:48:52 AM.





\16019\Engineering\Dwgs\16019-6001 Perc Plan.dwg, 6/19/2017 11:45:37 AM, 1.50