


**Bureau of Environmental Health** 8930 Stanford Blvd | Columbia, MD 21045 410.313.2640 - Voice/Relay 410.313.2648 - Fax 1.866.313.6300 - Toll Free ASJOH33


Maura J. Rossman, M.D., Health Officer

# APPLICATION

FOR PERCOLATION TESTING AND SITE EVALUATION
PROPERTY LOCATION
SUBDIVISION/PROPERTY NAME Mc. Alister Property
PROPERTY ADDRESS Lot 3 Mullimix Mill Kd Mt Hiry MD 21771
TAX ACCOUNT # 04-341996 TAX MAP 12 GRID 16 PARCEL 72 LOT NO. 3 SIZE (ACRES) 3.042
ZONING CATEGORY TIER
PROPERTY OWNER(S) James McAlister
DAYTIME PHONE 410-489-7900 CELL EMAIL TIME Horitage Maryland.con
MAILING ADDRESS 30830 Mills Ridge Rd LEWES TE 19958
STREET CITY, STATE ZIP
APPLICANT Timethy Feage Relationship to owner:
DAYTIME PHONE 410-489-7900 CELL EMAIL Time Heritage Maryburg con
MAILING ADDRESS POBOX 482 LISDON MD 21765
STREET CITY, STATE ZIP
I HEREBY APPLY FOR THE NECESSARY TESTING/EVALUATION PRIOR TO ISSUANCE OF SEWAGE DISPOSAL SYSTEM PERMIT(S):
PROPERTY:
SUBDIVISION CLASSIFICATION (PER DEPT. OF PLANNING AND ZONING) 🔲 MAJOR 🔲 MINOR
UPGRADE EXISTING OSDS
BUILDING:
RESIDENTIAL WITH EXISTING OR PROPOSED BEDROOMS IN THE COMPLETED STRUCTURE     COMMERCIAL (PROVIDE DETAIL OF TYPE OF USE AND NUMBERS OF EMPLOYEES/CUSTOMERS ON ACCOMPANYING PLAN)
IS THE PROPERTY WITHIN 2500 FEET OF ANY RESERVOIR?
U /YES
AS APPLICANT, I UNDERSTAND THE FOLLOWING:
<ul> <li>THIS APPLICATION IS VALID FOR TWO(2) YEARS FROM DATE OF FEE PAYMENT AND APPROVAL IS BASED UPON HEALTH OFFICER</li> <li>SIGNATURE OF A PERC CERTIFICATION PLAN PRIOR TO EXPIRATION OF THIS PERMIT.</li> </ul>
THE APPLICATION FEE IS NON-REFUNDABLE
THIS APPLICATION MUST BE ACCOMPANIED BY ALL APPLICABLE FEES AND A SUITABLE SITE PLAN IN ORDER TO BE PROCESSED
THIS IS A PUBLIC DOCUMENT
I declare and affirm that to the best of my knowledge, the information contained herein is correct. I declare that I am the owner of the
property or duly authorized to make this application on behalf of the owner. I agree to comply with all applicable state and county
regulations. By signature of this application, I hereby grant Howard County Health Department officials the right to enter onto the property for the
purpose of inspecting the property as directly related to the requested permit/service.
770 1.1.2
<u> </u>
SIGNATURE OF APPLICANT DATE


Website: www.hchealth.org Facebook: www.facebook.com/hocohealth Twitter: @HoCoHealth





Perc Cert Signed Jan. 2020 . LEGEND VICINITY MAP 205. NHM Sef Belake-Baston showy have, 35 to 60 period steps Get Checks blow, 5 to 10 period steps Det Checks blow, 5 to 10 period steps 120 MCALISTER PROPERT 1/28/202

SEWAGE DISPOSAL TESTI STATE OF MARYLAND - DEPARTMENT OF HEALT HOWARD COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH SERVICES	-
P. O. BOX 473 ELLICOTT CITY, MARYLAND 21043 TELEPHONE: 992-2330	DATE - HALAT
TO: THE COUNTY HEALTH OFFICER ELLICOTT CITY, MARYLAND	
L HEREBY, APPLY FOR THE WECESSARY TEST IN ORDER TO CONSTRUCT (OR RECONSTRUCT)	A SEWAGE DISPOSAL SYSTEM.
PROPERTY OWNER UP OT MC ALISTEZ	· · · · · · · · · · · · · · · · · · ·
ADDRESS 26601 MULLINIX MILL RY MOPERTY LOCATION: MIT AIRY MOD 21771	PHONE
SUNDIVISION MEALISTRIZ PROPERLY	LOT NO
ROAD AND DESCRIPTION MULLINIX MILL PUL	
SIZE OF LOT 3.042 AC	NUMBER OF BEDROOMS)
THE SYSTEM INSTALLED UNDER THIS APPLICATION IS ACCEPTABLE ONLY UNTIL PUBL	ن کلر کی IC FACILITIES BECOME AVAILABLE. I FULLY UNDERSTAND
FEE CONNECTED WITH THE FILING OF THIS PERC TEST APPLICATION IS NON-REFUND	ABLE UNDER ANY CIRCUMSTANCES. I ALSO AGREE TO COM
WITH ALL MOSHA REQUIREMENTS IN TESTING THIS LOT	McAluila
APPROVED BY C. S' Nitreaker FOR Shal	Low Trance part 4/28/21
REJECTED BY FOR	DATE
HOLD PENDING FUNTHER TESTS	DATE
REASONS FOR ABLECTION OR HOLDING 4/28/21 FOR CERTIFIE	HALES HOUSE STE
- KATER NELL CITE PENTEN.	
C. 8: 94	
THIS IS NOT /	







**Bureau of Environmental Health** 8930 Stanford Blvd | Columbia, MD 21045 410.313.2640 - Voice/Relay 410.313.2648 - Fax 1.866.313.6300 - Toll Free L

ļ

-	AUdat >>
	Maura J. Rossman, M.D., Health Officer
	APPLICATION
	FOR PERCOLATION TESTING AND SITE EVALUATION
	PROPERTY LOCATION
	SUBDIVISION/PROPERTY NAME Mc. Alister Property
	PROPERTY ADDRESS Lot 3 Mullimix Mill Rd Mt Hing MD 21771
	TAX ACCOUNT # 04-34/996 TAX MAP 12 GRID 16 PARCEL 72 LOT NO. 3 SIZE (ACRES) 3.042 ZONING CATEGORY TIER
ļ	PROPERTY OWNER(S) James McHlister
ļ	DAYTIME PHONE 410-489-7900 CELL EMAIL TIM @ Heritasc Maryland.con
	MAILING ADDRESS 30830 Mills Ridge Rd Lewis DE 19958
,	APPLICANT TIMAThy Fraga Relationship to owner:
ſ	DAYTIME PHONE 410-489-7900 CELL EMAIL Time Heritage Maryburg con
1	MAILING ADDRESS POBOX 482 LISbon MD 21765
IH	STREET CITY, STATE ZIP EREBY APPLY FOR THE NECESSARY TESTING/EVALUATION PRIOR TO ISSUANCE OF SEWAGE DISPOSAL SYSTEM PERMIT(S):
	PROPERTY:
	SUBDIVISION: NUMBER OF LOTS INCLUDING RESIDUE:     SUBDIVISION CLASSIFICATION (PER DEPT. OF PLANNING AND ZONING) MAJOR MINOR     CONSTRUCT NEW OSDS ON UNDEVELOPED LOT     REPAIR OR REPLACE FAILING OSDS     UPGRADE EXISTING OSDS BUILDING:
	RESIDENTIAL WITH     EXISTING OR PROPOSED BEDROOMS IN THE COMPLETED STRUCTURE     COMMERCIAL (PROVIDE DETAIL OF TYPE OF USE AND NUMBERS OF EMPLOYEES/CUSTOMERS ON ACCOMPANYING PLAN)
	IS THE PROPERTY WITHIN 2500 FEET OF ANY RESERVOIR?
	T YES
SI	APPLICANT, I UNDERSTAND THE FOLLOWING:
•	THIS APPLICATION IS VALID FOR TWO(2) YEARS FROM DATE OF FEE PAYMENT AND APPROVAL IS BASED UPON HEALTH OFFICER SIGNATURE OF A PERC CERTIFICATION PLAN PRIOR TO EXPIRATION OF THIS PERMIT.
)	THE APPLICATION FEE IS NON-REFUNDABLE
•	THIS APPLICATION MUST BE ACCOMPANIED BY ALL APPLICABLE FEES AND A SUITABLE SITE PLAN IN ORDER TO BE PROCESSED
,	THIS IS A PUBLIC DOCUMENT
	I deciare and affirm that to the best of my knowledge, the information contained herein is correct. I deciare that I am the owner of the property or duly authorized to make this application on behalf of the owner. I agree to comply with all applicable state and county regulations. By signature of this application, I hereby grant Howard County Health Department officials the right to enter onto the property for the purpose of inspecting the property as directly related to the requested permit/service.
	SIGNATURE OF APPLICANT DATE

Website: www.hchealth.org Facebook: www.facebook.com/hocohealth Twitter: @HoCoHealth





## Bricker, Robert

From:	Bricker, Robert
Sent:	Tuesday, December 28, 2021 11:34 AM
То:	'ron@vanmar.com'
Cc:	gauntps@comcast.net
Subject:	McAllister Property Lot 3 plans

Good morning Ron,

I have reviewed the submitted (Dec 21) plans for McAllister Property Lot 3. The Percolation Certification Plan does not have an illustrated construction envelope (which is required content), however, I am forwarding it for consideration of signature approval as the associated OSDS Design Plan has the proposed foundation footprint illustrated in an approvable location. Maybe it will be signed, but you may rush a revision just in case. Also, the 'old' perc location in the southwest corner of the sewage disposal area is mis-labeled: the correct location identifier is 5, 6.

The OSDS Design Plan will not be approved: Under Septic System Trench Design, the elevations presented for grade, trench inlet invert, and trench bottom are all nonsensical. If you had included a trench cross-section, I may have a chance at describing the errors. As it is, you will have to review the elevations and make sense of the elevations you want to propose that makes the design correct.

Other notable issues:

- 1. The percolation test location in the southwest SDA corner is mis-labeled. The correct location identifier is 5,6.
- 2. The bend before the septic tank inlet will not be installed as you have illustrated. The 90-degree turn will be installed as two 1/8 bends with a cleanout at the first 1/8 bend.
- 3. The Failed Percolation Test symbol in Legend is not needed as there are no failed locations within the scope of the plan.

You may re-submit corrected plans directly to my attention at the Bureau of Environmental Health.

Robert Bricker, REHS/RS, L.E.H.S. Environmental Sanitarian II Bureau of Environmental Health, Well and Septic Program 8930 Stanford Blvd., Columbia, MD 21045

Phone: (410)313-2691 Email: rbricker@howardcountymd.gov



#### CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

1

### **Ron Thompson**

From:	Bricker, Robert <rbricker@howardcountymd.gov></rbricker@howardcountymd.gov>
Sent:	Tuesday, December 28, 2021 11:34 AM
То:	Ron Thompson
Cc:	gauntps@comcast.net
Subject:	McAllister Property Lot 3 plans

Good morning Ron,

I have reviewed the submitted (Dec 21) plans for McAllister Property Lot 3. The Percolation Certification Plan does not have an illustrated construction envelope (which is required content), however, I am forwarding it for consideration of signature approval as the associated OSDS Design Plan has the proposed foundation footprint illustrated in an approvable location. Maybe it will be signed, but you may rush a revision just in case. Also, the 'old' perc location in the southwest corner of the sewage disposal area is mis-labeled: the correct location identifier is 5, 6.

The OSDS Design Plan will not be approved: Under Septic System Trench Design, the elevations presented for grade, trench inlet invert, and trench bottom are all nonsensical. If you had included a trench cross-section, I may have a chance at describing the errors. As it is, you will have to review the elevations and make sense of the elevations you want to propose that makes the design correct.

Other notable issues:

- 1. The percolation test location in the southwest SDA corner is mis-labeled. The correct location identifier is 5,6.
- 2. The bend before the septic tank inlet will not be installed as you have illustrated. The 90-degree turn will be installed as two 1/8 bends with a cleanout at the first 1/8 bend.
- 3. The Failed Percolation Test symbol in Legend is not needed as there are no failed locations within the scope of the plan.

You may re-submit corrected plans directly to my attention at the Bureau of Environmental Health.

Robert Bricker, REHS/RS, L.E.H.S. Environmental Sanitarian II Bureau of Environmental Health, Well and Septic Program 8930 Stanford Blvd., Columbia, MD 21045

Phone: (410)313-2691 Email: rbricker@howardcountymd.gov







#### **CONFIDENTIALITY NOTICE**


This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

1




	SOIL	LEGEND		
MAPPING UNIT	HYDROLOGIC SOIL GROUP	HYDRIC? COMPONENTS	Kw	SLOPE
LENELG LOAM	В	NO	0.24	3-8%
LENELG LOAM	В	NO	0.24	3-8%
CCOQUAN LOAM	C	NO	0.37	8-15%





GgA OF 161 \_\_\_\_\_\_ STA. -----OcC The second second second - ---\_\_\_\_ 1271110 STATE OF MARYLAND ( L. 1617 F. 7 APPROVED: FOR PRIVATE WATER AND PRIVATE SEWERAGE SYSTEMS. HOWARD COUNTY HEALTH DEPARTMENT HOWARD COUNTY HEALTH OFFICER MS PATE/ 1.



	SOIL	LEGEND		
MAPPING UNIT	HYDROLOGIC SOIL GROUP	HYDRIC? COMPONENTS	Kw	SLOPE
GLENELG LOAM	В	NO	0.24	3-8%
GLENELG LOAM	В	NO	0.24	3-8%
CCOQUAN LOAM	C	NO	0.37	8-15%

 $\square$ 

 $\triangleleft$ 


01

MILL

LINIX


5

1271450



# GENERAL NOTES


- I. OWNER: DAVID N. & VICKI T. GAUNT DEED REFERENCE: LIBER 19865 AT FOLIO 235 DATE: SEPTEMBER 15, 2020 GRANTOR: JAMES E. MCALLISTER
- 2. TAX MAP: 6 GRID: 6 PARCEL: 138
- 3. NEAREST POTABLE WATER SUPPLY: DAMASCUS: 4 MILES ±.
- 4. THE SUBJECT PROPERTY IS NOT LOCATED IN SPECIAL FLOOD HAZARD AREA PER NATIONAL FLOOD INSURANCE PROGRAM, FLOOD INSURANCE RATE MAP, COMMUNITY PANEL NO. 240044 00128\*.
- 5. TOPOGRAPHY & PLANIMETRIC FEATURES SHOWN HEREON TAKEN FROM COPYRIGHTED GIS DATA FROM HOWARD COUNTY, SUPPLEMENTED WITH FIELD LOCATIONS BY VANMAR ASSOCIATES, INC. CONTOUR INTERVAL IS 2 FEET. VERTICAL DATUM IS NAVD88.
- 6. THE BASIS OF BEARINGS FOR THIS PLAN IS THE MARYLAND COORDINATE SYSTEM (NAD83/91) PER HOWARD COUNTY SURVEY CONTROL STATIONS 12FA N 595609.160 E. 1272171.241 12CB N 597303.860 E. 1272860.629
- DISTANCES SHOWN HEREON ARE GROUND DISTANCES.
- 7. THERE ARE NO WELLS OR SEPTIC SYSTEMS WITHIN 100' OF THE PROPERTY BOUNDARY UNLESS OTHERWISE SHOWN HEREON.
- 8. THE EXISTING WELLS SHOWN ON THIS PLAN HAVE BEEN FIELD LOCATED BY VANMAR ASSOCIATES OR TAKEN FROM AVAILABLE RECORDS AND ACCURATELY SHOWN.
- 9. SOIL TYPE: SOIL TYPE: GLENELG (GgA, GgC), GLENVILLE (GMB), OCCOQUAN (OcC). WEB SOIL SURVEY
- 10. THE SUBJECT PROPERTY IS ZONED RC-DEO IN ACCORDANCE WITH THE OCTOBER 6, 2013 COMPREHENSIVE ZONING REGULATIONS.
- 11. THE LOTS SHOWN HEREON COMPLY WITH THE MINIMUM OWNERSHIP WIDTH AND LOT AREAS
- REQUIRED BY THE MARYLAND DEPARTMENT OF THE ENVIRONMENT. 12. THERE ARE NO HISTORIC SITES OR CEMETERIES ON THIS PROPERTY.
- 13. NO ENVIRONMENTAL FEATURES EXIST WITHIN THE LOD.
- 14. THERE ARE NO FLOODPLAINS, WETLANDS OR OTHER ENVIRONMENTAL FEATURES LOCATED ON THE SITE AS DETERMINED DURING A FIELD INVESTIGATION PERFORMED BY VANMAR ASSOCIATES, INC. AUGUST 2021.



NOTE: THE PURPOSE OF THIS REVISED PERCOLATION CERTIFICATION PLAN IS TO SHOW THE EXISTING WELL HO-18-0193 AND THE REVISED ALTERNATE WELL SITES.

	DATE REVISIONS	REV	ISED PERCOLATION CERTI	FICATION PLAN
	12/28/21 PER HD COMMENTS		2620 MULLINIX MILL	
			LOT 3	
			MCALLISTER PROP	PERTY
DEVELOPER: VICKI T. GAUNT		PLAT NO. 5023		
ARIAN WAY Y, MD. 21771 40-9611	OF MAR	TAX MAP: 12 GRID NO: 16 PARCEL NO: 72	ELECTION DISTRICT: No. 4 HOWARD COUNTY, MARYLAND EX. ZONING: RC-DEO	SCALE:  " = 30' DATE: DECEMBER, 202   SHEET   OF
<u>CERTIFICATION</u> nts were prepared or approved by me, sional engineer under the laws of the provide the state of the stateo	PROFILE STORE	VANMAR ASSOCIATES, INC. Engineers Surveyors Planners 310 South Main Street Mount Airy, Maryland 21771 (301) 829–2890 (301) 831–5015 (410) 549–2751 Fax (301) 831–5603 ©Copyright, Latest Date Shown		

CI-6185



	SOIL	LEGEND		
MAPPING UNIT	HYDROLOGIC SOIL GROUP	HYDRIC? COMPONENTS	Kw	SLOPE
LENELG LOAM	В	NO	0.24	3-8%
GLENELG LOAM	В	NO	0.24	3-8%
CCOQUAN LOAM	С	NO	0.37	8-15%

0

A


201

MILL

LINIX 1


AL

12





- 1. OWNER: DAVID N. & VICKI T. GAUNT DEED REFERENCE: LIBER 19865 AT FOLIO 235 SEPTEMBER 15, 2020 DATE:
- GRANTOR: JAMES E. MCALLISTER
- 2. TAX MAP: 6 GRID: 6 PARCEL: 138 3. NEAREST POTABLE WATER SUPPLY: DAMASCUS: 4 MILES ±.
- 4. THE SUBJECT PROPERTY IS NOT LOCATED IN SPECIAL FLOOD HAZARD AREA PER NATIONAL FLOOD INSURANCE PROGRAM, FLOOD INSURANCE RATE MAP, COMMUNITY PANEL NO. 240044 00128\*.
- 5. TOPOGRAPHY & PLANIMETRIC FEATURES SHOWN HEREON TAKEN FROM COPYRIGHTED GIS DATA FROM HOWARD COUNTY, SUPPLEMENTED WITH FIELD LOCATIONS BY VANMAR ASSOCIATES, INC. CONTOUR INTERVAL IS 2 FEET. VERTICAL DATUM IS NAVD88.
- 6. THE BASIS OF BEARINGS FOR THIS PLAN IS THE MARYLAND COORDINATE SYSTEM (NAD83/91) PER HOWARD COUNTY SURVEY CONTROL STATIONS 12FA N 595609.160 E. 1272171.241 12CB N 597303.860 E. 1272860.629
- DISTANCES SHOWN HEREON ARE GROUND DISTANCES.
- 7. THERE ARE NO WELLS OR SEPTIC SYSTEMS WITHIN 100' OF THE PROPERTY BOUNDARY UNLESS OTHERWISE SHOWN HEREON.
- 8. THE EXISTING WELLS SHOWN ON THIS PLAN HAVE BEEN FIELD LOCATED BY VANMAR ASSOCIATES OR TAKEN FROM AVAILABLE RECORDS AND ACCURATELY SHOWN.
- 9. SOIL TYPE: SOIL TYPE: GLENELG (GgA, GgC), GLENVILLE (GMB), OCCOQUAN (OcC). WEB SOIL SURVEY
- 10. THE SUBJECT PROPERTY IS ZONED RC-DEO IN ACCORDANCE WITH THE OCTOBER 6, 2013 COMPREHENSIVE ZONING REGULATIONS.
- 11. THE LOTS SHOWN HEREON COMPLY WITH THE MINIMUM OWNERSHIP WIDTH AND LOT AREAS REQUIRED BY THE MARYLAND DEPARTMENT OF THE ENVIRONMENT.
- 12. THERE ARE NO HISTORIC SITES OR CEMETERIES ON THIS PROPERTY.
- 13. NO ENVIRONMENTAL FEATURES EXIST WITHIN THE LOD.
- 14. THERE ARE NO FLOODPLAINS, WETLANDS OR OTHER ENVIRONMENTAL FEATURES LOCATED ON THE SITE AS DETERMINED DURING A FIELD INVESTIGATION PERFORMED BY VANMAR ASSOCIATES, INC. AUGUST 2021.



NOTE THE PURPOSE OF THIS REVISED PERCOLATION CERTIFICATION PLAN IS TO SHOW THE EXISTING WELL HO-18-0193 AND THE REVISED ALTERNATE WELL SITES.

	DATE REVISIONS 12/28/21 PER HD COMMENTS	LOT 3 McALLISTER PROPERTY		LROAD
DEVELOPER: ICKI T. GAUNT RIAN WAY 40-9611	OF MAR	TAX MAP: 12 GRID NO: 16 PARCEL NO: 72	PLAT NO. 5023 ELECTION DISTRICT: No. 4 HOWARD COUNTY, MARYLAND EX. ZONING: RC-DEO	SCALE:  " = 30' DATE: DECEMBER, 2021 SHEET   OF
CERTIFICATION s were prepared or approved by me, onal engineer under the laws of the Expiration Date: <u>9-18-23</u> .	DINIONAL ENDIN	VANMAR ASSOCIATES, INC. Engineers Surveyors Planners 310 South Main Street Mount Airy, Maryland 21771 (301) 829–2890 (301) 831–5015 (410) 549–2751 Fax (301) 831–5603 ©Copyright, Latest Date Shown		