



APPLICATION

FOR PERCOLATION TESTING AND SITE EVALUATION

TEST DATE(S) _____ TEST TIME _____

AP 538005

AGENCY REVIEW: _____

DATE 7-18-12

DO NOT WRITE ABOVE THIS LINE

I HEREBY APPLY FOR THE NECESSARY TESTING/EVALUATION PRIOR TO ISSUANCE OF SEWAGE DISPOSAL SYSTEM PERMIT(S) TO:

CHECK AS NEEDED:

- CONSTRUCT NEW SEPTIC SYSTEM(S)
- REPAIR/ADD TO AN EXISTING SEPTIC SYSTEM
- REPLACE AN EXISTING SEPTIC SYSTEM

CHECK AS NEEDED:

- NEW STRUCTURE(S)
- ADDITION TO AN EXISTING STRUCTURE
- REPLACE AN EXISTING STRUCTURE

CHECK ONE:

- CREATE NEW LOT(S)
- BUILD ON AN EXISTING LOT IN A SUBDIVISION
- BUILD ON AN EXISTING PARCEL OF RECORD

IS THE PROPERTY WITHIN 2500' OF ANY RESERVOIR?

- YES
- NO

THE TYPE OF STRUCTURE IS:

- RESIDENTIAL WITH 4 PROPOSED BEDROOMS IN THE COMPLETED STRUCTURE (NOTE UNKNOWN IF APPROPRIATE)
- COMMERCIAL (PROVIDE DETAIL OF NUMBERS AND TYPES OF EMPLOYEES/ CUSTOMERS ON ACCOMPANYING PLAN)
- INSTITUTIONAL/GOVERNMENT (PROVIDE DETAIL OF NUMBERS AND TYPES OF EMPLOYEES/USERS ON ACCOMPANYING PLAN)

PROPERTY OWNER(S) Walters Pamela Eals

DAYTIME PHONE _____ CELL _____ FAX _____

MAILING ADDRESS 12783 Folly Quarter Rd Ellicott City MD 21042
STREET CITY/TOWN STATE ZIP

APPLICANT Ronnie Heaps

DAYTIME PHONE 443-277-7526 CELL Same FAX 410552 5815

MAILING ADDRESS 425 Obrecht Rd Sykesville MD 21784
STREET CITY/TOWN STATE ZIP


APPLICANT'S ROLE: DEVELOPER BUILDER BUYER RELATIVE/FRIEND REALTOR CONSULTANT

PROPERTY LOCATION
SUBDIVISION/PROPERTY NAME 12783 Folly Quarter Rd LOT NO. _____


PROPERTY ADDRESS Ellicott City MD 21042
STREET TOWN/POST OFFICE

TAX MAP PAGE(S) _____ GRID _____ PARCEL(S) _____ PROPOSED LOT SIZE _____

AS APPLICANT, I UNDERSTAND THE FOLLOWING: THE SYSTEM INSTALLED SUBSEQUENT TO THIS APPLICATION IS ACCEPTABLE ONLY UNTIL PUBLIC SEWERAGE IS AVAILABLE. THIS APPLICATION IS COMPLETE WHEN ALL APPLICABLE FEES AND A SUITABLE SITE PLAN HAVE BEEN RECEIVED. I ACCEPT THE RESPONSIBILITY FOR COMPLIANCE WITH ALL M.O.S.H.A. AND "MISS UTILITY" REQUIREMENTS. APPROVAL IS BASED UPON SATISFACTORY REVIEW OF A PERC CERTIFICATION PLAN. TEST RESULTS WILL BE MAILED TO APPLICANT.


SIGNATURE OF APPLICANT

HOWARD COUNTY HEALTH DEPARTMENT, BUREAU OF ENVIRONMENTAL HEALTH, WELL AND SEPTIC PROGRAM
7178 COLUMBIA GATEWAY DRIVE COLUMBIA, MARYLAND 21046 (410) 313-2640 FAX (410) 313-2648
TDD (410) 313-2323 TOLL FREE 1-877-4MD-DHMH



Bureau of Environmental Health
7178 Gateway Drive Columbia, MD 21046
(410) 313-2640 Fax (410) 313-2648
TDD (410) 313-2323 Toll Free 1-866-313-6300
website: www.hchealth.org

Peter L. Beilenson, M.D., M.P.H., Health Officer

August 29, 2012

To Whom It May Concern:

Walter Thomas Fahs, paid for a septic/PERC repair, in the amount of \$330.00 (check #1058); J.M. Contracting LLC did not have to PERC or Repair the property (12783 Folly Quarter Rd). Walter Thomas Fahs is requesting \$330.00 refund – (receipt #38005) . If you have any questions please call Walter Thomas Fahs at 410-504-4878


Mail Check To
Walter Thomas Fahs
12783 Folly Quarter Road
Ellicott City, MD 21042

#38005 07/18/2012 written by Juanita King
#87828 07/19/2012 written by Willie Sims

Thanks in advance

Juanita King ext. 4251
Juanita King 8/29/2012

Curtis Hughes ext. 1774
Curt Hughes 8/29/12



Bureau of Environmental Health
7178 Columbia Gateway Drive, Columbia, MD 21046-2147
Main: 410-313-2640 | Fax: 410-313-2648
TDD 410-313-2323 | Toll Free 1-866-313-6300
www.hchealth.org
Facebook: www.facebook.com/hocohealth
Twitter: HowardCoHealthDep

Peter L. Beilenson, M.D., M.P.H., Health Officer

MEMORANDUM

TO: Curtis Hughes
FROM: Jeff Williams *JW*
RE: Refund, receipt # 38005, \$330, septic repair perc test and installation
12783 Folly Quarter Road
DATE: August 28, 2012

Please submit the paperwork for a refund to Walter Fahs, who paid \$330 for a septic repair perc test and installation at 12783 Folly Quarter Road on 7/18/2012, receipt #38005.

Subsequent to his application, he determined that his failing system was due to a leaking toilet in the house and he no longer needed to perform any repairs to his septic system. No work was performed by the Health Department as part of this application.

August 8, 2012

To: Mr. Jeffrey Williams
Howard County Health Department Administration
7178 Columbia Gateway Drive
Columbia, MD 21046

From: Walter Thomas Fahs
12783 Folly Quarter Road
Ellicott City, MD 21042
Phone: 410-504-4878

Subject: Inspection Fee for Perc/Repair to
12783 Folly Quarter Road, Ellicott City, MD 21042
Ticket: 38005 [A538005]

Dear Mr. Williams,

I am writing to request a refund of \$330.00 for the above noted septic inspection fee. On 7/18/2012, JM Contracting filed for the noted inspection of my home's septic system on my behalf, as they believed that the system was failing due to seeing septic water surfacing in a small area of my back yard. As it turns out, the septic system was being flooded by two leaky toilets in my home that I subsequently fixed. After learning that the repair immediately remedied the septic situation, we quickly called the inspector at his office, explained the situation, and the inspector agreed that it was no longer necessary to pursue on the county's behalf. We prevented any time expended by the county on this issue.

I would greatly appreciate your consideration of a full refund in this amount. Please call me with any questions or comments. Thank you very much.

Sincerely,



W. Thomas Fahs
Home Owner

Cc: Ms. Juanita King (JuKing@howardcounty.md.gov)

FILE INQUIRY NOTES

| DATE | RESULTS OF REVIEW FOR FILE |
|---------|---|
| 7/30/12 | <p>~ 8:40, RE: <u>12783 Folly Quarter Road</u> Ronnie Heaps called-in. Describes flooded condition of trenches that he observed prior to obtaining Perc Application for repair. (Owner had called him about soil saturation in drainfield area.) He says now that the owner has had 2 toilets fixed, the drainfield area is dry. I decline to conduct an inspection that would require exposing septic system components.</p> |
| 8/23/12 | <p>Field review conducted (walkover). Area of excavation at previously flooded drainfield is observed. Surface of soil is dry; there is no evidence of surface discharge. Homeowner, Mrs Fahs, indicates that grass did not grow in that area until after toilets were repaired. Checked sight boundary area towards back of property for potential repair area. That area appears 'OK'. Area at left property line is much lower. Wet-season soil likely occurs there. K. Baker</p> |