



# HOWARD COUNTY HEALTH DEPARTMENT

46204

CODES

DATE

12/5/13

P.5

CASH

CHECK

NO.

4211

Received From

Scott Joonis

For

Septic Permit - 13598  
Anson Chapel


One hundred sixty-five <sup>00</sup>/<sub>100</sub> Dollars

\$

165 | 00

Received By

J King



Bureau of Environmental Health  
 7178 Gateway Drive Columbia, MD 21046  
 (410) 313-2640 Fax (410) 313-2648  
 TDD (410) 313-2323 Toll Free 1-866-313-6300  
 website: www.hchealth.org

Maura J. Rossman, M.D., Health Officer

RECEIPT DATE: 12/5/13

**ONSITE SEWAGE DISPOSAL SYSTEM**

P 530993

INSTALLATION  
 APPROVAL DATE: \_\_\_\_\_

**PERMIT**

A \_\_\_\_\_

**SEWER HOUSE CONNECTION**

PROPERTY ADDRESS: 15598 Union Chapel Road

SUBDIVISION: \_\_\_\_\_ LOT: \_\_\_\_\_ TAX ID: 04-326636

CONTRACTOR: \_\_\_\_\_ EMAIL: \_\_\_\_\_

CONTRACTOR ADDRESS: \_\_\_\_\_ PHONE: \_\_\_\_\_

PROPERTY OWNER: Scott Loomis EMAIL: \_\_\_\_\_

OWNER ADDRESS: 15598 Union Loomis PHONE: 301-502-5133

NUMBER OF BEDROOMS: 4 HOUSE SQ. FT. ~3500 CONNECTED TO PUBLIC WATER:  YES  NO

LOCATION:	<b>INSTALL 4" SEWER LINE PER APPROVED SITE PLAN.</b>
NOTES:	Permit is to install a washroom in pole barn w/ plumbing to tie into existing septic. Cleanouts every 70'. Maintain at least 1 – 2% fall. Connection must occur before existing septic tank.

ISSUED BY: Kevin Wolf ISSUE DATE: \_\_\_\_\_ EXPIRATION DATE: \_\_\_\_\_

**NOTE: HOWARD COUNTY BUREAU OF UTILITIES APPROVAL OF GRINDER PUMP INSTALLATION IS REQUIRED PRIOR TO SEPTIC PERMIT APPROVAL**

**NOTE: CONTRACTOR MUST SCHEDULE AN INSPECTION AND GAIN APPROVAL OF ALL COMPONENTS PRIOR TO COVERING**

**NOTE: AN ELECTRICAL PERMIT IS REQUIRED FOR INSTALLATION OF ANY ELECTRICAL COMPONENTS OF THE SYSTEM**

**NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM. PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT. CALL 410-313-1771 FOR INSPECTION OF SEPTIC SYSTEM.**

NOT TO SCALE

**TRENCH/DRAINFIELD DATA**

WIDTH                  INLET                  BOTTOM

NUMBER OF TRENCHES \_\_\_\_\_

TOTAL LENGTH \_\_\_\_\_

ABSORPTION AREA \_\_\_\_\_

DISTRIBUTION BOX LEVEL \_\_\_\_\_

DISTRIBUTION BOX BAFFLE \_\_\_\_\_

DISTRIBUTION BOX PORT \_\_\_\_\_

**SEPTIC TANK DATA**

**SEPTIC TANK 1 LEVEL** \_\_\_\_\_

MANUFACTURER \_\_\_\_\_

CAPACITY \_\_\_\_\_ GAL

SEAM LOC \_\_\_\_\_

TANK LID DEPTH \_\_\_\_\_

BAFFLES \_\_\_\_\_

BAFFLE FILTER \_\_\_\_\_

MANHOLE LOC \_\_\_\_\_

6" PORT LOC \_\_\_\_\_

WATERTIGHT TEST \_\_\_\_\_

SLOTTED \_\_\_\_\_

DATE ON LID \_\_\_\_\_

**PUMP/SEPTIC TANK LEVEL** \_\_\_\_\_

MANUFACTURER \_\_\_\_\_

CAPACITY \_\_\_\_\_ GAL

SEAM LOC \_\_\_\_\_

TANK LID DEPTH \_\_\_\_\_

BAFFLES \_\_\_\_\_

BAFFLE FILTER \_\_\_\_\_

MANHOLE LOC \_\_\_\_\_

6" PORT LOC \_\_\_\_\_

WATERTIGHT TEST \_\_\_\_\_

SLOTTED \_\_\_\_\_

DATE ON LID \_\_\_\_\_

**ROAD NAME**

PRE-CONSTRUCTION:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

INSTALLATION:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

FINAL INSPECTOR \_\_\_\_\_ DATE OF APPROVAL \_\_\_\_\_

SEPTIC SPECIFICATIONS WORKSHEET

Subdivision \_\_\_\_\_

A 546204

Street Name 15598 Union Chapel Rd.

Lot Number \_\_\_\_\_

Average Percolation Rate(min./in.) N/A

Application Rate (GPD/sq. ft.) N/A

Number of Bedrooms N/A

Design Flow (BRx150) N/A

Square Footage (of House) N/A

Septic Tank Capacity (gal.) N/A

Sidewall Credit / % Reduction NA /

Total Length of Trench (ft.) N/A

**\*All Septic/Pump tanks must be top seamed unless otherwise approved by this agency.**

**\*All Septic tanks must be compartmented unless otherwise approved by this agency.**

Baffle Filter Required? Yes No

TRENCH DIMENSIONS: Trench to \_\_\_\_\_ feet wide. Inlet at \_\_\_\_\_ feet below original grade. Bottom maximum depth \_\_\_\_\_ feet below original grade. Effective area begins at \_\_\_\_\_ feet below original grade. \_\_\_\_\_ feet of stone below the distribution pipe.

PUMP SYSTEM PROPOSED? YES NO

*\*SHC Free\**

Pump system details: \_\_\_\_\_ gallon pump chamber

Note 1: Septic pump detail to be provided by installer prior to issuance of septic permit.

Note 2: Pump performance test required prior to Health Department approval of pumped septic system.

LOCATION: Permit B to install wash room in pole barn w/ plumbing to tie in to existing septic. Clearcuts every 70'.

ADDITIONAL NOTES: Maintain @ least 1-2% fall. Connection must occur before existing septic tank.

Reviewed by: K. Wolf

Date: 12/6/13



HOWARD COUNTY DEPARTMENT OF INSPECTIONS, LICENSES AND PERMITS

3430 Courthouse Drive ■ Ellicott City, Maryland 21043 ■ 410-313-2433

Robert J. Frances, P.E., Director  
bfrances@howardcountymd.gov

FAX 410-313-3298  
TDD 410-313-2323

November 13, 2013

Mr. Scott C. Loomis  
15598 Union Chapel Road  
Woodbine, Maryland 21797

RE: 15598 Union Chapel Road: Woodbine, Maryland 21797  
Construction of New Pole Barn

Dear Mr. Loomis:

I have reviewed your letter, dated November 9, 2013, referencing the intended use of the new pole barn to be constructed on your property. This Department has determined that the structure will be used for agricultural storage of feed and pesticides only. Howard County will not require a building permit for the construction of this structure in accordance with the Howard County Building Code Section 101.2, Exception 3.

If the use of this structure changes in the future to a non-agricultural use, then a building permit for a change of use will be required, and the building will need to meet all the current requirements of the Howard County Building Code. Plumbing and electrical permits are still required for any work performed as all trade permits are not subject to exemption.

You must also check with the Department of Planning and Zoning about any possible issues within their Department such as setback requirements, accessory use structure requirements, etc. You must also get approval from the Health Department regarding the addition of the bathroom to the existing septic system.

If you have any questions, I can be reached at 410-313-3948.

Sincerely,

Donald L. Mock, P.E.  
Plan Review Chief  
Inspections, Licenses and Permits

Copy: Robert J. Frances, Director, DILP  
Bruce Forejt, Chief Building Inspector, DILP  
Cindy Hamilton, DPZ  
Robert Bricker, Health Department  
T:\PlanReview\dMock\DLM\15598 Unioun chapel road.doc

