



Bureau of Environmental Health
8930 Stanford Blvd | Columbia, MD 21045
410.313.2640 - Voice/Relay
410.313.2648 - Fax
1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

APPLICATION
FOR PERCOLATION TESTING AND SITE EVALUATION

PROPERTY LOCATION

SUBDIVISION/PROPERTY NAME 3001
PROPERTY ADDRESS 11927 Meadow Vista Way Clarksville, Md. 21029-1251
TAX ACCOUNT # 409063 TAX MAP 0029 GRID 0019 PARCEL 0356 LOT NO. 22 SIZE (ACRES) 5.6800 AC
ZONING CATEGORY TIER

PROPERTY OWNER(S) Krishna Abbinav / Janaki Raman Savitha

DAYTIME PHONE 703-608-4529 CELL EMAIL

MAILING ADDRESS 11927 Meadow Vista Way Clarksville 21029

APPLICANT R+E Chief Septic, LLC RELATIONSHIP TO OWNER: Contractor

DAYTIME PHONE 410-635-3237 CELL 301-596-9061 EMAIL chiefsepa@gmail.com

MAILING ADDRESS P.O Box 199 MT. Airy Md. 21771

I HEREBY APPLY FOR THE NECESSARY TESTING/EVALUATION PRIOR TO ISSUANCE OF SEWAGE DISPOSAL SYSTEM PERMIT(S):

PROPERTY:

- SUBDIVISION: NUMBER OF LOTS INCLUDING RESIDUE:
SUBDIVISION CLASSIFICATION (PER DEPT. OF PLANNING AND ZONING) MAJOR MINOR
CONSTRUCT NEW OSDS ON UNDEVELOPED LOT
REPAIR OR REPLACE FAILING OSDS
UPGRADE EXISTING OSDS

BUILDING:

- RESIDENTIAL WITH 6 EXISTING OR PROPOSED BEDROOMS IN THE COMPLETED STRUCTURE
COMMERCIAL (PROVIDE DETAIL OF TYPE OF USE AND NUMBERS OF EMPLOYEES/CUSTOMERS ON ACCOMPANYING PLAN)

IS THE PROPERTY WITHIN 2500 FEET OF ANY RESERVOIR?

- YES
NO

AS APPLICANT, I UNDERSTAND THE FOLLOWING:

- THIS APPLICATION IS VALID FOR TWO(2) YEARS FROM DATE OF FEE PAYMENT AND APPROVAL IS BASED UPON HEALTH OFFICER SIGNATURE OF A PERC CERTIFICATION PLAN PRIOR TO EXPIRATION OF THIS PERMIT.
THE APPLICATION FEE IS NON-REFUNDABLE
THIS APPLICATION MUST BE ACCOMPANIED BY ALL APPLICABLE FEES AND A SUITABLE SITE PLAN IN ORDER TO BE PROCESSED
THIS IS A PUBLIC DOCUMENT

I declare and affirm that to the best of my knowledge, the information contained herein is correct. I declare that I am the owner of the property or duly authorized to make this application on behalf of the owner. I agree to comply with all applicable state and county regulations.
By signature of this application, I hereby grant Howard County Health Department officials the right to enter onto the property for the purpose of inspecting the property as directly related to the requested permit/service.
SIGNATURE OF APPLICANT DATE 2/2/2024

**RECEIPT**

Howard County, MD  
HOWARD COUNTY HEALTH DEPARTMENT  
ASCEND ONE BUILDING  
Columbia, MD 21045  
8930 STANFORD BLVD

Application: WS-PT-24-00258  
Application Type: EnvHealth/Well and Septic/Percolation Test/Application  
Address: 11927 MEADOW VISTA WAY, Clarksville, 21029

---

<b>Receipt No.</b>	8845					
<b>Payment Method</b>	<b>Ref Number</b>	<b>Amount Paid</b>	<b>Payment Date</b>	<b>Cashier ID</b>	<b>Received</b>	<b>Comments</b>
Credit Card		\$265.00	02/02/2024	PUBLICUSER593582		

**Owner Info.:** KRISHNA ABBINAV  
11927 MEADOW VISTA WAY  
CLARKSVILLE, MD 21029

**Work Description:**



Bureau of Environmental Health  
 8930 Stanford Blvd | Columbia, MD 21045  
 410.313.2640 Voice/Relay  
 410.313.2648 - Fax  
 1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

**INFORMATION FORM - SEPTIC SYSTEM REPAIR/UPGRADE**

**Reason for Request:**

- Failing System
- System relocation for proposed addition
- System upgrade for proposed addition
- Inadequate treatment zone
- Collapsed septic tank
- Collapsed drywell

**Has the septic tank been pumped within the last month?**

Yes      Date pumped: 2/1/24  
 No

**Was a visual inspection of the septic tank and/or drain fields conducted?**

Yes      Explain observation: drainfields saturated  
 No

**Existing system design**

- Drywell
- Trench
- Mound
- Unknown
- Other: \_\_\_\_\_

**Was a visual inspection of the sewage line conducted?**

Yes  
 No

**Blockage Leading to the field**

Yes      Explain \_\_\_\_\_  
 No

**Is discharge surfacing on the ground?**

No  
 Yes

**Additional Comments:**

\_\_\_\_\_  
 \_\_\_\_\_



\*For REPAIRS, are the owners proposing, or do they plan to add in the future any additions or modifications to the property, i.e. pools, living space additions, garages, etc? This information must be disclosed at the time of this application. The Health Department will not be able to accommodate requests in the field for property modifications unrelated to the repair request. Such requests may require an additional fee, testing, and submittal of a Percolation Certification Plan, if the property does not meet current Code and Regulations.

Septic Contractor: R+E Chief Septic      Contractor's Phone: 410-635-3237  
 Contractor's Address: 2502 Gillis Rd MT. Airy, Md. 21771 /mailing: P.O Box 199, MT. Airy MD 21771  
 Property Address: 11927 Meadow Vista Way      County File: \_\_\_\_\_  
 Subdivision: 3001      Lot: 22      Year Built: 1992  
 Owner's Name: Krishna Abbinav / Janakiraman SaviTha      Existing bedrooms: 6  
 Name of previous owners: Caddigan Peter J      Existing bedrooms: \_\_\_\_\_  
 Proposed bedrooms: \_\_\_\_\_

\*A Sanitarian will be in contact within three business days, depending upon the urgency of the situation, to coordinate the scheduling/review of the repair or upgrade.

\*Prior to scheduling inspections, scaled plans should be submitted to clarify the nature of the addition.\*  
 Print out a copy of Real Property Data via Dept. of Taxation website \_\_\_\_\_ Indexed file found \_\_\_\_\_  
 If soil/site conditions are limited and sewer and/or Metro District status is not conducive to connection, the Sanitarian may recommend pursuit of Emergency Sewer Extension or Emergency Metro District Inclusion. The Owner should contact the Bureau of Utilities for details.  
 No permit is to be issued nor inspection to be scheduled without prior fee collection at the office unless an emergency exists.  
 The contractor is to notify the office of the emergency as soon as possible.

2/2020



12"  
 5'-6"  
 5'  
 9'  
 12'

(A)  
 Drk to, over  
 m255K, m2j

Rd/CL  
 M Co 50K  
 CW, Frable  
 trace 1A

Rd/CL  
 L, m Co 50K  
 Frable CW  
 some clay on  
 soil pads  
 15% Rk

11B rly SL  
 WK Co pl.  
 Mcomms

DATE	TEST #	DEPTH	START	BREAK 1" DROP	STOP 2" DROP	TIME OF 2ND INCH	P/F/H
2/29/2024	(A)	4'8" 12'	00:31	gullied	- < 1/4"		F
		6'8"	00:52	01:00	01:10	10	P
		H2O pooled @ 12'				≈ 5 min	P

HO-88-2017

REMARKS 6 Bedrooms = Property Transfer  
 SANITARIAN K. Wolf BACKHOE Juan = Chief operator OTHERS seller Agents  
 TEST HOLES USED IN SDA 1 AVG. PERC TIME 10 SQ. FT/BR 0.20  
 TRENCH WIDTH 3 INLET DEPTH 4 MAX. BOT DEPTH 8' EFFECTIVE SW 6 (.62)

$$GDR = \frac{900}{0.5} = 1800 \div 3 = 375 (.62) = 234$$



# HOWARD COUNTY HEALTH DEPARTMENT

7579

DATE  
2/22/24

PS

Received From

R+E Septic

PHONE #

For

Septic Repair - 11927 Meadows Vista Way

CASH

CHECK

NO.

00

Two hundred sixty five

Dollars

\$

265 00

Received By

*[Handwritten Signature]*



# HOWARD COUNTY HEALTH DEPARTMENT

75796

DATE  
2/22/24

p5

Received From

R+E Septic

PHONE #

For

Septic repair - 11927 Meadows Vlk - Wey

CASH

CHECK

NO. (2)

Just hundred sixty five

00/100 Dollars

\$

265.00

Received By

[Signature]

**RECEIPT**

Howard County, MD  
HOWARD COUNTY HEALTH DEPARTMENT  
ASCEND ONE BUILDING  
Columbia, MD 21045  
8930 STANFORD BLVD

**Application:** WS-SP-APP-24-00037

**Application Type:** EnvHealth/Well and Septic/Sewage Disposal System/Application

**Address:** 11927 MEADOW VISTA WAY, Clarksville, 21029

Receipt No.	Ref Number	Amount Paid	Payment Date	Cashier ID	Received	Comments
8973		\$265.00	02/22/2024	SMARTIN		

**Owner Info.:** KRISHNA ABBINAV  
11927 MEADOW VISTA WAY  
CLARKSVILLE, MD 21029

**Work Description:**

**Transaction Code:** BA0P7C2C833C.  
**Date:** 02/22/2024 03:08:05 PM  
**Card Type:** Visa  
**Card Number:** xxxxxxxxxxxx6999  
**Authorization Code:** 111111  
**Total Amount:** \$265.00  
**Operator ID:** SMARTIN  
**Cash Drawer ID :**  
**Record:** WS-SP-APP-24-00037  
I agree to pay the above amount according to the Credit Card issuer agreement.  
**Sign Below:**

-----  
**Print Receipt**

**Cancel**





YOUNG SEPTIC SERVICES  
 1802 BALTIMORE BOULEVARD  
 WESTMINSTER, MD 21157  
[INFO@YOUNGSEPTIC.COM](mailto:INFO@YOUNGSEPTIC.COM)  
 (443)775-7353

MDE Recommended  
 OSDS Inspection Report Form  
 For Property Transfers in Maryland

General Information			
Property Address	11927 Meadow Vista Way, Clarksville, MD 21029		
County	Howard	Date and Time of inspection	12:00 pm 1/29/2024
Inspector Name	Benjamin Holtzclaw		<a href="mailto:info@youngseptic.com">info@youngseptic.com</a>

General Property Information	
1.	Were records available? Yes
2.	Year Primary Structure Built: 1993
3.	Dwelling purpose: Residential
4.	Age of tank: 31 years      Age of absorption system: 31 years
5.	Is dwelling currently occupied? No      If Vacant, how long? N/A
6.	Number of bedrooms: 5
7.	Date of last pumping of treatment tank: Unknown
8.	List any known repairs made to system: Unknown



YOUNG SEPTIC SERVICES  
 1802 BALTIMORE BOULEVARD  
 WESTMINSTER, MD 21157  
[INFO@YOUNGSEPTIC.COM](mailto:INFO@YOUNGSEPTIC.COM)  
 (410) 775-7353

Inspection Findings & Comments

System Component	Condition	Comments
Septic Tank / Pre-Treatment Unit	<input type="checkbox"/> Acceptable <input checked="" type="checkbox"/> Acceptable with Concerns <input type="checkbox"/> Unacceptable <input type="checkbox"/> Needs further Evaluation <input type="checkbox"/> N/A	<ul style="list-style-type: none"> <li>The tank is currently backed up and needs pumped, recommend a larger manhole for more efficient maintenance.</li> <li>Due to age of tank plan accordingly for the future.</li> </ul>
Pump Tank	<input type="checkbox"/> Acceptable <input type="checkbox"/> Acceptable with Concerns <input type="checkbox"/> Unacceptable <input type="checkbox"/> Needs further Evaluation <input checked="" type="checkbox"/> N/A	
Distribution Box	<input type="checkbox"/> Acceptable <input checked="" type="checkbox"/> Acceptable with Concerns <input type="checkbox"/> Unacceptable <input checked="" type="checkbox"/> Needs further Evaluation <input type="checkbox"/> N/A	<ul style="list-style-type: none"> <li>Due to back ups the system will need to be excavated open and determine issue.</li> <li>Due to age of system plan accordingly for the future.</li> </ul>
Soil Absorption System	<input type="checkbox"/> Acceptable <input checked="" type="checkbox"/> Acceptable with Concerns <input type="checkbox"/> Unacceptable <input checked="" type="checkbox"/> Needs further Evaluation <input type="checkbox"/> N/A	<ul style="list-style-type: none"> <li>Probed and found dry, however due to back ups will need to be excavated open and determine issues.</li> <li>Due to age of system plan accordingly for the future.</li> </ul>
Conveyance System: (i.e. Piping)	<input type="checkbox"/> Acceptable <input checked="" type="checkbox"/> Acceptable with Concerns <input type="checkbox"/> Unacceptable <input checked="" type="checkbox"/> Needs further Evaluation <input type="checkbox"/> N/A	<ul style="list-style-type: none"> <li>Due to back ups, scope was fully submerged in the lines. Once dug opened and pumped, issues can be evaluated.</li> <li>Due to age of system plan accordingly for the future.</li> </ul>
Other:	<input type="checkbox"/> Acceptable <input type="checkbox"/> Acceptable with Concerns <input type="checkbox"/> Unacceptable <input type="checkbox"/> Needs further Evaluation <input checked="" type="checkbox"/> N/A	

Real Property Data Search ( )  
 Search Result for HOWARD COUNTY

[View Map](#)

[View GroundRent Redemption](#)

[View GroundRent Registration](#)

Special Tax Recapture: None

Account Identifier:

District - 05 Account Number - 409063

**Owner Information**

Owner Name:

KRISHNA ABBINAV  
 JANAKIRAMAN SAVITHA

Use:

RESIDENTIAL

Principal Residence:

YES

Mailing Address:

11927 MEADOW VISTA WAY  
 CLARKSVILLE MD 21029-1251

Deed Reference:

/16286/ 00220

**Location & Structure Information**

Premises Address:

11927 MEADOW VISTA WAY  
 CLARKSVILLE 21029-0000

Legal Description:

LOT 22 5.683 A  
 11927 MEADOW VISTA WAY  
 CLEARVIEW ESTATES S 1

Map:	Grid:	Parcel:	Neighborhood:	Subdivision:	Section:	Block:	Lot:	Assessment Year:	Plat No:	8940
0029	0019	0356	5030301.14	3001			22	2023	Plat Ref:	

Town: None

Primary Structure Built	Above Grade Living Area	Finished Basement Area	Property Land Area	County Use
1993	3,940 SF	1000 SF	5.6800 AC	

Stories	Basement	Type	Exterior	Quality	Full/Half Bath	Garage	Last Notice of Major Improvements
2	YES	STANDARD UNIT	SIDING/	5	5 full/ 1 half	1 Attached	

**Value Information**

	Base Value	Value		
		As of 01/01/2023	Phase-In Assessments As of 07/01/2023	As of 07/01/2024
Land:	330,100	316,300		
Improvements	587,600	764,700		
Total:	897,700	1,081,000	958,800	1,019,900
Preferential Land:	0	0		

**Transfer Information**

Seller: CADDIGAN PETER J	Date: 06/24/2015	Price: \$1,035,000
Type: ARMS LENGTH IMPROVED	Deed1: /16286/ 00220	Deed2:
Seller: CARPENTER GREGORY J	Date: 08/11/1997	Price: \$450,000
Type: ARMS LENGTH IMPROVED	Deed1: /03993/ 00101	Deed2:
Seller: NVHOMES LIMITED PARTNERSHIP	Date: 12/30/1992	Price: \$473,975
Type: ARMS LENGTH IMPROVED	Deed1: /02737/ 00653	Deed2:

**Exemption Information**

Partial Exempt Assessments:	Class	07/01/2023	07/01/2024
County:	000	0.00	
State:	000	0.00	
Municipal:	000	0.00 0.00	0.00 0.00

Special Tax Recapture: None

**Homestead Application Information**

Homestead Application Status: Approved 09/02/2015

**Homeowners' Tax Credit Application Information**

Homeowners' Tax Credit Application Status: No Application

Date:

Buyer Inquiry

11927 Meador Vista Way

**Freemon, Robert**

---

**From:** Freemon, Robert  
**Sent:** Tuesday, February 13, 2024 10:44 AM  
**To:** Srinivas Adapa; Ven Sunkara  
**Cc:** Wolf, Kevin  
**Subject:** RE: Septic Inspection Failed on my home purchase - Please help !

Sri,

Once the septic contractor figures out what is wrong with the septic system they will inform the owner of what needs to be fixed. Depending on the severity they may need to apply for a septic repair permit with the Health Dept. If it is just a clog or a cracked pipe the septic contractor may fix it without involving the Health Dept. If a tank or drain field needs to be replaced then the Health Dept. would have to be involved. Which ever part of the septic system needs to be repaired according to the contractors repair permit application is where the Health Dept would focus its efforts.

When it comes to repair permits we cannot require someone to install upgraded components based on current codes/regulations. With a repair permit we can only replace what was already existing. As a Health Dept. we can discuss with the owner what we think would be in there best interest however it would ultimately be up to the homeowner to decide. Only in extreme cases (septic pipe to stream) and/or if structural upgrades (via building permit) are proposed can we require certain upgrades.

If they apply for a repair permit with the Health Dept. we would keep those records. Those records can be available to the public upon completion. You can request those records either by Property Information Act (PIA) request or once the records have been uploaded to our online public file search.

We don't have a condensed check list of items the septic system must meet. We only go by the Howard County Code and Maryland Department of the Environments regulations which are on our website. Hope this helps. If you have any more questions don't hesitate to ask.

Well and Septic Program

Robert "Spencer" Freemon

Phone: 410-313-6357

Email: [rfreemon@howardcountymd.gov](mailto:rfreemon@howardcountymd.gov)

Website: <https://www.howardcountymd.gov/health/well-septic-program>

**From:** Srinivas Adapa <srini\_q8@yahoo.com>  
**Sent:** Thursday, February 8, 2024 3:52 PM  
**To:** Ven Sunkara <ven@venrealestate.com>; Freemon, Robert <rfreemon@howardcountymd.gov>  
**Subject:** Re: Septic Inspection Failed on my home purchase - Please help !

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Thankyou so much Spencer,

The seller of the property agreed to fix the septic system to pass the howard county standards. Is there a checklist that you can share with me or a set of questions that I can ask the seller for assurance that they infact reached out to howard county for inspection.

Is it normal that an owner(seller in my case) call howard county to inspect their septic system and issue them a pass or fail certificate that says that it(that home septic system) conforms to the Howard County Septic Guidelines ?

If the owner(my seller) infact reach out to howard county would have any records or a referencing ticket that the owner from this house requested for an inspection, howard county inspector made a visit on such and such day and here are the finding and recommendations provided by the county inspector.

My apologies for asking such dumb questions not knowing what is it that I can do as a buyer in addition to what I have done so far i.e., to get a contractor do an inspection and provide it to the seller with the failed report. Basically I am trying to cover all bases with respect to my due diligence.

Thanks in advance for your patience with me and my emails..

Best Regards,  
Sri (Srinivas Adapa)  
443 672 8556

On Thursday, February 8, 2024 at 03:27:21 PM EST, Freemon, Robert <[rfreemon@howardcountymd.gov](mailto:rfreemon@howardcountymd.gov)> wrote:

Hi Sri,

In order to figure out what exactly is wrong with the septic system the property owner will have to have it pumped out and inspected again by a septic contractor. Once pumped out, it can be determined whether or not a new system needs to be installed or if a minor repair needs to happen. It could be a clog, broken pipe or used up drain field backing up into the system. No one can know for sure until the system gets pumped out and inspected again.

The Health Dept. does not get involved with the buying and selling of homes. It is up to whoever owns the property to get the septic system serviced. The Health Dept. only gets involved if a building permit for an addition is proposed, the septic is failing to the surface causing a nuisance to the community or for inspections during a septic repair. Hope this helps. If you have any other questions don't hesitate to ask.

Note: If you are not already aware you can look up well and septic property records for homes in Howard County on our website in the Public File Search tab. Not all of our records are on the public file search however a good majority of them are. If they are not on the public file search you can fill out a PIA request (on our website, see signature below) and submit it to the Health Dept.

Well and Septic Program

Robert "Spencer" Freemon

Phone: 410-313-6357

Email: [rffreemon@howardcountymd.gov](mailto:rffreemon@howardcountymd.gov)

Website: <https://www.howardcountymd.gov/health/well-septic-program>

**From:** Srinivas Adapa <[srini\\_q8@yahoo.com](mailto:srini_q8@yahoo.com)>

**Sent:** Monday, February 5, 2024 10:40 AM

**To:** Freemon, Robert <[rffreemon@howardcountymd.gov](mailto:rffreemon@howardcountymd.gov)>; Ven Sunkara <[ven@venrealestate.com](mailto:ven@venrealestate.com)>

**Subject:** Septic Inspection Failed on my home purchase - Please help !

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Subject: Request for Assistance with Septic Inspection - Property at 11927 Meadow Vista Way, Clarksville, MD 21029

Dear Sir/Madam,

My name is Sri (Srinivas Adapa), and I am a resident of Howard County since 2012. My current address is 9307 Holly Brothers Ct, Laurel, MD. I am reaching out to you regarding an issue encountered during the home buying process.

I recently entered into a contract as a buyer for the property located at 11927 Meadow Vista Way, Clarksville, MD 21029. As part of the standard home inspection procedure, I requested a septic inspection. Unfortunately, the inspector discovered that the septic system is backed up. Upon further examination using a camera, it was determined that water is backing up within the septic pipe, rendering the inspection unable to proceed.

Given the gravity of this situation and the complexities involved in the home buying process, I am reaching out to request your assistance with the septic inspection and any county inspections that may be necessary. As a resident of Howard County, I am hopeful that you can provide guidance or support to resolve this issue promptly and effectively.

Your assistance in this matter would be greatly appreciated, as it will help facilitate the timely completion of the home purchase process and ensure the integrity of the property's septic system.

Thank you for your attention to this matter. I am available at 443 672 8556 or via email at [srini\\_q8@yahoo.com](mailto:srini_q8@yahoo.com) if you require any further information or clarification.

Sincerely,

Sri (Srinivas Adapa)

443 672 8556

P.S. Copying my realtor Ven Sukara on this email for his awareness.

Best Regards,

Srinivas

**Freemon, Robert**

---

~~\*~~ Kevin See This

**From:** Srinivas Adapa <srini\_q8@yahoo.com>  
**Sent:** Monday, February 19, 2024 1:52 PM  
**To:** Ven Sunkara; Freemon, Robert  
**Cc:** Wolf, Kevin  
**Subject:** Re: Septic Inspection Failed on my home purchase - Please help !

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Dear Mr. Spencer,

Thank you once again for your prompt response and guidance.

I wanted to share the latest update regarding the septic inspection for the property at 11927 Meadow Vista Way, Clarksville, 21029. Following the failed inspection, the sellers have informed me that they have applied for a permit. Kevin Wolf is scheduled to visit the site on February 20th, 2024, to conduct the PERC test and assess the need for a new septic field and or a new septic tank.

Upon reviewing the original septic application from 1992/1993, it appears that it was approved for a 4-bedroom house. However, the current property now features 6 bedrooms, which is the configuration under which I am purchasing the house. I hope that the sellers will address all aspects highlighted by the Howard County Inspector to ensure compliance with the requirements for a 6-bedroom residence.

I hold the Howard County officials in high regard and have full confidence in the expertise of the inspection team. I remain optimistic that the inspectors will work diligently to remediate any issues identified, ensuring the establishment of a robust and reliable septic system for the property.

Thank you once again for your assistance and support throughout this process.

Best Regards,  
Sri (Srinivas Adapa)

On Tuesday, February 13, 2024 at 10:44:34 AM EST, Freemon, Robert <rfreemon@howardcountymd.gov> wrote:

Sri,

Once the septic contractor figures out what is wrong with the septic system they will inform the owner of what needs to be fixed. Depending on the severity they may need to apply for a septic repair permit with the Health Dept. If it is just a clog



**Return to**

[Collections \(0\)](#) [Cart \(0\)](#) [Account Management](#) [Logout](#)

Logged in as:Edgard & E Chief Uzcatogu...

**\*\*NEW FEE SCHEDULE 2023\*\***

[Click here](#)

NEED HELP CREATING AN APPLICATION?

[CLICK HERE](#)

**Home** **Environmental Health**

[Create an Application or Log a Complaint](#)

[Search Applications](#)

[more](#) ▾

**Record WS-PT-24-00258:**

**Percolation Test Application**

**Record Status: Received**

**Add to cart**  
**Add to collection**

Like 0

Post

[Record Info](#) ▾

[Payments](#) ▾

---

## Record Details

### Applicant:

R & E Chief Septic  
R & E Chief Septic, LLC  
2504 Gillis Road  
Mount Airy, Maryland, 21771  
United States  
Work Phone:4106353237  
Mobile Phone:3015369061  
chiefsep@gmail.com

▶ **More Details**