Repair No:00 AM

PERMIT

SEWAGE DISPOSAL SYSTEM

HOWARD COUNTY HEALTH DEPARTMENT
BUREAU OF ENVIRONMENTAL HEALTH ISSUE DATE

BUREAU OF ENVIRONMENTAL HEALTH 410-313-2640 A -----

A REPATE

P 514980

APPROVAL DATE 3/02/01

Van Sant Plumbing & Heating	IS PERMITTED TO INSTALL ALTER _X_
DDRESS 3 N Main Street, Mt Airy, MD 2177	PHONE 1-800-682-6726
	NUMBER 6 ADDRESS 1811 Quarter Horse Drive
PROPERTY OWNER Teal	PROPERTY OWNER'S ADDRESS
SEPTIC TANK CAPACITYEX: 1250 GALLONS	
PUMP CHAMBER CAPACITY NA GALLON	IS
NUMBER OF BEDROOMS	
SQUARE FEET PER BEDROOM 180	
INEAR FEET OF TRENCH REQUIRED 180	<u></u>
RENCHES: Trenches to be 2 feet wide. Inlet	4 feet below original grade. Bottom maximum depth 8 eet of stone below distribution bex.pipe
OCATION:	eet of storie below distribution per pre
REPAIR - PURPOSE - Existing septic sys	tem has failed. I is opened so sanitarian can recommend repair. 3/14/01
	Hour (10'center to center) off of ex. distributi
box. Check baffles in	septic tanh and replace if necessary.
PLANS APPROVED Steven R. Krieg	DATE 3/15/01
PERMIT VOID AFTER 2 YEARS	
NOTE: CONTRACTOR RESPONSIBLE FOR SCHEDULING A PRE	-CONSTRUCTION INSPECTION FOR ALL INSTALLATIONS
NOTE: TOP OF SEPTIC TANKS ARE TO BE NO DEEPER THAN 3	.0 FEET BELOW FINISH GRADE
NOTE: WATERTIGHT SEPTIC TANKS REQUIRED	
ARE NOT ACCEPTABLE	AND/OR AT 90° SWEEPS IN LINES FROM HOUSE TO DRAIN FIELDS, 90° ELBOWS
NOTE: ALL PARTS OF SEPTIC SYSTEMS (I.E. TANK, DISTRIBUTION OTHERWISE SPECIFICALLY AUTHORIZED	TION BOX, DRAINFIELDS) TO BE 100 FEET FROM ANY WATER WELL UNLESS
NOTE: NO ABSORPTION TRENCH TO EXCEED 100 FEET IN LE	NGTH UNLESS SPECIFICALLY AUTHORIZED
NOTE: ALL PIPE FROM HOUSE TO SEPTIC TANK MUST BE CA	ST IRON OR SCHEDULE 35/40 PVC OR ABS
NOTE: MANHOLE RISERS REQUIRED ON ALL SEPTIC TANKS	AND PUMP CHAMBERS
NOTE: DISTRIBUTION BOXES MUST HAVE BAFFLES	
NOTE: IF PUMPED SEPTIC SYSTEM REQUIRED, (1) SEPTIC PU	MP DETAIL TO BE PROVIDED BY INSTALLER PRIOR TO ISSUANCE OF SEPTIC Y PRIOR TO HEALTH DEPARTMENT APPROVAL OF SEPTIC PERMIT

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM
PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT
CALL 410-313-2640 FOR INSPECTION OF SEPTIC SYSTEM

017100

NOTTOSCALE	
Well	TRENCH DATA
HO-88-1463	TRENCH WIDTH 2 '
7 (75)	TRENCH INLET DEPTH 4'
The tree of the state of the st	TRENCH BOTTOM DEPTH 8'
PERC HOLE	DEPTH OF STONE Y'
	NUMBER OF TRENCHES 2
The Rolling Top	TOTAL TRENCH LENGTH 186'
Approved Son State Or	ABSORBENT AREA 180 ft2
Son Or Stalling DECTS	DISTRIBUTION BOX LEVEL
40	BAFFLE IN DISTRIBUTION BOX
45 27 160	
A) I dark brown	SEPTIC TANK DATA
12" topsoil	SEPTIC TANK Ex: 1250 GALLONS
clay	MANHOLE RISER existing
beige- brown	6 INCH INSPECTION PORT Existing
Sandy	PUMP CHAMBER DATA
}	PUMP CHAMBER
	MANHOLE RISER
2'5"	ALARMNA
QUARTERHORSE DRIVE	PUMP PERFORMANCE TEST NA
PRE-CONSTRUCTION INSPECTION: 3/15/01-MET INSTALLER, PERC FOR OK. INSTRUCTED INSTALLER TO INSTALL 2(90') TRE EX. DISTRIBUTION BOX INTO APPROVED EASEMENT, NEEP TO CHECK EX. BAFFLES IN SEPTIC TANK AND REPLACE IF NE NSPECTION COMMENTS: 3/31/01-INSTALLER REPORTS (SOCIOS CLOS	RENCHES AS DISCUSSED ON REVERSE-OFF RENCHES 10' CENTER TO CENTER, ALL CESSARY-ERW GED D-BOX AND LINES) PROBABLY FROM LACK O
TANK PUMPING, INSTALLER PUT NEW D-BOX IN AND SEAL	
TO SOUTH THE A BAFFLE IN IT, TANK BAFFLE	S WERE IN PLACE (SRU) 3/2/2/01 - OK
70 COVER ALL WORK - (SRU)	
	MANUAL DESIGNATION OF THE PARTY OF THE PARTY OF
	KANDALA ISH SANKE SANKE
O+ 0) 11.	
INSPECTOR Steven R. Wing DATE SYST	TEM APPROVED 3/22/01
ENTIAL ZERA TO BE STEEDING RELIGIOUS	THE STATE OF STATES
THEATE THE THE STATE OF STATE AND THE STATE OF A SERVICE	Webseld - Seek