



Howard County  
Health Department

**Bureau of Environmental Health**

8930 Stanford Boulevard, Columbia, MD 21045

Main: 410-313-2640 | Fax: 410-313-2648

TDD 410-313-2323 | Toll Free 1-866-313-6300

[www.hchealth.org](http://www.hchealth.org)

Facebook: [www.facebook.com/hocohealth](https://www.facebook.com/hocohealth)

Maura J. Rossman, M.D., Health Officer

RECEIPT DATE: 01/14/2021

**ONSITE SEWAGE DISPOSAL SYSTEM**

P 572926

INSTALLATION

APPROVAL DATE: ~12/11/2020

**PERMIT**

A \_\_\_\_\_

**MINOR REPAIR**

PROPERTY ADDRESS: 4545 Ten Oaks Road

SUBDIVISION: Dayton

LOT: n/a TAX ID: 05-377919

CONTRACTOR: Prime Plumbing

EMAIL: Adam.hauf@primeplumbingmd.com

CONTRACTOR ADDRESS: 7617 Baltimore Annapolis Blvd, Glen Burnie, MD 21060

PHONE: 410-421-7161

PROPERTY OWNER: Ding, Chengri; Ding, Hong C T/E

EMAIL: \_\_\_\_\_

OWNER ADDRESS: 4545 Ten Oaks Road, Dayton, MD 21036

PHONE: \_\_\_\_\_

NUMBER OF BEDROOMS: \_\_\_\_\_

SEPTIC TANK SIZE: EX

DRAINFIELD SIZE/TYPE: EX

LOCATION:	
NOTES:	Work was done without permit application or notification to Health. Contractor retroactively applied for permit. COVID 19 Pandemic. No NOV issued.

ISSUED BY: Hank Oswald

ISSUE DATE: 01/14/2021

EXPIRATION DATE: 01/14/2022

NOTE: CONTRACTOR MUST SCHEDULE AN INSPECTION AND GAIN APPROVAL OF ALL COMPONENTS PRIOR TO COVERING

NOTE: AN ELECTRICAL PERMIT IS REQUIRED FOR INSTALLATION OF ANY ELECTRICAL COMPONENTS OF THE SYSTEM

NOTE: MDE RECOMMENDS SEPTIC TANKS, BAT, AND OTHER PRETREATMENT UNITS BE PUMPED AT A FREQUENCY ADEQUATE TO ENSURE THAT SOLIDS ARE NOT DISCHARGED TO THE DISPOSAL AREA

**NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE  
FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM.**

**PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT.**

**CALL 410-313-1771 FOR INSPECTION OF SEPTIC SYSTEM.**

NOT TO SCALE

SEE ATTACHED RECORD

ROAD NAME

**TRENCH/DRAINFIELD DATA**

WIDTH INLET BOTTOM

NUMBER OF TRENCHES \_\_\_\_\_  
TOTAL LENGTH \_\_\_\_\_  
ABSORPTION AREA \_\_\_\_\_  
DISTRIBUTION BOX LEVEL \_\_\_\_\_  
DISTRIBUTION BOX BAFFLE \_\_\_\_\_  
DISTRIBUTION BOX PORT \_\_\_\_\_

**SEPTIC TANK DATA**

SEPTIC TANK 1 LEVEL \_\_\_\_\_

MANUFACTURER \_\_\_\_\_  
CAPACITY \_\_\_\_\_ GAL  
SEAM LOC \_\_\_\_\_  
TANK LID DEPTH \_\_\_\_\_  
BAFFLES \_\_\_\_\_  
BAFFLE FILTER \_\_\_\_\_  
MANHOLE LOC \_\_\_\_\_  
6" PORT LOC \_\_\_\_\_  
WATERTIGHT TEST \_\_\_\_\_  
SLOTTED \_\_\_\_\_  
DATE ON LID \_\_\_\_\_

PUMP/SEPTIC TANK LEVEL \_\_\_\_\_

MANUFACTURER \_\_\_\_\_  
CAPACITY \_\_\_\_\_ GAL  
SEAM LOC \_\_\_\_\_  
TANK LID DEPTH \_\_\_\_\_  
BAFFLES \_\_\_\_\_  
BAFFLE FILTER \_\_\_\_\_  
MANHOLE LOC \_\_\_\_\_  
6" PORT LOC \_\_\_\_\_  
WATERTIGHT TEST \_\_\_\_\_  
SLOTTED \_\_\_\_\_  
DATE ON LID \_\_\_\_\_


PRE-CONSTRUCTION:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

INSTALLATION:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

FINAL INSPECTOR



DATE OF APPROVAL

01/14/2021



# HOWARD COUNTY HEALTH DEPARTMENT

72926

DATE 1/14/24

P15

Received From

Prime Plumbing

PHONE #

774 1129

For

Minor repair - 4545

Ten Oaks Rd.

☐ CASH

☒ CHECK

NO.

4130

Fifty-Five

Dollars

\$

55.00

Received By

J Kemp

**Maura J. Rossman, M.D., Health Officer**

**INFORMATION FORM - SEPTIC SYSTEM REPAIR/UPGRADE**

**Reason for Request:**

- ☒ Failing System  
☐ System relocation for proposed addition  
☐ System upgrade for proposed addition  
☐ Inadequate treatment zone  
☐ Collapsed septic tank  
☐ Collapsed drywell

**Has the septic tank been pumped within the last month?**

☐ Yes Date pumped: \_\_\_\_\_  
☒ No

**Was a visual inspection of the septic tank and/or drain fields conducted?**

☒ Yes Explain observation: Tank has baffles, operating properly at this time; did not see drain fields  
☐ No

**Existing system design**

- ☐ Drywell  
☐ Trench  
☐ Mound  
☒ Unknown  
☐ Other: \_\_\_\_\_

**Was a visual inspection of the sewage line conducted?**

☒ Yes  
☐ No

**Blockage Leading to the field**

☐ Yes Explain \_\_\_\_\_  
☒ No

**Is discharge surfacing on the ground?**

☐ Yes  
☒ No

**Additional Comments:**

Breakage in section of cast iron septic line from house to tank; replace 20' of existing piping and install a clean out.

\*For REPAIRS, are the owners proposing, or do they plan to add in the future any additions or modifications to the property, i.e. pools, living space additions, garages, etc? This information must be disclosed at the time of this application. The Health Department will not be able to accommodate requests in the field for property modifications unrelated to the repair request. Such requests may require an additional fee, testing, and submittal of a Percolation Certification Plan, if the property does not meet current Code and Regulations.

Septic Contractor: Prime Plumbing LLC

Contractor's Phone: 443-774-1129

Contractor's Address: 7617 Baltimore Annapolis Blvd Glen Burnie, MD 21060

Property Address: 4545 Ten Oaks Rd Dayton MD 21036 County File: \_\_\_\_\_

Subdivision: 1001

Lot: \_\_\_\_\_ Year Built: 1976

Owner's Name: Chengri Ding

Existing bedrooms: \_\_\_\_\_

Name of previous owners: \_\_\_\_\_

Existing bedrooms: \_\_\_\_\_

Proposed bedrooms: \_\_\_\_\_

\*A Sanitarian will be in contact within three business days, depending upon the urgency of the situation, to coordinate the scheduling/review of the repair or upgrade.

\*Prior to scheduling inspections, scaled plans should be submitted to clarify the nature of the addition.\*

Print out a copy of Real Property Data via Dept. of Taxation website \_\_\_\_\_ Indexed file found \_\_\_\_\_

If soil/site conditions are limited and sewer and/or Metro District status is not conducive to connection, the Sanitarian may recommend pursuit of Emergency Sewer Extension or Emergency Metro District Inclusion. The Owner should contact the Bureau of Utilities for details.

No permit is to be issued nor inspection to be scheduled without prior fee collection at the office unless an emergency exists.

The contractor is to notify the office of the emergency as soon as possible.

2/2020

## Cabahug, Joseph

---

**From:** Adam Hauf <adam.hauf@primeplumbingmd.com>  
**Sent:** Thursday, February 4, 2021 10:15 AM  
**To:** Cabahug, Joseph  
**Subject:** Fwd: 4545 Ten Oaks Rd : Septic Repair  
**Attachments:** a95be064-e9d3-4d8a-a6a6-03330df8607d\_cdv\_photo\_001.jpg; a4751ad3-f016-4098-9a0c-97166794da8f\_cdv\_photo\_002.jpg; e3afdb7d-ad23-465f-b4dc-0f9a482a1e99\_cdv\_photo\_008.jpg; 3770845a-d01b-4719-a3fd-df2439da6362\_cdv\_photo\_009.jpg; 6088c400-048b-4089-97f1-c26ae8606e57\_cdv\_photo\_007.jpg; 373328a6-6a50-4033-80c2-733a440065d8\_cdv\_photo\_016.jpg; 4a1ec87b-a9e5-4f78-b923-0b70290729f2\_cdv\_photo\_017.jpg; f207f2be-6f80-48dc-bc20-fa11f4380954\_cdv\_photo\_018.jpg

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Adam Hauf  
Operations Manager  
**Prime Plumbing**  
410-371-6385  
7617 Baltimore Annapolis Blvd. Glen Burnie, MD 21060

<https://primeplumbingmd.com/>

----- Forwarded message -----

**From:** Adam Hauf <[adam.hauf@primeplumbingmd.com](mailto:adam.hauf@primeplumbingmd.com)>  
**Date:** Fri, Dec 11, 2020 at 4:34 PM  
**Subject:** 4545 Ten Oaks Rd : Septic Repair  
**To:** <[hoswald@howardcountymd.gov](mailto:hoswald@howardcountymd.gov)>

Hi Hank,

Thanks again for all of your help today; attached are pictures of the repair completed at the above property in Dayton, MD 21036 today.

Please let me know if you need anything else, we will also mail in the permit application.

Happy Holidays,

Adam

Adam Hauf  
Operations Manager  
**Prime Plumbing**  
410-371-6385  
7617 Baltimore Annapolis Blvd. Glen Burnie, MD 21060












**PRIME**  
PLUMBING  
COMMERCIAL & RESIDENTIAL  
USDOT 2589270









## Cabahug, Joseph

---

**From:** Adam Hauf <adam.hauf@primeplumbingmd.com>  
**Sent:** Thursday, February 4, 2021 10:15 AM  
**To:** Cabahug, Joseph  
**Subject:** Fwd: 4545 Ten Oaks Rd : Septic Repair  
**Attachments:** a95be064-e9d3-4d8a-a6a6-03330df8607d\_cdv\_photo\_001.jpg; a4751ad3-f016-4098-9a0c-97166794da8f\_cdv\_photo\_002.jpg; e3afdb7d-ad23-465f-b4dc-0f9a482a1e99\_cdv\_photo\_008.jpg; 3770845a-d01b-4719-a3fd-df2439da6362\_cdv\_photo\_009.jpg; 6088c400-048b-4089-97f1-c26ae8606e57\_cdv\_photo\_007.jpg; 373328a6-6a50-4033-80c2-733a440065d8\_cdv\_photo\_016.jpg; 4a1ec87b-a9e5-4f78-b923-0b70290729f2\_cdv\_photo\_017.jpg; f207f2be-6f80-48dc-bc20-fa11f4380954\_cdv\_photo\_018.jpg

[Note: This email originated from outside of the organization. Please only click on links or attachments if you know the sender.]

Adam Hauf  
Operations Manager  
**Prime Plumbing**  
410-371-6385  
7617 Baltimore Annapolis Blvd. Glen Burnie, MD 21060

<https://primeplumbingmd.com/>

----- Forwarded message -----

**From:** Adam Hauf <[adam.hauf@primeplumbingmd.com](mailto:adam.hauf@primeplumbingmd.com)>  
**Date:** Fri, Dec 11, 2020 at 4:34 PM  
**Subject:** 4545 Ten Oaks Rd : Septic Repair  
**To:** <[hoswald@howardcountymd.gov](mailto:hoswald@howardcountymd.gov)>

Hi Hank,

Thanks again for all of your help today; attached are pictures of the repair completed at the above property in Dayton, MD 21036 today.

Please let me know if you need anything else, we will also mail in the permit application.

Happy Holidays,

Adam

Adam Hauf  
Operations Manager  
**Prime Plumbing**  
410-371-6385  
7617 Baltimore Annapolis Blvd. Glen Burnie, MD 21060



<https://primeplumbingmd.com/>

