

CASELL TESTING, INC.

ENVIRONMENTAL SAMPLING AND TESTING
10940 BEAVER DAM ROAD, HUNT VALLEY, MD 21030-2211
(410) 252-7742

REPORT DATE: Nov 20, 2004

County Howard

Lab Number 04-6372

Sample iced Yes
Residual Cl₂ <0.1 mg/L Yes

cc: County Health Dept. Yes

CERTIFICATE OF ANALYSIS

Maryland State Certified Water Quality
Laboratory No. 115

REQUESTER: Ms. Marybeth Teklits
3242 Huntersworth Way
Woodbine, Maryland 21797

Property Sampled: U&O: 3242 Huntersworth Way, NEW WELL

Station Sampled: Powder Room Tap & Pressure Tank

Tax Map #: 14

Date/Time Sampled: Nov 19, 2004 11:25 am

Parcel #: 264

Owner, Telephone No.: Teklits

Sampler: 6724GP

Subdivision Name: Wellington III

Lot Number: 14

Building Permit No.:

Well Number: HO-94-3991

Observation: 2-Piece Cap
Satisfactory

RESULTS OF ANALYSIS:

PARAMETER	RESULT	METHOD	*MCL/**SMCL	
Nitrate	1.5 mg/L as N	SM 4500D	*10 mg/L as N	Pass
Turbidity (Raw)	<1.0 NTU	EPA 180.1	*10 NTU	Pass
pH	5.4 Units	EPA 150.1	**6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	Absent	SM 9223B	*Absent	SAFE
E. coli (18 Hour Test)	Absent	SM 9223B	*Absent	SAFE

Treatment/Conditioning: Sediment filter

***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, odor, or color) in drinking water.

Heather R. Beam

Heather R. Beam

*MCL = Maximum Contamination Level
**SMCL = Secondary Maximum Contamination Level