



CERTIFICATE OF ANALYSIS

Requester:
 Ms. Michelle Coleman
 13102 Williamfield Drive
 Ellicott City, Maryland 21042

S/O Number: 68894
Report Date: July 7, 2008

Property Sampled: 13102 Williamfield Drive

County: Howard
Subdivision: Coleman Property **Tax Map #:** 22
Lot #: 2 **Parcel #:** 571
Building Permit #: B07001636

Date/Time Collected: July 3, 2008 at 11:38 am
Date/Time Received: July 3, 2008 at 12:30 pm

Sample Location: Pressure Tank **Samples Iced:** Yes
Sampler ID: 6308KW **Residual Cl₂ <0.1 mg/L:** Yes

Well Tag Number: HO-95-0534
Well Condition: 2-Piece Cap
 Satisfactory

Water Conditioning/Treatment: None

PARAMETER	RESULT	METHOD	MCL	
Total Coliform	Absent	SM 9223B	Absent	Pass
E.coli	Absent	SM 9223B	Absent	Pass

Allison R. Milburn
 Allison R. Milburn
 Manager-Drinking Water Testing