

CERTIFICATE OF ANALYSIS

Requester:
Douglas Homes
5034 Dorsey Hall Drive Suite 102
Ellicott City, Maryland 21041

S/O Number: 66168
Report Date: November 20, 2007



Property Sampled: 14315 Roxbury Meadow, 21738

County: Howard
Subdivision: Clarks Meadow
Lot #: 24
Building Permit #: B07001178
Tax Map #: 21
Parcel #: 271

Date/Time Collected: November 19, 2007 at 12:10 pm
Date/Time Received: November 19, 2007 at 1:35 pm

Sample Location: Laundry Tub Tap
Sampler ID: 5745KC
Samples Iced: Yes
Residual Cl₂ <0.1 mg/L: Yes

Well Tag Number: Tag Buried
Well Condition: 2-Piece Cap
Cap Removable
4 Bolts Missing

Water Conditioning/Treatment: None

PARAMETER	RESULT	METHOD	MCL/*SMCL	
Nitrate	5.8 mg/L as N	SM 4500D	10 mg/L as N	Pass
Turbidity	<1.0 NTU	EPA 180.1	10 NTU	Pass
pH	6.3 Units	EPA 150.1	*6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	Absent	SM 9223B	Absent	Pass
E.coli	Absent	SM 9223B	Absent	Pass

Allison R. Milburn
Allison R. Milburn
Manager-Drinking Water Testing

MCL=Maximum Contamination Level
*SMCL=Secondary Maximum Contamination Level
***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, color or odor) in drinking water.

Trace Laboratories, Inc.
Maryland

5 North Park Drive
Hunt Valley, MD 21030
Telephone: 410/252-7742
Telephone: 410/584-9099
Fax: 410/584-9117
Email: tracelab@comnext.net
www.tracelabs.com

Maryland State Certified
Water Quality Laboratory
No. 318

ISO 9001:2000



Cert No. C2005-01504