

CERTIFICATE OF ANALYSIS



Requester:
 NV Homes, Inc
 Attn: Buddy
 6085 Marshalee Drive Suite 130
 Elkridge, Maryland 21075

S/O Number: 66225
Report Date: November 27, 2007

**Trace Laboratories, Inc.
 Maryland**

5 North Park Drive
 Hunt Valley, MD 21030
 Telephone: 410/252-7742
 Telephone: 410/584-9099
 Fax: 410/584-9117
 Email: tracelab@connxxt.net
 www.tracelabs.com

Maryland State Certified
 Water Quality Laboratory
 No. 318

ISO 9001:2000



FERRY JOHNSON
 REGISTRARS, INC.
 Cert No. C2005-01504

Property Sampled: 12810 Macbeth Farm Road

County: Howard
Subdivision: Clarksville Overlook **Tax Map #:** 34
Lot #: 35 **Parcel #:** 90
Building Permit #: Not Provided

Date/Time Collected: November 26, 2007 at 3:15 pm
Date/Time Received: November 26, 2007 at 4:35 pm

Sample Location: Pressure Tank Tap
Sampler ID: 5745KC
Samples Iced: Yes
Residual Cl₂ <0.1 mg/L: Yes

Well Tag Number: HO-95-0302
Well Condition: 2-Piece Cap
 Satisfactory

Water Conditioning/Treatment: Neutralizer

PARAMETER	RESULT	METHOD	MCL/*SMCL	
Nitrate	<1.0 mg/L as N	SM 4500D	10 mg/L as N	Pass
Turbidity	1.3 NTU	EPA 180.1	10 NTU	Pass
pH	8.4 Units	EPA 150.1	*6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	PRESENT	SM 9223B	Absent	FAIL
E.coli	Absent	SM 9223B	Absent	

Allison R. Milburn
 Allison R. Milburn
 Manager- Drinking Water Testing

MCL=Maximum Contamination Level
 *SMCL=Secondary Maximum Contamination Level
 ***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, color or odor) in drinking water.