

CERTIFICATE OF ANALYSIS



Requester:
Dale Thompson Builders
6300 Woodside Court
Columbia, Maryland 21046

S/O Number: 61751
Report Date: January 23, 2007

**Trace Laboratories, Inc.
Maryland**

5 North Park Drive
Hunt Valley, MD 21030
Telephone: 410/252-7742
Telephone: 410/584-9099
Fax: 410/584-9117
Email: tracelab@connext.net
www.tracelabs.com

Maryland State Certified
Water Quality Laboratory
No. 318

ISO 9001:2000



PERRY JOHNSON
REGISTRARS, INC.
Cert No. C2005-01504

Property Sampled: 7024 Preservation Court

County: Howard
Subdivision: Pindell Woods
Lot #: 33
Building Permit #: B00158858

Tax Map #: 41
Parcel #: 274

Date/Time Collected: January 22, 2007 at 1:02 pm
Date/Time Received: January 22, 2007 at 3:15 pm

Sample Location: Powder Room Tap & Pressure Tank Tap
Sampler ID: 6308KW
Samples Iced: Yes
Residual Cl₂ <0.1 mg/L: Yes

Well Tag Number: HO-94-2997
Well Condition: 2-Piece Cap
Satisfactory

Water Conditioning/Treatment: Sediment Filter

PARAMETER	RESULT	METHOD	MCL/*SMCL	
Nitrate	<1.0 mg/L as N	SM 4500D	10 mg/L as N	Pass
Turbidity(Raw)	2.4 NTU	EPA 180.1	10 NTU	Pass
Turbidity(Treated)	1.5 NTU	EPA 180.1	10 NTU	Pass
pH	6.2 Units	EPA 150.1	*6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	Absent	SM 9223B	Absent	Pass
E.coli	Absent	SM 9223B	Absent	Pass

Heather R. Beam
Heather R. Beam
Manager-Drinking Water Testing

MCL=Maximum Contamination Level

*SMCL=Secondary Maximum Contamination Level

***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, color or odor) in drinking water.