

CERTIFICATE OF ANALYSIS



TRACE LABORATORIES-EAST

Headquarters
 5 North Park Drive
 Hunt Valley, MD 21030
 Telephone: 410/252-7742
 Telephone: 410/584-9099
 Fax: 410/584-9117
 Email:
 tracelab@connext.net
 www.tracelabs.com

Maryland State Certified
 Water Quality Laboratory
 No. 318

Requester:
 NV Homes, Inc
 Attn: Buddy
 6085 Marshalee Drive Suite 130
 Elkridge, Maryland 21075

S/O Number: 07-0087
Report Date: May 8, 2006

Property Sampled: 14855 Union Chapel Road, Retest #1

County: Howard
Subdivision: Warfield Estates
Lot #: 1
Building Permit #: B00156717
Tax Map #: 14
Parcel #: 154

Date/Time Collected: May 5, 2006 at 11:45 am
Date/Time Received: May 5, 2006 at 12:20 pm

Sample Location: Pressure Tank Tap
Sampler ID: 6724GP
Samples Iced: Yes
Residual Cl₂ <0.1 mg/L: Yes

Well Tag Number: HO-94-4027
Well Condition: 2-Piece Cap
 Satisfactory

Water Conditioning/Treatment: None

PARAMETER	RESULT	METHOD	MCL	
Total Coliform	PRESENT	SM 9223B	Absent	Fail
E.coli	Absent	SM 9223B	Absent	

Heather R. Beam
 Heather R. Beam
 Manager-Drinking Water Testing

MCL=Maximum Contamination Level

CERTIFICATE OF ANALYSIS



Trace Laboratories, Inc.
Maryland

5 North Park Drive
Hunt Valley, MD 21030
Telephone: 410/252-7742
Telephone: 410/584-9099
Fax: 410/584-9117
Email: tracelab@connex.net
www.tracelabs.com

Maryland State Certified
Water Quality Laboratory
No. 318

ISO 9001:2000



Cert No. C2005-01504

Requester:
NV Homes, Inc
Attn: Brandon
6085 Marshalee Drive Suite 130
Elkridge, Maryland 21075

S/O Number: 62797
Report Date: April 6, 2007

Property Sampled: 14855 Union Chapel Road, 21797

County: Howard
Subdivision: Mew Woods
Lot #: 1
Building Permit #: N/A
Tax Map #: 14
Parcel #: 154

Date/Time Collected: April 5, 2007 at 9:00 am
Date/Time Received: April 5, 2007 at 2:30 pm

Sample Location: Bathroom Tap
Sampler ID: 6308KW
Samples Iced: Yes
Residual Cl₂ <0.1 mg/L: Yes

Well Tag Number: HO-94-4027
Well Condition: 2-Piece Cap
Satisfactory

Water Conditioning/Treatment: Sediment Filter

PARAMETER	RESULT	METHOD	MCL/*SMCL	
Nitrate	9.0 mg/L as N	SM 4500D	10 mg/L as N	Pass
Turbidity	<1.0 NTU	EPA 180.1	10 NTU	Pass
pH	6.8 Units	EPA 150.1	*6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	Absent	SM 9223B	Absent	Pass
E.coli	Absent	SM 9223B	Absent	Pass

Allison R. Milburn
 Manager- Drinking Water Testing

MCL=Maximum Contamination Level

*SMCL=Secondary Maximum Contamination Level

***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, color or odor) in drinking water.