

CERTIFICATE OF ANALYSIS



Requester:
Dale Thompson Builders
6300 Woodside Court
Columbia, Maryland 21046

S/O Number: 62579
Report Date: March 23, 2007

Property Sampled: 7200 Preservation Court

County: Howard
Subdivision: Pindell Woods
Lot #: 24
Building Permit #: B00129871
Tax Map #: 41
Parcel #: 274

Date/Time Collected: March 22, 2007 at 1:45 pm
Date/Time Received: March 22, 2007 at 2:40 pm

Sample Location: Sink Tap near Kitchen
Sampler ID: 3175BH
Samples Iced: Yes
Residual Cl₂ <0.1 mg/L: Yes

Well Tag Number: HO-94-3429
Well Condition: 2-Piece Cap
Satisfactory

Water Conditioning/Treatment: Sediment Filter Bypassed

PARAMETER	RESULT	METHOD	MCL/*SMCL	
Nitrate	<1.0 mg/L as N	SM 4500D	10 mg/L as N	Pass
Turbidity	<1.0 NTU	EPA 180.1	10 NTU	Pass
pH	4.8 Units	EPA 150.1	*6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	Absent	SM 9223B	Absent	Pass
E.coli	Absent	SM 9223B	Absent	Pass

**Trace Laboratories, Inc.
Maryland**

5 North Park Drive
Hunt Valley, MD 21030
Telephone: 410/252-7742
Telephone: 410/584-9099
Fax: 410/584-9117
Email: tracelab@connext.net
www.tracelabs.com

Maryland State Certified
Water Quality Laboratory
No. 318

ISO 9001:2000



Cert No. C2005-01504

Allison R. Milburn
Allison R. Milburn
Manager-Drinking Water Testing

MCL=Maximum Contamination Level

*SMCL=Secondary Maximum Contamination Level

***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, color or odor) in drinking water.