

FOUNTAIN VALLEY ANALYTICAL LABORATORY, INC.

1413 Old Taneytown Rd. Westminster, MD (410) 848-1014 (410) 876-4554 FAX (410) 848-0298

REPORT OF ANALYSIS

Laboratory ID #:	63677	Account #:	9206
Reference:	Debbie & Russ Compton	Company:	CASH ACCOUNT
Location:	18220 Penn Shop Road Mount Airy, MD 21771	Requested By:	Debbie & Russ Compton
Date/ Time Collected:	6/11/2007 1105	Source:	Well Water
Date/Time Rec'd:	6/11/2007 1322	Site:	Pressure Tank
Chlorine ppm:	Free: ND Total: ND	Treatment:	Sediment Filter/Softener**
Collected By:	J.Yeager 6176JY	pH:	6.5
		Well #:	HO-95-0091

PARAMETERS	RESULTS	UNITS	REFERENCE	METHOD	DATE/TIME/ANALYST
Iron	3.03	mg/L	0.3	FR, 45 (126)	6/11/2007 / 1430 / AD/BD
Turbidity	45.9	NTU	<10	SM18 2130B	6/11/2007 / 1420 / AD/BD

NOTES:

- 1 **Sample collected prior to treatment
- 2 mg/L = milligrams per liter (also, parts per million)
- 3 NTU = Nephelometric Turbidity Units
- 4 Results less than or within the reference range are considered satisfactory and within potable water limits at the time of sampling.
- 5 ND:None Detected
- 6 Visual well check: Scaled, vented cap
- 7 pH tested on-site

Reason for Test : Use & Occupancy retest 63003
 Building Permit # : B06000195

Date Reported: 6/12/2007

FOUNTAIN VALLEY ANALYTICAL LABORATORY, INC.

1413 Old Taneytown Rd. Westminster, MD (410) 848-1014 (410) 876-4554 FAX (410) 848-0298

REPORT OF ANALYSIS

Laboratory ID #:	63678	Account #:	9206
Reference:	Debbie & Russ Compton	Company:	CASH ACCOUNT
Location:	18220 Penn Shop Road Mount Airy, MD 21771	Requested By:	Debbie & Russ Compton
Date/ Time Collected:	6/11/2007 1110	Source:	Well Water
Date/Time Rec'd:	6/11/2007 1322	Site:	Kitchen Sink Tap
Chlorine ppm:	Free: ND Total: ND	Treatment:	Sediment Filter/Softener
Collected By:	J.Yeager 6176JY	pH:	6.7
		Well #:	HO-95-0091

PARAMETERS	RESULTS	UNITS	REFERENCE	METHOD	DATE/TIME/ANALYST
Iron	<0.01	mg/L	0.3	FR, 45 (126)	6/11/2007 / 1430 / AD/BD
Turbidity	0.83	NTU	<10	SM18 2130B	6/11/2007 / 1420 / AD/BD

NOTES:

- 1 mg/L = milligrams per liter (also, parts per million)
- 2 NTU = Nephelometric Turbidity Units
- 3 Results less than or within the reference range are considered satisfactory and within potable water limits at the time of sampling.
- 4 ND:None Detected
- 5 Visual well check: Sealed, vented cap
- 6 pH tested on-site

Reason for Test : Use & Occupancy retest 63003

Building Permit # : B06000195

Date Reported: 6/12/2007