

CERTIFICATE OF ANALYSIS



Requester:
Trinity Homes/TBI Homes
3675 Park Avenue Suite 301
Ellicott City, Maryland 21043

S/O Number: 66045
Report Date: November 12, 2007

Property Sampled: 13447 Highland Road, 21029

County: Howard
Subdivision: Chris Mar Est Sec 2
Lot #: 5
Building Permit #: B07000072
Tax Map #: 34
Parcel #: 381

Date/Time Collected: November 9, 2007 at 12:20 pm
Date/Time Received: November 9, 2007 at 1:23 pm

Sample Location: Downstairs Bathroom Tap & Pressure Tank
Sampler ID: 5745KC
Samples Iced: Yes
Residual Cl₂ <0.1 mg/L: Yes

Well Tag Number: HO-94-3975
Well Condition: 2-Piece Cap
Satisfactory

Water Conditioning/Treatment: Sediment Filter

Trace Laboratories, Inc.
Maryland

5 North Park Drive
Hunt Valley, MD 21030
Telephone: 410/252-7742
Telephone: 410/584-9099
Fax: 410/584-9117
Email: tracelab@connext.net
www.tracelabs.com

Maryland State Certified
Water Quality Laboratory
No. 318

ISO 9001:2000



Cert No. C2005-01504

PARAMETER	RESULT	METHOD	MCL/*SMCL	
Nitrate	3.9 mg/L as N	SM 4500D	10 mg/L as N	Pass
Turbidity (Raw)	5.3 NTU	EPA 180.1	10 NTU	Pass
Turbidity (Treated)	1.5 NTU	EPA 180.1	10 NTU	Pass
pH (Raw)	5.8 Units	EPA 150.1	*6.5-8.5 Units	***
pH (Treated)	5.9 Units	EPA 150.1	*6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	Absent	SM 9223B	Absent	Pass
E.coli	Absent	SM 9223B	Absent	Pass

Allison R. Milburn
Manager-Drinking Water Testing

MCL=Maximum Contamination Level

*SMCL=Secondary Maximum Contamination Level

***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, color or odor) in drinking water.