

# APPLICATION

PERCOLATION TESTING

A 33667

P \_\_\_\_\_

HOWARD COUNTY HEALTH DEPARTMENT  
BUREAU OF ENVIRONMENTAL HEALTH  
3525-H ELLICOTT MILLS DRIVE/ELLICOTT CITY, MARYLAND 21043  
TELEPHONE: 313-2840

DISTRICT \_\_\_\_\_

DATE \_\_\_\_\_

TO: THE COUNTY HEALTH OFFICER  
ELLICOTT CITY, MARYLAND

LOT 2  
EX. HOUSE, WELL, SEPTIC SYSTEM  
A-33667  
"WALK-OUT" REQUIRED (CW)

I HEREBY APPLY FOR THE NECESSARY TEST PRIOR TO APPLICATION FOR PERMIT TO CONSTRUCT (OR RECONSTRUCT) A SEWAGE DISPOSAL SYSTEM.

PROPERTY OWNER RANDY L. HINZMAN

ADDRESS 820 HOODS MILL RD. COOKSVILLE MD. 21723 PHONE (301) 854-6182

AGENT OR PROSPECTIVE BUYER COLIN PORTER

ADDRESS 12707 CLAXTON RD., LAUREL, MD. 20708 PHONE (301) 604-1550

PROPERTY LOCATION:

SUBDIVISION HINZMAN PROPERTY LOT NO. 2

ROAD AND DESCRIPTION W. SIDE ROUTE 97, 5000' N. OF OLD FREDERICK RD

TAX MAP 8 PARCEL # 204

SIZE OF LOT OVER 3 AC TYPE BLDG. (SINGLE FAMILY DWELLING OR COMMERCIAL)

THE SYSTEM INSTALLED UNDER THIS APPLICATION IS ACCEPTABLE ONLY UNTIL PUBLIC FACILITIES BECOME AVAILABLE. I FULLY UNDERSTAND THE FEE CONNECTED WITH THE FILING OF THIS PERC TEST APPLICATION IS NON-REFUNDABLE UNDER ANY CIRCUMSTANCES. I ALSO AGREE TO COMPLY WITH ALL M.O.S.H.A. REQUIREMENTS IN TESTING THIS LOT. Colin Porter  
(SIGNATURE OF APPLICANT)

APPROVED BY \_\_\_\_\_ FOR \_\_\_\_\_ DATE \_\_\_\_\_

DISAPPROVED BY \_\_\_\_\_ FOR \_\_\_\_\_ DATE \_\_\_\_\_

HOLD PENDING FURTHER TESTS \_\_\_\_\_

REASONS FOR REJECTION OR HOLDING \_\_\_\_\_

PERCOLATION TEST PLAT/PRELIMINARY PLAT - TITLE OR I.D. # \_\_\_\_\_ DATE \_\_\_\_\_

SITE DEVELOPMENT PLAN/FINAL PLAT - TITLE OR I.D. # \_\_\_\_\_ DATE \_\_\_\_\_

# THIS IS NOT A PERMIT

Hinzman Lot 2 (existing house)

COUNTY #  
A33667

SOIL PROFILE

0' [Empty vertical box for soil profile data]

[Empty vertical box for soil profile data]

[Empty vertical box for soil profile data]


SOIL PROFILE

0' [Empty vertical box for soil profile data]

INDICATE NORTH - NAME ADJOINING ROADWAY AS BASE LINE.

DATE	TEST NO.	DEPTH	PRE-WET		TEST - 1" DROP		TIME
			START	STOP	START	STOP	
4/11/95		Not tested -	Existing	Septic	Not		
		where shown on <sup>pre</sup> plat					
		- proposed (previously tested) SDA site includes part of one swale and is close to another swale, is terraced, slope suggest some grading and has a nearby rock outcrop. Extent of usable septic area for this lot is questionable. Also part of existing septic trench may be on proposed lot #3.					

REMARKS \_\_\_\_\_

TYPE OF SOIL \_\_\_\_\_

TESTED BY *[Signature]* ALSO PRESENT \_\_\_\_\_

TRENCH DESIGN DATA: AVERAGE PERCOLATION TIME \_\_\_\_\_ TRENCH WIDTH \_\_\_\_\_

INLET DEPTH \_\_\_\_\_ MAXIMUM BOTTOM DEPTH \_\_\_\_\_ SQ. FT/BEDROOM \_\_\_\_\_