

# APPLICATION

PERCOLATION TESTING

A 08567

P \_\_\_\_\_

HOWARD COUNTY HEALTH DEPARTMENT  
BUREAU OF ENVIRONMENTAL HEALTH

P.O. BOX 476 ELLICOTT CITY, MARYLAND 21043  
TELEPHONE: 461-9933

DISTRICT 5

DATE 12/17/86

TO: THE COUNTY HEALTH OFFICER  
ELLICOTT CITY, MARYLAND

I, HEREBY, APPLY FOR THE NECESSARY TEST IN ORDER TO CONSTRUCT (OR RECONSTRUCT) A SEWAGE DISPOSAL SYSTEM.

461-1165

PROPERTY OWNER Altogether Limited Partnership Firetti Homes, INC

ADDRESS 10176 Baltimore National Pike Suite 210 PHONE 465-5855

PROSPECTIVE BUYER \_\_\_\_\_

ADDRESS \_\_\_\_\_ PHONE final 8 see 2

PROPERTY LOCATION:

SUBDIVISION Altogether Twelve Hills LOT NO. 8

ROAD AND DESCRIPTION Linden Church Rd + Rt 32 13006 Twelve Hills Rd.

TAX MAP 28 PARCEL # 66

SIZE OF LOT 3 acres TYPE BLDG. SFD  
(SINGLE FAMILY DWELLING OR COMMERCIAL)

THE SYSTEM INSTALLED UNDER THIS APPLICATION IS ACCEPTABLE ONLY UNTIL PUBLIC FACILITIES BECOME AVAILABLE. I FULLY UNDERSTAND THE FEE CONNECTED WITH THE FILING OF THIS PERC TEST APPLICATION IS NON-REFUNDABLE UNDER ANY CIRCUMSTANCES. I ALSO AGREE TO COMPLY WITH ALL M.O.S.H.A. REQUIREMENTS IN TESTING THIS LOT.

Mal S Kent  
(SIGNATURE OF APPLICANT)

APPROVED BY \_\_\_\_\_ FOR \_\_\_\_\_ DATE \_\_\_\_\_

REJECTED BY \_\_\_\_\_ FOR \_\_\_\_\_ DATE \_\_\_\_\_

HOLD PENDING FURTHER TESTS \_\_\_\_\_ DATE \_\_\_\_\_


REASONS FOR REJECTION OR HOLDING 1/29/87 - Wet Season or Change Area R 14

2-4-87 Hold For Subdivision PLAT EXPAND Field TO 125'x80' Building  
OFF LOW WATER HOLE AND Keep System SHALLOW. S. Hall

BDDG. PERMIT SIGNED  
AND RETURNED 9-19-88  
BP 20917

# THIS IS NOT A PERMIT

4578



LIVE BETWEEN  
LOT 98 & LOT 99

Lot 8

1/2 PERC 8min  
 180° 1/2R  
 INLET 3.5'  
 BOTTOM 5'

Change field to 125' x 80'  
pulling up hill of water hole #3

INDICATE NORTH - NAME ADJOINING ROADWAY AS BASE LINE

LINDEN CHAPEL RD

| DATE    | TEST NO.   | DEPTH.    | PRE-WET      |            | TEST - 1" DROP |            | TIME    |
|---------|------------|-----------|--------------|------------|----------------|------------|---------|
|         |            |           | START        | STOP       | START          | STOP       |         |
| 1/29/87 | 1 S<br>1 V | 5<br>13   | 317<br>LOOKS | 320        | 320<br>OK      | 326        | 6       |
| 1/29/87 | 2 S<br>2 D | 5<br>7.5  | 323<br>322   | 326<br>332 | 326<br>332     | 332<br>402 | 6<br>20 |
| 1/29/87 | 2 V        | 12        | LOOKS        |            | OK             |            |         |
| 11 11   | 3 S<br>3 V | 4<br>11.5 | 356<br>N/A   | 359<br>OK  | 359<br>OK      | 405<br>47  | 6       |
| 11 11   | 4 S<br>4 V | 5<br>12.5 | 401<br>LOOKS | 402        | 402            | 403        | 2       |
|         |            |           |              |            |                |            | (11)    |
|         |            |           |              |            |                |            |         |
|         |            |           |              |            |                |            |         |
|         |            |           |              |            |                |            |         |
|         |            |           |              |            |                |            |         |

only

ar lms  
8 men  
max  
depth  
3.5 ft

REMARKS

TYPE OF SOIL

TESTED BY

Holes appear to be dug similar to  
etch plan of Dec 1986  
SOIL snow covered ground

B HONGOS

**ALSO PRESENT**

DAVID  
WILSON  
MON  
CLINT

2 KETERMAYK

510